NOTICE OF USE AND DISCLAIMER

PLEASE READ CAREFULLY

The attached Asbestos Survey Report ("Report") was provided to Regions Bank for the property located at the street address stated in the Report ("Property") on or about the date stated in the Report ("Date") by the company stated in the Report ("Provider").

The Report on the Property is not current and may not be relied on by a register bidder or any third party in deciding whether to submit a bid for the Property ("Bidder") or in determining the amount of any bid ("Bid Amount").

Regions Bank is providing the Report as part of the auction process only because the Report is in the possession of Regions Bank.

Regions Bank makes no representation or warranty of any nature that the Report for the Property is accurate, correct, current, or complete.

Regions Bank is selling the Property "as is, where is, and with all faults."

Any Bidder is directed to the Auction Purchase and Sale Agreement form for the terms and conditions of the sale of the Property.

Any Bidder must conduct Bidder's own independent and investigation and evaluation of the Property in all respects in making any decisions of any nature relating to any and all Bid Amounts.

ANY BIDDER PROCEEDING TO READ OR REVIEW THE REPORT REPRESENTS TO REGIONS BANK THAT BIDDER IS NOT RELYING ON THE REPORT IN ANY MANNER (A) IN DECIDING WHETHER TO SUBMIT A BID FOR THE PROPERTY, (B) IN DETERMINING WHETHER THE CONDITION OF THE PROPERTY IS SUITABLE FOR A PARTICULAR USE OR OTHERWISE IN ACCEPTABLE CONDITION, (C) IN DETERMINING THE BID AMOUNT, AND/OR (D) AS A SUBSTITUTE FOR CONDUCTING OR AS A PART OF BIDDER'S INDEPENDENT INVESTIGATION AND EVALUATION OF THE PROPERTY.

ASBESTOS SURVEY REPORT

RUTHERFORD COST CENTER NO. RFC022694 202 EAST MAIN STREET RUTHERFORD, TENNESSEE

Terracon Project No. A8107001 PO No. CA118986

February 8, 2010



Prepared for:

REGIONS FINANCIAL CORPORATION c/o CB RICHARD ELLIS BIRMINGHAM, ALABAMA

Prepared by:

Tierracon Bartlett, Tennessee February 8, 2010

Consulting Engineers & Scientists

Regions Financial Corporation c/o CB Richard Ellis 250 Riverchase Parkway, Suite 600 Birmingham, Alabama 35244

Attn: Ms. Michelle Long

Re: Asbestos Survey Site Name: Rutherford Cost Center No. RFC022694 202 East Main Street Rutherford, Tennessee Terracon Project No. A8107001

Dear Ms. Long:

The purpose of this report is to present the results of an asbestos survey performed on January 20, 2010, at the above referenced building in Rutherford, Tennessee. This survey was conducted in general accordance with our Task Order dated January 6, 2010, in accordance with the Master Service Agreement dated April 11, 2003. We understand that this survey was requested due to the planned renovation of the facility.

Non-friable asbestos-containing materials were identified. Please refer to the attached report for details.

Terracon Consultants, Inc. (Terracon) appreciates the opportunity to provide this service to Regions Financial Corporation c/o CB Richard Ellis. If you have any questions regarding this report, please contact the undersigned at 901-377-7325.

Sincerely,

Terracon State of Tennessee Asbestos Accreditation No. A-F0692-2444

Matthew T. Howard, PG Staff Geologist

by Chinten for

Jeffrey S. Mutchler, MPH Project Industrial Hygienist

7876 Stage Hills Blvd. #105 Bartlett, TN 38133 Phone 901.377.7325 Fax 901.377.7327 www.terracon.com

TABLE OF CONTENTS

EXECUTIVE SUMMARY – RUTHERFORD TN (RFC022694)

1.0	INTRODUCTION	
2.0	BUILDING DESCRIPTION	1
3.0	FIELD ACTIVITIES	2
	3.1 Visual Assessment	2
	3.2 Physical Assessment	2
	3.3 Sample Collection	3
	3.4 Sample Analysis	3
4.0	REGULATORY OVERVIEW	3
5.0	FINDINGS AND RECOMMENDATIONS	4
6.0	GENERAL COMMENTS	5

LIST OF APPENDICES

Appendix A	Asbestos Survey Sample Summary
Appendix B	Confirmed Asbestos-Containing Materials
Appendix C	Asbestos Analytical Laboratory Data
Appendix D	Certifications
Appendix E	Photographs
Appendix F	Site Diagram

EXECUTIVE SUMMARY - RUTHERFORD (RFC022694)

Terracon Consultants, Inc. (Terracon) conducted an asbestos survey of the Regions Branch building located at 202 East Main Street in Rutherford, Tennessee. It is our understanding that Regions Financial Corporation c/o CB Richard Ellis is planning to renovate the building. The purpose of this survey was to identify and sample suspect asbestos-containing materials (ACM) and provide information regarding the identity, location, condition and approximate quantities of ACM in interior building components.

The survey was conducted on January 20, 2010, by an Asbestos Hazard Emergency Response Act (AHERA) and State of Tennessee-accredited building inspector in general accordance with the sampling protocols established in Environmental Protection Agency (EPA) 40 Code of Federal Regulations (CFR) 763. Sixty-two (62) bulk samples were collected from nineteen (19) homogeneous areas of suspect ACM. Asbestos in concentrations of more than one percent (1%) was identified in the following materials:

- Floor tile and black mastic below carpet in the vault
- Black mastic below floor tile in the east hallway
- Black mastic below floor tile in the break room
- Floor tile and black mastic in mop closet
- Sink Undercoating
- Gray exterior caulk around back door

Terracon recommends that the identified friable and non-friable ACM be removed and disposed of by a Tennessee-licensed asbestos abatement contractor prior to the renovation activity that will disturb the asbestos-containing materials identified.

ASBESTOS SURVEY REPORT

RUTHERFORD COST CENTER NO. RFC022694 202 EAST MAIN STREET RUTHERFORD, TENNESSEE

Terracon Project No. A8107001

1.0 INTRODUCTION

Terracon Consultants, Inc. (Terracon) conducted an asbestos survey of the Regions Branch located at 202 East Main Street in Rutherford, Tennessee. The survey was conducted on January 20, 2010 by an AHERA and State of Tennessee-accredited asbestos inspector in general accordance with Terracon Task Order dated January 6, 2010, in accordance with the Master Service Agreement dated April 11, 2003. Interior and exterior building components were surveyed and homogeneous areas of suspect asbestos-containing materials (ACM) were visually identified and documented. Although reasonable effort was made to survey accessible suspect materials, additional suspect but un-sampled materials could be located in walls, in voids or in other concealed areas. Suspect ACM samples were collected in general accordance with the sampling protocols outlined in EPA regulation 40 CFR 763 (Asbestos Hazard Emergency Response Act, AHERA). Samples were delivered to an accredited laboratory for analysis by polarized light microscopy.

1.1 **Project Objective**

We understand this asbestos survey was requested due to the planned renovation of the building. EPA regulation 40 CFR 61, Subpart M, National Emission Standards for Hazardous Air Pollutants (NESHAP), prohibits the release of asbestos fibers to the atmosphere during renovation or demolition activities. The asbestos NESHAP requires that potentially regulated asbestos-containing building materials be identified, classified and quantified prior to planned disturbances or demolition activities.

2.0 BUILDING DESCRIPTION

The building is a one-story, approximately 3,000 square foot brick and concrete structure, reportedly built in 1973. The exterior finishes consist of brick and concrete with metal frame windows and doors. Interior wall finishes consist of gypsum wall board. The floors are finished with ceramic tile, carpet with terrazzo underneath, 12"x12" vinyl floor tiles, and 9"x9" vinyl floor tiles. Ceilings throughout the building are either finished with gypsum wall board or 12"x12" suspended ceiling tiles. The heating, ventilation and air conditioning (HVAC) system is located in the attic in the northern portion of the building.

3.0 FIELD ACTIVITIES

The survey was conducted by Mr. Matt Howard, an AHERA and State of Tennessee-accredited asbestos inspector. A copy of Mr. Howard's asbestos inspector certificate is attached as Appendix D. The survey was conducted in general accordance with the sample collection protocols established in EPA regulation 40 CFR 763, the Asbestos Hazard Emergency Response Act (AHERA). A summary of survey activities is provided below.

3.1 Visual Assessment

Our survey activities began with visual observation of the interior and exterior of the building to identify homogeneous areas of suspect ACM. A homogeneous area consists of building materials that appear similar throughout in terms of color, texture and date of application. Interior and exterior assessment was conducted throughout visually accessible areas of the building. Building materials identified as concrete, glass, wood, masonry, metal or rubber were not considered suspect ACM.

The roof system was not included in this survey. Terracon lifted carpet in several areas in the building and observed additional floor coverings/layers where noted in this report; however, as Terracon could not assess beneath all carpeted areas, there may be isolated areas of additional suspect material present beneath carpet.

Terracon observed a (1) thermostat located on the south-facing wall next to the vault door, and attached to gypsum wall board. This wall appeared to have been covered with ceramic tiles in the past, however the tiles appeared to have been removed.

The lighting system in the building is located in the suspended ceiling tile system, with the exception of the mop closet, file room, and storage closet, which have gypsum wall board ceilings. The restrooms have gypsum wall board ceilings also, however the lighting systems are mounted on the walls above the mirror.

3.2 Physical Assessment

A physical assessment of each homogeneous area of suspect ACM was conducted to assess the friability and condition of the materials. A friable material is defined by the EPA as a material which can be crumbled, pulverized or reduced to powder by hand pressure when dry. Friability was assessed by physically touching suspect materials.

3.3 Sample Collection

Based on results of the visual observation, bulk samples of suspect ACM were collected in general accordance with AHERA sampling protocols. Random samples of suspect materials were collected in each homogeneous area. Mr. Howard collected bulk samples using wet methods as applicable to reduce the potential for fiber release. Samples were placed in sealable containers and labeled with unique sample numbers using an indelible marker.

Sixty-two (62) bulk samples were collected from nineteen (19) homogeneous areas of suspect ACM. A summary of suspect ACM samples collected during the survey is included as Appendix A.

3.4 Sample Analysis

Bulk samples were submitted under chain of custody to Steve Moody Micro Services, Inc. (SMMS) of Farmers Branch, Texas for analysis by polarized light microscopy with dispersion staining techniques per EPA methodology (40 CFR 763, Subpart F). The percentage of asbestos, where applicable, was determined by microscopical visual estimation. SMMS is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP Accreditation No. 102056).

4.0 **REGULATORY OVERVIEW**

The asbestos NESHAP (40 CFR Part 61, Subpart M) regulates asbestos fiber emissions and asbestos waste disposal practices. It also requires the identification and classification of existing building materials prior to demolition or renovation activity. Under NESHAP, asbestos-containing building materials are classified as either friable, Category I non-friable or Category II non-friable ACM. Friable materials are those that, when dry, may be crumbled, pulverized or reduced to powder by hand pressure. Category I non-friable ACM includes packings, gaskets, resilient floor coverings and asphalt roofing products containing more than 1% asbestos. Category II non-friable ACM are any materials other than Category I materials that contain more than 1% asbestos.

Friable ACM, Category I and Category II non-friable ACM which is in poor condition and has become friable or which will be subjected to drilling, sanding, grinding, cutting or abrading and which could be crushed or pulverized during anticipated renovation or demolition activities are considered regulated ACM (RACM). RACM must be removed prior to renovation or demolition activities which will disturb the materials. The owner or operator must provide the Tennessee Department of Environment and Conservation, Division of Air Pollution Control with written

Terracon

Rutherford ACM Survey RFC022694 Terracon Project No. A8107001 February 8, 2010

notification at least 10 working days prior to the commencement of any renovation activity which will include the disturbance of least 260 linear feet, 160 square feet or 35 cubic feet of RACM or prior to the commencement of demolition. Removal of RACM must be conducted by a Tennessee licensed asbestos abatement contractor.

The OSHA Asbestos standard for construction (29 CFR 1926.1101) regulates workplace exposure to asbestos. The OSHA standard requires that employee exposure to airborne asbestos fibers be maintained below 0.1 asbestos fibers per cubic centimeter of air (0.1 f/cc). The OSHA standard classifies construction and maintenance activities which could disturb ACM, and specifies work practices and precautions which employers must follow when engaging in each class of regulated work.

5.0 FINDINGS AND RECOMMENDATIONS

Laboratory analysis confirmed the presence of asbestos in the following materials:

- Floor tile and black mastic below carpet in the vault
- Black mastic below floor tile in the east hallway
- Black mastic below floor tile in the break room
- Floor tile and black mastic in mop closet
- Sink Undercoating in break room
- Gray exterior caulk around back door

The floor tile and mastics located in the vault, east hallway, break room, and mop closet are considered Category I non-friable ACM in good condition.

The sink undercoat located in the break room is considered Category II non-friable ACM in good condition.

The gray caulk located around the back door is considered Category II non-friable ACM in good condition.

Terracon recommends that the identified ACM be removed and disposed of by a Tennesseelicensed asbestos abatement contractor prior to the renovation activity that will disturb the asbestos-containing materials identified or assumed.

Terracon

Rutherford ACM Survey RFC022694 Terracon Project No. A8107001 February 8, 2010

It should be noted that suspect materials, other than those identified during the January 20, 2010 survey may exist within the building. Should suspect materials other than those which were identified during this survey be uncovered during the renovation process, those materials should be assumed asbestos-containing until sampling and analysis can confirm or deny their asbestos content.

A summary of the classification, condition and approximate quantity of identified ACM are presented in Appendix B. Laboratory analytical reports are included in Appendix C.

6.0 GENERAL COMMENTS

This asbestos survey was conducted in a manner consistent with the level of care and skill ordinarily exercised by members of the profession currently practicing under similar conditions in the same locale. The results, findings, conclusions and recommendations expressed in this report are based on conditions observed during our survey of the building. The information contained in this report is relevant to the date on which this survey was performed, and should not be relied upon to represent conditions at a later date. This report has been prepared on behalf of and exclusively for use by Regions Financial Corporation c/o CB Richard Ellis for specific application to their project as discussed. This report is not a bidding document. Contractors or consultants reviewing this report must draw their own conclusions regarding further investigation or remediation deemed necessary. Terracon does not warrant the work of regulatory agencies, laboratories or other third parties supplying information which may have been used in the preparation of this report. No warranty, express or implied is made.

APPENDIX A ASBESTOS SURVEY SAMPLE SUMMARY

APPENDIX A

ASBESTOS SURVEY SAMPLE SUMMARY RUTHERFORD COST CENTER NO. RFC022694 202 EAST MAIN STREET RUTHERFORD, TENNESSEE Terracon Project No. A8107001

HA	Sample No.	Description	Sample Location
1	1	12"x12" suspended ceiling tile	Lobby/offices/teller row
1	2	12"x12" suspended ceiling tile	Lobby/offices/teller row
1	3	12"x12" suspended ceiling tile	Lobby/offices/teller row
1	4	12"x12" suspended ceiling tile	Lobby/offices/teller row
1	5	12"x12" suspended ceiling tile	Lobby/offices/teller row
2	6	Gray cove base and cream mastic	Lobby
2	7	Gray cove base and cream mastic	Lobby
2	8	Gray cove base and cream mastic	Lobby
3	9	Wall board	Lobby
3	10	Wall board	Lobby
3	11	Wall board	Lobby
3	12	Wall board	Lobby
3	13	Wall board	Lobby
4	14	Carpet mastic	Lobby
4	15	Carpet mastic	Lobby
4	16	Carpet mastic	Lobby
4	17	Carpet mastic	Lobby
4	18	Carpet mastic	Lobby
5	19	12"x12" Tan floor tile and yellow mastic	Lobby
5	20	12"x12" Tan floor tile and yellow mastic	Lobby
5	21	12"x12" Tan floor tile and yellow mastic	Lobby
6	22	Carpet mastic and old tile below carpet with black mastic	Vault
6	23	Carpet mastic and old tile below carpet with black mastic	Vault
6	24	Carpet mastic and old tile below carpet with black mastic	Vault
7	25	12"x12" Tan floor tile and black mastic	East hallway
7	26	12"x12" Tan floor tile and black mastic	East hallway
7	27	12"x12" Tan floor tile and black mastic	East hallway
8	28	Wall board	East hallway
8	29	Wall board	East hallway
8	30	Wall board	East hallway
9	31	12"x12" Tan floor tile and black mastic	Break room
9	32	12"x12" Tan floor tile and black mastic	Break room
9	33	12"x12" Tan floor tile and black mastic	Break room
10	34	Green and yellow carpet mastic	File room
10	35	Green and yellow carpet mastic	File room

10	36	Green and yellow carpet mastic	File room
11	37	Wall plaster	Storage room
11	38	Wall plaster	Storage room
11	39	Wall plaster	Storage room
12	40	Green and yellow carpet mastic	Manager's office
12	41	Green and yellow carpet mastic	Manager's office
12	42	Green and yellow carpet mastic	Manager's office
13	43	Wall covering	Manager's office
13	44	Wall covering	Manager's office
13	45	Wall covering	Manager's office
14	46	9"x9" tan floor tile and black mastic	Mop closet
14	47	9"x9" tan floor tile and black mastic	Mop closet
14	48	9"x9" tan floor tile and black mastic	Mop closet
15	49	Green and yellow carpet mastic	Teller row
15	50	Green and yellow carpet mastic	Teller row
15	51	Green and yellow carpet mastic	Teller row
16	52	Gray cove base and yellow and cream mastic	Teller row
16	53	Gray cove base and yellow and cream mastic	Teller row
16	54	Gray cove base and yellow and cream mastic	Teller row
17	55	Painted cove base and tan mastic	Mop closet
17	56	Painted cove base and tan mastic	Mop closet
17	57	Painted cove base and tan mastic	Mop closet
18	58	Sink undercoating	Break room
18	59	Sink undercoating	Break room
19	60	Gray exterior caulk	Back door
19	61	Gray exterior caulk	Back door
19	62	Gray exterior caulk	Back door

APPENDIX B CONFIRMED ASBESTOS-CONTAINING MATERIALS

APPENDIX B

CONFIRMED ASBESTOS-CONTAINING MATERIALS RUTHERFORD COST CENTER NO. RFC022694 **202 EAST MAIN STREET** RUTHERFORD, TENNESSEE Terracon Project No. A8107001

HA No.	Description	Material Location	Percent/Type Asbestos	NESHAP Classification	Condition	Estimated Quantity*
6	Carpet mastic with additional layers of tile and mastic below	Vault	ND – Carpet ND – Green mastic 3%C – Floor tile ND – Yellow mastic 5%C – Black mastic	Category I non-friable	Good	500 ft ²
7	12"x12" Tan floor tile with yellow and black mastic	East hallway	ND – Floor tile ND – Yellow mastic 5%C – Black mastic	Category I non-friable	Good	100 ft ²
9	12"x12" Tan floor tile with yellow and black mastic	Break room	ND – Floor tile ND – Yellow mastic 5%C – Black mastic	Category I non-friable	Good	200 ft ²
14	9"x9" Tan floor tile with black mastic	Mop closet	5%C – Floor tile 5%C – Black mastic	Category I non-friable	Good	75 ft ²
18	Sink undercoating	Break room	10%C – Sink undercoating	Category II non- friable	Good	1 ft ²
19	Gray caulk	Back door	5%C- Caulking	Category II non- friable	Good	20 linear feet

* Quantities are estimates only. ft^2 = square feet C = Chrysotile asbestos

APPENDIX C

ASBESTOS LABORATORY ANALYTICAL REPORTS

PLM Summary Report

Steve Moody Micro Services, LLC 2051 Valley View Lane Farmers Branch, TX 75234 Phone: (972) 241-8460 NVLAP Lab No. 102056 TDSHS License No. 30-0084

Client :	Terracon - Memphis, TN		Lab Job No. : 10B-00628	3
Project :	Regions Bank, Rutherford, Tennessee		Report Date : 01/25/2010)
Project # :	A8107001	Sample Date : 01/20/2010		
Identification :	Asbestos, Bulk Sample Analysis			
Test Method :	Polarized Light Microscop	y / Dispersion Staining (PLM/DS)		
	EPA Method 600 / R-93 /	116		Page 1 of 5

On 1/21/2010, sixty two (62) bulk material samples were submitted by Matthew Howard of Terracon - Memphis, TN for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
1	12" x 12" Ceiling Tile, Lobby	None Detected - Acoustic Tile
2	12" x 12" Ceiling Tile, Lobby	None Detected - Acoustic Tile
3	12" x 12" Ceiling Tile, Lobby	None Detected - Acoustic Tile
4	12" x 12" Ceiling Tile, Lobby	None Detected - Acoustic Tile
5	12" x 12" Ceiling Tile, Lobby	None Detected - Acoustic Tile
6	Cove Base (Gray), Lobby	None Detected - Cove Base None Detected - Cream Mastic
7	Cove Base (Gray), Lobby	None Detected - Cove Base None Detected - Cream Mastic
8	Cove Base (Gray), Lobby	None Detected - Cove Base None Detected - Cream Mastic
9	Wallboard, Lobby	None Detected - Wall Material
10	Wallboard, Lobby	None Detected - Wall Material
11	Wallboard, Lobby	None Detected - Wall Material
12	Wallboard, Lobby	None Detected - Wall Material
13	Wallboard, Lobby	None Detected - Caulking None Detected - Wood
14	Carpet Mastic, Lobby	None Detected - Green Mastic
15	Carpet Mastic, Lobby	None Detected - Green Mastic
16	Carpet Mastic, Lobby	None Detected - Green Mastic
17	Carpet Mastic, Lobby	None Detected - Green Mastic
18	Carpet Mastic, Lobby	None Detected - Green Mastic
19	12" x 12" Floor Tile (Tan), Lobby	None Detected - Floor Tile None Detected - Yellow Mastic

	PLM Summary Repor	rt
Steve Moody Micro Services, LLC		NVLAP Lab No. 102056
2051 Valley View Lane		TDSHS License No. 30-0084
Farmers Branch, T	X 75234 Phone: (972) 241-8460	
Client : T	erracon - Memphis, TN	Lab Job No. : 10B-00628
	egions Bank, Rutherford, Tennessee	Report Date : 01/25/2010
5	8107001 Sample Date : 01/20/2010	
	sbestos, Bulk Sample Analysis	
	olarized Light Microscopy / Dispersion Staining (PLM/DS) PA Method 600 / R-93 / 116	
E	PA Method 6007 R-957 116	Page 2 of 5
	to (62) bulk material samples were submitted by Matthew Howard of Terr t is attached; additional information may be found therein. The results are	
Sample Number	Client Sample Description / Location	Asbestos Content
20	12" x 12" Floor Tile (Tan), Lobby	None Detected - Floor Tile None Detected - Yellow Mastic
21	12" x 12" Floor Tile (Tan), Lobby	None Detected - Floor Tile None Detected - Yellow Mastic
22	Carpet Mastic, Vault	None Detected - Carpet None Detected - Green Mastic 3% Chrysotile - Floor Tile None Detected - Yellow Mastic 5% Chrysotile - Black Mastic
23	Carpet Mastic, Vault	None Detected - Carpet None Detected - Green Mastic 3% Chrysotile - Floor Tile None Detected - Yellow Mastic 5% Chrysotile - Black Mastic
24	Carpet Mastic, Vault	None Detected - Carpet None Detected - Green Mastic 3% Chrysotile - Floor Tile None Detected - Yellow Mastic 5% Chrysotile - Black Mastic
25	12" x 12" Floor Tile (Tan), East Hallway	None Detected - Floor Tile None Detected - Yellow Mastic 5% Chrysotile - Black Mastic
26	12" x 12" Floor Tile (Tan), East Hallway	None Detected - Floor Tile None Detected - Yellow Mastic
27	12" x 12" Floor Tile (Tan), East Hallway	None Detected - Floor Tile None Detected - Yellow Mastic 5% Chrysotile - Black Mastic
28	Wallboard, East Hallway	None Detected - Wall Material
29	Wallboard, East Hallway	None Detected - Wall Material
	Wallboard, East Hallway	None Detected - Wall Material

	PLM Summary Report	
	cro Services, LLC	NVLAP Lab No. 102056
2051 Valley View Lane		TDSHS License No. 30-0084
Farmers Branch, T	X 75234 Phone: (972) 241-8460	
	erracon - Memphis, TN	Lab Job No. : 10B-00628
-	egions Bank, Rutherford, Tennessee	Report Date : 01/25/2010
5	8107001 Sample Date : 01/20/2010	
	sbestos, Bulk Sample Analysis olarized Light Microscopy / Dispersion Staining (PLM/DS)	
	PA Method 600 / R-93 / 116	Page 3 of 5
	o (62) bulk material samples were submitted by Matthew Howard of Terracon t is attached; additional information may be found therein. The results are sum	
Sample Number	Client Sample Description / Location	Asbestos Content
31	12" x 12" Floor Tile (Tan), Break Room	None Detected - Floor Tile None Detected - Yellow Mastic 5% Chrysotile - Black Mastic
32	12" x 12" Floor Tile (Tan), Break Room	None Detected - Floor Tile None Detected - Yellow Mastic 5% Chrysotile - Black Mastic
33	12" x 12" Floor Tile (Tan), Break Room	None Detected - Floor Tile None Detected - Yellow Mastic 5% Chrysotile - Black Mastic
34	Carpet Mastic, File Room	None Detected - Green Mastic None Detected - Yellow Mastic
35	Carpet Mastic, File Room	None Detected - Green Mastic None Detected - Yellow Mastic
36	Carpet Mastic, File Room	None Detected - Green Mastic None Detected - Yellow Mastic
37	Wallboard on Ceiling, Storage Room / Near Back Door	None Detected - Base Plaster None Detected - Top Plaster
38	Wallboard on Ceiling, Storage Room / Near Back Door	None Detected - Base Plaster None Detected - Top Plaster
39	Wallboard on Ceiling, Storage Room / Near Back Door	None Detected - Plaster
40	Carpet Mastic, Manager's Office	None Detected - Green Mastic None Detected - Yellow Mastic
41	Carpet Mastic, Manager's Office	None Detected - Green Mastic None Detected - Yellow Mastic
42	Carpet Mastic, Manager's Office	None Detected - Green Mastic None Detected - Yellow Mastic
43	Wallboard, Manager's Office	None Detected - Wall Coverings
44	Wallboard, Manager's Office	None Detected - Wall Covering
37 38 39 40 41 42 43	Wallboard on Ceiling, Storage Room / Near Back Door Wallboard on Ceiling, Storage Room / Near Back Door Wallboard on Ceiling, Storage Room / Near Back Door Carpet Mastic, Manager's Office Carpet Mastic, Manager's Office Carpet Mastic, Manager's Office Wallboard, Manager's Office	None Detected - Green Mastic None Detected - Yellow Mastic None Detected - Base Plaster None Detected - Top Plaster None Detected - Base Plaster None Detected - Top Plaster None Detected - Plaster None Detected - Plaster None Detected - Green Mastic None Detected - Green Mastic None Detected - Green Mastic None Detected - Yellow Mastic None Detected - Green Mastic None Detected - Green Mastic None Detected - Yellow Mastic None Detected - Yellow Mastic None Detected - Yellow Mastic

PLM Summary Report

Steve Moody Micro Services, LLC 2051 Valley View Lane Farmers Branch, TX 75234 Phone: (972) 241-8460 NVLAP Lab No. 102056 TDSHS License No. 30-0084

Client :	Terracon - Memphis, TN		Lab Job No. : 10B-00628	3
Project :	Regions Bank, Rutherford, Tennessee		Report Date : 01/25/2010)
Project # :	A8107001	Sample Date : 01/20/2010		
Identification :	Asbestos, Bulk Sample Analysis			
Test Method :	Polarized Light Microscop	y / Dispersion Staining (PLM/DS)		
	EPA Method 600 / R-93 /	116		Page 4 of 5

On 1/21/2010, sixty two (62) bulk material samples were submitted by Matthew Howard of Terracon - Memphis, TN for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
45	Wallboard, Manager's Office	None Detected - Wall Coverings
46	9" x 9" Floor Tile (Tan), Mop Closet	5% Chrysotile - Floor Tile 5% Chrysotile - Black Mastic
47	9" x 9" Floor Tile (Tan), Mop Closet	5% Chrysotile - Floor Tile 5% Chrysotile - Black Mastic
48	9" x 9" Floor Tile (Tan), Mop Closet	5% Chrysotile - Floor Tile 5% Chrysotile - Black Mastic
49	Carpet Mastic, Teller Row	None Detected - Green Mastic None Detected - Yellow Mastic
50	Carpet Mastic, Teller Row	None Detected - Green Mastic None Detected - Yellow Mastic
51	Carpet Mastic, Teller Row	None Detected - Green Mastic
52	Cove Base, Teller Row	None Detected - Cove Base None Detected - Yellow Mastic None Detected - Cream Mastic
53	Cove Base, Teller Row	None Detected - Cove Base None Detected - Yellow Mastic None Detected - Cream Mastic
54	Cove Base, Teller Row	None Detected - Cove Base None Detected - Yellow Mastic None Detected - Cream Mastic
55	Cove Base, Mop Closet	None Detected - Cove Base None Detected - Tan Mastic
56	Cove Base, Mop Closet	None Detected - Cove Base None Detected - Tan Mastic
57	Cove Base, Mop Closet	None Detected - Cove Base None Detected - Tan Mastic
58	Sink Undercoat, Break Room	10% Chrysotile - Sink Undercoating

PLM Summary ReportSteve Moody Micro Services, LLCNVLAP Lab No. 1020562051 Valley View LaneTDSHS License No. 30-0084Farmers Branch, TX 75234 Phone: (972) 241-8460Steve Model Control			
Project :RProject # :AIdentification :ATest Method :P	erracon - Memphis, TN egions Bank, Rutherford, Tennessee 8107001 Sample Date : 01/20/2010 sbestos, Bulk Sample Analysis olarized Light Microscopy / Dispersion Staining (PLM/DS) PA Method 600 / R-93 / 116	Lab Job No. : 10B-00628 Report Date : 01/25/2010 Page 5 of 5	
	o (62) bulk material samples were submitted by Matthew Howard of Terraco t is attached; additional information may be found therein. The results are sur		
Sample Number	Client Sample Description / Location	Asbestos Content	
59 60 61 62	Sink Undercoat, Break Room Window Caulk (Gray), Exterior Near Back Door Window Caulk (Gray), Exterior Near Back Door	10% Chrysotile - Sink Undercoating 5% Chrysotile - Caulking 5% Chrysotile - Caulking 5% Chrysotile - Caulking	
These samples were analyzed by layers. Quantification, unless otherwise noted, is performed by calibrated visual estimate. Results may not be reproduced except in full. This test report relates only to the samples tested. These test results do not imply endorsement by NVLAP or any agency of the U.S. Government. Accredited by the National Voluntary Laboratory Accreditation Program for Bulk Asbestos Fiber Analysis under Lab Code 102056. Analyst(s): Kirsten Tye, Robert W. Miracle			
Lab Manager : Bru		Bune Cull	
Lab Director : Stev	e Moody Approved Signator ————————————————————————————————————	Sx Mary	

PLM Detail Report

Supplement to PLM Summary Report

NVLAP Lab No. 102056 TDSHS License No. 30-0084

Client : Terracon - Memphis, TN

Regions Bank, Rutherford, Tennessee Project : Project #: A8107001

Lab Job No. : 10B-00628 Report Date : 01/25/2010

% Of % of Analysis Sample Number Layer Components Analyst Date Sample Layer 1 Acoustic Tile (Off-White) 100% Mineral Wool Fibers 95% 01/22 RM Binders / Fillers 5% 2 Mineral Wool Fibers Acoustic Tile (Off-White) 100% 95% 01/22 RM Binders / Fillers 5% 3 Acoustic Tile (Off-White) 100% Mineral Wool Fibers 95% 01/22 RM Binders / Fillers 5% 100% Mineral Wool Fibers 01/224 Acoustic Tile (Off-White) 95% RM Binders / Fillers 5% 5 Acoustic Tile (Off-White) 100% Mineral Wool Fibers 01/22 95% RM **Binders / Fillers** 5% 6 95% Calcite / Vinyl Binders 01/22Cove Base (Grey) 100% RM 5% Cream Mastic (Cream) Calcite 50% Glue Binders 50% 7 Cove Base (Grey) 95% Calcite / Vinyl Binders 100% 01/22RM 5% Cream Mastic (Cream) Calcite 50% Glue Binders 50% 8 Calcite / Vinyl Binders Cove Base (Grey) 95% 100%01/22 RM 5% Cream Mastic (Cream) Calcite 50% Glue Binders 50% 9 Wall Material (White) 100% Calcite / Talc / Binders 100%01/22 RM 10 Wall Material (White) 100% Calcite / Talc / Binders 100%01/22 RM 11 Wall Material (White) 100% Calcite / Talc / Binders 100% 01/22RM 12 Wall Material (White) 100% Calcite / Talc / Binders 01/22 RM 100% 13 70% Calcite 50% 01/22 RM Caulking (White) Binders / Fillers 50% Wood (Brown) 30% 100% Wood Note: No wallboard 14 Green Mastic (Green) 100% Glue Binders 100%01/22 RM 15 Green Mastic (Green) 100% Glue Binders 100% 01/22 RM

Page 1 of 6

PLM Detail Report

Supplement to PLM Summary Report

NVLAP Lab No. 102056 TDSHS License No. 30-0084

Client : Terracon - Memphis, TN

Project : Regions Bank, Rutherford, Tennessee Project #: A8107001

Lab Job No. : 10B-00628 Report Date : 01/25/2010

% Of % of Analysis Analyst Sample Number Layer Components Sample Layer Date 16 Green Mastic (Green) 100% Glue Binders 100% 01/22 RM 17 100% 100% Green Mastic (Green) Glue Binders 01/22 RM 18 Green Mastic (Green) 100% Glue Binders 100% 01/22RM 19 95% Calcite / Vinyl Binders 01/22Floor Tile (Light Tan) 100% RM Yellow Mastic (Yellow) 5% Glue Binders 100% 20 98% Calcite / Vinyl Binders 01/22 Floor Tile (Light Tan) 100% RM Yellow Mastic (Yellow) 2% Glue Binders 100% 21 Floor Tile (Light Tan) 95% Calcite / Vinyl Binders 100% 01/22RM Yellow Mastic (Yellow) 5% Glue Binders 100% 22 Carpet (Multi-colored) 60% Synthetic Fibers 85% 01/22RM Glue Binders 15% 5% Glue Binders 100% Green Mastic (Green) Floor Tile (Light Tan) 33% 3% Chrysotile Calcite / Vinyl Binders 97% Glue Binders Yellow Mastic (Yellow) 1% 100% Black Mastic (Black) 1% Chrysotile 5% Tar Binders 95% 23 60% Carpet (Multi-colored) Synthetic Fibers 85% 01/22 RM Glue Binders 15% Green Mastic (Green) 5% Glue Binders 100% Floor Tile (Light Tan) 31% Chrysotile 3% Calcite / Vinyl Binders 97% Yellow Mastic (Yellow) 1% Glue Binders 100% 3% Black Mastic (Black) Chrysotile 5% Tar Binders 95%

Page 2 of 6

PLM Detail Report

Supplement to PLM Summary Report

NVLAP Lab No. 102056 TDSHS License No. 30-0084

Client : Terracon - Memphis, TN

Regions Bank, Rutherford, Tennessee Project : Project #: A8107001

Lab Job No. : 10B-00628 Report Date : 01/25/2010

% Of % of Analysis Analyst Sample Number Layer Components Sample Date Layer 60% 01/22 24 Carpet (Multi-colored) Synthetic Fibers 85% RM Glue Binders 15% 100% Green Mastic (Green) 5% Glue Binders Floor Tile (Light Tan) 33% Chrysotile 3% Calcite / Vinyl Binders 97% Yellow Mastic (Yellow) 1% Glue Binders 100% 1% Chrysotile 5% Black Mastic (Black) Tar Binders 95% 25 Floor Tile (Light Beige) 97% Calcite / Vinyl Binders 100% 01/22KT 2% 100% Yellow Mastic (Yellow) Glue Binders Black Mastic (Black) 1% Chrysotile 5% Tar Binders 95% Calcite / Vinyl Binders 01/22 26 Floor Tile (Light Beige) 100% 100% KT <1% Glue Binders 100% Yellow Mastic (Yellow) 27 Floor Tile (Light Beige) 99% Calcite / Vinyl Binders 100% 01/22 KΤ Yellow Mastic (Yellow) 1% Glue Binders 100% Black Mastic (Black) <1% Chrysotile 5% Tar Binders 95% 28 Wall Material (White) 100% Calcite / Gypsum Binders 100% 01/22 KT 100% 29 Wall Material (White) Calcite / Talc / Binders 100% 01/22 KT 30 Wall Material (White) 100% Calcite / Talc / Binders 100%01/22 KΤ 31 Calcite / Vinyl Binders Floor Tile (Light Beige) 94% 100%01/22 KT 5% Glue Binders 100% Yellow Mastic (Yellow) Black Mastic (Black) 1% Chrysotile 5% Tar Binders 95% Calcite / Vinyl Binders 32 Floor Tile (Light Beige) 98% 100% 01/22 KΤ Yellow Mastic (Yellow) 2% Glue Binders 100% Black Mastic (Black) <1% Chrysotile 5% Tar Binders 95%

Page 3 of 6

PLM Detail Report

Supplement to PLM Summary Report

NVLAP Lab No. 102056 TDSHS License No. 30-0084

Page 4 of 6

Client : Terracon - Memphis, TN

Project : Regions Bank, Rutherford, Tennessee

Project #: A8107001

Lab Job No. : 10B-00628 Report Date : 01/25/2010

					Pag	e 4 01 0
Sample Number	Layer	% Of Sample	Components	% of Layer	Analysis Date	Analyst
33	Floor Tile (Light Beige)	90%	Calcite / Vinyl Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	5%	Glue Binders	100%		
	Black Mastic (Black)	5%	Chrysotile	5%		
			Tar Binders	95%		
34	Green Mastic (Green)	75%	Glue Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	25%	Glue Binders	100%		
35	Green Mastic (Green)	90%	Glue Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	10%	Glue Binders	100%		
36	Green Mastic (Green)	50%	Glue Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	50%	Glue Binders	100%		
37	Base Plaster (Light Beige)	50%	Aggregate	65%	01/22	KT
			Calcite / Gypsum Binders	35%		
	Top Plaster (White)	50%	Calcite / Gypsum Binders	100%		
38	Base Plaster (Light Beige)	7%	Aggregate	65%	01/22	KT
			Calcite / Gypsum Binders	35%		
	Top Plaster (White)	93%	Calcite / Gypsum Binders	100%		
39	Plaster (Light Beige)	100%	Aggregate	65%	01/22	KT
			Calcite / Gypsum Binders	35%		
40	Green Mastic (Green)	50%	Glue Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	50%	Glue Binders	100%		
41	Green Mastic (Green)	50%	Glue Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	50%	Glue Binders	100%		
42	Green Mastic (Green)	50%	Glue Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	50%	Glue Binders	100%		
43	Wall Coverings (Green/Tan)	100%	Cellulose Fibers	65%	01/22	KT
	,		Binders / Fillers	35%		
44	Wall Covering (Tan)	100%	Cellulose Fibers	60%	01/22	KT
			Binders / Fillers	40%		

PLM Detail Report

Supplement to PLM Summary Report

NVLAP Lab No. 102056 TDSHS License No. 30-0084

Client : Terracon - Memphis, TN

Project : Regions Bank, Rutherford, Tennessee Project #: A8107001

Lab Job No. : 10B-00628 Report Date : 01/25/2010

		% Of		% of	Analyzia	
Sample Number	Layer	% OI Sample	Components	% of Layer	Analysis Date	Analyst
45	Wall Coverings (Green/Tan)	100%	Cellulose Fibers	65%	01/22	KT
			Binders / Fillers	35%		
46	Floor Tile (Cream)	95%	Chrysotile	5%	01/22	KT
			Calcite / Vinyl Binders	95%		
	Black Mastic (Black)	5%	Chrysotile	5%		
			Tar Binders	95%		
47	Floor Tile (Cream)	95%	Chrysotile	5%	01/22	KT
			Calcite / Vinyl Binders	95%		
	Black Mastic (Black)	5%	Chrysotile	5%		
			Tar Binders	95%		
48	Floor Tile (Cream)	98%	Chrysotile	5%	01/22	KT
			Calcite / Vinyl Binders	95%		
	Black Mastic (Black)	2%	Chrysotile	5%		
			Tar Binders	95%		
49	Green Mastic (Green)	50%	Glue Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	50%	Glue Binders	100%		
50	Green Mastic (Green)	50%	Glue Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	50%	Glue Binders	100%		
51	Green Mastic (Green)	100%	Glue Binders	100%	01/22	KT
52	Cove Base (Black)	78%	Calcite / Vinyl Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	15%	Calcite	40%		
			Glue Binders	60%		
	Cream Mastic (Cream)	7%	Calcite	50%		
			Glue Binders	50%		
53	Cove Base (Black)	70%	Calcite / Vinyl Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	20%	Calcite	40%		
			Glue Binders	60%		
	Cream Mastic (Cream)	10%	Calcite	50%		
			Glue Binders	50%		

PLM Detail Report

Supplement to PLM Summary Report

NVLAP Lab No. 102056 TDSHS License No. 30-0084

Client : Terracon - Memphis, TN

Project : Regions Bank, Rutherford, Tennessee

Project #: A8107001

Lab Job No. : 10B-00628 Report Date : 01/25/2010

Sample Number	Layer	% Of Sample	Components	% of Layer	Analysis Date	Analyst
54	Cove Base (Black)	80%	Calcite / Vinyl Binders	100%	01/22	KT
	Yellow Mastic (Yellow)	15%	Calcite	40%		
			Glue Binders	60%		
	Cream Mastic (Cream)	5%	Calcite	50%		
			Glue Binders	50%		
55	Cove Base (Brown)	98%	Calcite / Vinyl Binders	100%	01/22	KT
	Tan Mastic (Tan)	2%	Glue Binders	100%		
56	Cove Base (Brown)	99%	Calcite / Vinyl Binders	100%	01/22	KT
	Tan Mastic (Tan)	1%	Glue Binders	100%		
57	Cove Base (Brown)	99%	Calcite / Vinyl Binders	100%	01/22	KT
	Tan Mastic (Tan)	1%	Glue Binders	100%		
58	Sink Undercoating (Cream)	100%	Chrysotile	10%	01/22	KT
			Calcite / Talc	30%		
			Binders / Fillers	60%		
59	Sink Undercoating (Cream)	100%	Chrysotile	10%	01/22	KT
			Calcite / Talc	30%		
			Binders / Fillers	60%		
60	Caulking (Grey)	100%	Chrysotile	5%	01/22	KT
			Calcite	55%		
			Binders / Fillers	40%		
61	Caulking (Grey)	100%	Chrysotile	5%	01/22	KT
			Calcite	55%		
			Binders / Fillers	40%		
62	Caulking (Grey)	100%	Chrysotile	5%	01/22	KT
			Calcite	55%		
			Binders / Fillers	40%		

	Asbestos Chain of Custody				Pageof
PLM-Bulk: 0 1 PLM-Bulk: 0 1 ANA **Please call in 2	PLM-Bulk: I day • 2 day • 2 day • 2 day • 3 day • 5 day 1 Inmediate (Call for quote) ANALYZE ALL • **Please call in advance for after-hour & weekend analysis**	PCM-Air: [] 1 day TEM-Air: [] 6 ir TEM-Bulk/Wipe/MVac: TEM-7402/Modified:	2 day 12 hr 24 hr 24 hr 24 hr	 ◆ □ 5 day ◆ □ 24 hr ◆ □ 48 hr ◆ □ 48 hr ◆ □ 72 hr 	Lab Job# 108-00628 R.M: 62 Lab Job#
Company Name	Company Name and City: Terracon Consultants, Inc. – Memphis, TN	N Samule date	lamiary 20-2010	010	P.O. No: A8107001
Project: Region	is Bank				Project No: A8107001
	tion: Name: Matt Howard				Phone #: 901-377-7325
E-mail: (address):	1 4				Mobile #: 901-487-4262
Hard copy: (addre	Hard copy: (address): 7876 Stage Hills Blvd #105, Bartlett, TN 38133	33			Fax #: 901-377-7327
Invoice Address (if different):	(if different):				
*** Please review pa	*** Please review paperwork and samples before submitting to lab. Uncontained / improperly packaged samples or excessive administrative requests may incur additional fees. ***	properly packaged sampl	es or excessive administ	rative requests may incur ad	lditional fees. ***
Sample No.	Sample Description		Vol. / Area		Location / Notes
	12"×12" Ceiliztile			(abby	
2	0 11			· · ·	
~				, ,	
2	(1			11	
	()			2	
\$	Gray covebase			1)	
	(]			17	
6	[]			(~	
σ	Wellboard			11	
Released by:	1999 Date/Time:	.10/4:30		in ex	3-2 Ex Date/Time: 1-2/40/8:50~
Released by:	Date/Time:	/	Received By:		Date/Time:
Notes: please c	Notes: please copy email results to: jsmutchler@terracon.com Steve Moody Mirro Services 11.C - 2051 Valley View Ln Farmers Branch.		1 TX 75234 - (972) 241-8460 / FAX (972) 241-8461		NVLAP Lab #102056 TX DSHS License # 30-0084 [COC 2009]

:::

	<u>Asbestos</u> Chain of Custody				Page of
PLM-Bulk:	\mathbb{P}_{Cob} Service PLM-Bulk: \Box 1 day $\diamond \Box$ 2 day $\diamond \bigwedge$ 3 day $\diamond \Box$ 5 day	PCM-Air: □ 1 day ◆ □	/ ◆ □ 2 day ◆ □ 5 day	□ 5 day Lab Job#	10b# 10B-00e28
	Immediate (Call for quote)	TEM-Air: 0 6 hr +	□ 12 hr ♦	24 hr 24 in	lob#
	ALYZE ALL \diamond \Box POSITIVE STOP	TEM-Bulk/Wipe/MVac: TFM_7407/Modified	□ 24 hr ◆	48 hr ♦ 48 hr ♦	#00/
Comnany Name	**Please call in advance for after-hour & weekend aftarysts			• 11 01	
Submitter's Name:	: Matt Howard	Sample date:	January 20, 2010	P.O. No:	A8107001
Project: Regio	is Bank				Project No: A8107001
Contact Information: Name:	tion: Name: Matt Howard		4	Phone #:	Phone #: 901-377-7325
E-mail: (address):	E-mail: (address): mthoward@terracon.com			Mobile #	Mobile #: 901-487-4262
Hard copy: (addre	Hard copy: (address): 7876 Stage Hills Blvd #105, Bartlett, TN 38133	33		Fax #: <u>9</u> (Fax #: 901-377-7327
Invoice Address (if different):	(if different):				
*** Please review pap	*** Please review paperwork and samples before submitting to lab. Uncontained / improperly packaged samples or excessive administrative requests may incur additional fees. ***	properly packaged samples or	excessive administrativ	ve requests may incur additional fees.	***
Sample No.	Sample Description	>	Vol. / Area	Locatic	Location / Notes
0	Wallboard			Lobby	
11	(/			, u	
21	(-			(1	
m				()	
14	Certred Masfic			()	
15				, ,	
17	11			1)	
17	۲ ₁			()	
8	()			~ _	
Released by:	1999 Date/Time:	.10/4:30	Received By:	R	Date/Time: 1/0 /8; 50+
Relcased by:	Date/Time:		Received By:		Date/Time:
Notes: please copy email re	Notes: please copy email results to: jsmutchler@terracon.com	un h TX 75734 - (972) 241-846() / FAX (972) 241-8461	460 / FAX (972) 24		NVLAP Lab #102056 TX DSHS License # 30-0084 [COC 2009]

_	Asbestos Chain of Custody				Pageof
Terry Servic [] 1 PLM-Bulk:]] 1	$\mathbb{R}_{0,0}^{\mathbb{R}_{0,0}}$ Servic PLM-Bulk: \Box 1 day $\diamond \Box$ 2 day $\diamond \mathbf{A}$ 3 day $\diamond \Box$ 5 day	PCM-Air: □ 1 day ◆ □	/ ◆ 🗌 2 day →	◆ □ 5 day	Lab Job# 10B-00028
□ / ·	□ Immediate (Call for \u00e9uote)	TEM-Air: 🗆 6 hr		[Lab Job#
AN X	🕅 ANALYZE ALL 🔸 🗆 POSITIVE STOP	TEM-Bulk/Wipe/MVac:			Lab Job#
Please call in	**Please call in advance for after-hour & weekend analysis	TEM-7402/Modified:		→ □ 48 hr → □ /2 hr	
Company Name	nd Cit				
Submitter's Name:	e: Matt Howard	Sample date:	January 20, 2010		O. NU. ABIV/001
Project: Regi	Regions Bank – Rutherford, TN				Project No: A8107001
Contact Inform	Contact Information: Name: Matt Howard			P	Phone #: 901-377-7325
E-mail: (address)	E-mail: (address): mthoward@terracon.com	5		2	Mobile #: 901-487-4262
Hard copy: (addr	Hard copy: (address): 7876 Stage Hills Blvd #105, Bartlett, TN 38133	33		H	Fax #: 901-377-7327
Invoice Address (if different):	(if different):				
*** Please review p.	*** Please review paperwork and samples before submitting to lab. Uncontained / improperly packaged samples or excessive administrative requests may incur additional fees. ***	properly packaged samples or	excessive administ	rative requests may incur additi	onal fees. ***
Sample No.	Sample Description	>	Vol. / Area		Location / Notes
81	12"x 12" Tan Floor tile			Labby	
20		-		11	
12	(1			, ,	
22	Corpet Mastic			Veult	
23	-			1	1
24				(,	
25	12"x 12" Tan Floor file			East Hallw.	~
92	1			11	/
27	L 1			()	
Released by:	12 Date/Time:	.10/4:30	Received By:	ex	Date/Time: 10/8; 50.4
Released by:	Date/Time:		Received By:		Date/Time:
Notes: please . Steve Moody Micr.	Notes: please copy email results to: jsmutchler@terracon.com Steve Moody Micro Services, LLC - 2051 Valley View Ln Farmers Branch, 3	b m h, TX 75234 - (972) 241-8460 / FAX (972) 241-8461	1460 / FAX (972)) 241-8461 NVLAP Lab #102056	102056 TX DSHS License # 30-0084 [COC 2009]

_	Asbestos Chain of Custody			Page H_of]
آهری _{Servi} د PLM-Bulk: 🗍 1	$\mathbb{P}_{\text{Co}_{\text{D}}\text{ Servic}}$	PCM-Air: □ 1 day ◆ □	• 🗆 2 day 🔸 🔲 5 day	5 day Lab Job# 108-00628	
	Immediate (Call for quote)	TEM-Air: □ 6 hr ◆	12 hr ◆ □	(
NV X	🕅 ANALYZE ALL 🔸 🗆 POSITIVE STOP	TEM-Bulk/Wipe/MVac:	$24 \text{ hr} \bullet \square$	⊐ [◆	
Please call in a	**Please call in advance for after-hour & weekend analysis	TEM-7402/Modified:	□ 24 hr ♦ □ 48	48 hr ◆ □ 72 hr 「	
Company Name	Company Name and City: Terracon Consultants, Inc. – Memphis, TN	Z			
Submitter's Name:	:: Matt Howard	Sample date: Ja	January 20, 2010	P.O. No: A8107001	I
Project: Regic	Regions Bank – Rutherford, TN			Project No: A8107001	
Contact Information: Name:	ation: Name: Matt Howard			Phone #: 901-377-7325	
E-mail: (address):	E-mail: (address): mthoward@terracon.com			Mobile #: 901-487-4262	
Hard copy: (addre	Hard copy: (address): 7876 Stage Hills Blvd #105, Bartlett, TN 38133	3		Fax #: 901-377-7327	
Invoice Address (if different):	(if different):				
*** Please review pa	*** Please review paperwork and samples before submitting to lab. Uncontained / improperly packaged samples or excessive administrative requests may incur additional fees. ***	roperly packaged samples or exc	essive administrative re _l	quests may incur additional fees. ***	
Sample No.	Sample Description	Vol.	Vol. / Area	Location / Notes	
82	Wallboard		Fa	et Hallway	
62	n			4 h	
0 %	(
27	12"×12" Tan Floor file		Br	ent roon	
25	=			1	
33					
34	Corperts Martic		File	e koon	
33	-				
36					
Released by:	1999 Date/Time:	.10/4:30 Re	Received By:	X Date/Time: 1-21-10/8	8:50+
Released by:	Date/Time:	/ Re	Received By:	Date/Time:	
Notes: please c	Notes: please copy email results to: jsmutchler@terracon.com Steve Moody Micro Services, LLC - 2051 Valley View Ln Farmers Branch, TX 75234 - (972) 241-8460 / FAX (972) 241-8461	m , TX 75234 - (972) 241-8460	1 / FAX (972) 241-84	161 NVLAP Lab #102056 TX DSHS License # 30-0084 [COC 2009]	[COC 2009]

l'coc'

_	<u>Asbestos Chain of Custody</u>	Ā			Pageof
PLM-Bulk:	$\mathbb{PLM-Bulk}$: \Box 1 day \blacklozenge \Box 2 day \blacklozenge d 3 day \blacklozenge 5 day	PCM-Air: 🔲 1 da	♦ 🗌 2 đay	• 🗌 5 day	Lab Job# 108-00028
	□ Immediate (Call for quote)	TEM-Air: □ 6 hr ◆		24 hr	Lab Job#
Ar K	🕅 ANALYZE ALL 🔸 🗆 POSITIVE STOP	TEM-Bulk/Wipe/MVac:		48 hr •	Lab Job#
Please call in	**Please call in advance for after-hour & weekend analysis	TEM-7402/Modified:	LU 24 hr	♦ □ 48 hr ♦ □ 72 hr	
Company Nam	Company Name and City: Terracon Consultants, Inc. – Memphis, TN	, TN			
Submitter's Name:	le: Matt Howard	Sample date:	January 20, 2010	i i	P.O. No: A8107001
Project: Regi	Regions Bank – Rutherford, TN				Project No: A8107001
Contact Information: Name:	iation: Name: Matt Howard			đ	Phone #: 901-377-7325
E-mail: (address	E-mail: (address): mthoward@terracon.com			N	Mobile #: 901-487-4262
Hard copy: (add	Hard copy: (address): 7876 Stage Hills Blvd #105, Bartlett, TN 38	38133		ſ L	Fax #: 901-377-7327
Invoice Address (if different):	(if different):				
*** Please review p	*** Please review paperwork and samples before submitting to lab. Uncontained / improperly packaged samples or excessive administrative requests may incur additional fees. ***	improperly packaged samples o	or excessive administr	rative requests may incur additi	onal fees, ***
Sample No.	Sample Description		Vol. / Area		Location / Notes
4	Wallboard on ceiling			Storage Room	m / NBar Buckdoor
38				11	
3.9				11	
05	Cerped Mastic			Managel's	ollia
Ĵ	(1			5	
42	()			11	
43	Wallboord			-	
44	~			1	
برح	· ·			~ ~	
Released by:	1999 Date/Time.	me.10/4:30	Received By:	Ŕ	DateCime: 1-3/-10 /8', 50 A-
Released by:	Date/Time:	ne:	Received By:		Date/Time:
Notes: please Steve Moody Micr	Notes: please copy email results to: jsmutchler@terracon.com Steve Moodv Micro Services. LLC - 2051 Vallev View Ln Farmers Branch, TX 75234 - (972) 241-8460 / FAX (972) 241-8461	com nch, TX 75234 - (972) 241-	8460 / FAX (972)	241-8461 NVLAP Lab #102056	102056 TX DSHS License # 30-0084 [COC 2009]

_	<u>Asbestos</u> Chain of Custody	2			Pageof
Técho Servico PLM-Bulk: 🛛 1	PLM-Bulk: □ 1 day ◆ □ 2 day ◆ 4 3 day ◆ □ 5 day	PCM-Air: 🔲 1 d	□ 1 day ◆ □ 2 day	◆ □ 5 day [Lab.	Lab Job# 108-00028
		TEM-Air: □ 6 hr ◆			Lab Job#
NA X	A ANALYZE ALL + 🗆 POSITIVE STOP	TEM-Bulk/Wipe/MVac:	Vac: $\Box 24 hr$	$\bullet \Box 48 hr \bullet \Box 72 hr Lab.$	Lab Job#
Please call in	**Please call in advance for after-hour & weekend analysis	L EIVI-/402/MI0UIIIeu:]] ▶	
Company Name		S, IIV Comula data	Internation 10, 2010		P.O. No: A 8107001
2			- (v- (mninc		Droisort Nov. A 8107001
Project: Kegi	Kegions Bank – Kutherford, 1.N				0. 4010/001
Contact Information: Name:	ation: Name: Matt Howard			Phone #:	Phone #: 901-377-7325
E-mail: (address)	E-mail: (address): mthoward@terracon.com			Mobile #	Mobile #: 901-487-4262
Hard copy: (addr	Hard copy: (address): 7876 Stage Hills Blvd #105, Bartlett, TN 38133	8133		Fax #: <u>9(</u>	Fax #: 901-377-7327
Invoice Address (if different):	(if different):				
*** Please review pa	*** Please review paperwork and samples before submitting to lab. Uncontained / improperly packaged samples or excessive administrative requests may incur additional fees. ***	improperly packaged samples (or excessive adminis	trative requests may incur additional fees.	***
Sample No.	Sample Description		Vol. / Area	Locatic	Location / Notes
46	P"x 9" Ton Floor file			Mop Closet	
4 7	11				
84				11	
49	Carped Mashic			Teller Row	
50	11			2	
ر ا					
52	Covebose			0	
53	11			-	
۶4	1			5	
Released by:	1-20	me: 0/4:30	Received By:	R	Date(Time: 1-21-10 / 8'. 50 +
Released by:	Date/Time:	me:	Received By:		Date/Time:
Notes: please c Steve Moody Micro	Notes: please copy email results to: jsmutchler@terracon.com Steve Moody Micro Services, LLC - 2051 Valley View Ln Farmers Branch, J	.com nch, TX 75234 - (972) 241-8460 / FAX (972) 241-8461	-8460 / FAX (972		NVLAP Lab #102056 TX DSHS License # 30-0084 [COC 2009]

SMMS	Asbestos Chain of Custody	-			Pageof
PLM-Bulk: 0	PLM-Bulk: \Box 1 day \diamond \Box 2 day \diamond A 3 day \diamond \Box 5 day	PCM-Air: □ 1 day - TEM_Air: □ 6 hr ◆	• 12 day		Lab Job# 108-00028
Please call in	ANALYZE ALL ◆ □ POSITIVE STOP **Please call in advance for after-hour & weekend analysis	N N		$\Box 48 \text{ hr} \bullet \Box 72 \text{ hr}$	Lab Job#
Company Name	Company Name and City: Terracon Consultants, Inc. – Memphis, TN	, TN		,	
Submitter's Name:	:: Matt Howard	Sample date:	January 20, 2010		P.O. No: A8107001
Project: Regic	Regions Bank – Rutherford, TN	- •		Pr	Project No: A8107001
Contact Information: Name:	tion: Name: Matt Howard			Ч	Phone #: 901-377-7325
E-mail: (address)	١×	-		Ŵ	Mobile #: 901-487-4262
Hard copy: (addre	Hard copy: (address): 7876 Stage Hills Blvd #105, Bartlett, TN 38133	8133		Fa	Fax #: 901-377-7327
Invoice Address (if different):	(if different):				
*** Please review pa	*** Please review paperwork and samples before submitting to lab. Uncontained / improperly packaged samples or excessive administrative requests may incur additional fees. ***	improperly packaged samples or	excessive administ	rative requests may incur additio	nal fees. ***
Sample No.	Sample Description	Ń	Vol. / Area		Location / Notes
55	Covebese			Mop Closet	
56	11			n.	
57	6	· · · · · · · · · · · · · · · · · · ·		11	
5 8	Sink Undercoct			Breakroom	
59		•		2	
60	Grang Window Caul			Exterior ne	neor back cloor
61	11			11	
29	11			()	
\times	X		\times	\times	
Released by:	1999 Date/Time:	D.10/4:30	Received By:	R	Date/Time: 7-01-10/8:50 h
Released by:	Date/Time:	ne:	Received By:		Date/Time: /
Notes: please c Steve Moody Micro	Notes: please copy email results to: jsmutchler@terracon.com Steve Moody Micro Services, LLC - 2051 Valley View Ln Farmers Branch,	com nch, TX 75234 - (972) 241-8460 / FAX (972) 241-8461	460 / FAX (972)) 241-8461 NVLAP Lab #102056	02056 TX DSHS License # 30-0084 [COC 2009]

APPENDIX D

CERTIFICATIONS



THE STATE OF TENNESSEE

Department of Environment and Conservation Solid & Hazardous Waste Management Toxic Substances Program 401 Church Street 5th Floor L'&'C Tower Nashville TN 37243

By virtue of the authority vested in me, I hereby accredit:

Matthew T. Howard

7876 Stage Hills Blvd #105 Bartlett TN, 38133



to conduct ASBESTOS ACTIVITIES in the following discipline(s) in schools or public and commercial buildings in Tennessee. This individual is responsible for compliance with the applicable requirements of Rule 1200-01-20.

Discipline	Туре	Accreditation Number	Effective Date	Expiration Date	
Inspector	Initial	A-1-48754-2457	December 16, 2009	December 31, 2010	

Given under my hand and the Seal of the State of Tennessee in Nashville,

This 16th Day of December 2009

Upple

Mike Apple, Director Division of Solid Waste Management

CN-1324



RDA (Pending)

APPENDIX E

PHOTOGRAPHS



Photo #1 Overview of bank from the south.



Photo #3 View of carpet mastic and covered tile (HA6).



Photo #5 View of floor tile in break room with black mastic below (HA9).



Photo #2 View of back of bank.



Photo #4 View of floor tile in hallway with black mastic below (HA7).



Photo #6 View of floor tile in mop closet with black mastic below (HA14).



Photo #7 View of lobby area.



Photo #8 Typical offices



Photo #9 Terrazzo located below carpeted areas in lobby and offices.



Photo #11 View of roof decking above suspended ceiling tiles.



Photo #10 View of roof decking above suspended ceiling tiles.



Photo #12 View of typical lighting installed in suspended ceiling system.



Photo #13 View of lighting in break room.



Photo #15 Thermostat located in lobby.




Photo #14 View of lighting in restroom.



Photo #16 View of ductwork located above suspended ceiling.

APPENDIX F

SITE DIAGRAM



LEGEND

	T	THERMOSTAT MOUNTED ON GYPSUM WALLBOARD W/CERAMIC TILES		
	A	TERRACON OBSERVED ABOVE CEILING TILES		N
	₿	TERRACON OBSERVED BELOW EXISTING FLOOR COVERING		
	U	SINK UNDERCOAT (HA 18)		
		TAN FLOOR TILE AND BLACK MASTIC (HA 14)		<u> </u>
		FLOOR TILE AND BLACK MASTIC BELOW CARPET (HA 6)		
		BLACK MASTIC BELOW FLOOR TILE		
		GRAY CAULK ON BACK DOOR (HA 19)		NOT TO SCALE
тн	IIS DIAGRAM IS FOR GENEF	RAL LOCATION ONLY, AND IS NOT INTENDED FOR CONSTRUCTION PURPOSES		
Proje	ect Mngr: MT1	H Project No. A8107001	SITE DIAGRAM	FIG. No
Draw	vn By:		ASBESTOS SURVEY	

Project Mngr.	MTH	Project No.	A8107001		SITE DIAGRAM	FIG. No.	
Drawn By:	TLY	Scale:	AS SHOWN	lierracon	ASBESTOS SURVEY		
Checked By:		File No.	ASA8107001-1	Consulting Engineers and Scientists	REGIONS BANK-RUTHERFORD		
	MTH/MRF		ASA8107001-1		202 EAST MAIN STREET		1
Approved By:	мсс	Date:	JANUARY 2010	7876 Stage Hills Blvd. Suite 105 Bartlett, TN 38133 (901) 377-7325 (901) 377-7327	RUTHERFORD, TN		