



RENAISSANCE DESIGN BUILD, INC.

INDIANA OFFICES
117 S Indiana Avenue
Sellersburg, IN 47172
Tel: 812-246-5897
Fax: 812-248-4320

rdbi@rdbi-inc.com

KENTUCKY OFFICES
1012 S. Fourth Street
Louisville, KY 40203
Tel: 502-424-8373
Fax: 502-587-0931

[web: rdbi-inc.com](http://web:rdbi-inc.com)



Structural Engineering Investigation
For
Joe Gribbins
Estate of Dr. Robert Sexton, Jr.
10410 Forest Garden Lane
Louisville, KY 40223
Job No. 2022-534



By
Nathan Grimes, P.E., P.L.S., C.F.E.I., C.F.I.I., R.H.I.

**ENGINEERING • DESIGN • LAND SURVEYING • GENERAL CONTRACTING •
• CONSTRUCTION MANAGEMENT • PLANNING • ENGINEERING INVESTIGATION SERVICES •
• BUILDING & HOME INSPECTIONS •**

On Monday, December 5, 2022, at 2:00 PM, Nathan Grimes, P.E., P.L.S., C.F.E.I., C.F.I.I., R.H.I., conducted a non-destructive visual structural investigation on the structural integrity of a single-family residence as requested by Joe Gribbins, Auctioneer. Mr. Gribbins was present at the site during the engineering investigation. No warranty or guarantee is made or implied by this report. It should be noted that physical conditions reported, as satisfactory when examined does not imply continued satisfactory conditions in the future.

The 1½ story wood framed brick veneer and Hardie Board sided house is constructed over a full concrete walled basement. The weather was cloudy and 45°F in temperature.

The purpose of this structural engineering investigation was to determine the structural integrity of various cracks at the single-family residence. Our structural investigation is limited to these issues.

Note: All directional references to left, right, front, or rear assume the reader is standing in the street, facing the front doors of the building being referenced. The front facade of house faces North.

The following documentation was reviewed as part of this investigation:

1. Property information from Jefferson County, KY PVA (This information is included in Appendix “A” of this report).
2. Foundation repair proposal from TFS dated 06/07/2019.
3. Foundation repair proposal from TFS dated 11/15/2022.
4. No original house plans were available for us to review as part of this investigation.

The following items were observed during our investigation:

5. The house was originally constructed in 1999 and has been owned by the original owners since that time. The house has been well maintained.
6. There are no large trees or bushes planted next to foundation walls around the house.
7. All finished grades are sloping away from foundation on all sides of the house.
8. All gutters and downspouts have pipe extensions or splash blocks to direct storm water from roof away from foundation and footings.
9. There are brick veneer masonry joint cracks on front facade, right side facade, and rear facade in several locations. These cracks vary in width from hairline to 2.5mm and none were offset. There is evidence that brick veneer masonry joints have been repaired in other locations previously.
10. On the right side there is an opening between concrete foundation wall and brick veneer of 5.5mm in one location at base of exterior wall.
11. There are drywall cracks in garage front wall, kitchen right side wall, and front office right side wall. These cracks vary in width from hairline to 1.00mm and none of them are offset.
12. The rear walkout basement is completely finished except for a mechanical room area that is a rear of garage. There are 2 vertical cracks in reinforced concrete basement walls in the mechanical room. One is 2.5mm in width and is not offset. The other is in corner where rear of garage and basement wall meet common wall with adjoining property. This crack varies in width up to 5/8” in width and is entire height of basement wall. There is no visible reinforcing steel in the crack. The reinforced concrete basement wall is 7’-8 ½ tall. There is no evidence of ground water or storm water entering these basement wall cracks.
13. There are repaired cracks in concrete driveway slab that were up to ¾” in width.
14. The interior garage window trims have separated on front wall of house.
15. All windows and doors were operable.
16. There is a crack in joint connection of rear concrete patio to the brick veneer and also a crack in the patio slab itself in one location. Neither of these are offset.
17. The caulking seam has failed at rear wood deck where the Hardi-Board wall connects the brick veneer wall.
18. There are several loose nails on wood deck that connect deck boards to framing on the rear deck.

19. There is an offset in joint in garage floor slab near rear wall of garage. This offset is ½” height at the joint in the concrete floor slab.
20. Most of the reinforced basement and foundation walls are not visible on exterior of the house due to the finished grade of the soil.
21. The visible garage and basement concrete slab floors were not cracked except as listed above.

Conclusions regarding this engineering investigation are as follows:

Reasons Concrete Basement Walls:

1. It is common for concrete cracks to develop in poured concrete foundation and basement walls. Some of the reasons this happen are as follows:
 - a. Settlement of footings due to:
 - i. Improperly compacted sub grades.
 - ii. Improperly sized or reinforced support building loads.
 - iii. Plumbing leaks or downspouts not diverting water away from building.
 - b. Shrinkage cracks due to:
 - i. Improper concrete mix (high water content).
 - ii. Rapid curing of concrete during construction process.
 - iii. Omission of control joints.
 - iv. Omission or patterns placement of steel reinforcement.
 - c. Expansive clay soils
 - d. Frost heave due to inadequate covering of footings or unheated structures.
 - e. Damage from trees or shrubs located next to building foundation.
 - f. Vehicle loading
 - g. Surface or subsurface water freezing.
 - h. Absent footings
 - i. Catastrophic weather events such as earthquakes, floods, tornadoes, hurricanes, etc.
 - j. Deferential settlement of structure where a section or side of building is moving up or down at a different rate or amount than the other.

Reasons Brick Veneer Masonry Joints Crack

1. The brick veneer facade of a building is not structural. There are many possible reasons for brick veneer masonry joints to crack. Some of the reasons this happens is as follows:
 - a. Settlement of existing footings and foundation wall
 - b. Inadequate brick ledge support on foundation
 - c. Poor construction techniques during installation
 - d. Faulty construction materials
 - e. Insufficient amount of brick ties connecting brick veneer to structure of house
 - f. Catastrophic or severe weather events such as earthquakes, tornados, hurricanes, etc.
 - g. Lack of shrinkage control joints in the brick veneer
 - h. Storm water infiltration of brick veneer wall
 - i. Expansion and contraction forces stressing brick veneer wall

Reasons Drywall Cracks

1. There are many reasons gypsum wall board (drywall) cracks:
 - a. Improper installation of drywall, including errors in taping, insufficient number of fasteners, incorrect fasteners, application of joist compound, or incorrect type of drywall compound.
 - b. Moisture behind wall.
 - c. Heavy objects on the wall causing the wall to stress.
 - d. Foundation settlement or differential frost heaving of foundation

- e. High stress areas in wall such as door headers, window headers and over beams with long spans.
 - f. Framing shrinkage caused by using wet lumber or, poor quality framing connections that permit movement and settlement in wall assembly.
 - g. Overloaded or over spanned structural members or framing assemblies causing deflections in drywall assemblies.
 - h. Installing gypsum board across uneven surfaces (framing bowed, bent or uneven) due to inconsistent or sloppy framing adding to material stress.
 - i. Arching roof or floor trusses caused by moisture/temperature differences between trusses upper and lower members.
 - j. Significant change in the building moisture level or moisture content causing expansion or shrinkage of drywall assembly.
 - k. Significant changes in building interior temperature causing expansion or shrinkage of drywall assembly.
 - l. Lack of control joints in drywall at problem or stress points and in areas of drywall extending beyond 30 length of a broken or unrelieved panel.
22. The house is structurally sound for manual residential dead and live loading conditions, but some repairs are required to maintain the existing structural integrity to the house. These repairs recommendations are listed in the following section of this report.

Recommendations regarding this investigation are as follows:

- 23. All interior drywall cracks should be repaired with fiberglass mesh tape.
- 24. All brick veneer masonry joint cracks should be tuckpointed with mortar that matches the existing to keep stormwater infiltration from entering wall assembly and causing further damage.
- 25. Garage floor slab joint crack and rear patio slab crack should be sealed with concrete crack sealer.
- 26. Basement wall cracks should be sealed with injected concrete crack sealer.
- 27. The failed caulking joint between Hardi-Board siding and brick veneer walls at rear deck should be recalced to keep storm water infiltration from entering walls and causing further damage. Repair using exterior polyurethane caulking.
- 28. All loose nails and missing nails on rear deck boards should be removed and replaced with exterior deck screws to securely fasten deck boards to deck framing structure.
- 29. Separated garage windowsill and trim should be re-caulked and painted to match existing. Repair using exterior polyurethane caulking.
- 30. The large crack in corner of basement mechanical room needs to be repaired with injected concrete crack sealer as stated in item # 26 above but it also needs to be reinforced since there is no visible steel tying the 2 walls together. Reinforce as shown on attached detail.


We retain the right to revise or amend this report if additional information is discovered or if further investigation is required or requested. See attached photographs for additional information.

Sincerely,
Renaissance Design Build, Inc.



Nathan Grimes, P.E., P.L.S., C.F.E.I., C.F.I.I., R.H.I.






PLAN
SCALE: 1/2" = 1'-0"


NOTE: CONTRACTOR SHALL
FIELD VERIFY
ALL DIMENSIONS
& MEASUREMENTS.

REPAIR SCHEDULE


- ① INSTALL 1/2" X 6" X 12" STEEL ANGLE TO EX. WALLS. TO TIE WALLS TOGETHER IN CORNER OF BASEMENT MECH. ROOM.
- ② DOWEL & EPOXY 6" X 1/2" DIA. THREADED METAL ANCHOR, NUT & WASHER (2 PER ANGLE)
- ③ COAT BACK OF STEEL ANGLE WITH BLACK JACK BEFORE INSTALLING ANGLE TO WALL.



SECTION A-A
SCALE: 1/2" = 1'-0"



ELEVATION



PLAN

STEEL ANGLE DETAILS
SCALE: 1" = 1'-0"



Nathan R. Grimes
1/31/2023

Sheet Of	Dwn by: WJws Chk by: [Signature] Scale: As NOTED Date: 1/31/2023 Project No: 2022-524	RENAISSANCE DESIGN BUILD, INC. 1012 South Fourth Street Louisville, Kentucky 40203 Tel: 502-424-8373 Fax: 502-587-0931 www.renaissance designbuild.com
	BASEMENT WALL REPAIR DETAIL 10410 FOREST GRADE LANE LOUISVILLE, KY 40223 Revisions:	

PHOTO SHEETS



Front Facade




Brick Veneer Masonry Joint Cracks Front Facade




Brick Veneer Masonry Joint Cracks Front Facade



Downspout Detail Front Right Corner



Brick Veneer Masonry Joint Crack Right Side Facade



Brick Veneer Masonry Joint Crack Right Side Facade



Brick Veneer Masonry Joint Crack Right Side Facade



Foundation Front Right Corner Detail




Eave Front Right Corner Detail



Repaired Concrete Driveway Slab Cracks



Repaired Concrete Driveway Slab Cracks



Drywall Crack in Kitchen Right Wall




Drywall Crack in Kitchen Right Side Wall



Offset Joint in Garage Floor



Offset Joint in Garage Floor



Foundation Crack in Basement Mechanical Room Wall



Foundation Crack in Basement Mechanical Room Wall



Foundation Crack in Basement Mechanical Room Wall



Foundation Crack in Basement Mechanical Room Wall



Downspout Drain Rear Facade Detail



Interior Office Front Right Corner



Interior Office Front Right Corner



Interior Kitchen

Blank



Separated Wood Window Sill and Garage Front Wall



Drywall Crack in Garage Front Wall



Interior Garage Front Wall




Separated Wood Window Sill and Garage Front Wall



Foundation Crack in Basement Mechanical Room Wall



Foundation Crack in Basement Mechanical Room Wall



Foundation Crack in Basement Mechanical Room Wall



Rear Wall Basement Bedroom



Rear Wall Basement Family Room



Rear Wall Basement Library



Rear Wall 2nd Floor Bedroom



Rear Wall Main Floor Bedroom



Repaired Concrete Driveway Slab Cracks



Downspout Detail Front Facade



Front Facade



Brick Veneer Masonry Joint Cracks Front Facade



Brick Veneer Masonry Joint Cracks Front Facade



Brick Veneer Masonry Joint Cracks Front Facade



Brick Veneer Masonry Joint Cracks Front Facade



Brick Veneer Masonry Joint Cracks Front Facade



Brick Veneer Masonry Joint Cracks Front Facade



Brick Veneer Masonry Joint Cracks Front Facade



Previous Repaired Brick Veneer Masonry Joint Crack Front Facade



Previous Repaired Brick Veneer Masonry Joint Crack Right Side Facade



Previous Repaired Brick Veneer Masonry Joint Crack Right Side Facade



Previous Repaired Brick Veneer Masonry Joint Crack Right Side Facade



Right Side Facade



Downspout Drain Detail Front/Right Corner of House



Brick Veneer Masonry Joint Crack Right Side Facade



Brick Veneer Masonry Joint Crack Right Side Facade



Downspout Drain Detail Rear Right Corner



Brick Veneer Masonry Joint Crack Right Side Facade



Brick Veneer Masonry Joint Cracks Rear Facade



Brick Veneer Masonry Joint Cracks Rear Facade



Brick Veneer Masonry Joint Cracks Rear Facade



Brick Veneer Masonry Joint Cracks Rear Facade



Brick Veneer Masonry Joint Cracks Rear Facade



Brick Veneer Masonry Joint Cracks Rear Facade



Brick Veneer Masonry Joint Cracks Rear Facade



Brick Veneer Masonry Joint Cracks Rear Facade



Basement Walkout Patio Detail



Rear Facade



Brick Veneer Masonry Joint Cracks Rear Facade



Brick Veneer Masonry Joint Cracks Rear Facade



Rear Patio Slab Cracks Detail



Rear Patio Slab Cracks Detail



Rear Patio/Wall Connection Detail



Rear Patio/Wall Connection Detail



Rear Patio/Wall Connection Detail



Rear Patio/Wall Connection Detail



Loose Nails Rear Patio Detail



Loose Nails Rear Patio Detail



Partial Rear Facade Detail



Caulking Seam Cram at 2nd Floor Deck



Caulking Seam Crack at 2nd Floor Deck



Brick Veneer Masonry Joint Cracks Rear Facade



Loose Nails Rear Patio Detail



Right Side Facade



Rear Patio and Stair Detail



Driveway Concrete Slab Repaired Crack Detail

APPENDIX 'A'
Jefferson County, KY PVA

JEFFERSON COUNTY PVA

10410 FOREST GARDEN LN

Mailing Address 10811 PINEVIEW CT,
LOUISVILLE, KY 40299-3977

Owner SEXTON ROBERT F JR
ESTATE OF

Parcel ID 306500150000

Land Value \$50,000

Improvements Value \$312,960

Assessed Value \$362,960

Approximate Acreage 0.1265

Property Class 510 RES 1 FAMILY
DWELLING

Deed Book/Page 778 557 (N/A Online)

District Number 148020

Old District 21

Fire District ANCHORAGE MIDDLETOWN
FIRE & EMS

School District JEFFERSON COUNTY

Neighborhood 806109 / FOREST GREEN

Home Rule City Lyndon

Sheriff's Tax Info [View Tax Information](#)

County Clerk [Delinquent Taxes](#)



Area Type	Gross Area	Finished Area
Main Unit	-	2,170
Basement	1,488	1339
Attic	NONE	0
Attached Garage	452	n/a
Detached Garage	-	n/a

All measurements in square feet.

Property Details

Type	1 : SINGLE FAMILY
Year Built	1999
Exterior Wall	BV BRICK VENEER
Roof	HIP
Basement Foundation	FULL BSMT
Condition	NORMAL FOR AGE
Heating Type	1 CENTRAL WARM AIR
Central Air	Yes
Fireplace	Yes
Construction Frame	Wood frame
Stories	1.50
Full Bathrooms	3
Half Bathrooms	0

Property Sketch



Sales History

Deed Book/Page	Price	Date	Previous Owner
778 557 (N/A Online)	\$0	05/25/2022	SEXTON ROBERT F
10180 0904	\$327,590	12/17/2013	SEXTON ROBERT F Jr
10180 0903	\$0	12/17/2013	SEXTON NANCY N

Assessment History

Record Year	Land	Improvements	Total	Reason
2022	\$50,000	\$312,960	\$362,960	CR - Computer Reassessment
2016	\$45,000	\$291,830	\$336,830	RC - Residential computer reass
2011	\$40,000	\$287,590	\$327,590	DC - Decrease by comp-reass
2009	\$40,000	\$302,730	\$342,730	NC - Residential no change
2005	\$40,000	\$302,730	\$342,730	RC - Residential computer reass

Legal Lines

LN	Legal Description
1	LOT 15 FOREST GREEN PATIO HOMES SEC 1 PB.44 PG.16 0.1265 AC+-

Property is assessed per KRS 132.20 on January 1st of each year. The current year assessments are updated and posted on the website in mid April. Information deemed reliable but not guaranteed. Data last updated: 01/29/2023.