

Mr. Gary Schlegel Jones Lang LaSalle Gary.Schlegel@am.jll.com

Subject:

Path of Construction Asbestos Survey Bank of America - 2700 Main St Site 2700 Main Street Newfane, New York Mail Code: MY7-127

Dear Mr. Schlegel:

ARCADIS U.S., Inc. (ARCADIS) conducted a Path of Construction (POC) asbestos survey of certain Homogeneous Applications (HAs) that may be impacted during the planned construction project at the above-referenced building for the Bank of America. ARCADIS' scope of work and the findings of POC survey are summarized herein.

ASBESTOS SURVEY SCOPE OF WORK

Based on review of information provided to ARCADIS, sample collection and analysis of the following HAs was required to determine if these HAs were asbestoscontaining building materials (ACBMs):

- HA-37, Window Caulk;
- HA-38, Window Glazing;
- HA-39, Window Caulk;
- HA-40, Patch/Repair Caulk;
- HA-41, Patch/Repair Glazing;
- HA-42, Window Glazing;
- HA-43, Window Glazing; and
- HA-44, Window Caulk.

On April 27, 2011, Mr. Tom Ashman visited the building to collect samples of these HAs. A copy of Mr. Dolan's asbestos inspector license is provided in Attachment A. In total, 28 bulk samples were collected and submitted for laboratory analyses.

ARCADIS U.S., Inc.

111 S. Independence Mall East

Suite 1010 Philadelphia

Pennsylvania 19106 Tel 215.931.4351 Fax 215.625.0172 www.arcadis-us.com

ENVIRONMENT

Date:

May 16, 2011

Contact:

John Luxford

Phone:

215.931.4351

Email:

John.Luxford@arcadis-us.com

Our ref:

HT119375.0000

ARCADIS

Mr. Gary Schlegel

May 16, 2011

The results of the POC asbestos survey are presented in the Attachments to this report as follows:

- Attachment B Homogeneous Application Table (HAT)
- Attachment C Laboratory Data Package and Chain of Custody
- Attachment D Floor Plans indicating Sampling Locations
- Attachment E Photographs of the HAs

The scope of this POC survey was limited to sampling only the HAs previously listed. If additional suspect ACBMs not referenced in this report are encountered, samples of the material(s) should be collected and analyzed for the presence or absence of asbestos prior to disturbance.

CONCLUSIONS

As presented in the HAT in Attachment B and the Laboratory Data Package in Attachment C, the following HAs are ACBMs:

- HA-38, Window Glazing, located in the stairwell and Men's & Women's Rooms;
- HA-41, Patch/Repair Glazing, West Elevation. Women's Room;
- HA-42, Window Glazing, West Elevation Men's & Women's Rooms;
- HA-43, Window Glazing, West Elevation Stairwell; and
- HA-44, Window Caulk, West Elevation Men's & Women's Rooms, Stairwell.

As the above listed ACBMs will be disturbed during construction activities, compliance with the asbestos regulations (notification, control measures and/or abatement) is required. Contact the Property Manager or ARCADIS if you have questions or need assistance concerning this report or in reading the HAT.

ARCADIS recommends that the ACBMs be managed in accordance with an Operations & Maintenance (O & M) Program with abatement only being required when materials will be disturbed (i.e., renovation and some maintenance activities). ACBMs that are "Damaged" or "Significantly Damaged" present a greater risk of releasing asbestos fibers. Therefore, these materials should be evaluated to determine if they require repair or abatement. If the materials are repaired or abated, the HAT should be updated to reflect this modification to the materials. Contact the building's Property Manager to determine what actions are necessary with respect to "Damaged" or "Significantly Damaged" materials, if present.

ARCADIS

Mr. Gary Schlegel
May 16, 2011

CLOSING

The POC asbestos survey described herein was conducted by the undersigned of ARCADIS. This investigation consisted solely of the activities described herein and is subject to the Limitations and Service Constraints in Attachment F.

Thank you for your time and consideration on this project. Please do not hesitate to call if you have questions regarding the results of this limited survey or require additional information.

Sincerely,

ARCADIS U.S., Inc.

Tom Ashman Asbestos Inspector Timothy M. Downey Reviewer

Frintly Man

John R. Luxford Senior Toxicologist

Attachments:

- A Certifications and Licenses
- B Asbestos Homogeneous Application Table (HAT)
- C Laboratory Data Package and Chain of Custody
- D Floor Plans
- E Photographs
- F Limitations and Service Constraints

Attachment A

Certifications and Licenses

STATE OF NEW YORK - DEPARTMENT OF LABOR ASBESTOS CERTIFICATE



THOMAS E ASHMAN
CLASS(EXPIRES)
CATEC(11/11) DINSP(11/11)
HPM (11/11)

CERT# 04-07493 DMV# 309991936

MUST BE CARRIED ON ASBESTOS PROJECTS

EYES BLU HAIR BLN HGT 5' 11" IF FOUND RETURN TO: NYSDOL - L&C UNIT ROOM 161A BUILDING 12 STATE OFFICE CAMPUS ALBANY NY 12240

Attachment **B**

Asbestos Homogeneous Application Table (HAT) Data Extraction Date 2011-05-12 4:46:05 PM

Mail Code NY7-127 2700 Main St Address City Newfane State NY Survey Date 5/12/2011

Path of Construction 1,B,E Survey Type

Floors

Overwrite Existing HA1Yes

Do Not Modify

e.g. 1,2,6
If you choose "yes" all existing HA data in IDEA will be lost! Any ACM data from previous surveys that you wish to save must be included in

HA No.	Material Type	Primary Color	Texture	Description	NESHAP Cat.	Floor	Rooms	Location	Condition	Amt.	Units	Status	Modified Description	РК	ModDate
1	T - Pipe Insulation (Fittings, Elbows, Runs)	Gray	Rough	Pipe Fitting Insulation	Friable RACM	B,1	Basement, Hallway,1st Floor Janitor's closet	Other	Good	10	LF			148522	
2	T - Insulation - Misc.	White	Rough	Pipe Insulation	Friable RACM	B,1	Basement, Hallway, 1st Floor Janitor's closet	Other	Good	135	LF			148496	
3	S - Wall Plaster White Coat	White	Smooth	White Top Coat Wall Plaster	Non-ACM, Sampled	1	ATM Room, Back Room, Conference Room	Wall	Good	0	SF			148426	
4	S - Wall Plaster	Gray	Rough	Gray Base Coat Wall Plaster	Non-ACM, Sampled	1	ATM Room, Back Room, Conference Room	Wall	Good	0	SF			148402	
5	M - Gypsum Board	Brown	Smooth	Gypsum Board	Non-ACM, Sampled	1	ATM Room	Wall	Good	0	SF			147792	
6	M - Joint Compound	White	Smooth	Joint Compound Associated with HA-5	Non-ACM, Sampled	1	ATM Room	Wall	Good	0	SF			147875	
7	M - Gypsum Board	Gray	Smooth	Gypsum Board	Non-ACM, Sampled	B,1	Ceiling-Men's Room, Walls-Basement, Break Room, Kitchen	Multiple	Good	0	SF			147793	
8	M - Joint Compound	White	Smooth	Joint Compound Associated with HA-7	Non-ACM, Sampled	B,1	Ceiling-Men's Room, Walls-Basement, Break Room, Kitchen	Multiple	Good	0	SF			147874	
9	M - Ceiling Tiles and Lay-in Panels	White	Rough	2' x 4' Acoustical Suspended Ceiling Tile	Non-ACM, Sampled	1	ATM Room	Ceiling	Good	0	SF			147067	
10	M - Ceiling Tiles and Lay-in Panels	White	Rough	2' x 4' Pinhole Suspended Ceiling Tile	Non-ACM, Sampled	В	Basement, Break Room, Kitchen	Ceiling	Good	0	SF			147068	
11	M - Ceiling Tiles and Lay-in Panels	White	Rough	2' x 4' Suspended Ceilling Tile	Non-ACM, Sampled	В	Basement, Stairway Landing	Ceiling	Good	0	SF			147069	
12	M - Ceiling Tiles and Lay-in Panels	White	Rough	2' x 2' Spline-Set Ceiling Tile	Non-ACM, Sampled	1	Main Lobby	Ceiling	Good	0	SF			147070	
13	M - Ceiling Tiles and Lay-in Panels	Gray	Rough	1' x 2' Spline-Set Ceiling Tile	Non-ACM, Sampled	1	Main Lobby, Back Room	Ceiling	Good	0	SF			147066	
14	M - Ceiling Tiles and Lay-in Panels	White	Rough	12" x 12" Spline-Set Ceiling Tile	Non-ACM, Sampled	В	Storage #2	Ceiling	Good	0	SF			147071	
15	M - Ceiling Panel	White	Rough	Ceiling Fiberboard	Non-ACM, Sampled	1	Janitor's Closet	Ceiling	Good	0	SF			146987	
16	M - Wall Paper	Blue	Smooth	Lower Wall Paper	Non-ACM, Sampled	1	Main Lobby, Back Room	Wall	Good	0	SF			148765	
17	M - Wall Paper	White	Smooth	Upper Wall Paper	Non-ACM, Sampled	1	ATM Room, Conference Room, Teller Area	Wall	Good	0	SF			148766	
18	M - Carpet Glue/Mastic	Tan	Rough	Tan Carpet Mastic	Non-ACM, Sampled	1	Main Lobby, Back Room, Conference Room	Floor	Good	0	SF		<1% Chrysotile	146921	
19	M - Carpet Glue/Mastic	Brown	Rough	Brown/Black Carpet Mastic	Non-ACM, Sampled	1	Front Vestibule	Floor	Good	0	SF			146920	
20	M - Vinyl Floor Tile	White	Smooth	12" x 12" Floor Tile	Non-ACM, Sampled	1	ATM Room	Floor	Good	0	SF			148227	
21	M - Floor Tile Mastic	Yellow	Rough	Floor Tile Mastic Associated with HA-20	CAT 1 Non-friable RACM	1	ATM Room	Floor	Good	50	SF			148652	
22	M - Vinyl Floor Tile	Pink	Smooth	Floor Tile Beneath HA-20	CAT 1 Non-friable RACM	1	ATM Room, Safe Deposit Room #1 & 2, Teller area, Janitor's closet, safe	Floor	Good	640	SF			148224	
23	M - Floor Tile Mastic	Black	Rough	Floor Tile Mastic Associated with HA-22	CAT 1 Non-friable RACM	1	ATM Room, Safe Deposit Room #1 & 2, Teller area, Janitor's closet, safe	Floor	Good	640	SF			148649	
24	M - Vinyl Floor Tile	Beige	Smooth	12" x 12" Floor Tile	CAT 1 Non-friable RACM	B,1	Top of Stairway to Basement, Basement, Break Room, Kitchen	Floor	Good	250	SF			148222	
25	M - Floor Tile Mastic	Yellow	Rough	Floor Tile Mastic Associated with HA-24	Non-ACM, Sampled	B,1	Top of Stairway to Basement, Basement, Break Room, Kitchen	Floor	Good	0	SF		<1% Chrysotile	148653	
26	M - Vinyl Floor Tile	Tan	Smooth	12" x 12" Floor Tile	CAT 1 Non-friable RACM	В	Underneath HA-24 in Basement Break Room	Floor	Good	220	SF			148225	

HA No.	Material Type	Primary Color	Texture	Description	NESHAP Cat.	Floor	Rooms	Location	Condition	Amt.	Units	Status	Modified Date	Description	РК	ModDate
27	M - Floor Tile Mastic	Yellow	Rough	Floor Tile Mastic Associated with HA-26	Non-ACM, Sampled	В	Underneath HA-24 in Basement Break Room	Floor	Good	0	SF			<1% Chrysotile	148654	
28	M - Vinyl Floor Tile	Tan	Smooth	9" x 9" Floor Tile	CAT 1 Non-friable RACM	В	Boiler Room, storage room 2	Floor	Good	280	SF				148226	
29	M - Floor Tile Mastic	Black	Rough	Floor Tile Mastic Associated with HA-28	CAT 1 Non-friable RACM	В	Boiler Room, storage room2	Floor	Good	280	SF				148650	
30	M - Vinyl Floor Tile	Green	Smooth	12" x 12" Green Mottled Floor Tile	Non-ACM, Sampled	1	Main Lobby, back room, back vault, bathrooms, conference room, safety deposit room 1 and 2, safe	Floor	Good	0	SF			<1% Chrysotile	148223	
31	M - Floor Tile Mastic	Tan	Rough	Floor Tile Mastic Associated with HA-30	CAT 1 Non-friable RACM	1	Main Lobby, back room, back vault, bathrooms, conference room, safety deposit room 1 and 2, safe	Floor	Good	1150	SF				148651	
32	M - Tile Grout	Purple	Rough	Tile Grout associated with 8" x 8" Pink Ceramic Floor Tile	Non-ACM, Sampled	1	Main Lobby	Floor	Good	0	SF				148077	
33	M - Mortar	Gray	Rough	Mortar Associated with 8" x 8" Pink Ceramic Floor Tile	Non-ACM, Sampled	1	Main Lobby	Floor	Good	0	SF				147943	
34	M - Cove Base Mastic	Tan	Rough	Dark Tan Cove Base Mastic	Non-ACM, Sampled	1	ATM Room	Wall	Good	0	LF				147592	
35	M - Cove Base Mastic	Tan	Smooth	Tan Cove Base Mastic	Non-ACM, Sampled	1	Main Lobby	Wall	Good	0	LF				147593	
36	M - Ceramic Tile	Beige	Smooth	Ceramic Floor Tile	Non-ACM, Sampled	1	Main Lobby	Floor	Good	0	SF				147198	
37	M - Caulking/Putties	Gray	Grooved	Window Caulk	Non-ACM, Sampled	1	North Lobby Windows	Other	Good	384	LF					
38	M - Exterior Window Glazing Compound	Gray	Grooved	Window Glazing	CAT 2 Non-friable RACM	В	Stairwell, Men's & Women's Rooms	Other	Good	105	LF					
39	M - Caulking/Putties	Gray	Grooved	Window Caulk	Non-ACM, Sampled	1	East, North and South Elevations	Other	Good	384	LF					
40	M - Caulking/Putties	White	Grooved	Patch/Repair Caulk	Non-ACM, Sampled	1	West Elevation - Men's & Women's Rooms, Stairwell	Other	Good	70	LF					
41	M - Exterior Window Glazing Compound	White	Grooved	Patch/Repair Glazing	CAT 2 Non-friable RACM	1	West Elevation - Women's Room	Other	Good	7	LF					
42	M - Exterior Window Glazing Compound	Gray	Grooved	Window Glazing	CAT 2 Non-friable RACM	1	West Elevation - Men's & Women's Rooms	Other	Good	70	LF					
43	M - Exterior Window Glazing Compound	Beige	Grooved	Window Glazing	CAT 2 Non-friable RACM	1	West Elevation - Stairwell	Other	Good	35	LF					
44	M - Caulking/Putties	Gray	Grooved	Window Caulk	CAT 2 Non-friable RACM	1	West Elevation - Men's & Women's Rooms, Stainwell	Other	Good	63	LF					

HA No.	Material Type	ld	Location	Content	Туре	Friable	Sample Date	Consultant	Method	Lab	Notes	РК	ModDate
1	T - Pipe Insulation (Fittings, Elbows, Runs)	NY7-127- 01A	BASEMENT, HALLWAY	>10%	Chrysotile	Yes	8/26/2010	ARCADIS	PLM	EMSL		365606	
1	T - Pipe Insulation (Fittings, Elbows, Runs)	NY7-127- 01B	BASEMENT, HALLWAY	Pos Stop		Yes	8/26/2010	ARCADIS	PLM	EMSL		369963	
1	T - Pipe Insulation (Fittings, Elbows, Runs)	NY7-127- 01C	BASEMENT, BREAK ROOM	Pos Stop		Yes	8/26/2010	ARCADIS	PLM	EMSL		369964	
2	T - Insulation - Misc.	NY7-127- 02B	BASEMENT, HALLWAY	Pos Stop		Yes	8/26/2010	ARCADIS	PLM	EMSL		369965	
2	T - Insulation - Misc.	NY7-127- 02C	BASEMENT, BREAK ROOM	Pos Stop		Yes	8/26/2010	ARCADIS	PLM	EMSL		369966	
2	T - Insulation - Misc.	NY7-127- 02A	BASEMENT, HALLWAY	>10%	Chrysotile	Yes	8/26/2010	ARCADIS	PLM	EMSL		365607	
3	S - Wall Plaster White Coat	NY7-127- 03A	ATM ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368575	
3	S - Wall Plaster White Coat	NY7-127- 03B	BACK ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368576	
3	S - Wall Plaster White Coat	NY7-127- 03C	CONFERENCE ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368577	
4	S - Wall Plaster	NY7-127- 04A	ATM ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368578	
4	S - Wall Plaster	NY7-127- 04B	BACK ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368579	
4	S - Wall Plaster	NY7-127- 04C	CONFERENCE ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368580	
5	M - Gypsum Board	NY7-127- 05A	ATM ROOM, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368581	
5	M - Gypsum Board	NY7-127- 05B	ATM ROOM, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368582	
5	M - Gypsum Board	NY7-127- 05C	ATM ROOM, NORTH	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368583	
6	M - Joint Compound	NY7-127- 06A	ATM ROOM, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368584	
6	M - Joint Compound	NY7-127- 06B	ATM ROOM, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368585	
6	M - Joint Compound	NY7-127- 06C	ATM ROOM, NORTH	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368586	
7	M - Gypsum Board	NY7-127- 07A	MEN'S ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368587	
7	M - Gypsum Board	NY7-127- 07B	BASEMENT, BREAK ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368588	

HA No.	Material Type	ld	Location	Content	Туре	Friable	Sample Date	Consultant	Method	Lab	Notes	РК	ModDate
7	M - Gypsum Board	NY7-127- 07C	BASEMENT, KITCHEN	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368589	
8	M - Joint Compound	NY7-127- 08A	CEILING, MEN'S ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368590	
8	M - Joint Compound	NY7-127- 08B	WALL, BASEMENT, BREAK ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368591	
8	M - Joint Compound	NY7-127- 08C	WALL, BASEMENT, KITCHEN	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368592	
9	M - Ceiling Tiles and Lay-in Panels	NY7-127- 09A	ATM ROOM, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368593	
9	M - Ceiling Tiles and Lay-in Panels	NY7-127- 09B	ATM ROOM, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368594	
9	M - Ceiling Tiles and Lay-in Panels	NY7-127- 09C	ATM ROOM, NORTH	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368595	
10	M - Ceiling Tiles and Lay-in Panels	NY7-127- 10A	BASEMENT, BREAK ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368596	
10	M - Ceiling Tiles and Lay-in Panels	NY7-127- 10B	BASEMENT, BREAK ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368597	
10	M - Ceiling Tiles and Lay-in Panels	NY7-127- 10C	BASEMENT, KITCHEN	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368598	
11	M - Ceiling Tiles and Lay-in Panels	NY7-127- 11A	BASEMENT, STAIRWAY LANDING	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368599	
11	M - Ceiling Tiles and Lay-in Panels	NY7-127- 11B	BASEMENT, STAIRWAY LANDING	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368600	
11	M - Ceiling Tiles and Lay-in Panels	NY7-127- 11C	BASEMENT, STAIRWAY LANDING	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368601	
12	M - Ceiling Tiles and Lay-in Panels	NY7-127- 12A	MAIN LOBBY, EAST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368602	
12	M - Ceiling Tiles and Lay-in Panels	NY7-127- 12B	MAIN LOBBY, SOUTH WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368603	
12	M - Ceiling Tiles and Lay-in Panels	NY7-127- 12C	MAIN LOBBY, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368604	
13	M - Ceiling Tiles and Lay-in Panels	NY7-127- 13A	MAIN LOBBY, SOUTH WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368605	
13	M - Ceiling Tiles and Lay-in Panels	NY7-127- 13B	MAIN LOBBY, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368606	
13	M - Ceiling Tiles and Lay-in Panels	NY7-127- 13C	BACK ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368607	
14	M - Ceiling Tiles and Lay-in Panels	NY7-127- 14A	STORAGE #2, NORTH EAST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368608	

HA No.	Material Type	ld	Location	Content	Туре	Friable	Sample Date	Consultant	Method	Lab	Notes	PK	ModDate
14	M - Ceiling Tiles and Lay-in Panels	NY7-127- 14B	STORAGE #2, NORTH EAST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368609	
14	M - Ceiling Tiles and Lay-in Panels	NY7-127- 14C	STORAGE #2, SOUTH WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368610	
15	M - Ceiling Panel	NY7-127- 15A	JANITOR'S CLOSET	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368611	
15	M - Ceiling Panel	NY7-127- 15B	JANITOR'S CLOSET	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368612	
15	M - Ceiling Panel	NY7-127- 15C	JANITOR'S CLOSET	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368613	
16	M - Wall Paper	NY7-127- 16A	MAIN LOBBY, SOUTH EAST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368614	
16	M - Wall Paper	NY7-127- 16B	MAIN LOBBY, SOUTH WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368615	
16	M - Wall Paper	NY7-127- 16C	BACK ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368616	
17	M - Wall Paper	NY7-127- 17A	ATM ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368617	
17	M - Wall Paper	NY7-127- 17B	CONFERENCE ROOM	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368618	
17	M - Wall Paper	NY7-127- 17C	TELLER AREA	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368619	
18	M - Carpet Glue/Mastic	NY7-127- 18A	MAIN LOBBY, WEST	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365636	
18	M - Carpet Glue/Mastic	NY7-127- 18B	BACK ROOM, WEST	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365637	
18	M - Carpet Glue/Mastic	NY7-127- 18C	CONFERENCE ROOM, WEST	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365638	
19	M - Carpet Glue/Mastic	NY7-127- 19A	FRONT VESTIBULE, EAST	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366101	
19	M - Carpet Glue/Mastic	NY7-127- 19B	FRONT VESTIBULE, WEST	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366102	
19	M - Carpet Glue/Mastic	NY7-127- 19C	FRONT VESTIBULE, WEST	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366103	
20	M - Vinyl Floor Tile	NY7-127- 20A	ATM ROOM	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366104	
20	M - Vinyl Floor Tile	NY7-127- 20B	ATM ROOM	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366105	
20	M - Vinyl Floor Tile	NY7-127- 20C	ATM ROOM	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366106	

HA No.	Material Type	ld	Location	Content	Туре	Friable	Sample Date	Consultant	Method	Lab	Notes	РК	ModDate
21	M - Floor Tile Mastic	NY7-127- 21A	ATM ROOM	>1%-10%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365432	
21	M - Floor Tile Mastic	NY7-127- 21B	ATM ROOM	Pos Stop		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		369730	
21	M - Floor Tile Mastic	NY7-127- 21C	ATM ROOM	Pos Stop		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		369731	
22	M - Vinyl Floor Tile	NY7-127- 22B	SAFE DEPOSIT RM #1	Pos Stop		No	8/26/2010	ARCADIS	PLM NOB	EMSL		369722	
22	M - Vinyl Floor Tile	NY7-127- 22C	SAFE DEPOSIT RM #2	Pos Stop		No	8/26/2010	ARCADIS	PLM NOB	EMSL		369723	
22	M - Vinyl Floor Tile	NY7-127- 22A	ATM ROOM	>1%-10%	Chrysotile	No	8/26/2010	ARCADIS	PLM NOB	EMSL		365428	
23	M - Floor Tile Mastic	NY7-127- 23B	SAFE DEPOSIT RM #1	>1%-10%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365433	
23	M - Floor Tile Mastic	NY7-127- 23A	ATM ROOM	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365639	
23	M - Floor Tile Mastic	NY7-127- 23C	SAFE DEPOSIT RM #2	Pos Stop		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		369732	
24	M - Vinyl Floor Tile	NY7-127- 24C	BASEMENT, KITCHEN	Pos Stop		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		369733	
24	M - Vinyl Floor Tile	NY7-127- 24B	BASEMENT, BREAK ROOM	>1%-10%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365434	
24	M - Vinyl Floor Tile	NY7-127- 24A	TOP OF STAIRWAY TO BASEMENT	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366107	
25	M - Floor Tile Mastic	NY7-127- 25B	BASEMENT, BREAK ROOM	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366108	
25	M - Floor Tile Mastic	NY7-127- 25C	BASEMENT, KITCHEN	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366109	
25	M - Floor Tile Mastic	NY7-127- 25A	TOP OF STAIRWAY TO BASEMENT	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365640	
26	M - Vinyl Floor Tile	NY7-127- 26A	BASEMENT, BREAK ROOM	>1%-10%	Chrysotile	No	8/26/2010	ARCADIS	PLM NOB	EMSL		365429	
26	M - Vinyl Floor Tile	NY7-127- 26B	BASEMENT, BREAK ROOM	Pos Stop		No	8/26/2010	ARCADIS	PLM NOB	EMSL		369724	
26	M - Vinyl Floor Tile	NY7-127- 26C	BASEMENT, BREAK ROOM	Pos Stop		No	8/26/2010	ARCADIS	PLM NOB	EMSL		369725	
27	M - Floor Tile Mastic	NY7-127- 27A	BASEMENT, BREAK ROOM	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365641	
27	M - Floor Tile Mastic	NY7-127- 27B	BASEMENT, BREAK ROOM	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365642	

HA No.	Material Type	ld	Location	Content	Туре	Friable	Sample Date	Consultant	Method	Lab	Notes	PK	ModDate
27	M - Floor Tile Mastic	NY7-127- 27C	BASEMENT, BREAK ROOM	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365643	
28	M - Vinyl Floor Tile	NY7-127- 28A	BOILER ROOM	>1%-10%	Chrysotile	No	8/26/2010	ARCADIS	PLM NOB	EMSL		365430	
28	M - Vinyl Floor Tile	NY7-127- 28B	BOILER ROOM	Pos Stop		No	8/26/2010	ARCADIS	PLM NOB	EMSL		369726	
28	M - Vinyl Floor Tile	NY7-127- 28C	STORAGE ROOM #2	Pos Stop		No	8/26/2010	ARCADIS	PLM NOB	EMSL		369727	
29	M - Floor Tile Mastic	NY7-127- 29B	BOILER ROOM	Pos Stop		No	8/26/2010	ARCADIS	PLM NOB	EMSL		369728	
29	M - Floor Tile Mastic	NY7-127- 29C	STORAGE ROOM #2	Pos Stop		No	8/26/2010	ARCADIS	PLM NOB	EMSL		369729	
29	M - Floor Tile Mastic	NY7-127- 29A	BOILER ROOM	>1%-10%	Chrysotile	No	8/26/2010	ARCADIS	PLM NOB	EMSL		365431	
30	M - Vinyl Floor Tile	NY7-127- 30A	MAIN LOBBY, WEST	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365644	
30	M - Vinyl Floor Tile	NY7-127- 30B	MAIN LOBBY, SOUTH WEST	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365645	
30	M - Vinyl Floor Tile	NY7-127- 30C	SAFE DEPOSIT ROOM #2	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366110	
31	M - Floor Tile Mastic	NY7-127- 31A	MAIN LOBBY, WEST	0.1% to <1%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365646	
31	M - Floor Tile Mastic	NY7-127- 31B	MAIN LOBBY, SOUTH WEST	>1%-10%	Chrysotile	No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		365435	
31	M - Floor Tile Mastic	NY7-127- 31C	SAFE DEPOSIT ROOM #2	Pos Stop		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		369734	
32	M - Tile Grout	NY7-127- 32A	MAIN LOBBY, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368620	
32	M - Tile Grout	NY7-127- 32B	MAIN LOBBY, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368621	
32	M - Tile Grout	NY7-127- 32C	MAIN LOBBY, SOUTH WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368622	
33	M - Mortar	NY7-127- 33A	MAIN LOBBY, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368623	
33	M - Mortar	NY7-127- 33B	MAIN LOBBY, WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368624	
33	M - Mortar	NY7-127- 33C	MAIN LOBBY, SOUTH WEST	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368625	
34	M - Cove Base Mastic	NY7-127- 34A	ATM ROOM	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366111	

HA No.	Material Type	ld	Location	Content	Туре	Friable	Sample Date	Consultant	Method	Lab	Notes	РК	ModDate
34	M - Cove Base Mastic	NY7-127- 34B	ATM ROOM	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366112	
34	M - Cove Base Mastic	NY7-127- 34C	ATM ROOM	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366113	
35	M - Cove Base Mastic	NY7-127- 35A	MAIN LOBBY, SOUTH EAST	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366114	
35	M - Cove Base Mastic	NY7-127- 35B	MAIN LOBBY, SOUTH WEST	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366115	
35	M - Cove Base Mastic	NY7-127- 35C	CONFERENCE ROOM	ND		No	8/26/2010	ARCADIS	PLM/TEM NOB	EMSL		366116	
36	M - Ceramic Tile	NY7-127- 36A	MAIN LOBBY	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368626	
36	M - Ceramic Tile	NY7-127- 36B	MAIN LOBBY	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368627	
36	M - Ceramic Tile	NY7-127- 36C	MAIN LOBBY	ND		Yes	8/26/2010	ARCADIS	PLM	EMSL		368628	
37	M - Caulking/Putties	NY7-127- 01A	FLOOR 1 INTERIOR, NORTH LOBBY WINDOWS	ND		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
37	M - Caulking/Putties	NY7-127- 01B	FLOOR 1 INTERIOR, NORTH LOBBY WINDOWS	ND		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
37	M - Caulking/Putties	NY7-127- 01C	FLOOR 1 INTERIOR, NORTH LOBBY WINDOWS	ND		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
38	M - Exterior Window Glazing Compound	NY7-127- 02A	FLOOR 1 INTERIOR, WEST BSMT. STAIRWELL	>1%-10%	Blend	No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
38	M - Exterior Window Glazing Compound	NY7-127- 02B	FLOOR 1 INTERIOR, MENS RM	Pos Stop		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
38	M - Exterior Window Glazing Compound	NY7-127- 02C	FLOOR 1 INTERIOR, LADIES RM	Pos Stop		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
39	M - Caulking/Putties	NY7-127- 03A	EXT. EAST ELEVATION	ND		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
39	M - Caulking/Putties	NY7-127- 03B	EXT. NORTH ELEVATION	ND		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
39	M - Caulking/Putties	NY7-127- 03C	EXT. SOUTH ELEVATION	ND		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
40	M - Caulking/Putties	NY7-127- 04A	EXT. WEST ELEVATION MEN	ND		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
40	M - Caulking/Putties	NY7-127- 04B	EXT. WEST ELEVATION LADIES	ND		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
40	M - Caulking/Putties	NY7-127- 04C	EXT. WEST ELEVATION STAIRWELL	ND		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			

HA No.	Material Type	ld	Location	Content	Туре	Friable	Sample Date	Consultant	Method	Lab	Notes	PK	ModDate
41	M - Exterior Window Glazing Compound	NY7-127- 05A	EXT. WEST ELEVATION LADIES	0.1% to <1%	Anthophylite	No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
41	M - Exterior Window Glazing Compound	NY7-127- 05B	EXT. WEST ELEVATION LADIES	>1%-10%	Anthophylite	No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
41	M - Exterior Window Glazing Compound	NY7-127- 05C	EXT. WEST ELEVATION LADIES	Pos Stop		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
42	M - Exterior Window Glazing Compound	NY7-127- 06A	EXT. WEST ELEVATION MEN	>1%-10%	Chrysotile	No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
42	M - Exterior Window Glazing Compound	NY7-127- 06B	EXT. WEST ELEVATION LADIES	Pos Stop		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
42	M - Exterior Window Glazing Compound	NY7-127- 06C	EXT. WEST ELEVATION LADIES	Pos Stop		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
43	M - Exterior Window Glazing Compound	NY7-127- 07A	EXT. WEST ELEVATION STAIRWELL	>1%-10%	Blend	No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
43	M - Exterior Window Glazing Compound	NY7-127- 07B	EXT. WEST ELEVATION STAIRWELL	Pos Stop		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
43	M - Exterior Window Glazing Compound	NY7-127- 07C	EXT. WEST ELEVATION STAIRWELL	Pos Stop		No	4/27/2011	ARCADIS	PLM/TEM NOB	EMSL			
44	M - Caulking/Putties	NY7-127- 08A	EXT. WEST ELEVATION LADIES	>1%-10%	Chrysotile	No	4/27/2011	ARCADIS	PLM NOB	EMSL			
44	M - Caulking/Putties	NY7-127- 08B	EXT. WEST ELEVATION MEN'S	Pos Stop		No	4/27/2011	ARCADIS	PLM NOB	EMSL			
44	M - Caulking/Putties	NY7-127- 08C	EXT. WEST ELEVATION STAIRWELL	Pos Stop		No	4/27/2011	ARCADIS	PLM NOB	EMSL			

HA Table Values and Instructions

Overwrite: If you choose "yes" to overwrite the existing HAT, all of the current HAT data for the site will be lost. Any ACM data from prior surveys that needs to be kept must be included in this HAT file if you choose "yes". If you are simply adding to the existing data in IDEA, then choose "no" on the overwrite.

Location of Homogenous Location
Floor Rooms Location
Use "," with no space Free text
between values and
"..." with no spaces
between ranges of
values.

Koof
Multiple
Shaftways
Other

- Only one homogenous application number (HA No.) can be used for each application. Multiple entries for the same HA must use the same HA number.
 When available, predetermined values in the drop down menu must be used. These values cannot be changed by the user.
 When an inspector determines that a material is non-ACM, this should be indicated by selecting the "non-ACM" listing in the "NESHAP Cat. Column. In this case, the "Quantity" information is not required.
 A listing of the preset values for the tables is provided below.

IN NESHAP Cat.
Friable RACM
CAT 1 Non-friable RACM
CAT 2 Non-friable RACM
Non-ACM, Sampled
ACCM
Non-Suspect ACM, Not Sampled
Suspect ACM, Not Sampled

		Material Des			
A No	Material Type M - Acoustic Wall Panel	Aqua	lor Texture Fissured	Description Free Text	n F
	M - Asphalt Floor Tile	Beige	Grooved	FIEB TEXT	C
3	M - Asphalt Roof Shingle	Black	Rough		C
4	M - Asphalt Shingle Siding M - Base Flashing	Blue	Smooth Not Applicable		N A
	M - Batt Insulation, Wall or Ceiling w/ Tar Cover	Clear	Not Visible	1	N
7	M - Blown-in Insulation	Gold			S
8	M - Built-up Roofing M - Carpet Glue/Mastic	Gray Green			
10	M - Caulking/Putties	Orange			
11	M - Ceiling Panel	Pink			
12	M - Ceiling Tiles and Lay-in Panels M - Ceiling Tile, 12" - Spline or Glue Set	Purple Red			
14	M - Ceiling Tile Glue	Tan			
	M - Cement Pipes	White			
	M - Cement Siding M - Cement Wallboard	Yellow Not Visible			
18	M - Cementitious Roof Shingle	1	I		
	M - Ceramic Tile				
	M - Chalkboards M - Chimney Flashing				
22	M - Construction Mastics				
23	M - Cooling Towers				
	M - Cooling Tower Louvers/Panels M - Cove Base				
26	M - Cove Base Mastic				
27	M - Duct Mastic M - Electrical Cloth				
	M - Electrical Panel Partitions				
30	M - Electrical Wiring Insulation				
31 32	M - Elevator Brake Shoes M - Elevator Equipment Panels				
	M - Exterior Door Caulk				
	M - Exterior Façade Seam Caulk/Sealant				
35 36	M - Exterior Window Caulk M - Exterior Window Glazing Compound				
37	M - Exterior Stucco				
	M - Fire Brick M - Fire Blankets				
	M - Fire Bankets M - Fire Curtains				
41	M - Fire Doors				
	M - Fireproofing Materials M - Fire Stop Penetration Sealant				
44	M - Floor Backing				
	M - Floor Tile Mastic				
	M - Gypsum Board w/ Joint Compound M - Gypsum Board				
48	M - Heating and Electrical Ducts				
	M - HVAC Unit Caulk				
	M - Joint Compound M - Laboratory Gloves				
52	M - Laboratory Hoods/Table Tops				
53	M - Mastic Coating on Surface				
55	M - Mortar M - Packing Materials (Wall/Floor Penetrations)				
56	M - Pitch Pocket Mastic				
57	M - Rolled Asphalt Roofing M - Roof Caulk				
	M - Roof Decking				
60	M - Roof Expansion Joint Flashing				
61	M - Roofing Felt Paper M - Roof Flashing				
63	M - Roof Insulation				
64	M - Roofing Shingles M - Rubber Roof Membrane				
	M - Rubber Roof Membrane Mastic/Sealant				
67	M - Sidewalk Caulk				
68	M - Sink Undercoating M - Slate Roof Shingle Mastic				
70	M - Spackling Compounds				
71	M - Tile Grout				
72	M - Transite Panels M - Transite Siding				
74	M - Underlayment				
75	M - Vapor Barrier				
77	M - Vinyl Floor Tile M - Vinyl Sheet Flooring				
78	M - Vinyl Wall Compounds				
79	M - Wall Paper M - Wall Paper Glue				
81	M - Wall Paper Mastic				
82	M - Waterproofing Felt				
83 84	M - Waterproofing Mastic S - Acoustical Plaster				
85	S - Ceiling Plaster				
	S - Ceiling Plaster White Coat S - Ceiling Plaster Brown Coat				
88	S - Ceiling Texture				
89	S - Decorative Plaster				
90	S - Exterior Plaster S - Fireproofing				
92	S - Interior Stucco				
93					
	S - Spray-Applied Insulation S - Textured Paints/Coatings				
96	S - Wall Plaster				
97	S - Wall Plaster White Coat S - Wall Plaster Brown Coat				
	S - Wall Plaster Brown Coat T - Boiler Insulation				
100	T - Breaching Insulation				
101	T - Ductwork Flexible Fabric Connections				
102	T - Exterior Pipe Insulation T - Exterior Duct Insulation				
104	T - High Temperature Gaskets				
105	T - HVAC Duct Insulation				
	T - Insulation - Misc. T - Mastic Coating on Thermal Pipe Jacket Cover				
100					
107 108	T - Pipe Insulation (Corrugated Air-Cell, Block, etc.))			
107 108 109)			

ENTRY - Fac Info Values

Status Modified Description Id Location Content Type Friable Sample Date Consultant Method Lab Notes Stdd/mm/yyyy Free Text Free Text Free Text Free Text Postop Chrysotile O.1% Location Co.1% Location

Survey Type	Overwrite Existing HAT
Complete Interior Survey	Yes
Retail Only Interior Survey	No
Partial Interior Survey	
Path of Construction	

Attachment C

Laboratory Data Package and Chain of Custody

Fax:

Customer ID: ACAD78J Customer PO: 20208

Received: 04/29/11 9:15 AM

EMSL Order:

EMSL Proj:

041110465

Test Report: Asbestos Analysis of Bulk Material

Phone: (781) 356-7300

Project: ARCADIS; BANK OF AMERICA; NY7-127; 2700 MAIN STREET, NEWFANE, NY- JOHN LUXFORD/ NANCY KATZ

		Analyzed		Non Asb	estos		
Sample Description	Test	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comments
NY7-127-01A	PLM NYS 198.1 Friable						Not Analyzed
041110465-0001	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive: None Detected	
FLOOR 1 INTERIOR, NORTH LOBBY WINDOWS - GREY WINDOW CAULK	TEM NYS 198.4 NOB	5/3/2011	Gray		N/A	None Detected	
NY7-127-01B	PLM NYS 198.1 Friable						Not Analyzed
041110465-0002	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive: None Detected	
FLOOR 1 INTERIOR, NORTH LOBBY WINDOWS - GREY WINDOW CAULK	TEM NYS 198.4 NOB	5/3/2011	Gray		N/A	None Detected	
NY7-127-01C	PLM NYS 198.1 Friable						Not Analyzed
041110465-0003	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive: None Detected	
FLOOR 1 INTERIOR, NORTH LOBBY WINDOWS - GREY WINDOW CAULK	TEM NYS 198.4 NOB	5/3/2011	Gray		N/A	None Detected	
NY7-127-02A	PLM NYS 198.1 Friable						Not Analyzed
041110465-0004	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive : <1% Anthophyllite <1% Total	
FLOOR 1 INTERIOR, WEST BSMT. STAIRWELL - GREY WINDOW GLAZING	TEM NYS 198.4 NOB	5/3/2011	Gray		N/A	<1% Anthophyllite 9.2% Chrysotile 9.2% Total	
NY7-127-02B	PLM NYS 198.1 Friable						Not Analyzed
041110465-0005	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive : <1% Anthophyllite <1% Total	
FLOOR 1 INTERIOR, MENS RM - GREY WINDOW GLAZING	TEM NYS 198.4 NOB	5/3/2011			N/A	Positive Stop (Not Analyzed)	
NY7-127-02C	PLM NYS 198.1 Friable						Not Analyzed
041110465-0006	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive : <1% Anthophyllite <1% Total	
FLOOR 1 INTERIOR, LADIES RM - GREY WINDOW GLAZING	TEM NYS 198.4 NOB	5/3/2011			N/A	Positive Stop (Not Analyzed)	

Initial Report From 05/04/2011 16:12:43

Fax:

Customer ID: ACAD78J Customer PO: 20208

Received: 04/29/11 9:15 AM 041110465

EMSL Order:

EMSL Proj:

Test Report: Asbestos Analysis of Bulk Material

Phone: (781) 356-7300

Project: ARCADIS; BANK OF AMERICA; NY7-127; 2700 MAIN STREET, NEWFANE, NY-JOHN LUXFORD/ NANCY KATZ

		Analyzed		Non As	bestos		
Sample Description	Test	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comments
IY7-127-03A	PLM NYS 198.1 Friable						Not Analyzed
41110465-0007	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive: None Detected	
EXT. EAST ELEVATION - GREY VINDOW CAULK	TEM NYS 198.4 NOB	5/3/2011	Gray		N/A	None Detected	
IY7-127-03B	PLM NYS 198.1 Friable						Not Analyzed
41110465-0008	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive: None Detected	
XT. NORTH ELEVATION - GREY /INDOW CAULK	TEM NYS 198.4 NOB	5/3/2011	Gray		N/A	None Detected	
IY7-127-03C	PLM NYS 198.1 Friable						Not Analyzed
41110465-0009	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive: None Detected	
XT. SOUTH ELEVATION - GREY VINDOW CAULK	TEM NYS 198.4 NOB	5/3/2011	Gray		N/A	None Detected	
IY7-127-04A	PLM NYS 198.1 Friable						Not Analyzed
41110465-0010	PLM NYS 198.6 NOB	5/2/2011	White		N/A	Inconclusive: None Detected	
XT. WEST ELEVATION MEN - WHITE REPAIR CAULK	TEM NYS 198.4 NOB	5/3/2011	White		N/A	None Detected	
Y7-127-04B	PLM NYS 198.1 Friable						Not Analyzed
41110465-0011	PLM NYS 198.6 NOB	5/2/2011	White		N/A	Inconclusive: None Detected	
XT. WEST ELEVATION LADIES - VHITE REPAIR CAULK	TEM NYS 198.4 NOB	5/3/2011	White		N/A	None Detected	
Y7-127-04C	PLM NYS 198.1 Friable						Not Analyzed
41110465-0012	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive: None Detected	
XT. WEST ELEVATION STAIRWELL - VHITE REPAIR CAULK	TEM NYS 198.4 NOB	5/3/2011	Gray		N/A	None Detected	
Y7-127-05A	PLM NYS 198.1 Friable						Not Analyzed
41110465-0013	PLM NYS 198.6 NOB	5/2/2011	White		N/A	Inconclusive: None Detected	
EXT. WEST ELEVATION LADIES - VHITE REPAIR GLAZING	TEM NYS 198.4 NOB	5/4/2011	White		N/A	<1% Anthophyllite <1% Total	

Fax:

Customer ID: ACAD78J Customer PO: 20208

Received: 04/29/11 9:15 AM

EMSL Order:

EMSL Proj:

041110465

Test Report: Asbestos Analysis of Bulk Material

Phone: (781) 356-7300

Project: ARCADIS; BANK OF AMERICA; NY7-127; 2700 MAIN STREET, NEWFANE, NY-JOHN LUXFORD/ NANCY KATZ

		Analyzed		Non Ash	oestos		
Sample Description	Test	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comments
NY7-127-05B	PLM NYS 198.1 Friable						Not Analyzed
041110465-0014	PLM NYS 198.6 NOB	5/2/2011	White		N/A	Inconclusive: None Detected	
EXT. WEST ELEVATION LADIES -	TEM NYS 198.4 NOB	5/4/2011	White		N/A	3.3% Anthophyllite	
WHITE REPAIR GLAZING						3.3% Total	
NY7-127-05C	PLM NYS 198.1 Friable						Not Analyzed
041110465-0015	PLM NYS 198.6 NOB	5/2/2011	White		N/A	Inconclusive: None Detected	
EXT. WEST ELEVATION LADIES - WHITE REPAIR GLAZING	TEM NYS 198.4 NOB	5/4/2011			N/A	Positive Stop (Not Analyzed)	
NY7-127-06A	PLM NYS 198.1 Friable						Not Analyzed
041110465-0016	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive : <1% Chrysotile	Suggest TEM
						<1% Total	
EXT. WEST ELEVATION MEN - GREY WINDOW GLAZING	TEM NYS 198.4 NOB	5/4/2011	Gray		N/A	8.3% Chrysotile	
						8.3% Total	
NY7-127-06B	PLM NYS 198.1 Friable						Not Analyzed
041110465-0017	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive : <1% Chrysotile <1% Total	Suggest TEM
EXT. WEST ELEVATION LADIES - GREY WINDOW GLAZING	TEM NYS 198.4 NOB	5/4/2011			N/A	Positive Stop (Not Analyzed)	
NY7-127-06C	PLM NYS 198.1 Friable						Not Analyzed
041110465-0018	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	Inconclusive : <1% Chrysotile	Suggest TEM
						<1% Total	
EXT. WEST ELEVATION LADIES - GREY WINDOW GLAZING	TEM NYS 198.4 NOB	5/4/2011			N/A	Positive Stop (Not Analyzed)	
NY7-127-07A	PLM NYS 198.1 Friable						Not Analyzed
041110465-0019	PLM NYS 198.6 NOB	5/2/2011	Cream		N/A	Inconclusive : <1% Anthophyllite <1% Total	Suggest TEM
EXT. WEST ELEVATION STAIRWELL - IVORY WINDOW GLAZING	TEM NYS 198.4 NOB	5/4/2011	Cream		N/A	<1% Anthophyllite 9.3% Chrysotile	
						9.3% Total	

Initial Report From 05/04/2011 16:12:43

Customer ID: ACAD78J Customer PO: 20208

Received: 04/29/11 9:15 AM

EMSL Order:

041110465

Fax:

Phone: (781) 356-7300

EMSL Proj:

Test Report: Asbestos Analysis of Bulk Material

Project: ARCADIS; BANK OF AMERICA; NY7-127; 2700 MAIN STREET, NEWFANE, NY- JOHN LUXFORD/ NANCY KATZ

		Analyzed		Non Asl	bestos		
Sample Description	Test	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comments
NY7-127-07B	PLM NYS 198.1 Friable						Not Analyzed
041110465-0020	PLM NYS 198.6 NOB	5/2/2011	Cream		N/A	Inconclusive : <1% Anthophyllite <1% Total	Suggest TEM
EXT. WEST ELEVATION STAIRWELL - IVORY WINDOW GLAZING	TEM NYS 198.4 NOB	5/4/2011			N/A	Positive Stop (Not Analyzed)	
NY7-127-07C	PLM NYS 198.1 Friable						Not Analyzed
041110465-0021	PLM NYS 198.6 NOB	5/2/2011	Cream		N/A	Inconclusive : <1% Anthophyllite <1% Total	Suggest TEM
EXT. WEST ELEVATION STAIRWELL - IVORY WINDOW GLAZING	TEM NYS 198.4 NOB	5/4/2011			N/A	Positive Stop (Not Analyzed)	
NY7-127-08A	PLM NYS 198.1 Friable						Not Analyzed
041110465-0022	PLM NYS 198.6 NOB	5/2/2011	Gray		N/A	1.4% Chrysotile 1.4% Total	
EXT. WEST ELEVATION LADIES - GREY WINDOW CAULK	TEM NYS 198.4 NOB				N/A		Not Analyzed
NY7-127-08B	PLM NYS 198.1 Friable						Not Analyzed
041110465-0023	PLM NYS 198.6 NOB	5/2/2011			N/A	Positive Stop (Not Analyzed)	
EXT. WEST ELEVATION MEN'S - GREY WINDOW CAULK	TEM NYS 198.4 NOB				N/A		Not Analyzed
NY7-127-08C	PLM NYS 198.1 Friable						Not Analyzed
041110465-0024	PLM NYS 198.6 NOB	5/2/2011			N/A	Positive Stop (Not Analyzed)	
EXT. WEST ELEVATION STAIRWELL - GREY WINDOW CAULK	TEM NYS 198.4 NOB				N/A	,	Not Analyzed

Customer ID: Customer PO:

ACAD78J 20208

Received: 04/29/11 9:15 AM 041110465

EMSL Order:

Fax:

Phone: (781) 356-7300

EMSL Proj:

Test Report: Asbestos Analysis of Bulk Material

ARCADIS; BANK OF AMERICA; NY7-127; 2700 MAIN Project: STREET, NEWFANE, NY- JOHN LUXFORD/ NANCY KATZ

Non Asbestos

Analyzed Sample Description Test Color Non-Fibrous **Asbestos** Date **Fibrous** Comments NOB = Non Friable Organically Bound N/A = Not Applicable

Analyst(s)

Chris Little Debbie Little Stephen Siegel, CIH, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The results in this report meet all requirements of the NELAC Standards unless otherwise noted. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB's. Quantitative TEM is currently the only method that can be used to determine if a NOB material can be considered or treated as non-asbestos containing.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NYS ELAP 10872



041110465

860 Hooper Road, Endwell, NY 13760 Tel: 607.231.6600 Fax 607.231.6640 www.deltaengineers.com

Bulk Sample Data Sheet

Client: Arcadis	Delta Project No.:	2010.153.080	Date: 4/27/11	
Project: 2700 Main Street, Newfane, NY Bank of America Site - POC Asbestos Survey		BOA Bldg Mail Code NY7-127	Turnaround Time: 24 Hour	

Sample Numbe		PLM NOB	Material Type	Material Condition	Floor	Description / Sample Location
NY7-127-	01A		Misc	6000		Grey window Coulk- laterior Notobby windows
NY7-127-	01B			1	1	
NY7-127-	01C		d	1		
NY7-127-	02A		Misc	Gouss	1	Grey window GLAZING - Interior - WEST BSMT. STAINE
NY7-127-	02B			1	1	1 1 - 1 1 Men's Rm
NY7-127-	02C				1	LAMES Ru
NY7-127-	03A	1 2	MISC	6000	EXT	Grey win sow laulk - No EAST ELEVATION
NY7-127-	03B	37		1	Exr	North Elevation
NY7-127-	03C		J	J	EXT	I South ELEVATION

Analyze all non-NOB samples by NYS ELAP 198.1 PLM methodology. Analyze all NOB samples initially by NYS ELAP 198.6 PLM methodology. If all samples from a given sample set are reported as non-asbestos by 198.6, analyze by NYS ELAP 198.4 TEM methodology. Stop analysis after 1st positive for a given sample set. Email results to John Luxford (john.luxford@arcadisus.com) and Nancy Katz (nancy.katz@arcadis-us.com).

Notes: Invoice A	Arcadis directly for all Analytical Serv	rices		
Submitted By:	Tom As HMAN	1 Aer	Date:	4/27/11
Received By:	Jason Rufficton	(Signature)	Date:	MEGO GIS AM
	(Printed)	(Signature)	s ⁹²	100
		Page 1 of 2		



041110465

860 Hooper Road, Endwell, NY 13760 Tel: 607.231.6600 Fax 607.231.6640 www.deltaengineers.com


Bulk Sample Data Sheet

Client: Arcadis	Delta Project No.:	<u>2010.153.080</u>	Date: 4/27/11
Project: 2700 Main Street, Newfane, , NY Bank of America Site - POC Asbestos Survey	Client Project No.: Collected By: Tom	BOA Bldg Mail Code NY7-127	Turnaround Time: 24 Hour

Sample Number		PLM	NOB	Material Type	Material Condition	Floor	Description / Sample Location
NY7-127-	04A			MISE	6000	Ext	WHITE REPAIR Caulk - WEST ELEVATION MEN
NY7-127-	04B				1		LADIES
NY7-127-	04C						L L STANWEI
NY7-127-	05A						WHITE REPAIR GLAZING -WEST ELEVATION - LAIM
NY7-127-	05B						
NY7-127-	05C						
NY7-127-	06A						Grey window GLASSING - WEST ELEVA from MEN
NY7-127-	06B						LAINES
NY7-127- (06C						L L L LADIES
NY7-127-	07A						Tury winnow GLAZ-y-WEST ELEVATION- STAINNEY
NY7-127-	07B						- WEST ELEVATION
NY7-127- (07C				12		
NY7-127- (08A						Grey WINDOW Caulle- WEST Elevation-BADIE.
NY7-127- (08B						Men's
NY7-127- (08C			1	V	1	1 1 1 5TAINE
NY7-127- (09A						
NY7-127- 0	09B						NECEN
NY7-127- 0	9C				- 34 - j		
NY7-127- 1	10A						

Attachment **D**

Floor Plans



Attachment **E**

Photographs



BANK OF AMERICA NY7-127 PHOTO LOG



Attachment **F**

Limitations and Service Constraints

LIMITATIONS AND SERVICE CONSTRAINTS Asbestos Related Services

All professional opinions presented in this report are based on information made available to us either by review of data provided by others or data gathered by ARCADIS personnel.

ARCADIS affirms that data gathered and presented by ARCADIS in this report was collected in an appropriate manner in accordance with generally accepted methods and practices. ARCADIS cannot be responsible for decisions made by our client solely on the basis of economic factors.

Conditions described in this report are as found at the time of investigation, unless otherwise stated.

ARCADIS analyzed only the substances, conditions and locations described in the report at the time indicated. No inferences regarding other substances, conditions, location or time can be made unless specifically stated in this report.

No recommendations were provided for materials containing less than one- percent asbestos. Materials containing less than one percent asbestos do not meet either the generally accepted industry definition of asbestos-containing material (any material containing greater than one percent asbestos) or the EPA definition of friable ACM (any material friable bulk insulation material contain greater than one percent asbestos by weight as analyzed by Polarized Light Microscopy.) ARCADIS, however, makes no statement, implied or explicit, about the hazards of materials containing less than one percent asbestos.

This report is intended for the use listed in the section of this report described as the Introduction. The use of this report in any manner other than that listed in the Introduction requires the written consent of ARCADIS. This report must be presented in its entirety.