

Prepared For:

Jamail Larkins
Ascension Air Management
2007 FlightWay Drive
Atlanta, GA 30341
USA

678-468-1756

wsmith@ascensionaircraft.com

N928CS
Airframe Serial Number 0636
Engine Serial Number 1009113
Propeller Serial number NJ803B

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
77-12-06 R2	Prop blade	11/21/14 @ 529.8	N/A Superseded by 2002-09-08		X		Wayne Smith 2289662
89-22-05	Propeller hub failure	11/21/14 @ 529.8	N/A Superseded by 93-16-14		X		Wayne Smith 2289662
93-16-14	Prop hub cracks	11/21/14 @ 529.8	N/A Superseded by 94-17-13		X		Wayne Smith 2289662
94-17-13	Prop hub failure	11/21/14 @ 529.8	N/A By engine model or serial number		X		Wayne Smith 2289662
2001-07-03	CORRECTION - Prevent propeller failure of the propellers returned to service by BASCO	11/21/14 @ 529.8	N/A	X			Wayne Smith 2289662
2002-09-08	Prevent failure of the propeller blade from fatigue cracks	11/21/14 @ 529.8	N/A Superseded by 2007-26-09	X			Wayne Smith 2289662
2005-14-11	Prevent blade failure that could result in separation of a propeller blade	11/21/14 @ 529.8	N/A	X			Wayne Smith 2289662
2007-26-09	To prevent failure of the propeller blade from fatigue cracks in the blade shank radius	11/21/14 @ 529.8	N/A	X			Wayne Smith 2289662
2008-13-28	To prevent failure of the propeller hub	11/21/14 @ 529.8	N/A - not installed		X		Wayne Smith 2289662
2011-25-51	To address fractures in starter adapter shaft gears	11/21/14 @ 529.8	N/A Superseded by 2012-10-13	X			Wayne Smith 2289662
2012-01-11	To require inspection and modification of the air box flange welds and slots and installation of induction system air box seals	11/21/14 @ 529.8	N/A by S/N		X		Wayne Smith 2289662
2012-03-06	To prevent an in-flight shutdown due to a failed fuel servo diaphragm	11/21/14 @ 529.8	N/A - not installed		X		Wayne Smith 2289662
2012-10-13	To prevent starter adapter gear shaft failure	11/21/14 @ 529.8	N/A - not installed		X		Wayne Smith 2289662