


#1474 HARSHFIELD


Drainage Tile



- Installed before 2006
- Installed in 2006
- Installed in 2007
- Installed in 2008

$\{ 92^{\circ} 18.165' W$
 $\{ 43^{\circ} 21.605' N$





Customer: Rex Larson

Location:

Scale: 350 feet

Spacing: 70 FT

Date: 11-01-2008


Iowa Drainage

4 in: 37692 ft

5 in: 941 ft


Rex Larson2.gps

North



Customer: Rex Larson


27000 F.



NAME Betty Horshfield Farm
South of Davis Corners
 Section _____ Township _____ County Howard
 Contractor Four Drainage Date installed Oct. 06
 Amount of tile installed 5" 2,240 6" 1,470-4"
 10" _____ 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

IOWA DRAINAGE, INC. SHEFFIELD, IOWA 50475
Jim Blood — Telephone 641-892-4330




NAME 1474 Harsh Field Family Trust
 Section 30 Township Howard Center County Howard
 Contractor Iowa Drainage Date installed Nov. 87

Amount of tile installed 5" 1,255 6" 16,560 4" 4
 43° 21.696 10" _____ 12" _____ Larger _____
 92° 17.978

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

IOWA DRAINAGE, INC. SHEFFIELD, IOWA 50475
 Jim Blood — Telephone 641-892-4330



NAME RE #1474 Harshfield South of Davis Corners
 Section _____ Township _____ County _____
 (Rex Larson Tenant)

Contractor Iowa Drainage Date installed Fall 06

Amount of tile installed 5" _____ 6" _____ 8" _____
 10" _____ 12" _____ Larger _____


Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

IOWA DRAINAGE, INC. SHEFFIELD, IOWA 50475
Jim Blood — Telephone 515-892-4330

Fall 2006 N↑

#1474 Horsfield tile

Hwy 9



$\left\{ \begin{array}{l} N 43^{\circ} 21.964 \\ W 92^{\circ} 18.161 \end{array} \right\}$


where tile

intersects main waterway
waterway

$\left\{ \begin{array}{l} N 43^{\circ} 21.898 \\ W 92^{\circ} 17.998 \end{array} \right\}$

$\left\{ \begin{array}{l} N 43^{\circ} 21.958 \\ W 92^{\circ} 18.156 \end{array} \right\}$

where tile intersects N 43° 21.958 - S 46° 14' 48" W



NAME RE #1474 Harshfield South of Davis Corners

Section _____ Township _____ County _____

Contractor Iowa Drainage Date installed Fall 99

Amount of tile installed 5" _____ 6" _____ 8" _____

10" _____ 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

IOWA DRAINAGE, INC. SHEFFIELD, IOWA 50475
Jim Blood — Telephone 515-892-4330