

609 INNOVATON DRIVE CHESAPEAKE VIRGINIA 23320 (757) 436-3333

MOLD & MILDEW DISCLAIMER

This report is not a comprehensive moisture report regarding the entire structure and applies only to wood decay fungi (white rot, brown rot and dry rot) and moisture conditions conducive to the growth of wood decay fungi limited to the area below the first main floor. This property was not inspected for the presence or absence of health related molds or fungi. The inspector performing this inspection is not qualified authorized nor licensed to inspect for health related molds and/or fungi. Should information regarding the presence or absence of health related molds or fungi be desired an Industrial Hygienist or health related mold professional should be contacted. Therefore this report should not be relied upon in lieu of a complete physical inspection of the entire premises by interested parties or persons.

SELLER	DATE
BUYER	DATE

BOTH PARTIES ARE TO SIGN ABOVE AT TIME OF CLOSING

WOOD DESTROYING ORGANISM ATTACHMENT TO THE WOOD DESTROYING INSECT INFESTATION REPORT (NPMA-33)

This is not a structural damage report. NPMA-33 must accompany this report and this report must be listed in Section V of NPMA-33.

SECTION I. General Information

Inspection Address: 8978 RIVER CRESCENT, SUFFOR	K, VA 23433
HANDTON POADS TERMITE & PEST CIRL	Inspector: Inspector
Co. Address: 609 INNOVATION DRIVE, CHESAPEAKE, VA 23320	Co. Phone No.: 757-436-3333
SECTION II. Inspection	Findings
This report is indicative of the condition of the subject structure(s) ON THE DATI express or implied warranty or guarantee against latent, concealed, or future defuture treatment or inspections may be provided as a separate attachment and of the Wood Destroying Insect Infestation Inspection Report for important information.	only if indicated in Section V. See page 2 on the reverse side nation.
Based on a careful visual inspection of the readily accessible areas of the crawl s	space or basement of the structure(s) inspected:
X A. NO VISIBLE EVIDENCE OF WOOD DESTROYING FUNGI WAS OBSERVED.	
B. VISIBLE EVIDENCE OF WOOD DESTROYING FUNGI WAS OBSERVED AS F	OLLOWS:
Fungi observed (description and location):	
Any Fungi observed appears:	
Damage from wood destroying fungi was noted in the following area(s): NO DAMAGE IN ACCORDANCE WITH REIN CONTRACT	VISIBLE SUB STRUCTURAL MOISTURE
Regarding visible evidence of wood destroying fungi: The inspector may find woo should be considered only as evidence of current or previous activity of wood destroying the inspector of the properties of DAMAGE, INCLUDING HIDDEN DAMAGE, not qualify the inspector in damage evaluation or any other building construction the Seller or the Seller's AGENT SHALL NOTIFY THE BUYER THAT ANY DAM TO DETERMINE THE NEED FOR REPAIR.	MAY BE PRESENT. The inspector's training and experience do technology and/or repair, UPON RECEIPT OF THIS REPORT,
There is evidence of the presence of excessive moisture conditions in untreat	ed wood as follows:
Signature of Inspector. Neither I nor the company for which I am acting have the property. I do further state that neither I nor the company for which I am actransaction.	had, presently have, or contemplate having any interest in ting is associated in any way with any party to this
Limothy & Wym 73334C	02/15/2018
Signature of Inspector Certification or Registr	ation No. (if applicable) Date of Inspection
SECTION VIII. STATEMENT OF BU' THIS REPORT MUST BE SIGNED BY THE BUYER	
This report is integral to, and a necessary part of the inspecting company's full di	sclosure as to the scope and inherent limitations of the
inspection and report of findings. It is most important that the interested parties known property history information regarding wood destroying fungi, damage fro buyer. A legible copy of this page must be returned to the inspecting company by	m fungi, and treatment history has been disclosed to the
SIGNATURE OF SELLER(S) or OWNER (if refinancing)	DATE
The undersigned hereby acknowledge receipt of a copy of this report:	
SIGNATURE OF BUYER(S)	DATE

Wood Destroying Insect Inspection Report Notice: Please read important consumer information on page 2.					
Section I. General Information			Date of Inspection		
Inspection Company, Address & Phone	91000240		02/15/18		
HAMPTON ROADS TERMITE & PEST CTRL	Address of Property Inspe	ected			
609 INNOVATION DRIVE CHESAPEAKE, VA 23320	CHARLOT	TE SCOTT TO			
757-436-3333	8978 RIVE SUFFOLK,	R CRESCEN VA 23433	r		
	OOT OEA,	77120.00			
Inspector's Name, Signature & Certification, Registration, or Lic. #		Structure(s) Ir	nspected		
11/11	334-C HOUSE WI		ITH GARAGE		
THOUGHT WING					
Section II. Inspection Findings This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or defects. Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:					
A. No visible evidence of wood destroying insects was observed.					
B. Visible evidence of wood destroying insects was observed as follows:					
1. Live insects (description and location):					
2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location):					
3. Visible damage from wood destroying insects was noted as follows (description and location):					
NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs.					
	nove has a provincesty trac	tod Vicible e	vidence of nossible previous treatment		
Yes No trappears that the structure(s) or a portion thereof may	have been previously tree	aleu. Visibie e	vidence of possible previous reasonant.		
The inspecting company can give no assurances with regard to work done by other companies. The company that performed the treatment should be contacted for information on treatment and any warranty or service agreement which may be in place.					
Section III. Recommendations					
No treatment recommended: (Explain if Box B in Section II is checked)					
Recommend treatment for the control of:					
Section IV. Obstructions and Inaccessible Areas					
The following areas of the structure(s) inspected were obstructed or inaccessible:			The inspector may write out obstructions or use the following optional key:		
Basement			1. Fixed ceiling 13. Only visual access		
X Crawlspace 5 13 24			2. Suspended ceiling 14. Cluttered condition 15. Standing water		
X Main Level 134678913			Floor covering 16. Dense vegetation		
X Attic 11 21			5. Insulation 17. Exterior siding 5. Cabinets or shelving 18. Window well covers		
X Garage 134676913 19 Wood bile					
X Exterior 13 16 17			R. Furnishings 20. Snow		
Porch			3. Appliances 21. Unsafe conditions 10. No access or entry 22. Rigid foam board		
☐ Other ————————————————————————————————————			It Limited access 23 Synthetic stucco		
	her				
Section V. Additional Comments and Attachments (these are an integral part of the report)					
MOISTINE REPORT AND					
Attachments MOISTURE REPORT AND MOLD DISCLAIMER					
Signature of Seller(s) or Owner(s) if refinancing. Seller acknowledges that all information regarding W.D.I. infestation, damage, repair, and treatment history has been disclosed to the buyer.	Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.				
X	_	v			

Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. About the Inspection: A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reintesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms. This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- 2. Treatment Recommendation Guidelines Regarding Subterranean Termites: FHA and VA require treatment when any active infestation of subterranean termites is found. If signs of subterranean termites but no activity are found in a structure that shows no evidence of having been treated for subterranean termites in the past, then a treatment should be recommended. A treatment may also be recommended for a previously treated structure showing evidence of subterranean termites but no activity if there is no documentation of a liquid treatment by a licensed pest control company within the previous five years unless the structure is presently under warranty or covered by a service agreement with a licensed pest control company.
- 3. Obstructions and Inaccessible Areas: No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.