HAMPTON ROADS TERMITE & PEST CTRL 609 INNOVATION DRIVE CHESAPEAKE, VA 23320 757-436-3333

Service Slip/Invoice

INVOICE:	449397
DATE:	8/3/2021
ORDER:	449397

Bill To: [100280] ALPERIN LAW 500 VIKING DRIVE SUITE 202 VIRGINIA BEACH, VA 23452

Work Location: [175135] RICHARDSON TO BUYER 225 CHEYENNE ROAD VIRGINIA BEACH, VA 23462

Work Date	Time	Target Pest	Technicia	n l		Time In
8/3/2021			TAD		TREVOR DENNIS	
Purcha	ase Order	Terms	Last Service	Map C		Time Out
		NET 30 DAYS	8/3/2021		Lic:146264-T	
S	ervice		Des	cription		Price
LTR		TERMITE AND MOISTUR	RE REPORTS			\$50.00
					SUBTOTAL	\$50.00
					TAX	\$0.00
					AMT. PAID	\$0.00
					TOTAL	\$50.00
					AMOUNT DUE	\$50.00
						• • • • • •

WE ACCEPT CASH, CHECKS AND CREDIT CARDS

CREDIT CARD PAYMENTS CAN BE MADE VIA OUR WEBSITE

WWW.HAMPTONROADSTERMITE.COM

THANK YOU FOR YOUR BUSINESS!

WOOD DESTROYING ORGANISM ATTACHMENT

TO THE WOOD DESTROYING INSECT INFESTATION REPORT (FORM NPMA-33)

This is not a structural damage report. This form may be altered. Form NPMA-33 must accompany this report and this report must be listed in Section V of the Form NPMA-33.

SECTION I. GENERAL INFORMATION

Property Address: 225 CHEYENNE ROAD, VIRGINIA BEACH, VA 23462

Inspection Company: HAMPTON ROADS TERMITE & PEST CTRL

Company Address & Phone: 609 INNOVATION DRIVE, CHESAPEAKE, VA TREVOR DENNIS

23320, 757-436-3333

DATE

SECTION II. INSPECTION FINDINGS

Inspector Name:

This report is indicative of the condition of the subject structure(s) on the date of the inspection only and is NOT to be construed as an express or implied warranty or guarantee against latent, concealed, or future defects. Any such warranty or service agreement to provide future treatment or inspections may be provided as a separate attachment and only if indicated in Section V of Form NPMA-33. Information on the back of Form NPMA-33, Important Consumer Information Regarding the Scope and Limitations to the Inspection is incorporated by reference.

Based on a careful visual inspection of the readily accessible areas of the crawlspace or basement of the structure(s) inspected:

- A. NO VISIBLE EVIDENCE OF WOOD DECAY FUNGI WAS OBSERVED
- B. VISIBLE EVIDENCE OF WOOD DECAY FUNGI WAS OBSERVED AS FOLLOWS:

Fungi observed (description and location): _____

Damage from wood decay fungi was noted in the following area(s): NO VISIBLE MOISTURE DAMAGE AS PER REIN CONTRACT

CORRECTIVE ACTION RECOMMENDED AS FOLLOWS:

Regarding visible evidence of wood decay fungi: The inspector may find wood which has been damaged by fungi. Any damage noted should be considered only as evidence of current or previous activity of wood decay fungi. If box B is checked above, IT SHOULD BE UNDERSTOOD THAT SOME DEGREE OF DAMAGE, INCLUDING HIDDEN DAMAGE, MAY BE PRESENT. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair. UPON RECEIPT OF THIS REPORT, THE SELLER OR THE SELLER'S AGENT SHALL NOTIFY THE BUYER THAT ANY DAMAGE SHOULD BE EXAMINED BY A QUALIFIED INDIVIDUAL TO DETERMINE ANY NEED FOR REPAIR.

There is evidence of the presence of excessive moisture conditions in wood as follows:

SIGNATURE OF INSPECTOR

Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the property. I do further state that neither I nor the company for which I am acting is associated in any way with any party to this transaction.

breion Denno	146264-T	08/03/2021	
Signature of Inspector	Certification or Registration No. (if applicable)	Date of Inspection	
STATEMENT OF BUYER AND SELLER-THIS REPORT	MUST BE SIGNED BY THE BUYER AND SELLER AS A	PPLICABLE	

This report is integral to, and a necessary part of the inspecting company's full disclosure as to the scope and inherent limitations of the inspection and report of findings. It is most important that the interested parties acknowledge this advice. The seller hereto agrees that all known property history information regarding wood decay fungi, damage from fungi, and treatment history has been disclosed to the buyer. A legible copy of this page must be returned to the inspecting company by the person ordering this inspection.

SIGNATURE OF SELLER(S)	or OWNER D (if refinancing)	DATE
The undersigned hereby acknowledges	receipt of a copy of this report	

SIGNATURE OF BUYER(S)

2019 National Pest Management Association (NPMA). This form has been developed by NPMA as a service to inspection firms. By so doing, NPMA does not certify that the inspection firm is a member in good standing of NPMA or that it is qualified to perform the inspection. NPMA is not guaranteeing the inspection firm's work. NPMA shall not be a party to any claim or action by the buyer or seller against the inspection firm solely by reason of making this report form available for use.

Wood Destroying Insect Inspection Report	Notice: Please read imp	portant consumer info	ormation on page 2.
Section I. General Information	Company's Pest Control Business Lic. No.		Date of Inspection
Inspection Company, Address & Phone HAMPTON ROADS TERMITE & PEST CTRL	91000240		08/03/2021
609 INNOVATION DRIVE CHESAPEAKE, VA 23320	Address of Property Ins LORENE R	Pected	
757-436-3333	225 CHEYE	ENNE ROAD BEACH, VA 23462	
Inspector's Name, Signature & Certification, Registration, or Lic. #		Structure(s) Inspec	ted
TREVOR DENNIS Trevos Dennio #14	6264-T	SLAB	
Section II. Inspection Findings This report is indicative of the cond be construed as a guarantee or warranty against latent, concealed, or future inspection of the readily accessible areas of the structure(s) inspected	infestations or wood des		
X A No visible evidence of wood destroying insects was observed.			
B. Visible evidence of wood destroying insects was observed as follo			
1. Live insects (description and location):			
2. Dead insects, insect parts, frass, shelter tubes, exit holes, or s	taining (description and	location):	
· · · · · · · · · · · · · · · · · · ·			
3. Visible damage from wood destroying insects was noted as f	ollows (description and I	ocation):	
NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs.			
Section III. Recommendations			
X No action and/or treatment recommended: (Explain if Box B in Section	II is checked)		
Recommend action(s) and/or treatment(s) for the control of:			
Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed or inacces	sible		nspector may write out obstructions e the following optional key:
			d ceiling 15. Standing water bended ceiling 16. Dense vegetation
Crawlspace			d wall covering 17. Exterior siding r covering 18. Window well covers
X Main Level 1 3 4 67 8 9 13 24 5. Insulation 19. Wood pile 5. 0. <td< td=""></td<>			
7. Stored items 21. Unsafe conditions			
X Exterior 13.17 9. Appliances 23. Synthetic stucco			iances 23. Synthetic stucco
Porch			nited access and/or plumbing
Addition 12. No access beneath 25. Spray foam Other 13. Only visual access			
14. Cluttered condition 26. Equipment			
Section V. Additional Comments and Attachments (these are an integral part of the report)			
Attachments MOISTURE REPORT AND MOLD DISCLAIMER			
Signature of Seller(s) or Owner(s) if refinancing. Seller discloses to the buyer all information, to their knowledge, regarding W.D.I. infestation, damage, repair, and treatment history. Seller discloses to the information reported.			
x x			

Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. Please refer to the NPMA Suggested Guidelines for instructions on completing this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. About the Inspection: A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms. This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- 2. Treatment Recommendation Guidelines Regarding Subterranean Termites: Treatment or corrective action should be recommended if live termites are found. If no evidence of a previous treatment is documented and evidence of infestation is found, even if no live termites are observed, treatment or corrective action by a licensed pest control company should be recommended. Treatment or corrective action may be recommended if evidence of infestation is observed, and a documented treatment occurred previously, unless the structure is under warranty or covered by a service agreement with a licensed pest control company.

For other Wood Destroying Insects, please refer to the NPMA suggested guidelines for added guidance on actions and or treatment.

- 3. Obstructions and Inaccessible Areas: No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- 5. Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.



609 INNOVATON DRIVE CHESAPEAKE VIRGINIA 23320 (757) 436-3333

MOLD & MILDEW DISCLAIMER

This report is not a comprehensive molsture report regarding the entire structure and applies only to wood decay fungi (white rot, brown rot and dry rot) and moisture conditions conducive to the growth of wood decay fungi limited to the area below the first main floor. This property was not inspected for the presence or absence of health related molds or fungi. The inspector performing this inspection is not qualified authorized nor licensed to inspect for health related molds and/or fungi. Should information regarding the presence or absence of health related molds or fungi be desired an Industrial Hygienist or health related mold professional should be contacted. Therefore this report should not be relied upon in lieu of a complete physical inspection of the entire premises by interested parties or persons.

SELLER		DATE
BUYER	197 <u></u>	DATE
BOTH PARTIES ARE TO	SIGN ABOVE AT	TIME OF CLOSING