Wood Destroying Insect Inspection Report Section I. General Information Inspection Company, Address & Phone	Notice: Pl	ease read important consun	ici illioillation on	page 2.
		Company's Busin	see Lie Ne	Data of Incompation
maparism ouripany, radioss at Hone		Company's Busine	555 LIC. INO.	Date of Inspection
Dodson Bros. Ext. Co., Inc 770 Memorial Dr		91000163		02/09/2024
Danville VA 24541	4	Address of Proper 881 Court House Chase City VA 23	Rd	
Inspector's Name, Signature & Certification, Registration, or Lic.	No.		Structure(s) Inspec	ted
Melissa Warren 164454-T Melissa War		1, 1	House	
Section II. Inspection Findings This report is indicating	ve of the condition	of the above identified struc	ture(s) on the date	of inspection
and is not to be construed as a guarantee or warranty against late inspection of the readily accessible areas of the structure(s)	nt concealed or f	uture infestations or defects	. Based on a care	eful visual
A. No visible evidence of wood destroying insects was obse				
B. Visible evidence of wood destroying insects was observed				
1. Live insects (description and location):				
Dead insects, insect parts, frass, shelter tubes, exit holes,				
	or staining (descri	otion and location):		
3. Visible damage from wood destroying insects was noted a	s follows (descript	on and location):		
NOTE: This is not a structural damage report. If box B above i	s checked, it sho	uld be understood that so	me degree of dan	nage,
including hidden damage, may be present. If any questions ari	se regarding dama	ge indicated by this report, i	t is recommended	that the buyer
or any interested parties contact a qualified structural professional Section III. Recommendations	to determine the e	xtent of damage and the ne	ed for repairs.	
	40			
No treatment recommended: (Explain if Box B in Section II is	checked)			
	checked)			
	checked)			
✓ No treatment recommended: (Explain if Box B in Section II is	checked)			
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas		The inst	ector may write o	out obstructions or use
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:			pector may write o	out obstructions or use
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas		the follo	wing optional key ceilings	
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed of the structure of the str		the folio 1. Fixed 2. Suspe	wing optional key ceilings nded ceiling	<ul><li>15. Standing Water</li><li>16. Dense vegetation</li></ul>
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed of Basement  6, 7, 14  Crawlspace		the folio 1. Fixed 2. Suspe 3. Fixed	wing optional key ceilings nded ceiling wall covering	<ul><li>15. Standing Water</li><li>16. Dense vegetation</li><li>17. Exterior siding</li></ul>
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed of  Basement  6, 7, 14		the folio 1. Fixed 2. Suspe	wing optional key ceilings nded ceiling wall covering covering	<ul><li>15. Standing Water</li><li>16. Dense vegetation</li></ul>
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed of  Basement  6, 7, 14  Crawlspace		the folio 1. Fixed 2. Suspe 3. Fixed 4. Floor of 5. Insulat 6. Cabine	wing optional key ceilings nded ceiling wall covering covering ion ets or shelving	15. Standing Water 16. Dense vegetation 17. Exterior siding 18. Window well covers 19. Wood pile 20. Snow
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed of  Basement  6, 7, 14  Crawlspace  Main Level  1, 3, 4, 6, 7, 8, 9, 14		the folio 1. Fixed 2. Suspe 3. Fixed 4. Floor of 5. Insulat 6. Cabine 7. Stored	wing optional key ceilings nded ceiling wall covering covering ion ets or shelving items	15. Standing Water 16. Dense vegetation 17. Exterior siding 18. Window well covers 19. Wood pile 20. Snow 21. Unsafe conditions
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed of Basement 6, 7, 14  Crawlspace  Main Level 1, 3, 4, 6, 7, 8, 9, 14  Attic 10  Garage		the folio 1. Fixed 2. Suspe 3. Fixed 4. Floor of 5. Insulat 6. Cabine	wing optional key ceilings nded ceiling wall covering covering ion ets or shelving items nings	15. Standing Water 16. Dense vegetation 17. Exterior siding 18. Window well covers 19. Wood pile 20. Snow 21. Unsafe conditions 22. Rigid foam board
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed of  Basement 6, 7, 14  Crawlspace  Main Level 1, 3, 4, 6, 7, 8, 9, 14  Attic 10		the folio 1. Fixed 2. Suspe 3. Fixed 4. Floor of 5. Insulat 6. Cabine 7. Stored 8. Furnisl 9. Appliat 10. No act	wing optional key ceilings nded ceiling wall covering covering ion ets or shelving items nings nces ccess or entry	15. Standing Water 16. Dense vegetation 17. Exterior siding 18. Window well covers 19. Wood pile 20. Snow 21. Unsafe conditions
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed of  Basement 6, 7, 14  Crawlspace  Main Level 1, 3, 4, 6, 7, 8, 9, 14  Attic 10  Garage		the folio 1. Fixed 2. Suspe 3. Fixed 4. Floor of 5. Insulat 6. Cabine 7. Stored 8. Furnisl 9. Appliat 10. No act 11. Limite	wing optional key ceilings inded ceiling wall covering covering cion ets or shelving items inings inces ceess or entry et access	15. Standing Water 16. Dense vegetation 17. Exterior siding 18. Window well covers 19. Wood pile 20. Snow 21. Unsafe conditions 22. Rigid foam board 23. Synthetic stucco 24. Duct work, plumbing and/or wiring
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed of  Basement 6, 7, 14  Crawlspace  Main Level 1, 3, 4, 6, 7, 8, 9, 14  Attic 10  Garage  Exterior 19, 17  Porch		the folio 1. Fixed 2. Suspe 3. Fixed 4. Floor of 5. Insulat 6. Cabine 7. Stored 8. Furnisl 9. Appliat 10. No act 11. Limite 12. No act	wing optional key ceilings nded ceiling wall covering covering ion ets or shelving items nings nces ccess or entry ed access ccess beneath	15. Standing Water 16. Dense vegetation 17. Exterior siding 18. Window well covers 19. Wood pile 20. Snow 21. Unsafe conditions 22. Rigid foam board 23. Synthetic stucco 24. Duct work, plumbing and/or wiring 25. Spray foam
No treatment recommended: (Explain if Box B in Section II is  Recommend treatment for the control of:  Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed of  Basement  6, 7, 14  Crawlspace  Main Level  1, 3, 4, 6, 7, 8, 9, 14  Attic  10  Garage  Exterior  19, 17		the folio 1. Fixed 2. Suspe 3. Fixed 4. Floor of 5. Insulat 6. Cabine 7. Stored 8. Furnisl 9. Appliat 10. No act 11. Limite 12. No act 13. Only	wing optional key ceilings inded ceiling wall covering covering cion ets or shelving items inings inces ceess or entry et access	15. Standing Water 16. Dense vegetation 17. Exterior siding 18. Window well covers 19. Wood pile 20. Snow 21. Unsafe conditions 22. Rigid foam board 23. Synthetic stucco 24. Duct work, plumbing and/or wiring

## Important Consumer Information Regarding the Scope and Limitations of the Inspection

actions and or treatment.

Please read this entire page as it is part of this report. Please refer to NPMA Suggested Guidelines for instructions on completing this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- About the Inspection: A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew, or noninsect wood destroying organisms. This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used withing ninety (90) days from the date of inspection. This shall not be construed as a 90day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- Treatment Recommendation Guidelines Regarding Subterranean Termites: Treatment or corrective action should be recommended if live termites are found. If no evidence of a previous treatment is documented as evidence of infestation is found, even if no live termites are observed, treatment or corrective action by a licensed pest control company should be recommended. Treatment or corrective action may be recommended if evidence of infestation is observed, and a documented treatment occurred previously, unless the structure is under warranty or covered by a service agreement with a licensed pest control company. For other Wood Destroying Insects, please refer to the NPMA suggested guidelines for added guidance on
- 3. Obstructions and Inaccessible Areas: No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the areas is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attacked by wood destroying insects. Home owners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be take in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property in inspected.