00 p.m.) Location: Hughes Rd. Elementary, 11901 Hughes Rd., Dickinson, Tx 77539 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, May 28, 2019 - Monday, July 15, 2019 0 Removal Information Preview & Removal (By Appointment Only-Mandatory-No Exceptions) Tuesday, May 28, 2019 - Monday, July 15, 2019 0 Removal Information Preview & Removal Contacts: Daria Jarman, (281)229-7250 0 Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mi Bidding, This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No Exceptions I And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bi Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Re Meet The Minimum Insurance Requirements By Dickinson ISD And Must Contact Dickinson ISD For Requir Information.***Movers Will Need To Check With The City On Moving Permits & Hours And Days Allowed ⁴ Building #: 29 - Year Mfg: Unknown - Approx. Size: 60' X 26' - No Restrooms - (2) Rooms - T-111 Siding - Sh /Composition Roof, 30 Yr. Type, Put On A Couple Of Years Ago - Roof Condition: Recently Placed New Roof Years Ago - Wood Skid - (1) A/C Unit - Central A/C Unit, Mfg. Unknown, (1) Ruud Furnace/Gas - Exterior Co Room #2, Will Need Some Painting - Front (2) Door Entry - Overall Condition: Fair - Current Condition Fair 2 Building #: 30 - Year Mfg: Unknown - Approx. Size: 24' X 55' - Was Plumbed For (2) Bathrooms - (1) Room - Metal Siding - Metal Roof - Roof Condition: No Visible Leaks Upon Inspection DY Auctioneer - Wood Skid - Problems: Interior Has Been Partially Demoed, All Interior Walls Have Been Removed & Ceiling	nber Title	tle	Description
00 p.m.) Location: Hughes Rd. Elementary, 11901 Hughes Rd., Dickinson, Tx 77539 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, May 28, 2019 - Monday, July 15, 2019 0 Removal Monday, July 15, 2019 0 Information Preview & Removal Monday, July 15, 2019 0 Information Preview & Removal Contacts: Darla Jarman, (281)229-7250 0 Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mi Bidding. This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No Exceptions! And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bi Online Auction Site, Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Re Meet The Minimum Insurance Requirements By Dickinson ISD And Must Contact Dickinson ISD For Requir Information.***Movers Will Need To Check With The City On Moving Permits & Hours And Days Allowed* /Composition Roof, 30 Yr. Type, Put On A Couple Of Years Ago - Neof Condition: Recently Placed New Roof /Cargo - Wood Skid - (1) A/C Unit - Central A/C Unit, Mult, Nuud Furnace/Gas - Exterior Co /Problems: Lots Of New Siding Approx. 2 Years Ago - Interior Condition/Problems: Minor Scratches On Roo Room #2, Will Need Some Painting - Front (2) Door Entry - Overall Condition: Fair - Current Condition Fair 2 Building #: 30 - Year Mfg: Unknown - Approx. Size: 24' X 55' - Was Plumbed For (2) Bathrooms - (1) Room - Heat Units - Exterior Condition, Problems: Cuts On Metal, Rust On Lower Section Of Panel In Rear, Big Den Keeds Cleaning, Rust Around Windows In Front, Large Hole On Metal On Front Right		Removal	All purchases will be subject to a 13% buyer's premium.
Removal: (By Appointment Only-Mandator-No Exceptions) Removal Removal (Hours Of Operation: 8:00 a.m 2:00 p.m.) 0 Removal Tuesday, May 28, 2019 - Monday, July 15, 2019 1 Information Preview & Removal Contacts: Darla Jarman, (281)229-7250 Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building M Bidding. This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No ExceptionsII And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bi Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Ne Meet The Minimum Insurance Requirements By Dickinson ISD And Must Contact Dickinson ISD For Requir Information.***Movers Will Need To Check With The City On Moving Permits & Hours And Days Allowed* (1) Portable Building #: 29 - Year Mfg: Unknown - Approx. Size: 60' X 26' - No Restrooms - (2) Rooms - T-111 Siding - Sh /Composition Roof, 30 Yr. Type, Put On A Couple Of Years Ago - Nood Condition: Recently Placed New Rood Years Ago - Wood Skid - (1) A/C Unit - Central A/C Unit, Mfg. Unknown, (1) Ruud Furnace/Gas - Exterior Con Room #2, Will Need Some Painting - Front (2) Door Entry - Overall Condition: Feir - Current Condition Fair 1 Building : 30 - Year Mfg: Unknown - Approx. Size: 24' X 55' - Was Plumbed For (2) Bathrooms - (1) Room - Metal Siding - Metal Roof - Roof Condition: No Visible Leaks Upon Inspection By Auctioneer - Wood Skid - Heat Units - Exterior Condition/Problems: Cuts On Metal, Rust On Lower Section Of Panel In Rear, Big Deen Red Cleaning, Rust Around Windows In Front, Large Hole On Metal On Front Right Side Of Building - Inter /Problems: Interior Has Been Removed, Auctioneer Recommends P			Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, May 9, 2019 (Hours Of Operation: 8:00 a.m 2: 00 p.m.)
(1) Portable /Composition Roof, 30 Yr. Type, Put On A Couple Of Years Ago - Roof Condition: Recently Placed New Roof 1 Building /Composition Roof, 30 Yr. Type, Put On A Couple Of Years Ago - Roof Condition: Recently Placed New Roof 1 Building /Problems: Lots Of New Siding Approx. 2 Years Ago - Interior Condition/Problems: Minor Scratches On Roo 1 Problems: Lots Of New Siding Approx. 2 Years Ago - Interior Condition/Problems: Minor Scratches On Roo 2 Building - Current Condition Fair 1 Building Building #: 30 - Year Mfg: Unknown - Approx. Size: 24' X 55' - Was Plumbed For (2) Bathrooms - (1) Room - Metal Siding - Metal Roof - Roof Condition: No Visible Leaks Upon Inspection By Auctioneer - Wood Skid - Heat Units - Exterior Condition/Problems: Cuts On Metal, Rust On Lower Section Of Panel In Rear, Big Dem Needs Cleaning, Rust Around Windows In Front, Large Hole On Metal On Front Right Side Of Building - Interior Has Been Partially Demoed, All Interior Walls Have Been Removed & Ceiling Has Been (2) Front - Overall Condition Of Building: Poor 2 Building #: 3 - Year Mfg: Unknown - Approx. Size: 55' X 26 - (2) Rooms - No Bathrooms - Metal Siding - Meta Condition: Water Spots On Room #1 Ceiling Tile, Wood Paneling On Inside And Room #2, (1) Ceiling Tile Da Water Damage - Wood Skid - (2) Bard Wall Mount A/c Heat Units - Exterior Condition/Problems: Possible I Metal Roof, Recent Gutters Applied On Building, Some Dents All Over Building, Small Dent/Gash On Lower Section In Rear - Interior Condition/Problems: Water Stais I Metal Roof, Noted On Ceiling Tile In Both Rooms, Walls Okay, Some Scratches - (2) Door Entry In Front - I <td>0 Rem</td> <td>Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, May 28, 2019 - Monday, July 15, 2019 (Hours Of Operation: 8:00 a.m 2:00 p.m.) Preview & Removal Contacts:</td>	0 Rem		Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, May 28, 2019 - Monday, July 15, 2019 (Hours Of Operation: 8:00 a.m 2:00 p.m.) Preview & Removal Contacts:
2 Building #: 30 - Year Mfg: Unknown - Approx. Size: 24' X 55' - Was Plumbed For (2) Bathrooms - (1) Room - Metal Siding - Metal Roof - Roof Condition: No Visible Leaks Upon Inspection By Auctioneer - Wood Skid - Heat Units - Exterior Condition/Problems: Cuts On Metal, Rust On Lower Section Of Panel In Rear, Big Dem Needs Cleaning, Rust Around Windows In Front, Large Hole On Metal On Front Right Side Of Building - Interior Has Been Partially Demoed, All Interior Walls Have Been Removed & Ceiling Has Been (Problems: Interior Has Been Removed, Auctioneer Recommends Preview - Ready For Storage Use - (2) Front - Overall Condition Of Building: Poor 4 (1) Portable Building #: 3 - Year Mfg: Unknown - Approx. Size: 55' X 26 - (2) Rooms - No Bathrooms - Metal Siding - Metal Siding - Metal Siding #: 3 - Year Mfg: Unknown - Approx. Size: 55' X 26 - (2) Rooms - No Bathrooms - Metal Siding - Metal Condition: Water Spots On Room #1 Ceiling Tile, Wood Paneling On Inside And Room #2, (1) Ceiling Tile Date Water Damage - Wood Skid - (2) Bard Wall Mount A/c Heat Units - Exterior Condition/Problems: Possible I Metal Roof, Recent Gutters Applied On Building, Some Dents All Over Building, Small Dent/Gash On Lower Section In Rear - Interior Condition/Problems: Water Stains of Leaking Roof, Noted On Ceiling Tile In Both Rooms, Walls Okay, Some Scratches - (2) Door Entry In Front - Versite Right Side Of Building, Surface Rust On Lower Section In Rear - Interior Condition/Problems: Water Stains of Leaking Roof, Noted On Ceiling Tile In Both Rooms, Walls Okay, Some Scratches - (2) Door Entry In Front - Versite Right Side Of Date Proved Rooms, Walls Okay, Some Scratches - (2) Door Entry In Front - Versite Right Side Of Noted On Ceiling Tile In Both Rooms, Walls Okay, Some Scratches - (2) Door Entry In Front - Versite Room Rooms, Walls Okay, Some Scratches - (2) Door Entry In Front - Versite Room Room Screatches - (2) Door Entry I	1 Build	Building	Building #: 29 - Year Mfg: Unknown - Approx. Size: 60' X 26' - No Restrooms - (2) Rooms - T-111 Siding - Shingle /Composition Roof, 30 Yr. Type, Put On A Couple Of Years Ago - Roof Condition: Recently Placed New Roof Approx. 2-3 Years Ago - Wood Skid - (1) A/C Unit - Central A/C Unit, Mfg. Unknown, (1) Ruud Furnace/Gas - Exterior Condition /Problems: Lots Of New Siding Approx. 2 Years Ago - Interior Condition/Problems: Minor Scratches On Room #1 & Room #2, Will Need Some Painting - Front (2) Door Entry - Overall Condition: Fair
2(1) Portable Building /ClassroomMetal Siding - Metal Roof - Roof Condition: No Visible Leaks Upon Inspection By Auctioneer - Wood Skid - Heat Units - Exterior Condition/Problems: Cuts On Metal, Rust On Lower Section Of Panel In Rear, Big Dem Needs Cleaning, Rust Around Windows In Front, Large Hole On Metal On Front Right Side Of Building - Inter /Problems: Interior Has Been Partially Demoed, All Interior Walls Have Been Removed & Ceiling Has Been Electrical & Plumbing Has Been Removed, Auctioneer Recommends Preview - Ready For Storage Use - (2) Front - Overall Condition Of Building: Poor - Current Condition Poor3(1) Portable Building /ClassroomBuilding #: 3 - Year Mfg: Unknown - Approx. Size: 55' X 26 - (2) Rooms - No Bathrooms - Metal Siding - Metal Condition: Water Spots On Room #1 Ceiling Tile, Wood Paneling On Inside And Room #2, (1) Ceiling Tile Da Water Damage - Wood Skid - (2) Bard Wall Mount A/c Heat Units - Exterior Condition/Problems: Possible I Metal Roof, Recent Gutters Applied On Building, Some Dents All Over Building, Small Dent/Gash On Lower Right Side Of Building, Surface Rust On Lower Section In Rear - Interior Condition/Problems: Water Stains of Leaking Roof, Noted On Ceiling Tile In Both Rooms, Walls Okay, Some Scratches - (2) Door Entry In Front -			
Building #: 3 - Year Mfg: Unknown - Approx. Size: 55' X 26 - (2) Rooms - No Bathrooms - Metal Siding - Meta Condition: Water Spots On Room #1 Ceiling Tile, Wood Paneling On Inside And Room #2, (1) Ceiling Tile Da Water Damage - Wood Skid - (2) Bard Wall Mount A/c Heat Units - Exterior Condition/Problems: Possible I Metal Roof, Recent Gutters Applied On Building, Some Dents All Over Building, Small Dent/Gash On Lower Right Side Of Building, Surface Rust On Lower Section In Rear - Interior Condition/Problems: Water Stains (Leaking Roof, Noted On Ceiling Tile In Both Rooms, Walls Okay, Some Scratches - (2) Door Entry In Front -	2 Build) Portable uilding lassroom	Building #: 30 - Year Mfg: Unknown - Approx. Size: 24' X 55' - Was Plumbed For (2) Bathrooms - (1) Room - Panel Wall Metal Siding - Metal Roof - Roof Condition: No Visible Leaks Upon Inspection By Auctioneer - Wood Skid - (2) Bard A/C Heat Units - Exterior Condition/Problems: Cuts On Metal, Rust On Lower Section Of Panel In Rear, Big Dent In Rear, Needs Cleaning, Rust Around Windows In Front, Large Hole On Metal On Front Right Side Of Building - Interior Condition /Problems: Interior Has Been Partially Demoed, All Interior Walls Have Been Removed & Ceiling Has Been Removed, All Electrical & Plumbing Has Been Removed, Auctioneer Recommends Preview - Ready For Storage Use - (2) Door Entry In Front - Overall Condition Of Building: Poor
 Condition: Water Spots On Room #1 Ceiling Tile, Wood Paneling On Inside And Room #2, (1) Ceiling Tile Da Water Damage - Wood Skid - (2) Bard Wall Mount A/c Heat Units - Exterior Condition/Problems: Possible I Metal Roof, Recent Gutters Applied On Building, Some Dents All Over Building, Small Dent/Gash On Lower Right Side Of Building, Surface Rust On Lower Section In Rear - Interior Condition/Problems: Water Stains Classroom Condition: Water Spots On Room #1 Ceiling Tile, Wood Paneling On Inside And Room #2, (1) Ceiling Tile Da Water Damage - Wood Skid - (2) Bard Wall Mount A/c Heat Units - Exterior Condition/Problems: Possible I Metal Roof, Recent Gutters Applied On Building, Some Dents All Over Building, Small Dent/Gash On Lower Section In Rear - Interior Condition/Problems: Water Stains Classroom 			- Current Condition Poor
- Current Condition Fair	3 Build) Portable Jilding lassroom	
Condition: Some Ceiling Tiles Have Water Stains - Wood Skid - (2) Bard A/C Heat Units - Exterior Condition, Some Dents, Needs Cleaning, Dent On Lower Section On Left Side - Interior Condition/Problems: Inside Bu Building Been Utilized By DISD For A Small Shop For Maintenance, Carpet Has Bene Covered By Press Board, Walls	4 Build) Portable iilding	Building #: 2 - Year Mfg: Unknown - Approx. Size: 56 X 26 - No Bathrooms - (2) Rooms - Metal Siding - Metal Roof - Roof Condition: Some Ceiling Tiles Have Water Stains - Wood Skid - (2) Bard A/C Heat Units - Exterior Condition/Problems: Some Dents, Needs Cleaning, Dent On Lower Section On Left Side - Interior Condition/Problems: Inside Building Has Been Utilized By DISD For A Small Shop For Maintenance, Carpet Has Bene Covered By Press Board, Walls Are Paneled, Some Prior Damage On Walls, Carpet Condition Unknown - (2) Door Entry On Front - Overall Condition Of Building: Fair