Lot Number	Title	Description	Thumbnail
0	Removal	**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**	Read Me
		**All purchases will be subject to a 14% buver's premium. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order & Wire Transfer*	
		CDC COVID-19 GUIDELINES WILL BE OBSERVED – WEAR A MASK AND STAY AT LEAST 6 FT. APART.	
		Preview: (By Appointment Only-Mandatory-No Exceptions) Wednesday, April 28, 2021 (Hours Of Operation: 9:00 A.M 3:00 P.M.) Location: 18810 Juergen Road, Tomball, TX 77377 Driving Directions. Removal Dates & Times: (By Appointment Only-Mandatory-No Exceptions) Monday, May 3, 2021/Tuesday, May 4, 2021 (Hours Of Operation: 9:30 A.M 3:00 P.M.) Preview & Removal Contact: Lemons Auctioneers 281-357-4977	
		Anyone Entering The Lemons Auctioneers Premises Is Required To Show A Drivers License, State Issued ID, Passport, Or Equivalent. No merchandise will be released without proper ID and a Letter of Authorization to release merchandise to Buyer's Representative. This form may be found under the Resources Tab of OnlinePros.com. Please email release form to lemons@lemonsauctioneers.com or fax: (281) 357-4977.	
		Forklift Will Be Available For Removal	
1500	(1) Kawasaki Mule	Model: 3000 No Battery Dump Bed OHVFD620D Liquid Cooled V-Twin Gas Engine - Does Not Run Has Key Tires Are Worn On Right Rear - Some Rust On Roof - Seat Needs Repair - Oxidized Paint - No Doors Mas Load (Approx. 1,330 lbs.) Has Been Sitting Up *Recommend Preview* This Unit Will Need To Be Restored	
		- Current Condition Unknown	
1501	(1) John Deere 4x2 Gator UTV	SN# CP22-76-00317 Has Key Gas Has Dump Bed - Has Headache Rack Both Tires Are Worn - Body Is Hard Plastic & Metal - Paint Is Oxidized - Seats Are Torn - Missing Front Grill - No Doors Does Not Run - Will Need To Be Restored	5
		- Current Condition Unknown	
1502	(1) Yamaha 4 Wheel Electric Golf Cart	No Key Has Doors - Seat Worn & Torn - Needs Cleaning - All Tires Are Worn & Need To Be Replaced - Has Cargo Area In Rear - Oxidized Paint - Plastic Front Windshield On Top Left Is Cracked Off & Missing Will Need Restoration & Batteries - Current Condition Unknown	