Wood Destroying Insect Inspection Report Notice: Please read important consumer information on page 2.							
Section I. General Information	Company's Pest Control Business Lic. No. Date of Inspection						
Inspection Company, Address & Phone	LPCO-474 2023-08-04		2023-08-04				
Black Diamond Termite & Pest Control, Inc.	Address of Property Inspected						
4911 Hamburg Pike	3204 SENECA PARI						
Jeffersonville, IN 47130 (812) 944-0453 (502) 585-1919	Louisville, KY 40207						
(0.2) 0.10 (002) 000 10.10							
Inspector's Name, Signature & Certification, Registration, or Lic. #		Structure(s)	•				
Blaire Birge	47118	House, Att	ached Garage				
Section II. Inspection Findings This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or wood destroying insect damage. Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected: A. No visible evidence of wood destroying insects was observed. B. Visible evidence of wood destroying insects was observed as follows: 1. Live insects (description and location): TERMITES IN SHELTER TUBES IN GARAGE. 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location): TERMITE SHELTER TUBES, EXIT HOLES, SCARRING AND STAINING IN BASEMENT AND GARAGE. TERMITE SHELTER TUBES AND SHELTER TUBE STAINING IN CRAWLSPACE. 2. Visible damage from wood destroying insects was noted as follows (description and location): TERMITE DAMAGE IN SHELVING MEMBERS IN GARAGE AND IN SILL PLATE, RIM JOIST, FLOOR JOIST AND DOOR CASING IN BASEMENT.							
NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs. Section III. Recommendations							
☐ No action and/or treatment recommended: (Explain if Box B in Section	II is checked):						
Recommend action(s) and/or treatment(s) for the control of: TERMITE							
Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed or inaccessible: Basement 1,3,4,6,7,8,24 Crawlspace 5,6,24 Main Level 1,3,4,6,7,8,9 Attic Garage 1,3,6,7 Exterior Porch Addition Other			The inspector may write out obstructions or use the following optional key: 1. Fixed ceiling 2. Suspended ceiling 3. Fixed wall covering 4. Floor covering 5. Insulation 6. Cabinets or shelving 7. Stored items 8. Furnishings 9. Appliances 10. No access or entry 11. Limited access 12. No access beneath 13. Only visual access 14. Cluttered condition 15. Standing water 16. Dense vegetation 17. Exterior siding 18. Window well covers 19. Wood pile 20. Snow 21. Unsafe conditions 22. Rigid foam board 23. Synthetic stucco 24. Duct work, wiring, and/or plumbing 25. Spray foam insulation 26. Equipment				
Section V. Additional Comments and Attachments (these are an integral part of the report)							
Attachments PHOTOS Black Diamond Tracking #: c4a26eb8ccbe0ab2c688							
Signature of Seller(s) or Owner(s) if refinancing. Seller discloses to the buyer all information, to their knowledge, regarding W.D.I. infestation, damage, repair, and treatment history.			signed hereby acknowledges receipt of a seport and understands the information				

Important Consumer Information Regarding the Scope and Limitations of the Inspection


Please read this entire page as it is part of this report. Please refer to the NPMA Suggested Guidelines for instructions on completing this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. **About the Inspection:** A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms. This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- 2. Treatment Recommendation Guidelines Regarding Subterranean Termites: Treatment or corrective action should be recommended if live termites are found. If no evidence of a previous treatment is documented and evidence of infestation is found, even if no live termites are observed, treatment or corrective action by a licensed pest control company should be recommended. Treatment or corrective action may be recommended if evidence of infestation is observed, and a documented treatment occurred previously, unless the structure is under warranty or covered by a service agreement with a licensed pest control company. For other Wood Destroying Insects, please refer to the NPMA suggested guidelines for added guidance on actions and or treatment.
- 3. **Obstructions and Inaccessible Areas:** No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- 5. Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.

Inspection Photos




termites in shelter tube in garage




termite damage in rim joist in basement

Ref. c4a26eb8ccbe0ab2c688



termite damage in floor joist in basement





RE:	Address:			
То	Whom it May Concern:			
	ack Diamond Termite & Foperty address above or		•	• •
	reatment type: Chemical treatment	t for term	ites.	
	Structures treated: Other:		Attached Garage	_
	Sentricon termite b Structures treated:			Detached Garage
	Other:			
	Structures treated:	House		_
	ermite treatments carry a co ew owner at no additional c		newable warranty that	t is transferred to a
An	ny questions can be directe	d to our off	ice at 502-585-1919.	
Th	nank You,			
Bla	ack Diamond Termite & Pes	t Control, I	nc.	

Franchise opportunities available! For information, visit bdfranchising.com