Property Information Package

Court Ordered Estate Auction
The Hurst Estate – 108 +/- Acres and Lodge
Located in Thomas County
3000 Lower Meigs Road
Meigs, Georgia

Online Only Auction
Bidding Ends December 11, 2018



www.WeeksAuctionGroup.com

Final Contract to Include a 10% Buyer's Premium

Court Ordered Estate Auction of the Jack and Corine Hurst Estate! 108 +/- acre plantation style property and lodge are available for bidding at online only auction. With a 4,500 +/- sq ft custom built lodge, large barns and workshops, stocked ponds and more, this plantation style tract makes the ideal outdoor retreat. Looking for a home in the woods or a property to create your weekend get-a-away this property is for you. Browse and bid today!

Auction Date and Time: December 11, 2018 4:00 P.M.

Open House Dates and Times: November 27, 2018 2:00 P.M. to 6:00 P.M. December 7, 2018 2:00 P.M. to 6:00 P.M.











For More Information Contact: Tori Fuller

Weeks Auction Group, Inc.

(229)921-4065

Tori@BidWeeks.com

Thomas County Tax Card – Page 1



Summary

Parcel Number 061 009

3000 LOWER MEIGSRD 3000 LOWER MEIGSRD 108.85 AC Location Address Legal Description

(Note: Not to be used on legal documents)
A5-Agricultural
(Note: This is for tax purposes only. Not to be used for zoning.)

Zoning Tax District Millage Rate 04 Fire District 03 (District 04)

26.315

Acres Neighborhood 108.85 Rur Par North West (155022)

Homestead Exemption No (S0) Landlot/District

View Map



Owner

Hurst Jack C & Corine C (est) c\o Juanita Kuipers 730 Summerhill Rd Thomasville, GA 31757

The owner above is the owner as of Jan 1, 2018. Look at the Sales section below for most recent owner.

Rural Land

Туре	Description	Calculation Method	Soil Productivity	Acres
RUR	Open Land	Rural	3	1.52
RUR	Open Land	Rural	5	0.4
RUR	Open Land	Rural	6	0.24
RUR	Woodlands	Rural	2	1.84
RUR	Open Land	Rural	3	4.37
RUR	Open Land	Rural	5	1.93
RUR	Open Land	Rural	6	5.78
RUR	Open Land	Rural	9	5.58
RUR	Woodlands	Rural	2	46.69
RUR	Woodlands	Rural	4	0.05
RUR	Woodlands	Rural	6	16.76
RUR	Woodlands	Rural	7	9.88
RUR	Woodlands	Rural	9	13.81

Residential Improvement Information

Style Heated Square Feet One Family 4484 Sheetrock Wood Siding Conc Wall/Msnry Interior Walls Exterior Walls Foundation Attic Square Feet
Basement Square Feet
Year Built
Roof Type
Flooring Type 0 823 - 75% Finished 2002 Metal Galvanized Carpet/Hardwood

Heating Type
Number Of Rooms
Number Of Bedrooms
Number Of Full Bathrooms
Number Of Half Bathrooms CH AC 8 \$366,118 Number Of Plumbing Extras Condition Fireplaces\Appliances House Address Average FP Const 1 sty 1 Box 1 3000 LOWER MEIGSRD

Accessory Information

Description	Year Built	Dimensions/Units	Identical Units	Value
Canopy, Above Average	2004	60x100/0	0	\$34,395
Canopy, Above Average	2004	36x20 / 0	0	\$6,397
Garage - Detached	2004	36x80 / 0	0	\$21,963

Thomas County Tax Card – Page 2

Description	Year Built	Dimensions/Units	Identical Units	Value
Screen Room, Outdoor	2004	24x33/0	0	\$2,740
Boat Dock	2003	4x320/0	0	\$1,825
Deck, Detached	2003	20x20/0	0	\$552
Gazebo	2003	10×10/0	0	\$600
Well, Irrigation or Subd.	2001	1x1/1	0	\$5,000
Housesite w/Deep Well	2001	1x1/1	0	\$7,000
Housesite, Large, No Well	2001	1x1/1	0	\$2,000
Canopy, Low Cost Residential	2001	18x20/0	0	\$272
PreFab Farm Bldg 1000-3000	2001	30x60/0	0	\$8,684
Canopy, Above Average	2001	10x60/0	0	\$4,606
Pond 10.01-50 acs	1900	0x0 / 15	0	\$30,000

Prebill Mobile Homes

Account Number	Owner	Lot Number	Year Built	Manufacturer	Model	Width x Length	
1434	Hurst Bradford & Shirley		1996	PIONEER	PIONEER AV	16x76	

Permits

Permit Date	Permit Number	Туре
08/26/2015		Breach of Covenant
06/28/2004	219-04	OUTBUILDING
02/19/2002	55	NEW SFR
12/27/2001	686	MOBILE HOME
11/26/2001	322	OUTBUILDING
09/12/2001	39167	OUTBUILDING

Sales

Sale Date	Deed Book / Page	Plat Book / Page	Sale Price Reason	Grantor	Grantee
1/5/1998	616 259	3 64	\$90,000 Land Unimproved		HURST JACK C & CORIN

Valuation

	2018	2017	2016	2015
Previous Value	\$763,464	\$761,539	\$765,891	\$757,793
Land Value	\$243,013	\$272,468	\$272,468	\$272,468
+ Improvement Value	\$366,118	\$362,266	\$352,250	\$332,006
+ Accessory Value	\$126,034	\$128,730	\$136,821	\$161,417
= Current Value	\$735,165	\$763,464	\$761,539	\$765,891
10 Year Land Covenant (Agreement Year / Value)		2008 / \$57,238	2008 / \$55.571	2008 / \$53,953

Photos



Sketches

Tax Map





Thomas County 2018 Tax Bill

2018 THOMAS COUNTY AD VALOREM TAX NOTICE

Internet Tax Bill

11/09/2018 06:49 PM

Alicia Hester Thomas Co Tax Comm P.O. Box 2175 Thomasville, GA 31799



BILL NUMB. ACCT NUMB. 340530 010

 ACCT NUMB.
 340530 010

 TAXPAYER
 HURST JACK C & CORINE C

 MAP NUMBER
 00610-00000-009-000
 LOCATION 3000 LOWER MEIGS RD 108

CURRENT YEAR TAXES \$7,618.95

PAY THIS AMOUNT \$7.618.95 11/15/2018 ON OR BEFORE

Alicia Hester

HURST JACK C & CORINE C 730 SUMMERHILL RD THOMASVILLE GA 31757

If paying by check or money order, please include your tax bill number.

Thomas Co Tax Comm P.O. Box 2175 Thomasville, GA 31799

Please return this portion of your bill with your payment in the enclosed envelope

2018 THOMAS COUNTY AD VALOREM TAX NOTICE

YEAR	BILL NUM	ACCOUNT NUMBER	DI	LOCATION/DES	LOCATION/DESCRIPTION MAP/PARCEL		FAIR MARKET VAL	
2018	11351	340530 010	340530 010 04		MEIGS RD 108.	00610-00000	-009-000	735,165
TAXING	ENTITY	ASSESSMENT		EXEMPTION TAXABLE VALUE		MILLAGE RATE	CREDITS	TAXES DUE
COUNTY		294	1066	0	294066	0.007531	685.47	2214.61
EMER SER		294	1066	0	294066	0.001735	0	510.2
FIRE 3		294	1066	0	294066	0.00234	0	688.11
SCHOOL		294	1066	0	294066	0.014303	0	4206.03

The gradual reduction and elmination of the STATE MILLAGE RATE is the result of property tax relief passed by the Governor, the Georgia State Senate, and the House of Representatives.

BASE AMOUNT \$7,618.95 PENALTY/FEES \$0.00 INTEREST \$0.00 TOTAL AMT PAID \$0.00 TOTAL TAX DUE \$7.618.95

Alicia Hester

CREDITS ARE LISTED FOR INFORMATION PURPOSES ONLY

HURST JACK C & CORINE C 730 SUMMERHILL RD THOMASVILLE GA 31757

PAYMENT MUST BE MADE ON OR BEFORE 11/15/2018

Thomas Co Tax Comm P.O. Box 2175 Thomasville, GA 31799 YOUR CANCELLED CHECK IS YOUR RECEIPT

------ PLEASE READ, THIS IS AN IMPORTANT PART OF YOUR TAX BILL

Certain persons are eligible for certain homestead exemptions from ad valorem taxation. In addition to the regular homestead authorized for all homeowners, certain elderly persons are entitled to additional homestead exemptions. The full law relating to each exemption must be referred to in order to determine eligibility for the exemption. If you are eligible for one of the exemptions and are not receiving the benefit of the exemption, usus tapply for the exemption no later than 4/1/2018 in order to receive the exemption, you may contact the office of the County Tax Office at 225 N BROAD ST. 229-225-4136

If you feel that your property has been assigned too high a value for tax purposes by the the Board of Tax Assessors, you should file a tax return reducing the value no later than 4/1/2018 in order to have an opportunity to have this value lowered for next year's taxes. Information on filing a return can be obtained from the County Tax Office at 225 N BROAD STREET, and/or 229-225-4136

LOCAL OPTION SALES TAX CREDIT:
The General Assembly reenacted the Local Option Sales Tax Act and another part of your bill shows the dollar amount of reduction of local property taxes which you have received. The law now requires the following additional information to be provided to each taxpayer:

LOCAL TAX LEVY:
Mill rate required to produce local budget.
Reduction in mill rate due to rollback to taxpayers of
sales tax proceeds this previous year.
Actual mill rate set by local officials incorporated
Actual mill rate set by local officials unincorporated 11.618 2.360 8.037

Legal Description

Tract I. All that tract or parcel of land situate, lying and being in Land Lot No. 2 in the 17th District of Thomas County, Georgia, and being more particularly described as follows: BEGIN at the Northwest corner of said lot and run South along the Western lot line of said lot to a point at one-half the distance of the length of said lot line, and the extend East from said lot line a sufficient distance into said lot to make fifty acres, so that said tract will be in the shape of a rectangle bounded on the north and West by original lot lines and on the South by land of C. B. Hurst and on the East by land of C. E. Hurst Estate.

EXCEPT One acre on the Northern Side of said tract beginning at a point marked by an iron pin on the Southern right of way line of the public road which runs along the Northern side of said tract a distance of 1,263 feet East from said Western original lot line of said lot and running thence East along the right of way of said road a distance of 208.7 feet to a corner marked by an iron pin; thence South a distance of 208.7 feet to a corner marked by an iron pin; thence West a distance of 298.7 feet to a corner marked by an iron pin; and thence North a distance of 208.7 feet to the point of beginning; so that the land hereby conveyed contains forty-nine (49) acres.

TRACT II. All that tract or parcel of land situate, lying and being in Land Lot No. 2 of the 17th Land District of Thomas County, Georgia, containing 64.851 acres, more or less, and being more particularly described on a plat of survey for the Dixie Hurst Estate property, prepared by Leroy Outzs, GA. Reg. Surveyor, dated April 5, 1977, a copy of which said plat is recorded in Plat Book 3, folio 64 of the Public Records of Thomas County, Georgia, and being more particularly described as follows:

COMMENCE at an iron pin located at the original Southwest Corner of Land Lot No. 2 and run thence South 89 degrees 29 minutes 18 seconds East along the original South line of Land Lot No. 2 a distance of 1,318.96 feet to an iron pin and the point of beginning of the property herein conveyed. FROM SAID POINT OF BEGINNING continue thence South 89 degrees 29 minutes 18 seconds East along the original South line of Land Lot No. 2 a distance of 1,657.10 feet to an iron pin located at the point where Little Creek intersects the original South Line of said lot; thence North 32 degrees 28 minutes 59 seconds West 605.2 feet to an iron pin; thence North 11 degrees 02 minutes 58 seconds East 452.3 feet to an iron pin; thence North 09 degrees 38 minutes 02 seconds West 1,517.21 feet to an iron pin; thence North 89 degrees 52 minutes 01 seconds West 1,205.2 feet to an iron pin and the property of Lindy Hurst; thence South 00 degrees 50 minutes 00 seconds West along the property of Lindy Hurst and Klemon White 2,037.10 feet to an iron pin located on the original South Line of Land Lot No. 2 and the Point of Beginning of the property herein conveyed.


Legal Description Continued

LESS AND EXCEPT: All that tract or parcel of land lying and being in Land Lot 2 of the 17th Land District of Thomas County, Georgia, containing 5.0 acres, more or less, and being more fully described as follows:


COMMENCE at the intersection of the sourtherly right of way margin of the Lower Meigs Road with the west boundary line of said Land Lot 2 at an iron pin set and run thence, South 88 degrees 02 minutes 00 seconds East along the Southerly right of way margin of said Lower Meigs Road to an iron pin set; run thence, South 02 degrees 03 minutes 21 seconds West 337.14 feet to an iron pin set; run thence, North 88 degrees 02 minutes 00 seconds West 646.02 feet to an iron pin set on a fence line; run thence, North 02 degrees 03 minutes 21 seconds East 337.14 feet to the Point of Beginning of the tract herein described.

Said tract or parcel being more fully described and delineated pursuant to plat of survey prepared by Larry W. Grogan and Associates, Inc., dated the 26th day of February, 1998, recoreded in Plat Book 7, Page 685, Office of the Clerk of Superior Court, Thomas County, Georgia.

Plat for Tract II of Legal Description



Auction Sketch



Auction Sketch Overlay



Page 1 of 1



Home Inspectors of South GA 106 Southlake Drive MOULTRIE GA 31768 229-589-9987

 $https://venturi.blob.core.windows.net/fd-1069/0/061\%20\%20\%200\%2009/0?sv=2015-07-... \\ 11/1/2018$

Page 1 of 1



 $https://venturi.blob.core.windows.net/fd-1069/0/061\%20\%20\%20\%20009/0?sv=2015-07-... \\ 11/1/2018$

qPublic.net - Thomas County, GA

Page 1 of 3

Summary

Parcel Number Location Address Legal Description

061 009

0s1 00V 3000 LOWER MEIGS RD 3000 LOWER MEIGS RD 108.85 AC (Note: Not to be used on legal documents)

AS-Agricultural (Note: This is for tax purpuses only. Not to be used for zoning.) AG

Tax District 04 Fire District 03 (District 04)

Millage Rate Acres 26.315 108.85

Neighborhood Homestead Exemption Landiot/District Rur Par North West (155022)

View Map



Hurst Jack C & Corine C (est) cho Avanita Kuipers 730 Summerhill Rd Thomasville, GA 31757

The owner above is the owner as of Jan 1, 2018. Look at the Sales section below for most recent owner.

Rural Land

Type	Description	Calculation Method	Soil Productivity	Acres
RUR	Open Land	Rural	3	1.52
RUR	Open Land	Rural	5	0.4
RUR	Open Land	Rural	6	0.24
RUR	Woodlands	Rural	2	1.84
RUR	Open Land	Rural	3	4.37
RUR	Open Land	Rural	5	1.93
RUR	Open Land	Rural		5.78
RUR	Open Land	Rural	9	5.58
RUR	Woodlands	Rural	2	46.69
RUR	Woodlands	Rural	4	0.05
RUR	Woodlands	Rural	6	16.76
RUR	Woodlands	Rural	7	9.88
RUR	Woodlands	Rural	9	13.81

Residential Improvement Information

Style Hosted Square Feet 4484 Interior Walls Exterior Walls Foundation Sheetrock Wood Siding Conc Wall/Msnry Attic Square Feet Basement Square Feet Year Built 823 - 75% Finished 2002 Metal Galvanized Carpet/Hardwood CH AC Roof Type Flooring Type Heating Type Number Of Rooms Number Of Bedrooms Number Of Full Bathrooms Number Of Half Bathrooms Number Of Plumbing Extras Value Condition \$366,118 Average FP Const 1 sty 1 Box 1 3000 LOWER MEIGS RD Fireplaces\Appliances House Address

Accessory Information

Description	Year Built	Dimensions/Units	Identical Units	Value
Canopy, Above Average	2004	60x100/0	O.	\$34.395
Canopy, Above Average	2004	36x20/0		100000
Garage - Detached	2004	36x80/0	0	\$6,397 \$21,963
			0 ,	\$21,763

https://qpublic.schneidercorp.com/Application.aspx?AppID=682&LayerID=11372&Page... 10/31/2018

qPublic.net - Thomas County, GA

Page 2 of 3

WidthxLength

Description	Year Built	Dimensions/Units	Identical Units	Valu		
Screen Room, Osescor	2004	24x33./ 0	0	\$2.7		
Boat Dock	2003	4#320/0	0	\$1.8		
Gazebo	2003	10x10/0	0	\$60		
Deck, Detached	2003	20x20/0	0	\$55		
Housesite w/Deep Weil	2001	1x1/1	0	\$7,0	00	
Housesite, Large, No Well	2001	1×1/1	0	\$2,0		
Canopy, Low Cost Residential	2001	18x20/0	0	\$277		
Well, Irrigation or Subd.	2001	1x1/1	0	\$5,0		
PreFab Farm Bldg 1000-3000	2001	30x60/0	0	\$8,6		
Carropy, Above Average	2001	10x60/0	0	\$4.6		
Pond 10:01-50 acs	1900	0x0/15	D	\$30.		

Prebill Mobile Homes

12/27/2001

11/26/2001

09/12/2001

1434	Hurst Bradford & Shirley	1995	PIONEER	PIONEER AV	16x76
Permits					
Permit Date 08/26/2015	Permit Number		Type Breach of Covenant		
06/28/2004 02/19/2002	219-04 55		OUTBUILDING NEW SFR		

Year Bullt

Manufacturer

MOBILE HOME

OUTBUILDING

OUTBUILDING

Lot Number

686

Sales

Sale Date Plat Book / Page Sale Price Reason 1/5/1998 616 259 \$90,000 Land Unimproved HURST JACK C & CORIN

Valuation

Previous Value	2018 \$763,464	2017 \$761,539	2016 \$765,891	2015 \$757,793
Land Value	\$243,013	\$272,468	\$272.468	\$272,468
+ Improvement Value	\$366.118	\$362,266	\$352,250	\$332,006
+ Accessory Value	\$126,034	\$128,730	\$136,821	\$161,417
- Current Value	\$735,165	\$763,464	\$761,539	\$765,891
10 Year Land Covenant (Agreement Year / Value)		2008 / \$57.238	2008 / \$55 571	2008/553953

Photos




Sketches

https://qpublic.schneidercorp.com/Application.aspx?AppID=682&LayerID=11372&Page... 10/31/2018

qPublic.net - Thomas County, GA

Page 3 of 3



No data available for the following modules: Land, Conservation Use Rural Land, Commercial Improvement Information, Mobile Homes,


The Thomas County Assessor makes every effort to produce the most accurate information possible. No warranties, expressed or implied are provided for the data herein, its use or interpretation. The assessment information is from the 2017 Certified Values. All other data is subject to change.

Last Data Upload: 10/31/2018 7:17:17 AM



 $https://qpublic.schneidercorp.com/Application.aspx?AppID=682\&LayerID=11372\&Page... \ \ 10/31/2018$

a qPublic.net Thomas County, GA



Parcel ID 061 009
Class Code Agricultural
Taxing District 04 Fire District 03
04 Fire District 03

cres 108.85

iNote: Not to be used on legal documents)

Hurst Jack C & Corine C (est) c\o Juanita Kuipers 730 Summerhill Rd Thomasville GA 31757

Physical Address 3000 LOWER MEIGS RD Assessed Value \$735165 Last 2 Sales

Date Price Reason Qual 1/5/1998 \$90000 LM Q n/a 0 n/a n/a

Date created: 10/31/2018 Last Data Uploaded: 10/31/2018 7:17:17 AM

Developed by Schneider

3000 Lower Meigs Road

Meigs GA

Weeks Auction Group

Findings and Recommendations:

- Some of the back porch post need repairing or replaced(Wood Damage)
- Back porch main beam needs to be replaced or repaired (Rotted Wood)
- The Seals on most of the exterior doors are separating and are losing the insulation R-Value to them. Need to be replaced or repaired
- Please check several lighting fixture and electrical boxes that need to be repaired or install outlets or fixtures
- Water damage to front wall in Den area. Also damage to wood in wall from kitchen to den area
- · Kitchen disposal not working properly
- Dishwasher leaking at seal (Please replace)
- · Range not working properly
- Water damage to ceiling in Kitchen area
- · Cracked tile in kitchen floor at Kitchen and Hallway leading to garage
- Please check wiring in laundry room area. Place back in outlet box and cover
- Check all garage doors (Not opening properly)
- · Missing outlet and light switch covers in garage area (Please install)
- Water damage in garage area ceiling
- Water damage in master bath closet ceiling
- Master bedroom carpet needs to be cleaned or replaced
- Damage to master bath cabinet drawer
- Please clean out shower heads in master shower and 2nd bath
- Missing wall in Study area
- Basement area showing signs of termite damage and also water may be seeping through walls
- Water heater electrical needs cover
- Back bedroom has water damage to ceiling

- Most of water damage inside house may be coming from condensation from the roof. Personally I feel the metal roof was not installed properly and may need to be replaced. The roof was never decked properly. I believe some of the water damage is coming from the valleys of the roof and also the transitions from pitch to pitch.
- Moderate termite damage found in house (Basement area, Front foyer, Kitchen. Several termite tubes found in basement area and the crawlspace).
 Did not find any active termites.
- In order to check the damage for termites some of the interior paneling and baseboard will have to be removed.
- The Basement area on outside wall may need to be replace (Rotted wood and termite damage) Seems to be from moisture
- · Recommend to install new vapor barrier in crawlspace
- Some of the exterior siding needs to be replaced or repaired(Loose may cause water damage
- The front of the house is unfinished(Please finish all siding and windows or screens)

Thank You

Home Inspectors of South GA 106 Southlake Drive MOULTRIE GA 31768 229-589-9987

DATE 10/31/18

PROPERTY ADDRESS 3000 Lower Meigs Road

NAME OF BUYER/HOMEOWNER Weeks Auction Group

TOTAL CHARGES \$350.00

Make checks payable to Ponda Zack Clark



HOME INSPECTORS OF SOUTH GA PROPERTY INSPECTION SERVICES

229-589-9987

Re: Inspection of property, located at:	
	3000 Lower Meigs Road Meigs GA

At your request, a visual inspection of the above-referenced property was conducted on __10/31/2018_____. This inspection reflects only the visual condition of the property at the time of inspection. Hidden or concealed defects are not included in this report. This report does not imply or express any type of guarantee.

An earnest effort on your behalf was made to discover all visible defects. However in the event of an oversight, maximum liability must be limited to the fee paid for inspection. The summary page of the report is a list of observations made at the time of the inspection. This report was made on the basis of what was visible and accessible at the time of inspection. Nothing in this report shall be construed as representing the condition of the property, mechanical system, appliances, etc., beyond the date and time of the inspection.

Thank you for the opportunity to serve you and please feel free to have Agent call me with any questions about this report.

Portolo Zagle Clark

Sincerely

	INSPECTION REPORT
T	HIS AGREEMENT is made and entered into by and between Londa Z. Clark, JR, eferred to as "Inspector", and Weeks Auton Group. referred to as "Client".
	consideration of the promise and terms of this Agreement, the parties agree as follows:
1.	The client will pay the sum of s for the inspection of the "Property Ling of residence, and garage or carport, if applicable, located at 5000 DWC Meics Residence, and garage will be rendered in cash, check, or money order at time of inspection."
2.	The inspector will perform a visual inspection and prepare a written report of the apparent condition of the readily accessible installed systems and components of the property existing at the time of the inspection.

- Latent and concealed defects and deficiencies are excluded from the inspection.

 3. The parties agree that the National Association of Property Inspectors (NAPI®)/FHA Standards shall define the standard of duty and the conditions, limitations, and exclusions of the inspection and are incorporated by reference herein. A copy of the Standards is included with the report.
- 4. The Parties understand and agree that the Inspector and its employees and its agents assume no liability or responsibility for the costs of repairing or replacing any unreported defects or deficiencies either current or arising in the future or any property damage, consequential damage or bodily injury of any nature.
- The parties agree and understand the Inspector is not an insurer or guarantor against defects in the structure, items, components, or systems inspected. INSPECTOR MAKES NO WARRANTY, EXPRESS OR IMPLIED AS TO THE FITNESS FOR USE, CONDITION, PERFORMANCE, OR ADEQUACY OF ANY INSPECTED STRUCTURE, ITEM, and COMPONENT, OR SYSTEM.
- If Client is married, Client represents that this obligation is a family obligation incurred in the interest of the family,
- 7. This Agreement, including the terms and conditions on page two of this document. Represents the entire agreement between the parties and there are no other agreements either written or oral between them. This agreement shall be amended only by written agreement signed by both parties.
- 8. Systems, items, and conditions which are not within the scope of the building inspection include, but are not limited to: radon, formaldehyde, lead paint, asbestos, toxic or flammable material, other environmental hazards; other treatments to windows, interior walls, ceilings and floors; recreational equipment or facilities; swimming pools or spas; heating systems accessories; solar heating systems; sprinkling systems; water wells; softener; central vacuum systems, self cleaning ovens, washer, dryer, personal furnishings, telephone, intercom or cable TV systems; antennae, lightening arrestors, trees or plants; governing codes, ordinance statutes and covenants. Client understands that these systems, items and conditions are excepted from this inspection. Any NOT represent an inspection.
- 9. The inspection and report are performed and prepared for the sole and exclusive use and possession of the Client. No other person or entity may rely on the report issued pursuant to this Agreement. In the event that any person, not a party to this Agreement, makes any claim against Inspector, its employees or agents, arising out of the services performed by Inspector under this Agreement, the Client agrees to indemnify, defend, and hold harmless Inspector from any and all damages, expenses, costs and attorney fees arising from such a claim.
- 10. The Inspection will not include an appraisal of the value or a survey. The written report is not a compliance inspection or certification for past or present governmental codes or regulations of any kind.

On to page two>

DEFINITIONS

Apparent Condition Systems and Components are rated as follows:

SATISFACTORY (Sat.) - Indicates the component is functionally consistent with its original purpose but may show signs of normal wear and tear and deterioration.

MARGINAL (Marg.) - Indicates the component will probably require repair or replacement anytime within two to three years.

POOR - Indicates the component will need repair or replacement now or in the very near future.

- Installed systems and components; structural components; exterior; interior; roofing; plumbing; electrical; heating; central air-conditioning (weather permitting); insulation and ventilation. An inspection of the air conditioning system (except heat pumps) will not be conducted when the outside air temperature is below 60 degrees F. Operation during periods of low outside temperature can cause damage to the compressor.
- Readily accessible systems and components; only those systems and components where Inspector is not required to remove personal items, furniture, equipment, soil, snow or other items which obstruct access or visibility.

This inspection reflects only the visual condition of the property at the time of the inspection. Hidden or concealed defects are not included in this report. The inspector does not take responsibility for reporting non-compliance with any building, electrical, mechanical or plumbing codes established by ordinance or law. The inspection is not a total and complete inspection of the absolute quality or condition of the items inspected, but an inspection of the general condition and performance of the items which existed at the time of the inspection This report and inspection does not imply or express any type of guarantee. An earnest effort was made on your behalf to discover all visible defects. However in the event of an oversight, maximum liability must be limited to the fee paid.

In the event the inspection fee is not paid at inspection, client authorizes parties closing this transaction to collect fee and pay inspector. Fee is due and payable whether real estate transaction closes or not.

Client has read this entire Agreement and accepts and understands this Agreement as hereby acknowledged:

Signature:

Date: 10/31/18

Day: Werds.

Current Street Address

City/State/Zip

Agent's Name

Telephone

Buyer Present Yes

No

Client agrees to release reports to Seller

Buyer Yes

No

Realtor Yes

No

E Mail address

A fee of \$25.00 or 10% of total amount will be assessed for any returned check.

Page 2:

	GROUNDS
Service Walks	ne Concrete Brick Other
Condition Appears:	Satisfactory Marginal Poor Trip Hazard
	Concrete Gravel Brick Other Asphalt
Condition Appears: Sa	atisfactory Marginal Poor Settling cracks
Fill cracks and s	Pitched toward home
Patio None V	Concrete Brick Other
Condition Appears: Sa	atisfactory Marginal Poor Settling cracks
Deck Mai roofless ares None	Treated Painted/ Stained Pool
	Marginal Poor Railing/Balusters Recommended
	Support Pier Wood Concrete Other
Condition Appears: Satisfactory	Marginal Poor Railing/Balusters recommended
Balcony 2" floor plutform None	Railing: Yes No Recommended: Yes No
Condition Appears:	Satisfactory Marginal Poor
Stoop/Steps None	
Condition Appears: Adequate	Cracked Settled Dry Rot Railing Recommended
Fencing None_	Туре
	sfactory Marginal Poor
	tion Trim back trees/shrubbery Wood in contact with soil
	Recommend window wells/covers
Comments	The state of the s
Sea Wall Yes No	Condition Adquate
General comments;	-


•		Roo	f		
**General Informatio					
Roof Visibility	All_V	Percent None	Lim	ited By	
Inspected From	Roof_		Ground _		
Style of Roof	Type	Combination	Gable	Hip Flat	Mansard
	Pitch	Combination	Low N	1edium ✓ S	teep Flat
Exposed Roof Cov	ering	Combination	Asphalt	Slate Tile Built up _	· Wood
stimate Number o	of Layers	1 2 3	4	Built up _	Meta
entilation System	Combination	Soffit V	Ridge Powered	Gable	Top
lashing Material	Combination		Aspha	alt	
alley Material	Combination			ılt	Other
parent Condition of t	the Following at Time	of Inspection			
oof Covering	Appears: Satisfacto	ory Margin	alP	oor_	
Condition	Curling	Cupping Cra	alder se		hlles
	Moss Buildup	Nail Popping	Puddling	ssing tabs/shingle:	villes
ntilation	Moss Buildup	_ Nail Popping	Puddling_	ssing tabs/shingle: Other	villes
entilation	Appears: Adequat	Nail Popping te: Yes N Marginal	Poor Pusted	Recomme	nd sealing
	Appears: Adequat Appears: Satisfacto Pulled away from c	Nail Popping te: Yes N ory Marginal	Poor Rusted	Recomme	nd sealing
shings	Appears: Adequat Appears: Satisfacto Pulled away from c Appears: Satisfacto Holes	Nail Popping te: Yes N ory Marginal Ory Marginal ory Marginal Marginal	Poor Rusted Not visible Poor Rusted	Recomme Other sted Not v	nd sealing
lleys	Appears: Adequat Appears: Satisfacto Pulled away from c Appears: Satisfacto Holes	Nail Popping te: Yes N ory Marginal Ory Marginal Pecommend sealing Appears: Satisfactory	Poor Rusted Not visible Poor Rusted	Recomme Other sted Not v	nd sealing
lleys rlights	Appears: Adequat Appears: Satisfactor Pulled away from c Appears: Satisfactor Holes Yes No Condition	Nail Popping ie: Yes N ory Marginal chimney/roof ory Marginal Appears: Satisfactory cons reported above reflect	Poor Rusted Not visible Poor Rus N/A Marginal	Recomme Other sted Not v	nd sealing

Chimn	ney(s) None Location #1 DCN Location #2 Location #3
	Viewed from: Roof Ladder at Eaves Ground w/binoculars
	Chase: Brick Stone Framed Block Metal
	Evidence of: Cracked chimney cap Loose mortar joints
	Fluer Plaking
	Have cleaned and re-evaluated Not visible
Commen	is;
Gutters	& Downspouts None Insides need to be cleaned Other Galv/Alum
	Condition: Appears: Satisfactory Marginal Poor Rusting Leaking corners Joints
	Extension needed: North South East West
Comments	s
Siding	
	Condition: Appears: Satisfactory Marginal Poor Recommend repair/paint
Comments	
	Semi
window	Frames Wood Aluminum Vinyl Other
	Condition: Appears: Satisfactory Marginal Poor Recommend repair/paint
	Putty: Appears: Satisfactory NeededN/A
Comments:	
Storms &	Screens
	Screens: Appears: Satisfactory Torn Not installed Missing
	Storms: Appears: Satisfactory Broken/cracked Not installed
comments:	Not installed
	2 8-66 2 5 1
********	Vinyr Other
	Condition: Appears: Satisfactory Marginal Poor Recommend painting
Caulking	Condition: Appears: Satisfactory Marginal Poor
	Appeals: Satisfactory Marginal Poor
	Recommend around windows/doors/masonry ledges/corner/utility penetrations

Exterior Wall	Construction	Not Visible	Wood Frame	Masonr	y Other
Exterior Doors	Entrance (1)	Storm (2) Back	(2) Pation		(5) Screen Doors (6)
Conditi		Appears: Satisfactory	-	Marginal V	
Weathe Comments:	r-stripping A	ppears: Satisfactory	. /	Marginal	
Comments.					
Exterior Electric	10				0 1
41				Meter	
		/		esNo_	
	otected: Yes		Operale: Y	es No_	/
Reverse po		_ No	Open ground	Yes N	lo V
Potential safety I Comment:	hazard: Yes	_ No_V			
Garage/Carport	None Atta	ached V			./
		The state of the s	thed	1-car 2-ca	3-car_
Safety Reverse	ener: Yes	No Oper	rable	Inoperable V	
Roofing: S	ama as hausa	orstops Needs	adjusting	Does not operate	Recommend
Comment:	ame as house	Asphalt Rol	roofing	Wood	Other
			/		
Siding: Sar	pears: Satisfactory	Marginal	Poor_	None_	
Condition:	me as house	Wood	Vinyl	Stucco	Masonry
Condition/comment_	ne as house	Vood Alum	inum	Vinyl	
	crete Gra	./			
			phalt	Dirt	
verhead door:	ears: Satisfactory V	Marginal			
	Wood		Masonite	Metal_\	Other
Service door: At	s: Satisfactory V	Marginal _ Poor	Recomm	mend priming & pa	inting inside & edges
entricitu Person	pears: Satisfactory	Marginal	Poor_	None_	_ /
ectricity Present:	Yes No	G.F.C.I. Protected:	Yes No	Operates:	
Re	verse polarity: Yes	No	Open ground	Yes	No_
	ı garage & living area)		Present	Missing _	
mments:					

				CHEN			
Countertops:	Appears: Satis	sfactory V	Marginal		Poor		
Cabinets:	Appears: Satis	factory	Marginal	Poor	Reco	ommend Repair	
Plumbing:	Faucet Leaks:	Yes	. /	Pipe Leaks:			
Walls & Ceilin	ng: Appears: Sa	atisfactory	Marginal	Poor	Temi	col cracks	
Hot Water Pre	esent: Yes V	No		Stains: Yes	. /	car cracks	ē.
Floor: Ap	pears: Satisfactory	M		_ Poor			
Туре:	Ceramic:			Woo			/
Appliances:	Disposal: Y		0	Operates:	Yes	" V	
D	Dishwasher: Y	./		Operates:		No No	1-011
Countert		. /					- LOHKIN
V			·	Operates: Operates:	Yes		
	Range: Y				A 3000	-	
Ex		. /		Operates:	Yes		
			1	Operates:	Yes		
	Other:			Operates:	Yes	No	
	Protected: Yes_	61-6		Operates:		No	
Open ground/reve	erse polarity within					No	
Open ground/reve	rse polarity within					No_L	
Open ground/reve	rse polarity within				hazard: Yes	No L	
Open ground/rever	erse polarity within	LAUN	DRY/UTI	Safety	pazard: Yes	No_ <u></u>	
Open ground/rever	rse polarity within	LAUN	DRY/UTI	Safety	EA KS: Yes	No L	
Open ground/rever Comments: Laundry sink: N	I/A Fat	LAUN sucet leaks: Yes _	DRY/UTI	Safety LITY AR Pipe leai ter present:	EA	No_ <u></u>	
Open ground/rever Comments: Laundry sink: N Cross connections: Room vented:	YesN	LAUN uucet leaks: Yes_ lone apparent: No No	DRY/UTI	Safety [LITY AR] Pipe leal ter present:	EA Yes Yes	No L	
Open ground/rever Comments: Laundry sink; N Cross connections; Room vented; Oryer vented; N	I/A Fai	LAUN ucet leaks: Yes _ lone apparent: No No Wall Ce	DRY/UTI Hot was	Safety LITY AR Pipe leai ter present:	EA KS: Yes Hook	No	
Open ground/rever Comments: Laundry sink; N Cross connections; Room vented; Oryer vented; N Electrical; Outle	YesN	LAUN Jucet leaks: Yes_ Jone apparent: No No Wall Ce Juster Oper	DRY/UTI Hot was of visible illing	Safety [LITY AR] Pipe leal ter present: Not vented Revers	EA KS: Yes Yes Looe e polarity	No	
Open ground/rever Comments:	Yes Notes within None Within	LAUN one apparent: No No Vall Ce vasher De	Hot was of visible ground yer w	Safety [LITY AR] Pipe leal ter present: Not vented Revers	EA KS: Yes Yes Looe e polarity Furnace	No	
Open ground/rever Comments: Laundry sink; N Cross connections: Room vented: Oryer vented: N Electrical: Outle Expoliance present: as Pipe: N/A_	YesN	LAUN one apparent:	Hot was pround	Safety [LITY AR] Pipe leal ter present: Not vented Revers	EA KS: Yes Yes Furnace p needed:	No	

BATHROOMS



BATHROOMS

SINKS (1) TUBS (2) SHOWERS (3) Bath (/2) N/A / Yes / Yes / No / N
Toilet: Bowl loose: Yes No Operates: Yes No
Cracked Bowl: Yes No Toilet leaks: Yes No
Shower/tub: Ceramic/Plastic Finerglass Other
Condition: Appears: Satisfactor Magtinal Poor
Caulk/grout needed: Yes Vo Where:
Drainage: Appears: SatisfactoryMarginal Poor Water pressure: Appears: Satisfactory Marginal Poor
Walls/Ceiling Comment:
Moisture Stains: Yes No
Outlets present: Yes No G.F.C.I. Protected: Yes No Operates: Yes No
Open ground/reverse polarity within 6' of water: Yes NoSafety Hazard: Yes No
Hot water present: Yes No Exhaust fan: Yes No Operates: Yes No Comments
SINKS (1) TUBS (2) SHOWERS (3) Bath (
Cracked Bowl: Yes No Toilet leaks: Yes No
Shower/tub: Ceramic/Plastic Fiberglass Other
Condition: Appears: Satisfactory Marginal Poor
Caulk/grout needed: Yes Where:
Drainage: Appears: SatisfactoryMarginal Poor Water pressure: Appears: Satisfactory Marginal Poor
Walls/Ceiling Comment:
Moisture Stains: Yes No
Outlets present: Yes No_ G.F.C.I. Protected: Yes No_ Operates: Yes No_
Open ground/reverse polarity within 6' of water: Yes No Safety Hazard: Yes No
Hot water present: Yes No Exhaust fan: Yes No Operates: Yes No
Page 3

ROOM(S)
Location LIVING MAIN ROOM
Wall girlar Poor Typical cracks Mold
Molistic Stains: Yes No
100
Heat Source present: Yes No Holes: None Doors Walls Cellings
Doors & Windows: N/A Appears: Satisfactory Marginal Poor Cracked glass
Comments
Location DINING
Walls & Ceilings: Appears: Satisfactory Marginal Poor Typical cracks Mold
Flooring: Appears: Satisfactory Marginal Poor Moisture stains: Yes No
Electrical Switches: Yes No Outlets: Yes No
Heat Source present: Yes No Holes: None Doors Walls Ceilings
Doors & Windows: N/A Appears: Satisfactory Marginal Poor Cracked glass
Comments
Location DINETTE AREA N/A
Walls & Ceilings: Appears: Satisfactory Marginal Poor Typical cracks Mold
Flooring: Appears: Satisfactory Marginal Poor Moisture stains: Yes No
Electrical Switches: Yes No Outlets: Yes No No
Heat Source present: Yes No Holes: None Doors Walls Ceilings
Doors & Windows: N/A Appears: Satisfactory Marginal Poor Cracked glass
Comments Cracked glass

Location FAMILY N/A
Walls & Ceilings: Appears: Satisfactory Marginal Poor Typical cracks Mold
Flooring: Appears: Satisfactory Marginal Poor Moisture stains: Yes No
Electrical Switches: Yes No Outlets: N/A Yes No
Heat Source present: Yes No Holes: None Doors Walls Ceilings
Doors & Windows: N/A Appears: Satisfactory Marginal Poor Cracked glass
Comments
Page 14
F 02C 14

	ROOMS
Location MASTER BEDROOM	
Walls & Ceilings: Appears: Satisfactory	Marginal Pool Typical cracks Mold
Flooring: Appears: Satisfactory	Marginal Poor Moisture stains: Yes No
Electrical Switches: YesNo	Outlets; Yes No
Heat Source present: YesNo	Holes: None Doors Walls Ceilings
Doors & Windows: Appears: Satisfactory	Marginal Poor Cracked glass
Comments	S. HUNDO & IGOO
Location BEDROOM TWO F	00WT
Walls & Ceilings: Appears: Satisfactory	
	Marginal Poor Typical cracks Moid
Electrical Switches: Yes	Marginal Poor Moisture stains: Yes No
	Outlets: Yes No
Doors & Windows: Appears: Satisfactory \(\bu\)	Holes: None Doors Walls Ceilings
Comments	Marginal Poor Cracked glass

Location BEDROOM THREE	BACK
Walls & Ceilings: Appears: Satisfactory	Marginal Poor Typical cracks Mold
	Marginal Poor Moisture stains: Yes No
Rectrical Switches: Yes No	Outlets: Yes No
leat Source present: YesNo	Holes: None Doors Walls Ceilings
	Marginal Poor Cracked glass
omments	
ocation Shd	W -
/alls & Ceilings: Appears: Satisfactory	Marginal Poor Typical cracks Mold
ooring: Appears: Satisfactory	
ectrical Switches: Yes No	No
rat Source present: Yes No	Outlets: YesNo
ors & Windows: Appears: Satisfactory	Holes: None Doors Walls Ceilings
mments	Marginal Poor Cracked glass

Windows
General Condition: Appears: Satisfactory Marginal Poor Cracked glass
Representative number of windows operated: 10 Hardware Missing: Olazing compound needed
Fireplace None: Location #1 De N Locations #2 Location #3
Gas Wood
Blower Built-in: Yes No Operates: Yes No Damper operates Damper missing
Any open joints or cracks in firebrick should be sealed. Hearth: Appears Adequate: Yes No
Mantle: Appears: Adequate: Yes No Recommend having flu cleaned & re-examined Yes
Inside Stairs None None
Condition: Appear: Satisfactory Marginal Poor Handrails: Appear: Satisfactory Marginal Poor
Riser/Treads: Appear: Satisfactory Marginal Poor Risers uneven
Smoke Detectors Present: Yes No Operates: Yes No Not tested
Attic Access: Stairs Pulldown Scuttlehole Other No access
Inspected from: Access panel In the attic Other
Location: Bedroom hall Bedroom along
Flooring: Complete Partial None
Insulation: Fiberglass: Batts Loose None Average inches 8 to 10
Installed in: Floor Rafters Walls
Roof Sheathing: Rotted Delaminated Appears Satisfactory
Evidence of condensation: Yes None Apparent Fans exhausted to attic: Yes No
Structural problems observed: YesNone Apparent
Roof Structure: Rafters: Wood Metal Other
Trusses Others Collar ties present: Yes No.
Sheathing: Plywood Flakeboard Wood Ix Other
Certing Joist: Wood Other Not visible
Vapor barriers: Not visible Improperly installed None
Kraft faced Plastic
Comments:

Crawl Space/Slab on Grade
Slab on Grade N/A Not visible Signs of settlement: Yes No
Crawl space No access
Access Exterior Interior door hatch Did not access at request of buyer
Inspected from: Access panel In the crawl space
Foundation Concrete block Foured concrete Brick Other
Piers & Columns Cracks Have evaluated
Floor Dirt Concrete Gravel Other Typical cracks
Ventilation Wall vents Power vents None apparent
The apparent
Girder Steel Wood Block Not visible
Columns Condition: Appears Satisfactory Marginal Poor
Joist Not visible Wood Steel Other
2x8 2x10 2x12 Other
Sub Floor Not visible Wood Concrete Other
Moisture Stains None Walls Sub Floor Other
Insulation None Walls Ceiling Other Not Visible
Vapor Barrier Yes No Not Visible
Type: Kraft face Plastic
Crawl Space Walls
tartial VAPOR
Partial VAP OR North BArrier - North
South
Page)*

Plumbing
Water Service Water Supply: City Private Meter Location
Water Lines: Copper Galvanized /Plastic Unknown
Lead (other than solder joints): Yes No Service entry Unknown
Water Pressure: Appears; Adequate Poor
Pipes: Corroded Leaking Valves broken/missing Supported/Insulated
Drain, Waste & Vent pipe: Copper Cast Iron Plastic Other
Condition: Appears: Satisfactory Marginal Poor Waste discharge: Appears: Satisfactory Slow drain Not tested
Comments:
Water Heater #1 Brand Name: A.O. Smith Serial #: MSOZ-195/202-917
Gas Electric Other Capacity 50 gals. Approximate age / 6 YTAPS
Relief Valve: Yes No Extension proper Yes No Missing Other Vent Pipe: NA Appears Satisfactory Pitch proper Rusted Other
Comments:
Water Heater #2 N/A
Brand Name: Serial #:
Gas Electric Other Capacitygals. Approximate age
Relief Valve: Yes No Extension proper: Yes No Missing
Vent Pipe: N/A Appears Satisfactory Pitch proper Rusted Other
Comments:
Water Softener Unit not evaluated
Plumbing hooked up: Yes No
A number of fixtures, faucets, hose bibs, and drains were tested and found to be:
Sat Marginal Poor
Recommend a licensed plumber evaluate the plumbing
Comments:

HEATING SYSTEM Forced Air System System not operated due to: Energy Source Heat Strip Aux. Geothermal Emergency Heat Tested: Yes Distribution Cold Air Returns Other Filter Standard Other Condition: Replace/Clean Operated When turned on by thermostat Operation Controls Normal Operating & Safety Controls Observed Comments Others Gas Space Heater Ceiling Heat Comments Forced Air System Model # Central Air Gas Chiller Operated Not operated due to outside temperature Distribution Metal Duct Flex Duct Operation Recommend HVAC Technician Examine NO Refrigerant Lines Leak Damaged Insulation Missing Supply

Return

Main Panel	Loc Landry Room Electrical	
		pears Grounded: Yes No_
Main Wire	GFCI Present: Yes No Ope	rates: YesNo
Branch Wire	Copper Not Visible	-
	Romex BX Cable Conduit Oth	ners
-	Panel Not assessable Not evaluated Rea	son
Sub Panels/D	isconnect None Apparent	
	Loc Loc Loc	
Branch Wiring	Panel Not Assessable Not evaluated Reast Copper Aluminum	son
A representative were tested and f	number of installed lighting fixtures, switches and receptacles located ound to be:	inside the house, garage, and exterior
	Marginal Poor	
13.00		
Open Gr	ounds Reverse Polarity Other	
Open Gr		

Go Bid Now!

www.WeeksAuctionGroup.com