

SENTRICON ANNUAL INSPECTION 6/6/2019 0 Min.	Route: 506 Prod Value: \$0.00 Measure: 0 Started: 6/1/2006 Last Serv: 6/7/2018 Next:	@793976S@ Record: 793976 Account: 10381 Service
--	--	---

SERVICE INFORMATION
HAROLD HAYES
 602 ERNEST ST
 THOMASVILLE, GA 31792
 Home: 229-226-7810
 Work: 229-224-4972
 Subdivision:
 Map Code:

INSTRUCTIONS
 (BMP)
 CRAWL - PCO: 175371 -

ENTERED JUN 25 -

BILLING INFORMATION
 HAROLD HAYES
 P.O. BOX 3396
 THOMASVILLE, GA 31799

Balance as of 5/30/2019	\$0.00
Amount due for this service:	\$0.00
Total Due:	\$0.00
Total w/ additions:	

Amount Paid: _____
 Payment Type: _____
 Number: _____
 Exp. Date: _____

Astro Pest Control Services of Thomasville, Inc. 14576 U.S. Hwy 19 S • Thomasville, GA 31757 229-226-2414	<p style="text-align:center;"><i>Renewal Inspection/Monitoring</i></p> <p>The Georgia Structural Pest Control Act requires all pest control companies to maintain insurance coverage. Information about this coverage is available from this pest control company.</p>
--	--

BAITING SYSTEM	ANNUAL INSPECTION
-----------------------	--------------------------

___ Stations Added
 ___ Recruit IV Noviflumuron .5% EPA# 62719-453
 62 grams each
 ___ Recruit HD Noviflumuron .5% EPA# 62719-608
 150 grams each
 Method of Application Placement

Stations Baited	Precautionary Statement
	Hazards to Humans and Domestic Animals Do not tamper with bait material.

No Active Infestation Found
 ___ Termite Activity Found Treatment to be Scheduled
 ___ Outside Inspection Complete. Please call our Office to Schedule an Inside Inspection.
 ___ Today we observed the condition(s) circled below

Comments _____
 ___ Slab Crawl
 Time In 12:30 AM/PM Time Out 2:57 AM/PM Date 6/24/2018
 Technician R. Skuberski Customer [Signature]
5P13403

CONDITIONS CONDUCIVE FOR TERMITE INFESTATION

- | | | |
|---|---|------------------------------------|
| 1. Firewood next to foundation | 5. Standing water near / under structure | 9. Wood siding within 6" of soil |
| 2. Debris in crawl space / next to foundation | 6. Moisture problem under structure | 10. Inaccessible crawl area |
| 3. Landscape timbers / mulch around house | 7. Wet wood / damaged due to water / fungus | 11. Porch(es) inaccessible |
| 4. Wood-to-soil contact | 8. Insufficient ventilation | 12. Soil above the foundation line |

COLSON PRINTING COMPANY - 53875