

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/24/20 at 6:21:30 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History	🍰 Owner 1	Sowner 2
Year purchased	2014	2017
Type of owner	Personal lease	Personal
Estimated length of ownership	2 yrs. 7 mo.	3 yrs. 6 mo.
Owned in the following states/provinces	New York, Pennsylvania	Pennsylvania
Estimated miles driven per year	19,221/yr	7,557/yr
Last reported odometer reading	50,965	70,510

CARFAX Title History CARFAX guarantees the Information in this section	🍰 Owner 1	🚨 Owner 2
Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<b>Guaranteed</b> No Problem	Guaranteed No Problem
Not Actual Mileage   Exceeds Mechanical Limits	Guaranteed No Problem	Guaranteed No Problem



**GUARANTEED** - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. Register | View Terms | View Certificate



11/2	4/2020 CARFAX Vehicle History Report for this 2015 GM	YUKON	XL K1500 SLT: 1GKS	2HKC9FF	227026
	CARFAX recommends that you have this vehicle inspected by a collision repair specialist.		Reported	UTRAFFIC	Reported
	Airbag Deployment No airbag deployment reported to CARFAX.		No Issues Reported	V	No Issues Reported
	Odometer Check No indication of an odometer rollback.	<b>V</b>	No Issues Indicated	~	No Issues Indicated
	Accident / Damage Damage reported on 02/20/2019.		No Issues Reported		Minor Damage
	Manufacturer Recall At least 1 manufacturer recall requires service. Check for open recalls or schedule dealer service on GM vehicles at <u>recalls.gm.com</u> .		No Recalls Reported		Recall Reported
	Basic Warranty Original warranty estimated to have expired.	v	arranty Expired	١	Warranty Expired

CARFAX Detailed History

Owne Purcha	e <b>r 1</b> sed: 2014		Personal Lease Vehicle 19,221 mi/yr
Date	Mileage	Source	Comments
Original Equipment	ni manja ili ka na kika ga na aka na ka na ka Na ka na k	OnStar	Vehicle equipped with OnStar Get 3 free months of premium OnStar with Automatic Crash Response, Roadside Assistance and Remote Door Unlock by pressing the blue OnStar button Learn more
07/04/2014	1	Knight Automotive, Inc. Plattsburgh, NY 518-563-2000 knightauto.com	Vehicle offered for sale
07/07/2014	2	Knight Automotive, Inc. Plattsburgh, NY 518-563-2000 knightauto.com	Vehicle serviced - Pre-delivery inspection completed - Fluids checked - Safety inspection performed
08/27/2014	3	Knight Automotive, Inc. Plattsburgh, NY 518-563-2000 knightauto.com	Vehicle sold
08/28/2014	284	Vail Buick GMC Trucks Bedford Hills, NY 914-666-7537 vailbuickgmc.com	Vehicle offered for sale

11/24/2020 09/10/2014		CARFAX Vehicle History Report for this 20 Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	015 GMC YUKON XL K1500 SLT: 1GKS2HKC9FR227026 Vehicle offered for sale
09/11/2014		Vail Buick GMC Trucks Bedford Hills, NY 914-666-7537 vailbuickgmc.com	Vehicle sold
09/13/2014	313	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle serviced - Pre-delivery inspection completed - Roof rack rails installed - Roof rack installed
09/16/2014	326	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle sold
09/18/2014		New York Motor Vehicle Dept. Brewster, NY	Registration issued or renewed - Titled or registered as personal lease vehicle - Passed safety inspection
10/03/2014	2,240	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle serviced - Key(s) (re) programmed
10/09/2014		New York Motor Vehicle Dept. Minneapolis, MN	<b>Title issued or updated</b> - First owner reported - Titled or registered as personal lease vehicle - Loan or lien reported
		CAR	Two states? Vehicle leasing companies often title a car in one state but register it to be driven in another.
10/13/2014	2,604	New York Inspection Station	Passed safety inspection - Passed emissions inspection View what was inspected
12/31/2014	5,363	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated - A/C refrigerant recharged

https://www.carfax.com/showroom/reports/?vin=1GKS2HKC9FR227026

CARFAX Vehicle History Report for this 2015 GMC YUKON XL K1500 SLT: 1GKS2HKC9FR227026

24/2020	CARFAX Vehicle History Report for this 20	15 GMC YUKON XL K1500 SLT: 1GKS2HKC9FR227026
06/24/2015 11,725	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
09/29/2015 16,747	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
10/22/2015 19,706	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle serviced - Maintenance inspection completed - Back-up camera installed - Transfer module/computer reprogrammed
10/31/2015 20,029	New York Inspection Station	Passed safety inspection - Emissions inspection performed View what was inspected
12/11/2015 22,972	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
02/18/2016 25,546	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle serviced - Alignment performed
03/14/2016 27,835	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle serviced - Body computer/module replaced
04/06/2016 30,316	Ingersoll Auto of Danbury Danbury, CT 203-730-5766 ingersollauto.com	Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed - Maintenance reminder reset - Tire condition and pressure checked - Tires rotated - Tire pressure monitoring system reset
08/10/2016 37,390	Valvoline Instant Oil Change	Vehicle serviced

https://www.carfax.com/showroom/reports/?vin=1GKS2HKC9FR227026

11/24/2020 CARFAX Vehicle History Report for this 2015 GMC YUKON XL K1500 SLT: 1GKS2HKC9FR227026 🔬 - Oil and filter changed Concord, NH 603-228-3757 - Air filter replaced - Rear differential fluid flushed/changed - Front differential fluid flushed/changed vioc.com 4.6 / 5.0 - Fuel injection system checked 91 Verified Reviews 244 Customer Favorites 09/08/2016 New York Registration issued or renewed Motor Vehicle Dept. - Titled or registered as personal lease vehicle Brewster, NY - Passed safety inspection 09/30/2016 39,992 New York Passed safety inspection Inspection Station - Emissions inspection performed View what was inspected 12/12/2016 43.738 Ingersoll Auto of Danbury Vehicle serviced Danbury, CT 203-730-5766 ingersollauto.com 4.8 / 5.0 144 Verified Reviews 214 Customer Favorites 05/09/2017 50,766 Vehicle sold Auto Auction Millions of used vehicles are bought and sold at auction every year. 05/10/2017 **Dealer Inventory** Vehicle offered for sale 05/12/2017 50,965 **Inspection Station** Passed emissions inspection 05/18/2017 Pennsylvania Title issued or updated Motor Vehicle Dept. - Dealer took title of this vehicle while it was in Montgomeryville, PA inventory Title #7753403001 LA **Personal Vehicle Owner 2** Low mileage! This owner drove less than 7,557 mi/yr Purchased: 2017 the industry average of 15,000 miles per year. Date Mileage Source Comments 05/24/2017 Pennsylvania Vehicle purchase reported Motor Vehicle Dept. 05/31/2017 Title issued or updated Pennsylvania Motor Vehicle Dept. - New owner reported

> Vehicle serviced - Oil and filter changed

54,628

08/28/2017

Chalfont, PA

Colmar, PA

215-996-4281

3.212

Title #7753403002 MC

354 Verified Reviews

Customer

Favorites

All Star Express Lube

01/23/2018		Marcos Auto, Inc. North Wales, PA 215-628-9580 https://facebook.com/marcos- auto-423979667696483/	015 GMC YUKON XL K1500 SLT: 1GKS2HKC9FR227026 Vehicle serviced - Ignition coil(s) replaced - Spark plug(s) replaced
02/21/2018		Pennsylvania Motor Vehicle Dept. Chalfont, PA Title #7753403002 MC	Registration issued or renewed
08/16/2018	62,833	Yvon's Valvoline Express Care Lewiston, ME 207-777-3600 yvonsvalvolineexpresscare.com/ 25 Verified Reviews 42 Customer Favorites	Vehicle serviced - Recommended maintenance performed - Maintenance inspection completed - Oil and filter changed - Fluids checked
09/10/2018	63,676	Inspection Station	Passed emissions inspection
02/20/2019		Damage Report	Damage reported: minor damage - Damage to front Damage Severity Scale (i)
	~	CAR	Damage Location FRONT
			REAR Minor damage is usually cosmetic, including dents or scratches to the vehicle body.
09/06/2019		General Motors	Manufacturer Safety recall issued - Recall #N192268490 - INCREASED BRAKE PEDAL EFFORT

# CARFAX Vehicle History Report for this 2015 GMC YUKON XL K1500 SLT: 1GKS2HKC9FR227026

**Description:** General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2014-2018 model year Cadillac Escalade, Chevrolet Silverado, Chevrolet Suburban, Chevrolet Tahoe, GMC Sierra, and GMC Yukon vehicles. In some circumstances, these vehicle may have a condition in which the engine-mounted mechanical vacuum pump output may decrease over time, decreasing the amount of vacuum/power brake assist.

**Remedy:** Dealers will reprogram the electronic brake control module with a new calibration that will improve how the system utilizes the hydraulic brake boost assist function when vacuum assist is depleted.

09/19/2019	70,283	Inspection Station	Passed emissions inspection
09/20/2019		Bucks County Auto Care Dublin, PA 215-249-1977 buckscoautocare.com	Vehicle serviced - Safety inspection performed - Tires rotated - Tire condition and pressure checked - Emissions inspection performed - Emissions or safety inspection performed
10/04/2019	70,510	Bucks County Auto Care Dublin, PA 215-249-1977 buckscoautocare.com total 5.0 / 5.0 21 Verified Reviews 26 Customer Favorites	Vehicle serviced - Oil and filter changed - Fluids checked - Tire condition and pressure checked - Body lubricated
10/01/0010		General Motors	Manufacturer Safety recall issued
10/24/2019			- NHTSA #19V761 - Recall #N192261050 - UNEXPECTED PULL TO ONE SIDE - Status: Remedy Available
10/24/2019			- Recall #N192261050 - UNEXPECTED PULL TO ONE SIDE
Description: model year ( 3.08-ratio re with four-wh software err system to a the vehicle is experience to If a wheel-sp	Chevrolet Si ar axle, and eel drive, a or in the vel ctivate wher s driven bet unintended l peed sensor	Iverado and GMC Sierra 1500 vehicles certain 2015 2020 model year Chevro 5.3-liter engine, and a 3.08-ratio rear a nicles electronic-brake control module n (i) the vehicles electronic transfer ca ween the speeds of 41 and 60 MPH. If braking on the wheel on the opposite s	<ul> <li>Recall #N192261050</li> <li>UNEXPECTED PULL TO ONE SIDE</li> <li>Status: Remedy Available</li> <li>Locate an authorized General Motors dealer to obtain more information about this recall.</li> <li>Learn more about this recall</li> </ul> relates to motor vehicle safety exists in certain 2014 201 equipped with four-wheel drive, a 5.3-liter engine, and a let Suburban, Chevrolet Tahoe, and GMC Yukon equipped xile. If a wheel-speed sensor fails in these vehicles, a (EBCM) can cause the vehicles driveline-protection se is set to four-wheel drive or automatic mode, and (ii) the driveline-protection system activates, the driver will side of the failed sensor. Control (ESC) and Anti-Lock Braking System (ABS)
Description: model year ( 3.08-ratio re with four-wh software err system to ac the vehicle is experience to If a wheel-sp malfunction StabiliTrak n MPH, uninte Owners can	Chevrolet Si ar axle, and leel drive, a or in the vel ctivate wher s driven bet unintended l beed sensor indicator w nessage. If nded brakin eliminate th	Iverado and GMC Sierra 1500 vehicles certain 2015 2020 model year Chevro 5.3-liter engine, and a 3.08-ratio rear a nicles electronic-brake control module n (i) the vehicles electronic transfer ca ween the speeds of 41 and 60 MPH. If oraking on the wheel on the opposite s fails, the vehicles Electronic Stability arning lamps will illuminate and the ve- these vehicles are driven in this condit of on one wheel can occur, causing the	<ul> <li>Recall #N192261050</li> <li>UNEXPECTED PULL TO ONE SIDE</li> <li>Status: Remedy Available</li> <li>Locate an authorized General Motors dealer to obtain more information about this recall.</li> <li>Learn more about this recall</li> <li>relates to motor vehicle safety exists in certain 2014 201 equipped with four-wheel drive, a 5.3-liter engine, and a let Suburban, Chevrolet Tahoe, and GMC Yukon equipped xile. If a wheel-speed sensor fails in these vehicles, a (EBCM) can cause the vehicles driveline-protection se is set to four-wheel drive or automatic mode, and (ii) the driveline-protection system activates, the driver will die of the failed sensor.</li> <li>Control (ESC) and Anti-Lock Braking System (ABS) shicles driver information center will display a Service ion while in four-wheel drive or automatic mode at 41-60 evenicle to pull to one side, increasing the risk of a crash wheel-drive mode until the recall repair is performed.</li> </ul>
Description: model year ( 3.08-ratio re with four-wh software err system to ac the vehicle is experience to If a wheel-sp malfunction StabiliTrak n MPH, uninte Owners can	Chevrolet Si ar axle, and leel drive, a or in the vel ctivate wher s driven bet unintended l beed sensor indicator w nessage. If nded brakin eliminate th	Iverado and GMC Sierra 1500 vehicles certain 2015 2020 model year Chevro 5.3-liter engine, and a 3.08-ratio rear a nicles electronic-brake control module n (i) the vehicles electronic transfer ca ween the speeds of 41 and 60 MPH. If oraking on the wheel on the opposite s fails, the vehicles Electronic Stability arning lamps will illuminate and the ve- these vehicles are driven in this condit on one wheel can occur, causing the is risk by operating the vehicle in two-	<ul> <li>Recall #N192261050</li> <li>UNEXPECTED PULL TO ONE SIDE</li> <li>Status: Remedy Available</li> <li>Locate an authorized General Motors dealer to obtain more information about this recall.</li> <li>Learn more about this recall</li> <li>relates to motor vehicle safety exists in certain 2014 201 equipped with four-wheel drive, a 5.3-liter engine, and a let Suburban, Chevrolet Tahoe, and GMC Yukon equipper xle. If a wheel-speed sensor fails in these vehicles, a (EBCM) can cause the vehicles driveline-protection se is set to four-wheel drive or automatic mode, and (ii) the driveline-protection system activates, the driver will die of the failed sensor.</li> <li>Control (ESC) and Anti-Lock Braking System (ABS) shicles driver information center will display a Service ion while in four-wheel drive or automatic mode at 41-60 evenicle to pull to one side, increasing the risk of a crash wheel-drive mode until the recall repair is performed.</li> </ul>
Description: model year ( 3.08-ratio re with four-wh software err system to ac the vehicle is experience to If a wheel-sp malfunction StabiliTrak n MPH, uninte Owners can	Chevrolet Si ar axle, and leel drive, a or in the vel ctivate wher s driven bet unintended l beed sensor indicator w nessage. If nded brakin eliminate th	Iverado and GMC Sierra 1500 vehicles certain 2015 2020 model year Chevro 5.3-liter engine, and a 3.08-ratio rear a nicles electronic-brake control module n (i) the vehicles electronic transfer ca ween the speeds of 41 and 60 MPH. If oraking on the wheel on the opposite s fails, the vehicles Electronic Stability arning lamps will illuminate and the ve- these vehicles are driven in this condit on one wheel can occur, causing the is risk by operating the vehicle in two-	<ul> <li>Recall #N192261050</li> <li>UNEXPECTED PULL TO ONE SIDE</li> <li>Status: Remedy Available</li> <li>Locate an authorized General Motors dealer to obtain more information about this recall.</li> <li>Learn more about this recall</li> <li>relates to motor vehicle safety exists in certain 2014 201 equipped with four-wheel drive, a 5.3-liter engine, and a let Suburban, Chevrolet Tahoe, and GMC Yukon equippe xle. If a wheel-speed sensor fails in these vehicles, a (EBCM) can cause the vehicles driveline-protection se is set to four-wheel drive or automatic mode, and (ii) the driveline-protection system activates, the driver will ide of the failed sensor.</li> <li>Control (ESC) and Anti-Lock Braking System (ABS) shicles driver information center will display a Service ion while in four-wheel drive or automatic mode at 41-60 evenicle to pull to one side, increasing the risk of a crast wheel-drive mode until the recall repair is performed.</li> </ul>



## **Damage Indicator**

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

 This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/24/20 at 6:21:30 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### **Damage Severity**

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's
  operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

#### **First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

# Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

# **New Owner Reported**

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

## **Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

## **Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

C







About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2020 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved. 11/24/20 6:21:30 PM (CST)