Wood Destroying Insect Inspection Report	Notice: Please read impor	rtant consun	ner information on page 2.
Section I. General Information Inspection Company, Address & Phone	Company's Pest Control Business Lic. No. Date of Inspection BU7276 1/10/2025		
Raifsnider's Exterminating LLC			1/10/2025
131 East Broad St	Address of Property Inspected		
Souderton, PA 18964	6 Reeceville Road		
Coatesville, PA			
Inspector's Name, Signature & Certification, Registration, or Lic. #		Structure(s) Ir	nspected
Eric Raifsnider 707550 Eric Raif	sniaer	awe	lling only
Section II. Inspection Findings This report is indicative of the not to be construed as a guarantee or warranty against latent, concealed, or inspection of the readily accessible areas of the structure(s) inspected	future infestations or wood de		
A. No Visible evidence of wood destroying insects was observed.			
B. Visible evidence of wood destroying insects was observed as follow	rs:		
1. Live insects (description & location):			
right? Pead insects insect parts frass shelter tubes exit holes or sta	ining (description and location	n). Tern	nite shelter tubes/
right front area of baement/wood boring	exit holes throu	ghout	basement beams
<u>& subfloor</u>	71 12 11		
3. Visible damage from wood destroying insects was noted as followed basement beams & subfloor through	ows (description and location Nout	ı):	
	see attache	d grapł	ו
NOTE: This is not a structural damage report. If box B above is check	ed, it should be understoo	d that some	e degree of damage, including hidden
damage, may be present. If any questions arise regarding damage indicate	5	ended that th	e buyer or any interested parties contact
a qualified structural professional to determine the extent of damage and the	need for repairs.		
Section III. Recommendations			
☐ No action and/or treatment recommended: (Explain if Box B in Section	II is checked):		
Recommend action(s) and/or treatment(s) for the control of:	mites & Wood B	oring B	eetles
Heconimena action(s) and/or treatment(s) for the control or.			
Section IV. Obstructions and Inaccessible Areas		Th	e inspector may write out obstructions
The following areas of the structure(s) inspected were obstructed or inaccess	sible:		use the following optional key:
X Basement 24		1000	Fixed ceiling 15. Standing water
Crawlspace			Suspended ceiling 16. Dense vegetation 17. Exterior siding
X Main Level 1, 3, 4, 6, 11, 24 X Attic 11, 13		1000	Floor covering 18. Window well covers Insulation 19. Wood pile
X Attic 11, 13		6.	Cabinets or shelving 20. Snow
Garage			Stored items 21. Unsafe conditions Furnishings 22. Rigid foam board
x Exterior stone		9.	Appliances 23. Synthetic stucco
Porch		12.52	No access or entry 24. Duct work, wiring, Limited access and/or plumbing
Addition			No access beneath 25. Spray foam
Other	13. Only visual access insulation 14. Cluttered condition 26. Equipment		
O-M-V Additional O-M-V			
Section V. Additional Comments and Attachments (these	are an integral part of the rep	oort)	
Please see attached	page two		
	1 - 3		
Attachments			
Signature of Seller(s) or Owner(s) if refinancing. Seller discloses to the	Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.		
buyer all information, to their knowledge, regarding W.D.I. infestation, damage repair, and treatment history.	, copy of both page 1 and p		

Form NPMA-33 (7/01/19) © 2019 National Pest Management Association. All Rights Reserved. No reproduction of this form is permitted without the express permission of NPMA. Previous editions are obsolete after 12/31/19. This form is approved for FHA and VA loans.

Reorder Product #3358 from • CROWNMAX • 1-800-252-4011

Page 1 of 2