Green Earth Consulting Machesney Park IL 61115 815-520-3432

May 1st, 2019

Rich Ranft Beloit Auction & Realty Inc.

Re: 15052 White School Rd, South Beloit, IL 61080

Dear Mr. Ranft,

As you requested, the sewage disposal and potable water systems at the above address, were evaluated on April 29th, 2019.

A shock load test was conducted on the sewage disposal system and found the system <u>flowing and functioning normally</u> at that time. This test, however, in no way warrants the system will continue to perform properly. Tank additives, which claim to enhance septic tank function, do NOT remove the need for periodic pumping. Generally, a septic serving a year-round resident should be pumped every two or three years and the baffles inspected at that time.

During the course of the evaluation, I made a review of the potable water system that consisted of a drilled well located in front of the home. There were no obvious mechanical defects and the system appears to be in good working condition at this time. I did observe that the PVC well cap bracket was cracked and requires replacement (see photo). The pressure switch was turning on & off too rapidly. Contact an Illinois licensed well driller to evaluate the well further and to make necessary repairs. In addition, a water sample was collected. In addition, a water sample was collected. The results indicate that the water was <u>negative</u> for coliform bacteria and is considered satisfactory. The nitrate-nitrogen content in the water sample was 3.3 mg/L as Nitrogen, <u>below the action level</u> of 10 mg/L.

In closing, the scope of this inspection was limited to the well & private sewage disposal system serving this property. Furthermore, this inspection in no way warrants or guarantees that the well & private sewage disposal system will continue to operate satisfactory in the near or present future.

If you have any questions, please do not hesitate in giving me a call.

Sincerely,

Chris R. Schuler

Chris R. Schuler BS, Licensed Environmental Health Practitioner License # 183-000558

779-348-7	Illinois 61102	Rockford Water Division Environmental Laboratory B. Facility Name:							Coliform Analysis Report			
C. Sampling Period:									APR 29 pm 6:44 🛛 🥲			
							me Set Up:			ADD 00 0100 10		
Samples must reach laboratory within 30 hours after collection Items A-E & 1-6 must be completed or sample may be discarded. Date/Til						me Rea		MAY 1 PM 1:17 8				
1. Mail Water Supply Copy To:						3. Date Collected: 04/29/19						
Chris Schuler						4. Sample Collector:						
Address:						Chirs Schuler						
P.O. Box 2252 City:						5. Sample Purpose: Routine						
City.	Loves Park					Replacement Invalid Replacement Repeat Non-Community Follow-Up New Construction						
2. Contact for Unsatisfactory Results:						Original Lab Sample No						
Name: Phone:						Boil Order Repair		Other:	Mai	ntenan		
chris.schuler1@gmail.com 815.520.3432 New Construction Permit No.												
6. Col	iform Sampling:						7.	8.	9.	10.	11.	
Bottle#	Sample Site#	or Address		Sample Type	Time Collected	Res. Cl. F or T	Col Read	Total Coli	Fecal/ Ecoli	Opin	Laboratory Sample No.	
1	15052 White Sc	chool Rd		Bacti.	5 ^{:30} PM			X	A	S	C191019	
2	South Beloit, IL	61080										
3		3.3 p	PM	NOZ								
4				,,								
5								-				
6												
7												
8												
9												
10												
11												
12												
Method:	Membrane Filter Rea	adycult X			Person Notifie							
Analyst:	Ach			Legen P = Pr		Jon		Reason fo	or Replace	ment:		
Lab Cert.	A = Not Present S = Satisfactory U = Unsatisfactory				Samples more than 30 hours old No Date/Time of Collection							
				Other:								