

Inspection, Repair & Maintenance Record

1100 Dec Dot

VEHICLE IDENTIFICATION

| | |
|---------------------------|------------------|
| MAKE | SERIAL NUMBER |
| YEAR | TIRE SIZE |
| COMPANY NUMBER/OTHER I.D. | OWNER, IF LEASED |

| DATE | OPERATION PERFORMED, INSPECTION AND/OR REPAIR |
|----------|---|
| 6-29-12 | Ind DSI Replaced window Crank + Left Mirror Supports |
| 7-5-12 | Ind DSI Full Serv & Fix Leak at Power Divided |
| 7-19-12 | Ind DSI Fixed Drivers Door & Window |
| 7-23-12 | Ind DSI Replaced Drivers Door & A/C comp |
| 7-30-12 | Rthm Kenworth Fixed Hood that Temp Driver Backed into 3519.05 |
| 9-20-12 | <p>PM serv. WO# 19673. Replaced Both wipers, Replaced Driver side washer nozzle, Put Aluminum Plate around Park Brake controls, New Chrome Nut covers. New Mason's Replaced ALL Tires. B16 LP 22.5 on Drives Firestone S20 on steers. LEFT IN 2 Right IN 6 WT&T Replaced Dryer Filter Adg 5th wheel OUT 8 Adg Toe - Brake Job Rear Axle OUT 7</p> |
| 10-12-12 | Ind DSI Replaced wiper Motor |
| 12-13-12 | <p>PM wo# 20136 cb antenna, + fixed LH cb antenna cord. battery cables, + batteries, grounds, clamps. 5th wheel lube. WT&T Dored Replaced Both King Pins + Cold For Block + Fuel Heater + Power Steering hose Pass side</p> |
| 1-7-13 | 2nd DSI Replaced Clutch |
| 2-27-13 | <p>PM wo# 20589 taillight, chrome, tightened hood strap on rh side. tightened rh side mirror. WT&T Replaced Hood Cable + RR Air Bag + Block + Fuel Heater Cords</p> |
| 2-14-13 | Ind DSI Adg steer Brakes, LK Clutch Adg, LK steering & Test Block Hatch |
| 2-15-13 | Ind DSI Replaced Power steering Filter + Oil + Both Hoses |
| 3-4-13 | Ind DSI Replaced Air Governor + Freed up Throttle Pedal |
| 5-23-13 | <p>✓ 32nd's Pressure, Lug nuts, wipers, Replaced RH Fog Lamp Glass Head Seal wiper Blades, Lube Test Batteries, 2 L Lubes, A lot of corrosion. Clean & Seal Air cable ends lube doors, A and B Valve Noal Vines WT&T Replaced 1 steer shock Left</p> |
| 6-4-13 | <p>Ind DSI Fixed Cab lite, Tail lite, Replaced Over Guard Pin + Added Hub Oil - Replaced Mudd Flap + Cleaned 5th wheel Fix Air Leak Buy Left Steer + Buy Cab leveling Valve + Replaced Left Spot Mirror</p> |
| 6-12-13 | |
| 6-20-13 | |

Tires
9/19/14



wo# 21146

Dec
~~September~~
 1/00 ~~get~~ DOT

Inspection, Repair & Maintenance Record

VEHICLE IDENTIFICATION

| | |
|---------------------------|------------------|
| MAKE | SERIAL NUMBER |
| YEAR | TIRE SIZE |
| COMPANY NUMBER/OTHER I.D. | OWNER, IF LEASED |

| DATE | OPERATION PERFORMED, INSPECTION AND/OR REPAIR |
|------------|---|
| 9-28-2010 | PM Service Jverts WO# 16726. Replaced L high beam, driver side STEELER Belt in bug deflector, both wiper blades, 1/4" hose for 5th wheel cylinder. NEW BATTERY WELDED DEER GUARD. Fixed fog light. PAINTED wheels. ck'd Fuel & block heater, put 120 volt heater on fuel heater, ck'd brake strokes, D etc |
| 11-23-2010 | PM Service Jverts WO# 16705 Heartland Tire replaced All 8 drives w/ 22.5LP 558 drive caps replaced both Steer Tires 22.5LP SP 384 Altern Rims (L-602 R-1402 828,002 miles), Jverts tighten one bell housing bolt, RTR FWH wheel w/kit, installed Cat engine fuel primer VDS2 R-rear spring break canister replaced. |
| 10-28-2010 | Quality, replaced air governor, AD-9 air dryer, |
| 11-8-2010 | Quality Service Cell: constant hose leaking |
| 12-7-2010 | Buffalo City repaired & replaced RH headlight assembly. Patch Head. |
| 1-12-11 | PM Service Jverts WO# 16859, ADJUSTED DRIVER SIDE DOOR. ADJUSTED LEFT hood bracket. fixed right window. NEW ANTENNAS. fixed air controls bracket in dash was broke. both washer nozzles are replaced. bent right side of bumper out. Turned LRO tire to see valve stem. Torqued all. replaced Alternator belt, ck'd Ecm wire, ck's ck'd & cleaned all grounds. replaced Turbo drain & feed line gasket. |
| 2-1-11 | PM Serv WO# 17023 Replaced Wiper switch & Rt Nozzle & cleaned & fitting. Cleaned & v'd batteries & grounds. v'd tire pressures. Cleaned & greased fifth wheel. Replaced left Fog light & Lens, L clutch. Adjust brakes, replaced R-F Tamber Shock, replaced left rear air tank on truck, adjusted overhead #3 & #5 exhaust tight others OK |
| 4-26-2011 | PM Service WO# 17225, Adjust brakes, adjust clutch, A/c ck'd OK, Painted Steers, Bumper, Deerguard, Chrome. |
| 9-27-11 | Quality Doted Redox Next serv in MN. Replaced Tail lite, Pig Tail & Cab lite |
| 12-19-11 | PM Serv WO# 18233 W/T Doted Adg Clutch. Replaced Fuel & Block Heater cord End & LF Tandom Wheel Seal W/T Adg Clutch Brake |
| 3-15-12 | End DSI Free up Clevis Pins & Adg Brakes on Steer Axle |
| 6-23-12 | Replace Blower motor |

Dec
~~September~~
 OCT
 1100 ~~Nov~~ DOT

Inspection, Repair & Maintenance Record

VEHICLE IDENTIFICATION

| | |
|---------------------------|------------------|
| MAKE | SERIAL NUMBER |
| YEAR | TIRE SIZE |
| COMPANY NUMBER/OTHER I.D. | OWNER, IF LEASED |

| DATE | OPERATION PERFORMED, INSPECTION AND/OR REPAIR |
|-----------|--|
| 10-29-09 | PM Serv WO# 15342. Replaced Rt Tail lite & Center Cab lite Bulb. Replaced 2nd to Back Batt Convert from return fuel to water, DOT's, Block heater -ok, CK'L alignment, ok, Very slight left Pull, replace Steers & front drives near PM.# |
| 11-17-09 | Quality replaced Firewall Solenoid & Tach light |
| 12-23-09 | pm Service WO # 15507 replaced Front Driver & Both Steer Left @ 2 in Right 9 in miles 730034 Steers Dunlop SP384 replaced Drivers wind shield 372 Recaps Left Low Beam changed Brake for back up lite replaced Both wiper Blades moves whether stripping up in Left side window; Sues replaced rear motor - RT/S R-R tandem Shock replaced R-F tandem wheel seal replaced |
| 3-4-10 | PM serv WO# 15749 Replaced 2 Cab lites & AM/FM + CB Antennas Siliconed Hole in Back of Cab. Retoured Front Drives & Steers. Change driver side Steer Age Air line, Sues Cab Shocks replaced, CK'L whiz spin h/w had come on |
| 4-22-10 | PM Service WO# 15919, Changed Rst Middle Cab light Ad; and covered Silicone hose by Alt Stand rubbering Pointed down guard. Ready Air lines so not to Rubbing on deck Sues, put strap kit on u-join by tranny, replaced two exhaust clamps, one by turbo & rear elbow. G's just brakes |
| 6-15-2010 | Quality Full service R&R on Pan gasket R&R water pump replace Lst Card, CK'L Hanger bearings -ok, didn't write miles on invoice |
| 7-8-2010 | Butler / Jmst Added 2 lbs Freon, replaced Alternator & Pulley |
| 7-6-2010 | Quality 1 lb. Freon Added & blew out radiator |
| 8-11-2010 | PM service. New starter relay gelinoid. Engine air cleaner new. New left steer hose a.r. CAB clearance light out. Unplugged AC Drain hose. Fog light bulb replaced. JK-LW - Replaced seat with seat in 999. Air Ergo-Rate. ck brake strokes |
| 7-13-2010 | Quality replaced A/C Condenser & A/C hose |
| 8-2-2010 | Quality replaced Cab leveling valve & mud flap bracket |

1100 ~~September~~ Dec
 New DOT

Inspection, Repair & Maintenance Record

VEHICLE IDENTIFICATION

| | |
|---------------------------|------------------|
| MAKE | SERIAL NUMBER |
| YEAR | TIRE SIZE |
| COMPANY NUMBER/OTHER I.D. | OWNER, IF LEASED |

| DATE | OPERATION PERFORMED, INSPECTION AND/OR REPAIR |
|----------|---|
| 12-16-08 | Quality replaced fuel filter, replaced L-U-Joint, dropped Drive line to be towed in by Interstate Towing to Quality, lost U-Joint Straps, Called on Interstate |
| 1-16-09 | PM Serv WO# 14226 Replaced Left Wind shield + Rt C/A Antenna. Put in New Mirror switch. Checked Fuel Heater & it works on Return Fuel. Tightened up Left Door Hinge Bracket. Straightened Seat Belt Bracket + Put new Lock Mech on 2- SP384 steers 4-L 10-R 63460 miles Hood Cable installed, Backin plates, A/C Compressor Clutch, Steer And brake shoes & Brakes on rear Tandem next PM |
| 2-12-09 | Quality replaced broken Clips in drivers door latch, put extra Fuel Filter & wrench in Sleeper Comp. |
| 3-19-09 | Juvs WO# 14960 Replaced Back Battery Both glad hand rubber Both wiper blades new Driver window Seal retorque steers left rear tire are waling wear Flat in middle turn outside tire 1/2 turn from inside wear spot, Juvs replaced rear tandem & R-F tandem Shocks, replaced Flange Pipe (Exhaust) at turbo, replaced rear tandem brake shoes & Drums |
| 3-27-09 | Quality - Push button for starter replaced |
| 4-15-09 | Quality, replaced water Temp Sensor # 8039019A |
| 4-18-09 | Quality replaced mt starter # 10461053 |
| 5-14-09 | Juvs WO# 14698 replaced Both glad hand rubber Both wiper blades replaced Left Door Sill + weather stripping replaced Left Low Beam turn right Low Beam around + tighten up Left Fender mirror retorque Jaws + paint wheel + Deer guard put new cables on hood spring Juvs Adjust brakes, replaced Turbo Flange Pipe, replaced hood cone |
| 7-14-09 | Juvs WO# 14938 replaced Front 2 Batterys add hose sup for air Lines, replaced Both wiper blades + right wind shield straighten Deer guard + paint Deer guard replaced Both hoses on Left rear Brake replaced middle Flex pipe put new clamp on air hose under cab adjust brakes |
| 9-2-09 | PM Service, Juvs WO# 15134 Mason's MT# 4/372 Drive 3 on rear Tandem 699133 miles replaced air Filter replaced Left Steer axle air hose + replaced right Door stricker put new clamp on oil Fill tube. Cleaned 5th wheel Cleaned grounds on Frame + Cab Ground, fan belts tension, Exhaust repairs |
| 8-11-09 | Quality replaced bunk Blower motor |

Sept
Oct
Nov Dec
1100 DOT

Inspection, Repair & Maintenance Record

VEHICLE IDENTIFICATION

| | |
|---------------------------|------------------|
| MAKE | SERIAL NUMBER |
| YEAR | TIRE SIZE |
| COMPANY NUMBER/OTHER I.D. | OWNER, IF LEASED |

| DATE | OPERATION PERFORMED, INSPECTION AND/OR REPAIR |
|----------|---|
| 2-21-08 | Ryan Smt replaced mud flap, bracket & reflector |
| 4-1-08 | PM Serv WO# 13060 Replaced 2 Cab Lite Balls & HVAC Lite Checked 5th Wheel & in play Found Rear Pins & Pin Holes Needed to Be Built up on trailer. Jues replaced Front Tandem brake shoes & seals R/R Clutch, P/S mount gasket replaced 555814 miles. Fan belts & muffer bracket |
| 4-11-08 | Quality replaced glashane |
| 5-20-08 | PM serv WO# 13250 Replaced Both Mud Flap Brackets & Mounts & Both CB Antennas & Cab Ride Tight Rods & Retouched Front Drives. Replaced center Cab Lite Ball. muffer mt bracket, fan belt replaced. Adjust finished near pm |
| 7-22-08 | PM Serv WO# 13522 Replaced Left Air Fender. Put New Bolt in Left Rad Support Arms. Pulled Fuel Send Out & Replaced Gasket & Inner Rubber. Strainted Bot 2 Centch Beam in Deep Guard Rivited Alum Pieces in Grill, Couldn't adjust Fifth wheel to the next notch yet, Adjusted overhead, both rear tandem torque arms replaced coolant temp sensor |
| 9-18-08 | Jues WO# 13761 replaced Both wiper Blade & new air Filter & 2 Dash Light for air gauge replaced Latch on Drive vent window put new snap on for winter floor Replaced All Drives 308 Recaps 602782 Miles, Airdryer rebuilt Spring brake L-R tandem, adjusted finished, block heater ok, water fuel heater |
| 9-25-08 | Quality replaced mt-42 starter |
| 10-10-08 | Quality Cleaned ground cable at frame |
| 11-13-08 | Jues WO# 13985 DOT retorque R/R R Drivers Lube up Driver seat Latch replaced Back up alarm turn 2 F & L R Drivers replaced cable on hood with temp one knob replaced Right steer axle Hub cap Adjusted abs, Cab Shocks Day m6147 replaced, both Steer Axel shocks m65103 replaced, DOT's, repairs to flex pipe, meehanal fuel Pump replaced, tightend front cover bolts, CW's block fuel heater |

SM

1100

 sept
 OCT
 Nov Dec
 Dec DOT

Inspection, Repair & Maintenance Record

VEHICLE IDENTIFICATION

| | |
|---------------------------|------------------|
| MAKE | SERIAL NUMBER |
| YEAR | TIRE SIZE |
| COMPANY NUMBER/OTHER I.D. | OWNER, IF LEASED |

| DATE | OPERATION PERFORMED, INSPECTION AND/OR REPAIR |
|----------|--|
| 8-8-07 | pm Juevs W O # 12259 upper shover pm service replaced 8 Drives with 305 miles 489257 replaced Connector on coolant level sensor Flat wheel Jack Kit Simple Fifth wheel Kit |
| 8-25-07 | Quality R engine Clutch Fan # KYS 1070-09500-01 |
| 10-3-07 | Juevs W O # 12457 Replace Right CB Antenna Rotate & Balance steer LF2 RF8 replace Right tail Lite replace air Filter Both wiper blade left Wiper nozzle. Replaced Both Windshields Tightened UP Nuts In Fuse Box For Trailer lites & Changed cab lites drained Anti-freeze down & Add 3-gallons, Adjusted Clutch, Exhaust Clamps Air Filter replaced |
| 9-7-07 | Quality, replaced # 6 injector 9/12 Quality replaced Air lites |
| 10-9-07 | Quality replaced Starter Solenoid |
| 10-25-07 | Quality replaced Crane exhaust Stack |
| 10-26-07 | Quality replaced A/C Belt & Tensioner bearings. new relay on under |
| 11-28-07 | Juevs W O # pm service replaced Both steer & Balance with Dunlop SP384 LF 6in & RF 4in miles 524424 |
| 11-23-07 | Performance Truck Center Dickinson ND, Air compressor coolant hose blown, made up hose to get by # 382.63 |
| 12-11-07 | Juevs W O # 12593 DOT replaced Left Tripod mirror replaced Both wiper blades put new both in cab walk Lube up throttle in cab, Sm head Air line back of cab replaced re-fastened faring wire cable, over-haul in chassis, Cyl. Head replaced, recon all 6 recon Cyl pks, connecting rods, Bearings, Lifter Arms, throw shaft, waste gate solter expansion tank. 524,425 miles |
| 12-20-07 | Quality replaced, block heater |
| 1-24-08 | PM serv W O # 12829 VJS'2 Changed Left Low beam heater core replaced |
| 1-22-08 | Quality replace bunk heater core, Top radiator tank, Belt Tension visor clip |
| 1-15-08 | Crossroads replaced Primary Fuel Filter & water hose on rear of engine block |

1100 DOT ^{Sept} Dec ^{Oct} Nov ~~Dec~~

Inspection, Repair & Maintenance Record

Lic# ^PA H 3278

VEHICLE IDENTIFICATION

| | |
|---------------------------|------------------|
| MAKE | SERIAL NUMBER |
| YEAR | TIRE SIZE |
| COMPANY NUMBER/OTHER I.D. | OWNER, IF LEASED |

22.5

C-12 CAT

| DATE | OPERATION PERFORMED, INSPECTION AND/OR REPAIR |
|----------|--|
| 12-20-06 | Heartland Tire - LHS 395 Steer Tires 428779 miles L-202-R-402 Has new Seat (Fargo Fr. Liner) Jwers w.o # 11444, Air dry rebart Alignment, Set over head, replaced radiator, VIS |
| 1-12-07 | Installed CB + New Cable + Antennas + Adj. Drivers Door + Put New wretch stripping Greased All Light Replaced Left Fog light. Replaced 1 in Coolant Hose on Rt side + Put in Ext. Specker + For CB. Replaced Heater Control light - Adj. Fender Mirrors + Moved Bracket UP on Left one adjust Head Lite turn of Fender moves 5 wheel Back one hole |
| 1-29-07 | Quality replaced Alternator |
| 3-1-07 | PM Serv w.o # 11651 Replaced 2 Batt Jumper Labels + 2 Batt Cable End Tightened up Bolts on Back of Faring. Replaced Cab Rite High Rod. Fixed Ground Wire for Light Cord. Put CB. up in head liner. Put Rubber Hose on Clutch Rod. Put Frt liner Label on Grill Replaced Rt Door Striker replaced Starter (42 NT) Next Service Front engine Seal # |
| 3-6-07 | Quality replaced 15" Lite Cord |
| 3-12-07 | Quality vent window lock on order / 4-12 Quality windshield washer Pump |
| 4-18-07 | Jwers w.o # 11824 - PM Service, glad hand rubbers, 2 rear mud Flap reflectors change dash Lites replaced wiper blades Fasten Fire ext down Fix Back seat Broke Fix spring on cloth add new Fire ext - replaced 3 - 1/2" pins |
| | water pump replaced, Air governor, Both 1/2" Pulley bearings replaced Front engine crank seal repair |
| 5-10-07 | Quality recharged A/C system 2 1/2 lbs. Possible A/C Pump weeping, didn't find any leaks |
| 6-13-07 | PM Service replaced speed + Park Lite replace both wiper nozzles replaced over fill tank Jiders # 12036 replace Front Slack on Both Steer Axels Fix Broken wire on back up alarm, L-R Drive tire repaired, Front Clutch rod joint |
| 6-19-07 | Quality replaced Fuel transfer Pump / A/C Idler replaced + Belt |
| 6-28-07 | Quality replaced Turn Signal Switch |
| 7-10-07 | Quality replaced Low Water Sensor |

Inspection, Repair & Maintenance Record

1100 Dcc Dot

VEHICLE IDENTIFICATION

MAKE

SERIAL NUMBER

COMPANY NUMBER/OTHER I.D.

OWNER, IF LEASED

| <u>DATE</u> | <u>OPERATION PERFORMED, INSPECTION AND/OR REPAIR</u> |
|-------------|---|
| 8-22-13 | Ind DSI Replaced UJoint + Hanger Bag + UJoint + Flex Pipe Buy Muffler |
| 9-26-13 | Royal Air |
| 10-14-13 | Royal Flat Repair Rt Steer |
| 10-22-13 | Royal Replaced Both Steers LP22.5 F5501 |
| 10-10-13 | Ind DSI Replaced Rt King Pin + Brake shoes + Adg Clutch |
| 12-5-13 | PM work # 22380 3 batteries replaced, battery hold downs replaced. Fixed R-side hood stop. W/T Dot Replaced Coolant line From Air Comp to Back of Block + Coolant line to Sleeper + Rt side + LR + RFD Wheel Seals + Block Heater |
| 1-13-14 | Ind DSI Replaced 1 Batt Both Wipers, Starter + Firewall sol Fixed Marker + Tail Lite + Replaced Fog Lite Replaced Air Dryer |
| 1-20-14 | |
| 2-24-14 | |
| 3-13-14 | Royal Flat Repair LFI |
| 3-19-14 | Ind DSI Fixed Air leak in Dash |
| 4-3-14 | 7500 G/J Replace Fan Belt + Fix RF Out Fender |
| 7-21-14 | W/T work 23934 Replaced A/C Line From Exp Valve to Comp |
| 10-2-14 | W/TIR work 24401, Repair RN Fog Lite Lamp + Wiring, Repolish RAD Tire with RN oil, Clean + Paint Mirrors. W/T Adg Clutch, Replaced Rt + Lft Pig Packs + S/A Brakes + RF Cab Mount |
| 1-29-15 | Ind DSI Replaced Air Horn Valve. Fix Air leak on Trany + Removed Trany Cooler |
| 1-27-15 | work 25095 Replaced P/D Input Seal |
| 3-19-15 | Ind DSI G/J + Replaced Air Comp Discharge line |
| 5-21-15 | work 25832 4 Tired RN |
| 6-11-15 | W/T Serv Air Dryer, Adg 5th Wheel + Replaced Flex Pipes + Clamps work 25979 Recharged A/C |
| 7-1-15 | H/L Replaced Both Steers LP22.5 591 56973 |
| 6-24-15 | work 26062 Replaced Speed Sen |
| 7-1-15 | H/L Replaced Left Steer LP22.5 591 |
| 12-18-15 | Quality Replaced Turbo Clamp |
| 12-28-15 | Dot |