<u>10-550-N (42)</u>	<u>SN: 689803</u>			
<u>E7516</u>	<u>Condition</u>	ltem		<u>Cost</u>
Yes	As Received	Log Book		
Yes	Overhauled	Mag Left Bendix	\$	1,100.00
Yes	Overhauled	Mag Right Bendix	\$	1,100.00
Yes	New	Harness	\$	600.00
Yes	As Received	Spark Plugs- Tempest		
Yes	Overhauled	Fuel System	\$	2,000.00
Yes	As Received	Starter Adapter		
No	NA	Starter	-	
Yes	As Received	Oil filter Adaptor		
Yes	As Received	Oil Filler Tube / Gauge		
Yes	Overhauled	Oil Cooler	\$	1,100.00
Yes	As Received	Hyd Pump Drive Pad		
Yes	As Received	Vacuum Pump Drive Pad		
Yes	As Received	Intake Pipes Clamps	-	
Yes	As Received	Intake Pipes Bolts		
Yes	As Received (1)	Inner Cylinder Baffle		
Yes	As Received	Engine Bolts & Screws		
Yes	Rejected- Red Tagged	Case		
Yes	Cleaned/NDT Inspected	Crankshaft		
Yes	Rejected- Red Tagged	Oil Transfer Collar		
Yes	Overhauled x6	Connecting Rods	\$	67.88
Yes	Overhauled x6	Counter Weights	\$	61.58
Yes	As Received	Engine Mount Legs		
Yes	As Received	Oil Pump		
Yes	Overhauled x12	Rocker Arms	\$	777.15
		Gears, Internal Components &		
Yes	As Received	Misc. Other Parts		
		SEI Labor for Disassembly,		
		Cleaning, NDT Inspection	\$	4,012.50
		Storage	\$	550.00
		Net due SEI:	\$	11,369.10