

ESTIMATE

Registration: **N928CS**

This is an Estimate Only. Parts prices are subject to change without notice.
Miscellaneous Items, Consumables and Freight are not included

- AIRWORTHY ITEM R - RECOMMENDED M - MANDATORY SERVICE BULLETINS C- COSMETIC ITEMS O- OPTIONA

			DISCREPANCY	PARTS	LABOR	TOTAL
--	--	--	-------------	-------	-------	-------

RECORDS REVIEW

1	A		NEW AIRCRAFT POH	220.00	0.00	\$220.00
TOTAL				220.00	0.00	\$220.00

AIRWORTHINESS DIRECTIVES

1	A	3.0	AD2020-16-11 CYLINDER INSPECTION/MODIFICATION DUE	0.00	375.00	\$375.00
2	A	4.0	AD93-05-06 IGNITION SWITCH SERVICING	180.00	500.00	\$680.00
TOTAL				180.00	875.00	1,055.00

SERVICE BULLETINS

1	M	3.5	SB2X-95-23R1 CAPS AFT GRAIN REPLACEMENT	3,100.00	437.50	\$3,537.50
2	M	4.0	SB2X-74-02 IGNITION SWITCH SECURITY	285.00	500.00	\$785.00
3	M	2.0	SB2X-52-08R2 CATCHER/DIVERTER AND GAS STRUT ROD END REPLACEMENT	90.00	250.00	\$340.00
4	M	4.5	SB2X-42-17 PERSPECTIVE SOFTWARE UPDATE v0764.37	0.00	562.50	\$562.50
5	M	0.5	SB2X-34-29R1 PITOT AND TKS LINE ROUTING INSPECTION	0.00	62.50	\$62.50
6	M	0.5	SB2X-32-25 OLEO STRUT INSPECTION	0.00	62.50	\$62.50
7	M	1.0	SB2X-79-10 TURBOCHARGER OIL CHECK VALVE FILTER INSTALLATION	395.00	125.00	\$520.00
8	M	3.0	SB2X-71-27R1 ALTERNATE AIR BOX BRACKET INSPECTION DUE	15.00	375.00	\$390.00
TOTAL				\$3,885.00	\$2,375.00	\$6,260.00

CHAPTER 4 ITEMS

9	A	1.0	CAPS LINE CUTTER REPLACEMENT	1,450.00	125.00	\$1,575.00
10	A	1.0	REPLACE ELT BATTERY	225.00	125.00	\$350.00
11	A	2.0	REPLACE SEAT BELT EMA CONTROLLER	1,000.00	250.00	\$1,250.00
12	A	1.5	REPLACE CO DETECTOR	1,740.00	187.50	\$1,927.50
TOTAL				4,415.00	687.50	5,102.50

DOT ITEMS

1	A	2.0	5-YEAR OXYGEN BOTTLE HYDROSTATIC INSPECTION	650.00	250.00	\$900.00
TOTAL				650.00	250.00	\$900.00

CHAPTER 5 ITEMS

1	R	3.0	500-HOUR MAGNETO INSPECTION DUE	2,850.00	375.00	\$3,225.00
2	R	1.0	2-YEAR/500-HOUR BATTERY #2 REPLACEMENT DUE	175.00	125.00	\$300.00
3	R	1.0	2-YEAR/500-HOUR ALTERNATOR #1 INSPECTION DUE	185.00	125.00	\$310.00
4	R	1.0	2-YEAR/500-HOUR ALTERNATOR #2 INSPECTION DUE	185.00	125.00	\$310.00
5	R	1.5	5-YEAR/500-HOUR CABIN AIR CONTROL INSPECTION	0.00	187.50	\$187.50
6	R	4.0	1000-HOUR ELECTRICAL SHIELDING AND BONDING INSPECTION DUE	0.00	500.00	\$500.00
7	R	1.0	3-YEAR/1000-HOUR PITCH AND ROLL SERVO INSPECTION DUE	0.00	125.00	\$125.00
8	R	1.0	3-YEAR/1000-HOUR YAW SERVO INSPECTION DUE	0.00	125.00	\$125.00
9	R	1.0	2-YEAR MAGNATOMETER INSPECTION DUE	0.00	125.00	\$125.00
10	R	1.5	2-YEAR/1200-HOUR TKS FILTER REPLACEMENT DUE	1,071.00	187.50	\$1,258.50
11	R	1.5	2000-HOUR REPLACEMENT OF #1 ALTERNATOR	1,996.00	187.50	\$2,183.50
12	R	2.0	2000-HOUR REPLACEMENT OF #2 ALTERNATOR	1,138.00	250.00	\$1,388.00
13	R	1.0	SB15-03A OIL SUMP ASSEMBLY INPSECTION	0.00	125.00	\$125.00
TOTAL				7,600.00	2,562.50	10,162.50

14CFR 91-4.11 & 94-4.13 IFR CERTIFICATION

	A	4.8	2-YEAR IFR CERTIFICATION DUE	0.00	600.00	\$600.00
TOTAL				0.00	600.00	\$600.00

AIRFRAME FINDINGS

1	A	1.5	REPLACE NOSE LANDING GEAR OLEO STRUT	2,500.00	187.50	\$2,687.50
2	R	1.0	REPLACE AIRCRAFT PLACARDS	68.00	125.00	\$193.00
3	R	6.0	TKS EROSION STRIP PAINT AND REPAIR	84.00	750.00	\$834.00
4	A	1.5	DRAIN, FLUSH, AND SERVICE BRAKE SYSTEM	15.00	187.50	\$202.50
5	A	2.5	REPLACE L/H & R/H BRAKE LININGS	480.00	312.50	\$792.50
6	A	1.0	REPLACE R/H BRAKE DISC	235.00	125.00	\$360.00
7	A	0.5	REPLACE L/H NOSE WHEEL PANT BRACKET	165.00	62.50	\$227.50

8	R	6.5	TOUCH UP PAINT BELOW PILOT DOOR	125.00	812.50	\$937.50
9	R	3.5	REPLACE R/H HORIZONTAL STAB FAIRING - INCLUDES PAINTING	225.00	431.25	\$656.25
10	R	1.5	REPLACE LED LANDING LIGHT	1,500.00	187.50	\$1,687.50
TOTAL				5,397.00	3,181.25	8,578.25

ENGINE FINDINGS

1	R	1.0	REPLACE STARTER	2,338.00	125.00	\$2,463.00
2	A	1.5	REPLACE ALTERNATOR #1	1,996.00	187.50	\$2,183.50
3	R	3.0	REPLACE ALTERNATOR #2 HARNESS	75.00	375.00	\$450.00
4	A	1.0	REPLACE L/H TURBO AIRBOX	808.00	125.00	\$933.00
5	A	8.0	REPLACE R/H TURBO TRANSITION	2,243.00	1,000.00	\$3,243.00
6	R	6.0	REPLACE CENTER, R/H, AND R/H REAR BAFFLES	4,286.00	750.00	\$5,036.00
7	A	1.0	PROPERLY INSTALL ALTERNATE AIR VALVE	20.00	125.00	\$145.00
8	A	1.0	REPLACE #3 FUEL INJECTION LINE	160.00	125.00	\$285.00
9	A	1.0	REPLACE ALL SPARK PLUGS	675.00	125.00	\$800.00
10	A	1.0	REPLACE L/H FORWARD UPPER DECK LINES	20.00	125.00	\$145.00
11	A	0.5	REPLACE MAGNETO PRESSURIZATION LINE	20.00	62.50	\$82.50
12	A	0.5	REPLACE CLAMP N #3 FUEL LINE	5.00	62.50	\$67.50
13	A	1.0	MANIFOLD PRESSURE CONTROLLER LEAKING	15.00	125.00	\$140.00
14	A	1.0	OIL LEAK ON CRANKCASE SPINE	0.00	125.00	\$125.00
15	A	1.0	L/H TURBO INDUCTION TUBE HEAT SHIELD CHAFED	110.00	125.00	\$235.00
16	A	1.0	REPLACE A/C DRIVE TURBUCKLE	497.00	125.00	\$622.00
17	A	5.0	REPLACE MAGNETOS	2,850.00	625.00	\$3,475.00
18	A	1.0	REPLACE R/H INTERCOOLER SCAT HOSE	30.00	125.00	\$155.00
19	A	2.0	OIL SUMP GASKET LEAKING	0.00	250.00	\$250.00
20	A	1.0	ROCKER BOX COVERS LEAKING	0.00	125.00	\$125.00
21	A	10.0	OVERHAUL L/H & R/H TURBOS	7,500.00	1,250.00	\$8,750.00
TOTAL				23,648.00	6,062.50	29,710.50

PROPELLER FINDINGS

1	A	2.5	PROPELLER BLADES HAVE PLAY AROUND ROTATIONAL AXIS AND GREASE IS LEAKING AT HUB SEAMS. QUOTING OVERHAUL FOR THIS ITEM	7,000.00	312.50	\$7,312.50
2	A	3.0	REPLACE TKS SLINGER RING	1,700.00	375.00	\$2,075.00
TOTAL				8,700.00	687.50	9,387.50

INTERIOR FINDINGS

1	R	3.0	REPLACE BOLSTER PANEL	950.00	375.00	\$1,325.00
2	C	1.5	PAINT GLARESHIELD	15.00	187.50	\$202.50
3	R	1.5	TROUBLESHOOT ENVIROMENTAL CONTROL PANEL	1,500.00	187.50	\$1,687.50
TOTAL				2,465.00	750.00	\$3,215.00