



www.dlkaviation.com

PROFESSIONAL EMPLOYEE SERVICES, LLC
114 W WINCHESTER STREET
SUITE 200
MURRAY, UT 84107 USA

| | |
|----------------|--------------|
| INVOICE | 21959 |
|----------------|--------------|

Page # : 1 of 1
Date : May-20-2021
Terms : NET
Account : N928CS
Your PO# :
Our TEL : 770/427-4954
Your TEL : 239-920-2020
Tail# : N928CS
A/C Make : CIRRUS
Model : SR22T
Serial : 0636

- DETAILS
THIS INVOICE REFLECTS COST OF ENGINE. THANK YOU.

| Qty | Part # \ Serial # | Description | Each | Extended |
|------|-------------------|-------------|----------------|-----------|
| 1.00 | TSIO550K | ENGINE | 57,000.000 | 57,000.00 |
| | | | PARTS: | 57,000.00 |
| | | | Sub Total: | 57,000.00 |
| | | | Invoice TOTAL: | 57,000.00 |

THIS INVOICE IS DUE AND PAYABLE UPON RECEIPT. TO AVOID A FINANCE CHARGE PLEASE REMIT PAYMENT WITHIN 10 DAYS. OTHERWISE A 1.5% (18% APR) FINANCE CHARGE WILL BE ASSESSED ON ANY UNPAID BALANCE AFTER 30 DAYS. AIRCRAFT PARTS ARE PURCHASED FROM OEM AND OTHER VENDORS. PART WARRANTY QUARANTEED BY OEM OR VENDOR.



2601 Cessna Lane nw
Kennesaw, GA 30144

www.dlkaviation.com

PROFESSIONAL EMPLOYEE SERVICES, LLC
114 W WINCHESTER STREET
SUITE 200
MURRAY, UT 84107 USA

INVOICE 22048

Work Order# : 21237
Page # : 1 of 1
Date : Jun-04-2021
Terms : NET
Account : N928CS
Your PO# :
Our TEL : 770/427-4954
Your TEL : 239-920-2020
Tail# : N928CS
A/C Make : CIRRUS
Model : SR22T
Serial : 0636

DETAILS

DISCREPANCY: IFR CERT
ACTION: CERTIFIED GARMIN AIRDATA COMPUTER P/N 011-00882-10 S/N 20616070 AND UNITED STANDBY ALTIMETER MODEL 5934AD-3 TO AN ALTITUDE OF 20,000 FEET IN ACCORDANCE WITH 14CFR PART 43 APPENDIX E TO COMPLY WITH 14CFR 91.411. CERTIFIED GARMIN GTX33ES MODE S TRANSPONDER P/N 011-00779-30 IN ACCORDANCE WITH 14CFR PART 43 APPENDIX F TO COMPLY WITH 14CFR 91.413. NO DEFECTS NOTED.

DISCREPANCY: SOFTWARE UPDATE
ACTION: COMPLIED WITH CIRRUS SERVICE BULLETIN SB2X-42-19 TO UPGRADE GARMIN PERSPECTIVE SYSTEM SOFTWARE. ALL OPERATIONS ARE SATISFACTORY AT THIS TIME.

LABOR: 1,036.50
CONSUMABLES: 41.46
Sub Total: 1,077.96
Invoice TOTAL: 1,077.96

THIS INVOICE IS DUE AND PAYABLE UPON RECEIPT. TO AVOID A FINANCE CHARGE PLEASE REMIT PAYMENT WITHIN 10 DAYS. OTHERWISE A 1.5% (18% APR) FINANCE CHARGE WILL BE ASSESSED ON ANY UNPAID BALANCE AFTER 30 DAYS. AIRCRAFT PARTS ARE PURCHASED FROM OEM AND OTHER VENDORS. PART WARRANTY QUARANTEED BY OEM OR VENDOR.



2601 Cessna Lane nw
Kennesaw, GA 30144

www.dlkaviation.com

INVOICE

22286

PROFESSIONAL EMPLOYEE SERVICES, LLC
114 W WINCHESTER STREET
SUITE 200
MURRAY, UT 84107 USA

Page # : 1 of 1
Date : Aug-18-2021
Terms : NET
Account : N928CS
Your PO# :
Our TEL : 770/427-4954
Your TEL : 239-920-2020
Tail# : N928CS
A/C Make : CIRRUS
Model : SR22T
Serial : 0636

DETAILS

THIS INVOICE REFLECTS COST OF CURRENT MAJOR PARTS AND OVERHAULS

| Qty | Part # \ Serial # | Description | Each | Extended |
|------|-------------------|------------------------------|-----------|----------|
| 1.00 | 657633 | TURBO TRANSITION EXHAUSE | 2,067.250 | 2,067.25 |
| 2.00 | 657198 | V-BAND CLAMP | 1,343.200 | 2,686.40 |
| 6.00 | 14059-005 | ENGINE MOUNT ISOLATORS | 428.400 | 2,570.40 |
| 1.00 | 646204 | TUBE, INTAKE | 745.100 | 745.10 |
| 2.00 | 29211-001 | TIT SENSOR, CONTINENTAL TURB | 252.650 | 505.30 |
| 1.00 | 657121-4 | WASTEGATE | 8,834.350 | 8,834.35 |
| 1.00 | 15469-010 | REAR, RH | 1,564.540 | 1,564.54 |
| 1.00 | 15487-007 | FRONT, RH | 1,219.290 | 1,219.29 |
| 1.00 | 657970 | BELT V, ALT 2 CIRRUS TCM | 100.710 | 100.71 |
| 1.00 | 657199 | ALTERNATOR, TCM 24V-70A BELT | 1,196.664 | 1,196.66 |

| | |
|-----------------------|------------------|
| PARTS: | 21,490.00 |
| OUTSIDE WORK: | 13,654.49 |
| Sub Total: | 35,144.49 |
| STATE SALES TAX 6%: | 1,289.40 |
| Invoice TOTAL: | 36,433.89 |

THIS INVOICE IS DUE AND PAYABLE UPON RECEIPT. TO AVOID A FINANCE CHARGE PLEASE REMIT PAYMENT WITHIN 10 DAYS. OTHERWISE A 1.5% (18% APR) FINANCE CHARGE WILL BE ASSESSED ON ANY UNPAID BALANCE AFTER 30 DAYS. AIRCRAFT PARTS ARE PURCHASED FROM OEM AND OTHER VENDORS. PART WARRANTY QUARANTEED BY OEM OR VENDOR.



2601 Cessna Lane nw
Kennesaw, GA 30144

www.dlkaviation.com

INVOICE

22493

Work Order# : 21177
Page # : 1 of 5
Date : Oct-12-2021
Terms : NET
Account : N928CS
Your PO# :
Our TEL : 770/427-4954
Your TEL : 239-920-2020
Tail# : N928CS
A/C Make : CIRRUS
Model : SR22T
Serial : 0636

BULLDOG AUCTIONS
114 W WINCHESTER STREET
SUITE 200
MURRAY, UT 84107 USA

DETAILS

DISCREPANCY: FERRY FLIGHT PREPARATION
ACTION: INSPECTED AIRCRAFT AND DETERMINED THAT THE AIRCRAFT IS SAFE FOR FERRY FLIGHT. COMPLETED FERRY FLIGHT APPLICATION.

DISCREPANCY: FERRY FLIGHT
ACTION: FERRY FLIGHT COMPLETED

DISCREPANCY: REPLACE NOSE STRUT - COMPRESSED AND LEAKING
ACTION: INSTALLED NEW NLG OLEO STRUT IAW CIRRUS SR22T MM 32-20

DISCREPANCY: ANNUAL INSPECTION DUE
ACTION:
PERFORMED ANNUAL INSPECTION OF THIS AIRCRAFT IN ACCORDANCE WITH CIRRUS AIRCRAFT SR22T AMM 05-20 INSPECTION CHECKLIST. PERFORMED RESEARCH OF THE AIRCRAFT LOGBOOKS FOR APPLICABLE AIRWORTHINESS DIRECTIVES THROUGH ATP REVISION; . THERE ARE NO ADS THAT REQUIRE COMPLIANCE AT THIS TIME. PERFORMED RESEARCH OF THE AIRCRAFT RECORDS FOR ANY MANDATORY SERVICE BULLETINS THAT ARE DUE. SERVICED TIRES. LUBRICATED AIRCRAFT. SERVICED BATTERY. INSPECTED ELT IN ACCORDANCE WITH FAR 91.207D (D1) (D2) (D3) (D4). INSPECTED BRAKES FOR SIGNS OF OVERHEATING AND DAMAGE. CHECKED BRAKE DISC AND LININGS THICKNESS. COMPLETED PULL TEST ON NOSE GEAR PIVOT AS REQUIRED BY CIRRUS DESIGN MAINTENANCE MANUAL SECTION 32-20.

INSTALLED ENGINE TS10-550-K SN 1034229 IAW CIRRUS SR22T MM 71-00. OPERATIONAL CHECKS OK. SERVICED ENGINE WITH AEROSHELL 50/100 MINERAL OIL. RAN ENGINE AND INSPECTED FOR LEAKS, NONE NOTED. INSTALLED TURBOCHARGERS AND EXHAUST SYSTEM IAW TS10550K MM M-18. ADJUSTED FUEL SYSTEM IAW CMI MM M-0. RAN ENGINE AND INSPECTED FOR LEAKS, NONE NOTED. PERFORMED POST MAINTENANCE OPERATIONAL RUN, ALL CHECKS NORMAL.

PERFORMED ANNUAL INSPECTION OF THIS PROPELLER IN ACCORDANCE WITH CIRRUS AIRCRAFT SR22T AMM 05-20 INSPECTION CHECKLIST. SEE AIRCRAFT LOG FOR AD'S COMPLIED WITH DURING THIS ANNUAL. LUBRICATED PROPELLER HUB.

DISCREPANCY: 2-YEAR #2 BATTERY REPLACEMENT DUE
ACTION: INSTALLED NEW #2 BATTERIES P/N 50979-001 IAW CIRRUS AMM 24-30, NEXT REPLACEMENT DUE OCTOBER 2023 (2 YEARS).

DISCREPANCY: 1000-HOUR ELECTRICAL SHIELDING AND BONDING INSPECTION DUE.
ACTION: COMPLETED 10-YEAR/1000 HOUR ELECTRICAL SHIELDING AND BONDING INSPECTION CIRRUS AMM 51-80.

DISCREPANCY: 3-YEAR PITCH AND ROLL SERVO INSP DUE
ACTION: INSPECTED AND SERVICED PITCH AND ROLL SERVO IAW CIRRUS AMM 22-12.

DISCREPANCY: 3-YEAR YAW SERVO INSP DUE
ACTION: INSPECTED AN SERVICED YAW SERVO IAW CIRRUS AMM 22-10.

DISCREPANCY: REPLACE ENGINE
ACTION: INSTALLED ENGINE TS10-550-K SN 1034229 IAW CIRRUS SR22T MM 71-00. OPERATIONAL CHECKS OK.

DISCREPANCY: R/R CO GUARDIAN DETECTOR
ACTION: INSTALLED NEW CO GUARDIAN DETECTOR, PN: 24660-002 SN: 111574, IAW CIRRUS SR22T MM 31-20

DISCREPANCY: PROPELLER OVERHAUL
ACTION: REINSTALLED PROPELLER PN PHC-J3Y1F-1N/N7065B SN NJ803B OVERHAULED BY SENSENICH PROPELLER SERVICE WO #G27645 IAW CIRRUS SR22T MM 61-10

DISCREPANCY: PROPELLER GOVERNOR OVERHAUL
ACTION: REINSTALLED PROPELLER GOVERNOR PN S-1-44F SN G1724NJ OVERHAULED BY SOUTHWEST AERO WO #31531 IAW CIRRUS SR22T MM 61-20



2601 Cessna Lane nw
Kennesaw, GA 30144

www.dlkaviation.com

INVOICE

22493

Work Order# : 21177

Page # : 2 of 5

Date : Oct-12-2021

DISCREPANCY: L/H TURBO OVERHAUL

ACTION: REINSTALLED L/H TURBO PN 466304-0003 OVERHAULED BY MAIN TURBO SYSTEMS WO #61133 IAW CIRRUS SR22T MM 81-20.

DISCREPANCY: WASTEGATE OVERHAUL

ACTION: INSTALLED NEW WASTEGATE ASSEMBLY P/N 657121-4 IAW CIRRUS SR22T MM 78-20

DISCREPANCY: R/H TURBO REPLACEMENT

ACTION: INSTALLED R/H TURBO P/N 646677 SN H-QIL00006 OVERHAULED BY MAIN TURBO SYSTEMS WO #61132 IAW CIRRUS SR22T MM 81-20.

DISCREPANCY: ELT BATTERY DUE

ACTION: INSTALLED NEW ELT BATTERY IAW CIRRUS SR22T MM 26-60, NEXT REPLACEMENT DUE: AUG 2028

DISCREPANCY: BOTH CAPS EXIT PLACARDS WEATHERED

ACTION: INSTALLED NEW CAPS EXIT PLACARDS IAW CIRRUS SR22 MM 11-20.

DISCREPANCY: EROSION STRIP CHIPPING/FADING

ACTION: REAPPLIED TKS EROSION STRIPS ON WINGS, HORIZONTAL STABILIZERS, AND VERTICAL STABILIZER IAW CIRRUS 30-10.

DISCREPANCY: RESEAL ANTENNAS

ACTION: RESEALED ANTENNAS IAW CIRRUS SR22 MM 23-20

DISCREPANCY: PAINT CHIPPING UNDER LT DOOR

ACTION: PREPPED AND PAINTED PAINT AREA UNDER PILOT DOOR IAW CIRRUS 30-10.

DISCREPANCY: BOTH RESCUE PLACARDS FADED

ACTION: INSTALLED NEW RESCUE PLACARDS IAW CIRRUS SR22 MM 11-20.

DISCREPANCY: RT TKS DRAIN PLACARD MISSING

ACTION: REPLACED MISSING TKS DRAIN PLACARD ON R/H WING IAW CIRRUS AMM 11-20.

DISCREPANCY: BOTH "NO FUEL" PLACARDS FADED/CHIPPING

ACTION: INSTALLED NEW "NO FUEL" PLACARDS IAW CIRRUS SR22 MM 11-20.

DISCREPANCY: BOTH MLG GROMMETS ARE DEBONDED

ACTION: REBONDED MLG GROMMETS IAW CIRRUS AMM 32-20.

DISCREPANCY: PILOT'S SEATBELT TWISTED

ACTION: UNTWISTED PILOTS SEATBELT BOTH SHOULDER AND LAP BELT ON RT SIDE IAW CIRRUS AMM 25-10.

DISCREPANCY: 2YR SERVO CLUTCH TEST

ACTION: PERFORMED 2-YEAR SERVO CLUTCH TEST IAW CIRRUS SR22T MM 22-10.

DISCREPANCY: EMA CONTROLLER DUE

ACTION: INSTALLED NEW EMA CONTROLLER P/N 20902-001 S/N: A18JUN21-42 IAW CIRRUS SR22T MM 25-60, NEXT REPLACEMENT DUE OCTOBER 2028.

DISCREPANCY: GLARESHIELD FADED

ACTION: CLEANED AND REPAINTED GLARESHIELD IAW CIRRUS AMM 25-10.

DISCREPANCY: RH AFT CONSOLE PANEL CRACKED

ACTION: INSTALLED NEW RH AFT CONSOLE PANEL IAW CIRRUS SR22T MM 25-10.

DISCREPANCY: GLARESHIELD ATTACHMENT DEBONDED FROM RH BOLSTER PANEL

ACTION: REBONDED GLARESHIELD ATTACHMENT TO BOLSTER PANEL IAW CIRRUS AMM 25-10.

DISCREPANCY: NLG BULB SEAL MISSING BULB PART OF SEAL

ACTION: INSTALLED NEW NLG BULB SEAL IAW CIRRUS SR22 MM 32-20

DISCREPANCY: ICE PROTECTION FILTER DUE 2YR REPLACEMENT

ACTION: INSTALLED NEW TKS FILTER P/N S/N: A18JUN21-42 IAW CIRRUS SR22T AMM 30-06.

DISCREPANCY: LINE CUTTERS DUE CHANGE

ACTION: REPLACED CAPS LINE CUTTERS PN 25347-003 SN 5380/5532 - REPLACEMENT DUE JUNE 2026.



2601 Cessna Lane nw
Kennesaw, GA 30144

www.dlkaviation.com

INVOICE

22493

Work Order#: 21177

Page #: 3 of 5

Date: Oct-12-2021

DISCREPANCY: SPINNER BAFFLE CRACKED MULTIPLE PLACES

ACTION: INSTALLED NEW SPINNER BAFFLE P/N 15480-003 IAW CIRRUS 71-00.

DISCREPANCY: FIRE BOTTLE BELOW WEIGHT

ACTION: INSTALLED NEW HAND HELD FIRE EXTINGUISHER IAW CIRRUS SR22 MM 26-20.

DISCREPANCY: AD 2020-16-11 NOT C/W

ACTION: AD2020-16-11 N/A BY CYLINDER P/N 658859 INSTALLED.

DISCREPANCY: SB2X-32-22R4 NLG STRUT INSPECTION

ACTION: SB2X-32-22R4 NO LONGER APPLICABLE.

DISCREPANCY: SB2X-32-25 NLG OLEO STRUT PRODUCTION #

ACTION: COMPLIED WITH SB2X-32-25 BY INSTALLING NEW NLG OLEO STRUT PRODUCTION NUMBER: 0621-41

DISCREPANCY: SB2X-34-29R1 PITOT/TKS ROUTING

ACTION: COMPLIED WITH SB2X-34-29R1 BY INSPECTION, NO DEFECTS NOTED.

DISCREPANCY: SB2X-52-08R2 CATCHER/DIVERTER

ACTION: COMPLIED WITH SB2X-52-08R2 CATCHER/DIVERTER BY INSTALLING KIT NUMBER 70544-001.

DISCREPANCY: SB2X-71-25 INTERCOOLER FLANGE STIFFERS

ACTION: PREVIOUSLY COMPLIED WITH

DISCREPANCY: SB2X-71-27R1 ALT AIR BOX BRACKET INSPECTION

ACTION: COMPLIED WITH SB2X-71-27R1 BY INSPECTION, NO DEFECTS NOTED.

DISCREPANCY: SB2X-74-02 IGNITION SWITCH SECURITY

ACTION: REFER TO TASK #58 SB2X-74-02 NO LONGER REQUIRED DUE TO PUSH BUTTON IGNITION INSTALLATION.

DISCREPANCY: SB2X-53-10 CABIN DOOR SEAL

ACTION: COMPLIED WITH SB 2X-53-10 IAW CIRRUS SR22T MM 52.00

DISCREPANCY: NLG THRUST WASHER WORN BEYOND LIMITS

ACTION: INSTALLED NEW NLG THRUST WASHER IAW CIRRUS SR22T MM 32-20

DISCREPANCY: NLG FORK BUSHINGS WORN BEYOND LIMITS

ACTION: INSTALLED NEW NLG FORK BUSHINGS IAW CIRRUS SR22T MM 32-20

DISCREPANCY: NLG FAIRING BRACKETS CRACKED

ACTION: INSTALLED NEW NLG FAIRING BRACKETS IAW CIRRUS SR22T MM 32-20

DISCREPANCY: R/H REAR BAFFLE CRACKED

ACTION: INSTALLED NEW RT REAR BAFFLE P/N 15469-010 IAW CIRRUS 71-00.

DISCREPANCY: CAPS ROCKET SHELF GROUND WIRE

ACTION: COMPLETED SB 2X-95-24R2 BY INSTALLATION OF KIT PN 70572-001.

DISCREPANCY: REPLACE R/H FRONT ENGINE BAFFLE - CRACKED AND BROKEN.

ACTION: REPLACED R/H FRONT BAFFLE P/N 15487-007 IAW CIRRUS AMM 71-00.

DISCREPANCY: PUSH BUTTON IGNITION

ACTION: INSTALLED ELECTRO AIR IGNITION/STARTER SWITCH PANEL P/N EA-15000 S/N 21-209 IAW SA04280CH AND INSTALLATION MANUAL IM EA-15000 REVISION 1 DATED 02/04/202. OPERATIONAL AND FUNCTIONAL CHECKS OK. NO WEIGHT AND BALANCE ADJUSTMENT NEEDED.

DISCREPANCY: OXYGEN BOTTLE INSPECTION/TEST

ACTION: REMOVED OXYGEN BOTTLE FOR HYROSTATIC TEST. REINSTALLED OXYGEN BOTTLE AFTER HYDROSTATIC TEST IAW CIRRUS SR22 35-00.

DISCREPANCY: BERINGER BRAKE UPGRADE

ACTION: UPGRADED WHEELS AND BRAKES I/A/W SB2X-32-21 BY INSTALLING KIT P/N 70510-001. INSTALLED NEW NOSE WHEEL P/N RA-002. WEIGHT AND BALANCE CHANGE: -4.8 LBS AT 141.7 INCHES. WEIGHT AND BALANCE UPDATED AND PROVIDED TO OWNER.

DISCREPANCY: #2 ALT INOP



2601 Cessna Lane nw
Kennesaw, GA 30144

www.dlkaviation.com

INVOICE

22493

Work Order# : 21177

Page # : 4 of 5

Date : Oct-12-2021

ACTION: INSTALLED NEW #2 ALTERNATOR PN 657199 SN H-T072873IAW CIRRUS SR22T MM 24-30.

DISCREPANCY: #1 TANIS WIRE CHAFFED

ACTION: INSTALLED #1 TANIS HEATER ASSEMBLY.IAW 71-00

DISCREPANCY: R/H STATIC WICK BROKEN

ACTION: REMOVED AND REPLACED STATIC WICK IAW 23-20

DISCREPANCY: L/H INTERCOOLER MOUNTING TAB ABOUT 4" BROKEN OFF.

ACTION: REMOVED AND REPLACED L/H INTERCOOLER IAW CIRRUS SR22T 71-60. GROUND CHECK GOOD

DISCREPANCY: L/H AIRBOX AFT SECTION CRACKED 4"

ACTION: INSTALLED NEW AFT LH FILTER BOX WELDMENT IAW CIRRUS SR22 MM 71-60.

DISCREPANCY: SERVICE A/C

ACTION: SERVICED AIR CONDITIONING IAW CIRRUS SR22T MM 12-10.

DISCREPANCY: BOTH BOLSTER PANELS NEED TO BE RECONDITIONED

ACTION: RECONDITIONED BOTH BOLSTER PANELS IAW CIRRUS SR22T MM 25-10

DISCREPANCY: INSTALL NEW GPS/XM ANTENNA

ACTION: INSTALLED NEW GPS/XM ANTENNA IAW CIRRUS SR22T MM 23-20

DISCREPANCY: REPLACE AEROTECT

ACTION: INSTALLED AEROTECT PAINT PROTECTION KIT P/N FAK-009/G3 IAW CIRRUS AMM 11-20.

DISCREPANCY: REPAIR/PAINT MAIN AND NOSE WHEEL PANTS

ACTION: REMOVED AND REINSTALLED WHEEL PANTS FOR REPAIR AND PAINT. WHEEL PANTS REPAIRED AND PAINTED BY RMZ AVIATION FAA CRS #2RZR007C.

DISCREPANCY: REPLACE AIRCRAFT DECALS

ACTION: REPLACED L/H AND R/H ENGINE COWL DECALS IAW CIRRUS AMM 11-20.

| TASK | Qty | Part # \ Serial # | Description | Each | Extended |
|------|-------|-------------------|------------------------------|-----------|----------|
| 2 | 2.00 | 05-21250 | FUEL SAMPLE JAR | 18.750 | 37.50 |
| 3 | 1.00 | 27057-002 | STRUT, OLEO NLG CIRRUS | 2,442.960 | 2,442.96 |
| 4 | 39.60 | 100LL | AVGAS | 6.550 | 259.38 |
| 4 | 2.00 | 12391-002 | PLACARD,ROLL TRIM/CIRRUS | 15.870 | 31.74 |
| 4 | 2.00 | 15735-001 | GRAB PLACARD | 4.380 | 8.76 |
| 6 | 2.00 | 50979-001 | BTY, SEALED #2 STBY ALTN 7.0 | 85.680 | 171.36 |
| 13 | 6.00 | 14059-005 | ENGINE MOUNT ISOLATORS | 0.000 | 0.00 |
| 13 | 1.00 | 23623-110 | BOLT HEATER | 341.040 | 341.04 |
| 13 | 2.00 | 29211-001 | TIT SENSOR, CONTINENTAL TURB | 0.000 | 0.00 |
| 13 | 2.00 | 29486-001 | SEAL, INDUCTION, SR22T | 42.020 | 84.04 |
| 13 | 12.00 | 50/100 | OIL, MINERAL 20W/50M | 8.313 | 99.76 |
| 13 | 1.00 | 646204 | TUBE, INTAKE | 0.000 | 0.00 |
| 13 | 1.00 | 646462 | AFTERCOOLER | 1,187.500 | 1,187.50 |
| 13 | 2.00 | 654309 | BUSHING | 48.450 | 96.90 |
| 13 | 1.00 | 657198 | V-BAND CLAMP | 0.000 | 0.00 |
| 13 | 1.00 | 657198 | V-BAND CLAMP | 0.000 | 0.00 |
| 13 | 1.00 | 657632 | TIE ROD | 46.937 | 46.94 |
| 13 | 1.00 | 657633 | TURBO TRANSITION EXHAUST | 0.000 | 0.00 |
| 13 | 2.00 | AN7-33A | BOLT, UNDRILLED | 8.810 | 17.62 |
| 13 | 4.00 | AN7-40A | BOLT, HX HEAD | 13.616 | 54.46 |
| 13 | 12.00 | MS20500-428 | NUT, EXHAUST,SILVR PLATE,HGH | 8.320 | 99.84 |
| 13 | 6.00 | MS9276-13 | LOCK TAB / TCM / CIRRUS | 6.395 | 38.37 |
| 13 | 1.00 | TT02771 | TANIS HEATER PLUG | 140.000 | 140.00 |
| 14 | 1.00 | 24660-002 | CARBON MONOXIDE DETECTOR | 1,000.000 | 1,000.00 |
| 18 | 1.00 | 657121-4 | WASTEGATE | 0.000 | 0.00 |
| 18 | 4.00 | MS20034-5 | BOLT | 13.790 | 55.16 |
| 18 | 5.00 | NAS1587-4 | WASHER | 5.660 | 28.30 |
| 19 | 1.00 | 646677 | TURBO, OVERHAULED | 0.000 | 0.00 |
| 20 | 1.00 | 455-0012 | BATTERY REPLACEMENT ELT ME40 | 239.232 | 239.23 |
| 21 | 2.00 | 12430-001 | CAPS COVER, BLACK ON CLEAR | 7.690 | 15.38 |
| 25 | 2.00 | 12437-001 | PLACARD, RESCUE / WINDOW | 4.210 | 8.42 |
| 26 | 1.00 | 19655-001 | PLACARD, TKS, FLUID DRAIN | 1.180 | 1.18 |



2601 Cessna Lane nw
Kennesaw, GA 30144

www.dlkaviation.com

INVOICE 22493

Work Order#: 21177

Page #: 5 of 5

Date : Oct-12-2021

| | | | | | |
|----|-------|-------------------|------------------------------|-----------|----------|
| 27 | 2.00 | 21743-001 | PLACARD, NO FUEL / CIRRUS | 42.350 | 84.70 |
| 32 | 1.00 | 20902-001 | ELECTRONIC MODULE, AIRBAG SE | 889.920 | 889.92 |
| 34 | 1.00 | PAINT/MATERIALS | | 60.000 | 60.00 |
| 35 | 1.00 | 12221-110 | INTERIOR TRIM AFT CONS. SIDE | 119.160 | 119.16 |
| 37 | 3.00 | 53361-001 | SEAL TRIM, BLACK | 3.680 | 11.04 |
| 38 | 2.00 | 15164-094 | SEAL, RING 1/2 , TKS | 7.380 | 14.76 |
| 38 | 1.00 | 21986-203 | FILTER CARTRIDGE, TKS SYSTEM | 1,070.100 | 1,070.10 |
| 38 | 1.00 | AS3582-235 | O-RING 3 1/8 ID, TKS | 7.540 | 7.54 |
| 39 | 1.00 | 25347-003 | LINE CUTTER,SR20/22 | 1,415.000 | 1,415.00 |
| 40 | 1.00 | 15480-003 | SPINNER BAFFLE | 380.220 | 380.22 |
| 41 | 1.00 | RTA400 | HALON 0.9LB / B:C FIRE EXT. | 168.938 | 168.94 |
| 46 | 1.00 | 70544-001 | KIT, DOOR STRUT AND CATCHER | 89.980 | 89.98 |
| 47 | 2.00 | 31796-001 | FLANGE STIFFENER INTERCOOLER | 8.870 | 17.74 |
| 47 | 2.00 | 31796-002 | FLANGE STIFFENER INTERCOOLER | 8.870 | 17.74 |
| 50 | 26.00 | 52010-010 | DOOR SEAL (SELL IN 13 FOOT M | 10.880 | 282.88 |
| 51 | 1.00 | 50545-001 | THRUST WASHER, | 14.440 | 14.44 |
| 52 | 1.00 | 50543-001 | BUSHING, NLG CIRRUS | 24.520 | 24.52 |
| 52 | 1.00 | 50544-001 | BUSHING, NLG CIRRUS | 24.480 | 24.48 |
| 53 | 2.00 | 11799-004 | WHEEL FAIRING, NOSE LANDING | 67.160 | 134.32 |
| 54 | 1.00 | 15469-010 | REAR, RH | 0.000 | 0.00 |
| 56 | 1.00 | 70572-001 | KIT,CAPS SHELF GROUND WIRE | 153.725 | 153.73 |
| 57 | 1.00 | 15487-007 | FRONT, RH | 1,219.290 | 1,219.29 |
| 58 | 1.00 | EA-15000 | IGNITION PANEL | 349.810 | 349.81 |
| 60 | 1.00 | OXYGEN | OXYGEN SERVICE/AIRCRAFT | 65.000 | 65.00 |
| 63 | 1.00 | 70510-001 | BERINGER BRAKING SYSTEM W/TI | 6,298.600 | 6,298.60 |
| 64 | 1.00 | 657199 | ALTERNATOR, TCM 24V-70A BELT | 0.000 | 0.00 |
| 64 | 1.00 | 657970 | BELT V, ALT 2 CIRRUS TCM | 0.000 | 0.00 |
| 65 | 1.00 | TT02771 | TANIS HEATER ELEMENT | 175.000 | 175.00 |
| 66 | 1.00 | 33266-001 | STATIC DISCHARGER, CIRRUS | 137.360 | 137.36 |
| 67 | 1.00 | 646462 | INTERCOOLER | 8,270.520 | 8,270.52 |
| 67 | 1.00 | AN823-4 | STEEL FITTING | 26.250 | 26.25 |
| 68 | 1.00 | 26391-007 | WELDMENT BASE FILTER HOUSING | 337.830 | 337.83 |
| 69 | 2.00 | R134A | FREON | 16.850 | 33.70 |
| 71 | 1.00 | 11-05824 | ANTENNA, WAAS | 687.560 | 687.56 |
| 72 | 1.00 | FAK-009/G3 | AEROTECT KIT | 823.920 | 823.92 |
| 74 | 1.00 | 12343-XXX-LOGO-LH | TAIL & COWLING, LH, SR22 | 316.413 | 316.41 |
| 74 | 1.00 | 12343-XXX-LOGO-RH | TAIL & COWLING, RH, SR22 | 316.413 | 316.41 |
| | 10.00 | 53722-063U | SEAL,RUBBER COWL FLAP | 27.419 | 274.19 |
| | 1.00 | AA48108 | FILTER, ENGINE OIL TEMPEST | 40.500 | 40.50 |
| | 2.00 | AN900-10 | GASKET, CRUSH MS35769-11 | 1.860 | 3.72 |
| | 1.00 | 705-1015 | CLAMP (SIZE 20)[505-1220] | 2.840 | 2.84 |
| | 1.00 | 705-1017 | CLAMP (SIZE 28)[505-1228] | 2.985 | 2.99 |
| | 1.00 | MS35489-17 | GROMMET | 2.187 | 2.19 |
| | 4.00 | AN-3A | BOLT | 0.662 | 2.65 |
| | 1.00 | 633958-3 | SEAL, FUEL DRAIN | 1.935 | 1.94 |
| | 12.00 | URHB32E | PLUG, TEMPEST SPARK | 41.710 | 500.52 |
| | 1.00 | MIL-6000-1 | HOSE 1" , MEDIUM PRESSURE | 3.020 | 3.02 |

| | |
|--------------|-----------|
| LABOR: | 23,131.25 |
| PARTS: | 31,379.27 |
| OTHER: | 2,575.00 |
| SHIPPING: | 1,088.73 |
| CONSUMABLES: | 925.25 |
| Sub Total: | 59,099.50 |

Invoice TOTAL: 59,099.50

THIS INVOICE IS DUE AND PAYABLE UPON RECEIPT. TO AVOID A FINANCE CHARGE PLEASE REMIT PAYMENT WITHIN 10 DAYS. OTHERWISE A 1.5% (18% APR) FINANCE CHARGE WILL BE ASSESSED ON ANY UNPAID BALANCE AFTER 30 DAYS. AIRCRAFT PARTS ARE PURCHASED FROM OEM AND OTHER VENDORS. PART WARRANTY QUARANTEED BY OEM OR VENDOR.