



DA Exterminating Co, St Tammany
13433 Seymour Myers Blvd
Ste 2
Covington, LA 70433
985-893-2071

Service Inspection Report

INVOICE #: A1341000

WORK DATE: 09/16/2024

BILL-TO 109788

Vicki Marino
59525 Neslo Rd
Slidell, LA 70460-4105

Phone: 305-797-5344 xMs

LOCATION 109788

Vicki Marino
59525 Neslo Rd
Slidell, LA 70460-4105

Phone: 305-797-5344 xMs

Time In: 09/16/2024 12:18:00 PM

Time Out: 09/16/2024 01:12:26 PM

Customer Signature

Marino

Technician Signature

Logan Lindsey

License #: LA - 00418J

Purchase Order	Terms	Service Description	Quantity
None	NET 30	Conditions Corrected Inspection	1.00

TECHNICIANS

Logan Lindsey

License #:
LA - 00418J

GENERAL COMMENTS / INSTRUCTIONS

Tech's Comments from Order # 1257984 on 07-03-2023: Tech's Comments from Order # 1257704 on 07-27-2022: 07/27/22. Resumed stations inspection after last appointment. Previous job had to be stop due to rain. No termite activity. Conductive conditions still exist, Vines and vegetation covering the foundation and station G49 in the back of the guest room.

7/3/23 found stations but conditions still exist

L. Lindsey
9/16/24
Conditions still exist.

CONDITIONS / OBSERVATIONS	Reported	Severity	Responsibility	Reviewed
Open				
exterior	05/01/2019	High	Client	05/14/2019
Condition: Soil/Mulch above grade - Soil and or mulch are above the slab grade line				
Action: Grade level should be lowered to leave at least 3 inches of slab visible. May require chemical barrier to be reapplied or a waiver signed by the customer. Please call the office within 30 days to notify that condition(s) are corrected.				
Comment:				
exterior	05/14/2019	High	Client	05/14/2019
Condition: Wood to ground contact - Wood on or against structure is in contact with the soil				
Action: Remove or detach wood contacting structure or eliminate contact with soil or a waiver must be signed by customer. Please call the office within 30 days to notify that condition(s) are corrected.				
Comment:				
exterior	05/14/2019	High	Client	05/14/2019
Condition: Moisture Condition - Moisture Condition creating conducive conditions for infestation				
Action: Replace any rotten wood and repair source of leak or moisture. Please call the office within 30 days to notify that condition(s) are corrected.				
Comment:				

PRODUCTS APPLICATION SUMMARY

None Noted.



DA Exterminating Co, St Tammany
13433 Seymour Myers Blvd
Ste 2
Covington, LA 70433
985-893-2071

Service Inspection Report

INVOICE #: A1341000

WORK DATE: 09/16/2024

PEST ACTIVITY	# Areas	# Devices	Pest Totals
---------------	---------	-----------	-------------

None Noted.

DEVICE INSPECTION SUMMARY

AREA COMMENTS

None Noted.

DEVICE INSPECTION EXCEPTIONS

None Noted.

INSPECTION DETAIL

None Noted.

PRODUCTS APPLIED

None Noted.