

520 Hearthside Drive  
Winston-Salem, NC 27104

## Broker Disclosure

Upon removal of basement contents broker noticed crack along front left corner on the floor and the wall above. No structural evaluations or reports have been obtained.



Evidence of potential leak from basement window

