Image	Pos.	Lot #	Name	Description	Start Bid	Reserve
55	1	0A	(14%) Buyer's Premium, Surcharge and Payment Information	**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes** IMPORTANT NOTICE FOR	\$1	\$1
Calendar 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31	2	0B	Preview and Removal Information	Preview: (Manned Location-No Appointment Necessary) (Tuesday, April 30, 2024) (Hours of Operation: 9	\$1	\$1
	3	0C	Location	Old Maintenance Barn (106 S 2nd St, Richmond, TX 77469 Driving Direc- tions)	\$1	\$1
Read Me	4	0D	Terms & Conditions	**All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes** IMPORTANT NOTICE	\$1	\$1
	5	0E	Vehicle Title Information	Removal Note For Vehicles: Winning Bidder Is Solely Responsible For Bringing Own Batteries, Jumper C	\$1	\$1
	6	1	2007 Chevrolet Silverado Pickup - Will Need to be Towed	Will Need to be Towed 2007 Chevrolet Silverado Pickup Vin #: 1GCEC14C97Z612792 Unit #: VM4 Conventio	\$500	\$500
	7	2	2008 Ford F250 Super Duty Extended Cab Pick- up - Will Need to be Towed	Will Need to be Towed 2008 Ford F250 Super Duty Extended Cab Pickup Vin #: 1FTNX20548ED80600 Unit #:	\$500	\$500
	8	3	2006 Ford F150 Extended Cab Pickup (Bad Trans- mission) - Will Need to be Towed	Will Need to be Towed 2006 Ford F150 Ex- tended Cab Pickup Vin #: 1FTRX12W06KD14089 Unit #: 311 Conven	\$500	\$500
	9	4	2012 Chevrolet Tahoe - Will Need to be Towed	Will Need to be Towed 2012 Chevrolet Tahoe Vin #: 1GNLC2E01CR287364 Unit #: P12 Conventional Style 5	\$500	\$500

Image	Pos.	Lot #	Name	Description	Start Bid	Reserve
	10	5	2008 Ford Crown Victoria - Will Need to be Towed	Will Need to be Towed 2008 Ford Crown Victoria Vin #: 2FAHP71V38X143111 Unit #: P98 Conventional Sty	\$500	\$500
	11	6	2008 Ford Crown Victoria - Will Need to be Towed	Will Need to be Towed 2008 Ford Crown Victoria Vin #: 2FAHP71V58X143112 Unit #: P88 Conventional Sty	\$500	\$500
	12	7	2016 Chevrolet Silvera- do Pickup (Bad Transmis- sion) - Will Need to be Towed	Will Need to be Towed 2016 Chevrolet Silvera- do Pickup Vin #: 1GCNC- NEH3GZ234003 Conven- tional Style 2	\$250	\$250
	13	8	2006 Ford F250XLT Super Duty Pickup with Camper Bed - Will Need to be Towed	Will Need to be Towed 2006 Ford F250XLT Su- per Duty Pickup with Camper Bed Vin #: 1FTSW20546ED47812 U	\$500	\$500
	14	9	2009 Chevrolet 2500 Heavy Duty Pickup - Will Need to be Towed	Will Need to be Towed 2009 Chevrolet 2500 Heavy Duty Pickup Vin #: 1GCHC44K69F179278 Unit #: WD-2 Co	\$500	\$500
	15	10	1979 International Pak-Mor S1800 Garbage Truck (Bad Transmission) - Will Need to be Towed	Will Need to be Towed 1979 Interna- tional Pak-Mor S1800 Garbage Truck Vin #: AA182JHB15361 Unit #: ST	\$250	\$250
	16	11	2014 Chevrolet Tahoe - Will Need to be Towed	Will Need to be Towed 2014 Chevrolet Tahoe Vin #: 1GNLC2E07ER203096 Unit #: P14 Conventional Style 5	\$500	\$500
	17	12	2013 Chevrolet Tahoe - Will Need to be Towed	Will Need to be Towed 2013 Chevrolet Tahoe Vin #: 1GNLC2E09DR191371 Unit #: P13 Conventional Style 5	\$500	\$500
	18	13	1988 Chevrolet 70 Water Truck - Will Need to be Towed	Will Need to be Towed 1988 Chevrolet 70 Water Truck Vin #: 1GBM7D1F6JV111278 Unit #: ST-2 Convention	\$500	\$500

Image	Pos.	Lot #	Name	Description	Start Bid	Reserve
	19	14	2004 Ferrara Intruder 2 Fire Truck 4566 420 - Will Need to be Towed	Will Need to be Towed 2004 Ferrara Intruder 2 Fire Truck 4566 420 Vin #: 44KFT42884WZ20502 Unit #: E	\$500	\$500
	20	15	1990 Gradall G3WD Excavator - Will Need to be Towed	Will Need to be Towed 1990 Gradall G3WD Excavator Upper SN#: 0136277, Lower SN#: 01D461 Unit #: ST-1	\$500	\$500
BDMRG	21	16	Bomag MPH100R Recycler - Will Need to be Towed	Will Need to be Towed Bo- mag MPH100R Recycler Engine Vin #: 85935 Eng- ine Ser #: 6VF180514 Unit #: ST	\$500	\$500
	22	100	Dixie Chopper Xcaliber 3160 Zero Turn Mower	(1) Dixie Chopper Xcaliber 3160 Zero Turn Mower Approx. 60" Cut X2 Will Run and Operate Has Leaking	\$25	\$25
	23	101	Dixie Chopper Classic 2750 Zero Turn Mower	(1) Dixie Chopper Classic 2750 Zero Turn Mower Unit Runs and Operates Engine is Blowing Oil Smokes A	\$25	\$25
	24	102	Exmark Lazer Z Zero Turn Mower	(1) Exmark Lazer Z Zero Turn Mower Lazer Z Bad Engine The Rest of the Unit Works Gas HRS: Un- known Ap	\$25	\$25
	25	103	Dixie Chopper Xcaliber 3160 Zero Turn Mower	(1) Dixie Chopper Xcaliber 3160 Zero Turn Mower Approx. 60" Cut Gas HRS: Unknown Leaking Hy- draulic P	\$25	\$25