



PROPERTY SERVICE CHART

58<sup>33</sup> ~~7~~ Thacker Dairy Road S/T Permit: \_\_\_\_\_ Date: \_\_\_\_\_  
 ADDRESS (PRINT) Name: \_\_\_\_\_

Well Permit: \_\_\_\_\_ Date: \_\_\_\_\_  
 Name: \_\_\_\_\_

Subd: \_\_\_\_\_ Sec. \_\_\_\_\_ Lot \_\_\_\_\_

SERVICE	COMMENTS	DATE	SANITARIAN
Soil evaluation		8-15-91	RSS LRS
SOIL EVALUATION	AREA APPROVED FOR L.P.P. PLAT WITH NEW PROPERTY LINES FORTHCOMING	9-3-91	RSS WDN
SOIL EVAL.	AREA APPROVED FOR CONVENTIONAL INITIAL.	5-18-95	RSS, WDN MKN
LAYOUT/ PIN CHECK	OK	6-5-95	RSS, WDN
SEPTIC AND WELL PERMITS ISSUED	RELEASED TO P&D.	6-6-95	RSS
EXISTING SYSTEM CHECK ✓	Not approved septic tub or field not found. Owner must locate + make	9/12/96	M.D.C.
Preliminary plat	CHECKED. PROPERTY LINE BETWEEN ① AND ② NOT SET IN THE FIELD. NEEDS TO BE MOVED ABOUT 60'	8-26-96	RSS, WDN
Phone	owner + left message to call office back.	9/16/96	M.D.C.
Existing system	OK system in 10' <del>7</del> 3	9/12/96	M.D.C.