

Big Splash Pool Service  
 470 Buchanan Road  
 Perkasio, Pa 18944

# Invoice

Date	Invoice #
9/18/2017	14901

<b>Bill To</b>
Stacy McDowell 15 Voudy Road Telford, Pa 18969

<b>Ship To</b>

Item Code	Description	Amount
Pool Inspection	<p>Inspection of the pool and equipment at 15 Voudy Road.</p> <p>The equipment has a 2hp Hayward super pump, Hayward DE Filter, Rheem 400 BTU Propane heater, Pentair Intellichlor Salt Generator and a Blower for the spa. All of the above equipment was running and in good condition.</p> <p>The pool also has a Meyco Mesh Safety cover that was stored in a shed and is in good condition. The Plaster had 2 noticeable 3 inch chip marks at both ends of the pool on the bottom.</p>	275.00
<b>Total</b>		<b>\$275.00</b>

