


Hertz Farm Manager



Freeman Farm
Geneva 16
Spring 2014

4 inch tile 4074.15 ft
 5 269.76 ft


DRAINAGE TILE INSTALLATION MAP

#1808 Freeman

Spring, 1998


6,345' - 4" Plastic Tile

Existing - 6" Clay Tile



#1808
July 1998

TILE RECORD MAP



NAME Hertz - Cal'

Section _____ Township _____ County _____

Contractor _____ Date installed _____


Amount of tile installed 5" _____ 6" _____ 8" _____

10" _____ 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

IOWA DRAINAGE, INC. SHEFFIELD, IOWA 50475
Jim Blood — Telephone 515-892-4330

TILE RECORD MAP



NAME Hert Farm Manage. Freeman Farm

Section _____ Township _____ County _____

Contractor _____ Date installed _____

Amount of tile installed 5" _____ 6" _____ 8" _____

10" _____ 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair
of any failure will keep the system in working order and main-
tenance costs low.

FAX 423-7363

IOWA DRAINAGE, INC. SHEFFIELD, IOWA 50475
Jim Blood — Telephone 515-892-4330