

**PEACH BOTTOM TOWNSHIP**  
**BOARD OF SUPERVISORS**  
**6880 Delta Road, Suite 3, Delta, PA 17314**

October 14, 2021

Tina Stevens  
252 McCall Road  
Delta, PA 17314

On the 14th day of October, 2021, I Eric Swiger SEO, on behalf of Peach Bottom Township, visually inspected the septic system located at 252 McCall Road, Delta, PA 17314. Known as parcel 43-000-04-0127.00-00000.

Dale Miller and Sons was the pumper.

Type of System:


One (1) 1,000-gallon septic tank.

Gravity in-ground bed or trench type drainfield.

My inspection revealed that the existing system showed no sign of a regulatory malfunction. No indication of surface malfunction seen. The system may now be approved for transfer. This inspection does not warrant the condition of the system subterranean, as all parties acknowledge the same was not revealed by my inspection and that my inspection was limited to a service inspection. This report does not constitute a warranty as to the functional capabilities of the system or as to its future functional utility. This report does not endorse or certify the design of the existing septic and its use for the purposes stated herein. No determination was made with respect to the existence of contamination of on-site/off-site wells or nearby watercourses as related to the existing septic system functioning. This report does not address either the presence or absence of cross-hydro geologic contamination on or off site. My inspection is strictly on behalf of Peach Bottom Township to ensure that regulatory malfunctions are not occurring, and that proper maintenance is being done to ensure the public health within the Township. Please review the additional comments for any possible items of concern. Thank you.

ADDITIONAL COMMENTS: None.

Respectfully,



Eric Swiger, SEO 03899  
Peach Bottom Township