# **Home Inspection Summary / Report**

# 220 Lorraine Avenue Fredericksburg, Virginia, 22408 September 12, 2021

This is a beautiful single-story home. There are a few issues (please see attached notes and pictures) that I have highlighted. With the repairs noted and a few upgrades, this could be a good investment as well as a great place to live. Should you have any questions or concerns, please do not hesitate to contact me.

## Report 570



### **HOME INSPECTION AGREEMENT**

A member of the Housing Inspection Foundation prepared this Agreement, The Association of Home Inspectors

Inspector's Name: Jesse Dodd
Company: Home Inspections

Professional Membership# 23096
Report # 570

Company: Home Inspections Address: 123 Sunny Day Lane

City: Fredericksburg State: Virginia Zip: 22406 Cell: (703) 929-3400 Email: jessedodd99@yahoo.com

# THIS INSPECTION AGREEMENT IS INTENDED TO BE A LEGALLY BINDING CONTRACT. PLEASE READ IT CAREFULLY.

Client Name (s): Paul Carroll

Property Address 2220 Lorraine Avenue Fredericksburg, Va. 22408 Client Telephone 540-809-5857

Client e-mail <u>pcarroll1983@outlook.com</u> <u>john@nichollsauction.com</u> Realtor: Wilson Auction & Nicholls Auction Marketing Group

- Client requests a limited visual inspection of the residential structure identified at the above address by the listed inspector of the above company, herein after collectively referred as the "Company" and Client hereby represents and warrants that all approvals necessary have been secured for Company's entrance on to the property.
- Client warrants: (a) they have read the following Agreement carefully, (b) they understand they are bound by all the terms of this contract, and (c) they will read the entire inspection report when received and promptly call Company with any questions they may have.
- Client understands that the inspection and inspection report are performed and prepared for their sole, confidential, and exclusive use. Client agrees that they will not transfer or disclose any part of the inspection report to any other person with these exceptions ONLY. (a) One copy may be provided to the current seller(s) of the property. Only upon the express condition that the seller(s) covenant to use the inspection report only in connection with Client's transaction. And agree not to transfer or disclose the report to any persons other than their real estate agent, and (b) one copy may be provided to the real estate agent representing Client and/or a bank or other lender for use in Client's transaction only. Client agrees to indemnify, defend, and hold harmless Company from any third-party claims relating to this inspection or inspection report.
- 4. Company agrees to perform a limited visual inspection of the residential structure at the above address and to provide Client with a written opinion as to the apparent general condition of the structure's components and systems, including identification of significant observable deficiencies, as they exist at the time of inspection. The inspection will be performed in a manner consistent with the standards of the Housing Inspection Foundation. Copies of these Standards are provided to Client, upon request.
- The inspection only includes those systems and components expressly and specifically identified in the inspection report. Any areas which is not exposed to view, is concealed, is inaccessible because of soil, walls, floors, carpets, ceilings, furnishing of any other

thing, or those areas/items which have been excluded by the Housing Inspection Foundation standards and/or by agreement of the parties is not included in this inspection. The inspection does not include any destructive testing or dismantling. Client agrees to assume all the risk for all conditions, which are concealed from view at the time of the inspection or exists in any area excluded from inspection by the terms of this agreement. Maintenance and other items may be discussed but will NOT form a part of the inspection report. The following areas/items, systems and components are among those NOT included in the inspection:

- Code or zoning violations
- System or component installation
- Permit research
- Structural, geological, soil, wave action or hydrological stability, survey, engineering, analysis, or testing
- Termites or other wood destroying insects, rodents or other pests, dry rot, or fungus
- Latent or concealed defects
- Asbestos, radon gas, lead paint, urea formaldehyde, toxic or flammable chemicals, water or air quality, PCB's or other toxins, electro-magnetic fields, underground storage tanks, proximity to toxic waste sites or other environmental or health hazards
- Private water or sewage systems
- Pools, spas, hot tubs, saunas, steam baths, fountains, or other types of or related systems and components
- Repair cost estimates
- Building value appraisal
- Radio controlled devices
- Automatic gates
- Elevators, lifts, dumbwaiters
- Thermostatic or time clock controls
- Water softeners or purifiers
- Radiant heat systems
- Furnace heat exchanger
- Solar heating systems

Copyright 2001 Housing Inspection Foundation. This form may be reproduced without written consent; however, the Housing Inspection Foundation must be acknowledged and credited

## HOUSING INSPECTION REPORT

# THIS INSPECTION AGREEMENT IS INTENDED TO BE A LEGALLY BINDING CONTRACT. PLEASE READ IT CAREFULLY.

SEE PAGES 14 &15 FOR IMPORTANT LIMITATIONS, DISCLAIMERS, AND INFORMATION.

INSPECTOR Jesse Dodd LICENSE NO.

THIS REPORT IS OUR INVOICE INSPECTION FEE \$ 350.00 Paid 9/12/2021

TERMS: Cash Check # Money order

BUYER Paul Scott DATE September 12,2021 Time 10:00 am

PROPERTY ADDRESS 220 Lorraine Avenue CITY Fredericksburg STATE Virginia Zip 22408

OCCUPIED X VACANT X SINGLE-STORY TWO-STORY TOWNHOUSE/CONDO SPLIT-LEVEL BASEMENT FINISHED UNFINISHED X CRAW-SPACE SLAB

MECHANICAL APPLIANCES NOTE: THE FOLLOWING IS NOT INCLUDED IN THIS INSPECTION: CLOCKS, TIMERS AND AUTOMATIC COOKING OR CLEANING MODES OR INTERCOM, COMMUNICATION MODES. MICROWAVES will not be CHECKED FOR RADIATION LEAKAGE.

| Inspected | Repair | Intended |   |
|-----------|--------|----------|---|
|           |        | OK       | COOK TOP/RANGE GAS X ELECTRIC                   |
|           |        | OK       | BURNERS   |
|           |        | OK       | OVEN SELF CLEAN CONTINUOUS CLEAN X MANUAL CLEAN |
|           |        | OK       | SETTING 350 TEMP 350                            |
|           |        | OK       | MICROWAVE                                       |
|           |        | OK       | KITCHEN EXHAUST VENTED X NON-VENTED             |
|           | X      |          | GARBAGE DISPOSAL SEE notes on disposal.         |
|           |        | OK       | DISHWASHER                                      |
|           |        | OK       | REFRIGERATOR                                    |
|           |        | OK       | ICE MAKER X FREEZER FREE-STANDING               |
| 0         |        |          | TRASH COMPACTOR                                 |
| 0         |        |          | INTERCOM  |
| 0         |        |          | GAS GRILL                                       |
| 0         |        |          | CENTRAL VACUUM                                  |
|           |        |          |   |
|           |        |          |   |
|           |        |          |   |

NOTE: PIPES, PLUMBING EQUIPMENT AND RESERVOIRS CONCEALED IN ENCLOSURES OR UNDER GROUND, NOT CHECKED FOR LEAKS OR DEFECTS-ALSO-THE SERVICEABILITY OR CONDITION OF THE SEPTIC OR SEWER SYSTEM IS NOT INCLUDED IN THIS INSPECTION. SPRINKLER SYSTEMS ARE ONLY CHECKED IN THE MANUAL OPERATION MODE. POOL PLUMBING SYSTEMS ARE NOT LEAK CHECKED.

#### PLUMBING, OUTSIDE

| 0 |    | METER-MAIN SHUT-OFF   |
|---|----|---|
|   | OK | OUTSIDE FAUCETS (2)   |
| 0 |    | SPRINKLER SYSTEM BACKFLOW PREVENTER ANTISIPHON VALVE NO. STATIONS () WINTERIZED |
| 0 |    | OIL LINE CHECK VISUAL 5-MINUTE CHECK  |
|   | OK | GAS LINE CHECK VISUAL 5-MINUTE CHECK  |
| 0 |    | WATER METER CHECK VISUAL 5-MINUTE CHECK   |
| 0 |    | DRAIN FIELD   |
| 0 |    | WELL  |
|   | X  | COUNTY/CITY WATER-SEWER   |

©Copyright 2001 Housing Inspection Foundation

#### PLUMBING, INSIDE

NOTE: PIPES AND PLUMBING IN WALLS, IN OR UDER CONCRETE SLABS OR CONCEALED BY PERSONAL EFFECTS AND THEIR QUALITY, CONDITION ORPURIFICATION OF WATER IS NOT INCLUDED IN THIS INSPECTION.

|   | OK | KITCHEN FAUCET & DRAIN   |
|---|----|--|
|   |    |  |
| 0 |    | UTILITY FAUCET & DRAIN   |
|   | OK | LAVATORIES (2)   |
|   | OK | TUBS (1)   |
|   | OK | SINKS (2)  |
|   | OK | SHOWERS (2)  |
|   | OK | COMMODES (2)   |
|   | OK | WATER HEATER () GAS (X) ELECTRIC SIZE 40 Gallons No. OF UNITS, One |
| 0 |    | WATER HEATER PAN AND OVERFLOW DRAIN                                |
| 0 |    | TEMPERATURE & PRESSURE VALVE OPERATION                             |
| 0 |    | WATER CONDITIONER PLUMBING   |
|   | OK | WATER HEATER LOCATION Closet in dining room.                       |
|   | OK | MAIN WATER SHUT OFF LOCATION Kitchen.                              |
|   |    |  |

# ELECTRICAL OUTSIDE

NOTE: LIGHTS AND EQUIPMENT ACTIVATED BY PHOTOCELL SWITCHES ARE NOT CHECKED. ALSO, LANDSCAPE AND EXTERIOR GROUNDS LIGHTING IS NOT INCLUDED IN THIS INSPECTION. ANTIQUATED WIRING UPDATED. IT CREATES A POSSIBLE HAZARD.

TYPE OF WIRING IN PANEL: () COPPER () ALUMINUM () CIRCUIT BREAKERS () FUSES

|   | OK | SERVICE ENTRANCE / METER Left side of house. |
|---|----|--|
| 0 |    | SERVICE PANEL – LOCATION                     |
| 0 |    | SUB SERVICE PANEL – LOCATION                 |
|   | OK | GFCI-OUTLETS                                 |
|   |    |  |
| 0 |    | POOL/SPA ELEC.                               |
|   | OK | OUTLETS                                      |

#### **ELECTRICAL, INSIDE**

NOTE: ONLY REPRESENTATIVE NUMBER OF ACCESSIBLE OUTLETS IS CHECKED. SECURITY SYSTEMS ARE NOT INCLUDED IN THIS INSPECTION

|   | OK | FIXTURES – SWITCHES AND OUTLETS         |
|---|----|---|
|   | OK | BREAKER BOX – LOCATION Laundry room.    |
|   | OK | DOORBELL/CHIME                          |
|   | OK | SMOKE DETECTORS                         |
|   | OK | GFCI () GARAGE () KITCHEN (X) BATHROOMS |
|   | OK | CARBON MONOXIDE TESTER                  |
|   |    |   |
|   |    |   |
| 0 |    | BACK UP NATURAL GAS GENERATOR           |

#### **FIREPLACE**

|   | OK | FIREPLACE (X) GAS (X) WOOD () OTHER Gas insert. |
|---|----|---|
|   |    | WOOD STOVE                                      |
|   | OK | (X) DIRECT VENT () NON-DIRECT VENT              |
|   | OK | LINTEL-DAMPER-FLUE                              |
|   | OK | MANTEL FIXTURES - SWITCHES AND OUTLETS          |
|   | OK | CHIMNEY   |
| Χ |    | CHIMNEY CAP See notes on chimney cap.           |

©Copyright 2001 Housing Inspection Foundation

#### **HEATING**

NOTE: ONLY THE EMERGENCY HEAT MODE IS CHECKED ON HEAT PUMPS WHEN TEMPERATURE IS ABOVE 80°. WE RECOMMEND THE HEATING SYSTEM IS COMPLETELY SERVICED BEFORE EACH HEATING SEASON. FILETERS SHOULD BE CHANGED, AS NEEDED (AT LEAST EVERY 2 MONITHS).

CHECKING HUMIFIDERS, ELECTRIC AIR FILTERS AND PROPER AIR FLOW BALANCE IS NOT INCLUDED IN THIS INSPECTION.

|  | OK | () CENTRAL () GAS () FLR/WALL (X) ELECTRIC () RADIANT () HEAT PUMP () OIL. |
|--|----|--|
|  | OK | BURNER/ELEMENT   |
|  | OK | (X) FLOOR VENTS () CEILING VENTS   |
|  | OK | THERMOSTAT 'S  |
|  | OK | BASEBOARD  |
|  | OK | DUCT-WORK (X) METAL (X) FLEX   |
|  | OK | NUMBER OF UNITS One.   |
|  |    |  |
|  |    |  |

#### **COOLING**

NOTE: AIR CONDITIONING UNITS ARE NOT CHECKED WHEN OUTSIDE TEMP IS BELOW 80°. WE RECOMMEND THE A.C. UNIT BE COMPLETELY SERVICED BEFORE EACH COOLING SEASON AND THE CONDENSATE DRAIN BE FLUSHED WITH A CHLORINE BLEACH EVERY 2 MONTHS DURING THE COOLING SEASON TO PREVENT CLOGGING.

|   |   | OK | (X) CENTRAL () ZONED (X) REFRIGERATED () SASH/WALL (X) EVAPORATIVE     |
|---|---|----|--|
|   |   | OK | NUMBER OF UNITS One.   |
|   |   | OK | COMPRESSOR   |
|   |   | OK | CONDESNER – COIL & FAN   |
|   |   | OK | CONDENSATE DRAIN   |
|   |   | OK | THERMOSTAT   |
|   |   | OK | CEILING FANS   |
|   |   | OK | ATTIC FANS () CEILING (X) ROOF   |
|   |   | OK | BATH VENT FANS   |
| 0 |   |    | WINDOW UNIT'S  |
|   | Χ |    | See notes on duct in crawl space. See notes on disconnect box at unit. |

NOTE: FOUNDATION ON CLAY SOIL REQUIRES ADEQUATE AND EVEN MOISTURE AROUND THE PERIMETER FO THE FOUNDATION THE ENTIRE YEAR

TO PREVENT MOVEMENT. TREES AND SHRUBS CAN CAUSE FOUNDATION DAMAGE WHEN GROWING TOO CLOSE. WATER SHOULD NOT BE PERMITTED TO POND OR ERODE, UNDER OR ALONG ANY PART OF THE FOUNDATION. DEPENDING ON THE DESIGN AND METHOD OF

STRUCTURAL

ORIGINAL CONSTRUCTION OF A PIER AND BEAM FOUNDATION, THE FLOOR SYSTEM MAY NEED LEVELING PERIODICALLY.

| CONDAI | ONDATION |    |   |  |  |
|--------|----------|----|---|--|--|
|        |          | OK | OBSERVATIONS  |  |  |
|        |          |    |   |  |  |
|        |          | OK | VENTILATION Crawl space-foundation vents.             |  |  |
|        | Χ        |    | See notes on water leak in sewer pipe in crawl space. |  |  |
|        |          |    |   |  |  |

#### **FOUNDATION DRAINAGE**

| Ξ. | 0.0000000000000000000000000000000000000 |  |    |              |  |  |
|----|---|--|----|--------------|--|--|
|    |   |  | OK |              |  |  |
|    |   |  | OK | SCREEN PORCH |  |  |
|    |   |  |    |              |  |  |
|    |   |  |    |              |  |  |

#### **EXTERIOR WALLS**

|  | OK | () STONE (X) FRAME () BRICK () SHAKES (X) CONCRETE/CINDER BLOCK () STUCCO () POURED CONCRETE |
|--|----|--|
|  | OK | SIDING Vinyl.  |
|  |    |  |
|  |    |  |

## GARAGE

|  | OK | GARAGE DOOR OPENER      |
|--|----|-------------------------|
|  | OK | AUTO REVERSE            |
|  | OK | DOORS (X) METAL () WOOD |
|  | OK | DETACHED GARAGE         |

### ROOF

NOTE: WEATHER CONDITIONS, WIND, HAIL AND EXTREME TEMPERATURES AFFECT ALL ROOFING FROM DAY TO DAY, SO, CONTINUAL OBSERVATION IS REQUIRED. () ASPHALT () WOOD SHINGLE () SLATE/TILE () BUILT-UP

|  | OK | OBSERVATIONS           |
|--|----|------------------------|
|  | OK | PLUMBING VENT PIPES    |
|  | OK | RIDGE VENT             |
|  | OK | ROOF VENTS – RAIN CAPS |
|  | OK | GUTTERS – DOWNSPOUTS   |
|  | OK | SOFFITS – FASCIA       |
|  | •  |                        |
|  |    |                        |

### ATTIC: ATTICS ARE NOT ALWAYS TOTALLY OBSERVABLE

|   | OK | TRUSS ROOF SYSTEM (X) YES () NO                               |  |  |
|---|----|---|--|--|
|   | OK | RAFTERS – PURLINS – COLLAR TIES                               |  |  |
|   | OK | DECKING   |  |  |
|   | OK | CEILING JOIST – RATER TIES (X) YES () NO                      |  |  |
|   | OK | INSULATION TYPE (X) BLOWN () BATT AVERAGE HEIGHT 8-10 Inches. |  |  |
|   | OK | VENTILATION   |  |  |
|   | OK | GABLE LOUVERS & SCREENS                                       |  |  |
| 0 |    | TURBINES POWER VENTS  |  |  |
|   |    |   |  |  |
|   |    |   |  |  |

NOTE: ONLY A REPRESENTATIVE NUMBER OF ACCESSIBLE WINDOWS are CHECKED FOR OPERATION AT THIS INSPECTION. AS THERMAL PANE WINDOWS LOSE THEIR VACUUM, MOISTURE MAY APPEAR, AND THEN DISAPPEAR, DEPENDING ON INSIDE AND OUTSIDE TEMPERATURE,

#### **INTERIOR**

BAROMETRIC PRESSURE AND THE HUMIDITY LEVEL. THEREFORE, WINDOWS ARE LISTED AS OBSERVED AT TIME OF INSPECTION ONLY, AND NO WARRANTY IS IMPLIED.

|   | OK | CEILINGS AND WALLS Some surface cracks and scrapes on walls.    |
|---|----|---|
|   | OK | FLOORS  |
| Χ |    | DOORS See notes on kitchen door.                                |
|   | OK | WINDOWS   |
|   |    |   |
|   | OK | WATER PENETRATION No signs of <u>present</u> water penetration. |
|   |    |   |
|   |    |   |

## **EXTERIOR**

|  | OK | WINDOWS               |
|--|----|-----------------------|
|  | OK | DOORS                 |
|  | OK | WINDOW & DOOR TRIM    |
|  | OK | CAULK & WEATHER STRIP |
|  |    |                       |
|  |    |                       |

#### POOL/SPA

NOTE: POOLS & SPAS ARE CHECKED FOR EQUIPMENT ONLY, NOT LEAKAGE, POOL TIMER FUNCTION

| 0 | () GUNITE () FIBERGLASS () VINYL |  |
|---|----------------------------------|--|
|   |                                  |  |
| 0 | TYPE-COPING-DECK                 |  |
|   |                                  |  |
| 0 | HEATER                           |  |
| 0 | POOL SWEEP                       |  |
| 0 | DIVING BOARD () LADDER () SLIDE  |  |

©Copyright 2001 Housing Inspection Foundation

#### **LAUNDRY ROOM**

|   |   | OK | WASHER HOOK-UP  |  |
|---|---|----|---|--|
|   | Χ |    | WASHER OVERFLOW PAN & DRAIN See notes on washer drain line. |  |
|   |   | OK | DRYER HOOK-UP   |  |
|   |   |    |   |  |
|   | Χ |    | DRYER VENT See notes on dryer exhaust pipe vent.            |  |
|   |   |    |   |  |
| 0 |   |    | DRYER (X) ELECTRIC () GAS                                   |  |

NOTES: PLEASE SEE ATTACHED NOTES AND PICTURES:



The disconnect box for the AC unit is rusted. The bottom is completely rusted out. Because this wiring is 220 volts and the connections are open, it is recommended a new box and breaker be installed.




The mortar on top of the brick chimney is cracked and loose at one corner.




The nail in the corner flashing on the bottom of the brick chimney has popped up. This nail should be secured and caulked.



Some of the BAT insulation has fallen down under the house.



There is a small area under the house where the insulation is missing. It appears to be in the hall and part of the master bedroom.



There is a small water leak in the sewer drainpipe under the house. It appears to be from the sink in the back bathroom. This coupling will need to be replaced and sealed. <u>See picture below.</u>



The main truck line under the house is rusted where its laying on the ground. This is directly below the water leak mentioned above. The water is dripping on the ground and rusting the bottom of the unit. The trunk line should be cleaned and sealed. A small piece of plastic sheathing should also be installed under the metal duct.



The drain line for the washer should be sealed. This is <u>ONLY</u> because the drain is within 24" of the electric panel box.



The dryer exhaust line has too many curves. The exhaust line should be as short and direct as possible. Clogged dryer vents are the number one cause of homeowner fires.




The garbage disposal only hums when engaged. It most likely needs to be reset. The reset button is usually located on the bottom of the unit.




The door between the kitchen and hall does not close completely. Hinge adjustments can usually adjust the door.




The main return air vent is in the hall closet floor (next to master bedroom). There is currently NO filter system. The entire return duct is dirty and should be cleaned. See pictures below.




This is the view inside the main return air trunk. It was dirty as far back as I could see. See pictures below.



This is a view further down the return air trunk line.



Each room (except the addition) has its own return air vent and duct. Each one is dirty and needs to be cleaned. See pictures below.



The entire return trunk line should be cleaned. To keep it clean and protect the unit, some type of filter system should be installed. Most likely at a central location or at each return.

#### IMPORTANT AGREEMENTS AND LIMITATIONS

SPECIAL NOTE: THE FOLLOWING IS NOT INCLUDED IN THIS INSPECTION: 1. WATER OR AIR QUALITY 2. PRESENCE OF TOXIC OR CARCINOGENIC MATTER EMITTED FROM THE GROUND, BUILDING MATERIALS, IN WATER OR AIR SUPPLY OR FROM THE OPERATION OF ANY EQUIPMENT 3. ITEMS THAT ARE OBSTRUCTED, INACCESSIBLE OR NOT IN PLAIN VIEW. - The Client is hereby informed structural and mechanical insurance is available for a nominal fee From insurance companies. Your real estate agent may be able to help you with obtaining structural Alternatively, mechanical insurance coverage. The client understands that the Comments and Notations made On this report is subjective opinion of the inspector based on observations at the time of inspection. Therefore, the INSPECTOR desires it be clearly understood he offers NO WARRANTY concerning Future operation or condition of any item inspected - OR - that all defects of such items were observed At the time of inspection and noted on the report. THEREFORE, the INSPECTOR does not imply that He warrants or guarantees any item regardless of whether they were inspected or reported.

#### 1. What We Do:

- a. All inspections are performed in accordance with Standards of Practice. The inspection is of conditions, which are present and visible at the time of the inspection. All mechanical and electrical equipment, systems, and appliances are operated in normal modes and operating range at the time of the inspection.
- b. We shall observe, render an opinion, and report which of the parts, components and systems are not functioning at the time of the inspection or need repair and report on visible existing or recognized hazards.
  - c. If you have questions, we will explain what we saw about the item.

#### 2. What We Do Not Do:

- a. We do not make guarantees, warranties, representations, or insure the future performance or condition of any item. If you want a warranty, guarantee, or insurance policy, you must obtain it from a warranty or insurance company. Please remember that almost every item in any used home is in *used condition* and has ordinary wear and tear, and all houses will change and deteriorate in the future. WE DISCLAIM ALL OTHER WARRANTIES.
- b. We do not inspect any item, which we cannot see in a normal inspection. For example, we do not Move furniture, rugs, carpet, paintings, appliances, or other furnishings in performing an inspection. We do Not un-cover buried pipes or items. We cannot see items covered by wallpaper, flooring, or plants. Repairs Alternatively, remodeling may hide evidence of prior damage or defects. We do suggest that you ask the seller about

Repairs that are covered up or any previous problems because we DO NOT report on past conditions that Appear corrected. We do not inspect for latent defects, therefore, you should obtain a copy of the sellers Disclosure statement.

c. We do not inspect for building codes, soil analysis, adequacy of design, capacity, efficiency size, value, floor plain location, pollution, habitability, environmental hazards such as asbestos, UFFI, EMF, lead base paint, etc. Please remember older homes do not meet the same standards as newer homes, even though items in both may perform the function for which they are intended.

©Copyright 2001 Housing Inspection Foundation

- d. We do not allow the inspector to change or add to these printed provisions in any way.
- e. We do not hold ourselves to be specialists for any item or engineers. We are a general real Estate improvement Inspection Company. If we report an item is not performing its intended function, needs repair, or shows evidence of prior damage, we urge you to have that item examined by a specialist before purchasing the house. We do not and cannot give cost estimates to repair any item.

#### 3. What You Must Do:

- a. If you have any complaints about our inspection, you must notify us in writing within seven days After you discovered any problem, and allow us to re-inspect before changing the condition on the item, Except in an emergency.
- b. If we report an item needs immediate repair, or is not performing its intended function or shows Past damage and you intend to purchase the property anyway; you should first have the item re-inspected by a specialist in that field (i.e., foundation structural engineer//plumbing plumber).
- c. You agree that, to the extent allowed by law, any damages for breach of this contract or report are limited to the amount of the inspection fee only.
  - d. If you sue on this inspection, but do not prevail, you agree to pay all our reasonable attorney's fees.
- e. You represent to us that (1) the inspector has not made any oral representations that are different from, or in addition to, what is written in this report, and (2) you agree to each provision of this report by relying on it any way, whether or not you sign it.
  - f. You shall not allow anyone else to use or rely on this report without prior written consent

THIS REPORT CANNOT AND DOES NOT REPRESENT THE OPERATION OR CONDITION OF ANY ITEM AFTER THE DATE AND TIME OF THIS INSPECTION. ALL WARRANTIES EXPRESSED OR IMPLIED ARE DISCLAIMED.

| Dated this 12th | Day of  | September 2021 |
|-----------------|---------|----------------|
| NAME Jesse D    | odd     | SIGNATURE      |
| REGISTERED H    | HOUSING | GINSPECTOR #   |

Copyright 2001 Housing Inspection Foundation Housing Inspection Form #2700 7/99

Housing Inspection Foundation • 1224 North Nokomis NE • Alexandria, Minnesota 56308 USA Tel: (320)763-6350 • Fax: (320)763-9290 • E-Mail: hif@iami.org • Website: http://www.iami.org