


Address: 1771 Rawling Hills Rd. Blackstone VA.

6-23-99



ST = Septic tank GWD = Grey water discharge (W) = Well

Septic Tank

Location of septic tank: Behind house between out Bldgs. Location undetermined

- Appears Functional** Approximate tank size: 1,000 gallons # of Bedrooms 2 # of Baths
- Dry around tank Wet around tank Evidence of poor drainage Surface raised/settled
- Well 50' or more from tank Well less than 50' from tank Well location unknown
- Depth to top of tank: _____ inches Distance of tank from house: 78 feet
- House vacant at time of inspection Recommend adding _____ ounces of Rid-X™ to reactivate cesspool

Comments: _____

Grey Water

Location of grey water discharge: Behind House in Field Location undetermined

- Appears Functional** Integrated with septic system Grey water discharges on surface
- Evidence of poor drainage Surface raised/settled
- Well 50' or more from discharge Well less than 50' from discharge Well location unknown

Comments: Recommend cleaning around end of discharge pipe to expose pipe

Well

Location of well: _____ Location undetermined

- Appears Functional** Centrifugal pump—1 pipe (shallow well) Centrifugal pump—2 pipe (deep well) Submersible
- Evidence of leaks Approximate size of pressure tank: _____ gallons _____ P.S.I. differential
- Gallons per cycle: _____ Flow rate: gallons per minute: _____ Water pressure: _____ P.S.I.
- Tank is short cycling Pressure gauge provided Pressure gauge is nonfunctional
- Tank is leaking Tank is corroding Tank is corroding
- Pressure tank is located in: garage/crawlspace/well housing/other: _____
- Well housing damaged Well housing insulated Well housing not insulated
- Heat source provided: light/heater Outlet Grounded outlet GFCI outlet
- Bacteria test performed (see water test page) Bacteria test recommended

Comments: _____

◆ Item in need of additional attention or repair. * Item unsafe or below current safety standard