


NOTES:


1. No Title Report Furnished
2. Easements Not Shown May Exist
3. This Plat Is Based On A Field Survey Dated 3 August 2021
4. This Property Lies Inside The Area of Minimal Flood Hazard (Zone X)



Denotes Rod Found Unless Stated
 Denotes Overhead Power Line
 Denotes Creek or Branch
 Denotes Gravel Road

LINE	BEARING	DISTANCE
L1	S 23°11'28" E	260.00'
L2	S 69°24'20" W	20.00'
L3	S 23°11'28" W	259.98'
L4	N 08°51'50" W	209.93'
L5	N 00°16'53" W	51.43'
L6	S 09°52'23" E	107.43'
L7	S 05°17'57" E	250.86'
L8	S 13°08'37" E	350.65'
L9	S 04°09'45" E	33.55'
L10	S 88°49'06" W	107.30'
L11	S 84°25'58" W	198.58'
L12	S 81°44'53" W	93.32'
L13	N 83°44'12" W	406.39'
L14	N 11°30'21" W	292.70'
L15	S 11°30'21" E	286.18'
L16	N 11°31'49" W	220.51'

Lewis Surveying Inc.
 David A. Lewis, L. S.
 518 Graves Road
 Graves Mill VA 22727
 (540) 948-7136
 Copyright © 2021



00044C