

MATTHEWS SANITATION SERVICES, LLC

1226 HUDSON RD

VIRGINIA, VA 24598

(434) 572-6098 / (434) 575-1535

[matthews.sanitation03@gmail.com](mailto:matthews.sanitation03@gmail.com)

ON-SITE WASTEWATER INSPECTION

PROPERTY ADDRESS: 2181 Siouan Rd. Ebony, VA

CLIENT NAME: Neikirk Holdings, LLC

DATE OF INSPECTION: 10/09/2024

SIZE OF TANK: 1,000 Gallon

LOCATION OF SEPTIC TANK AND SEPTIC DETAILS: The septic tank is located on the right-hand side of the house.

FROM THE HOUSE OR STRUCTURE: 15 Ft.

FROM THE WELL, IF APPLICABLE: 50 + Ft.

FROM PROPERTY LINE IF SAID PROPERTY LINES ARE KNOWN OR IF MARKED: Unknown.

ACCESS RISER(S) \_\_\_ YES \_\_\_ X \_\_\_ NO

TANK LIDS INTACT YES \_\_\_ NO \_\_\_ X \_\_\_

TANK HAS BAFFLE WALL \_\_\_ X \_\_\_ YES \_\_\_ NO / CONDITION OF BAFFLE WALL: Good.

INFLOW TO TANK IS NOTED AS SUFFICIENT, INSUFFICIENT OR BLOCKED: Sufficient. The line was snaked and it's open.

THE WATER LEVEL IN TANK IS RELATIVE TO TANK OUTLET: The septic tank is at working level.

OUTLET Tee IS PRESENT \_\_\_ X \_\_\_ YES \_\_\_ NO / CONDITION OF OUTLET Tee: Good.

OUTLET HAS FILTER \_\_\_ YES \_\_\_ X \_\_\_ NO / CONDITION OF FILTER:

EFFLUENT LEAVES THE OUTLET  YES  NO

ROOTS PRESENT IN TANK  YES  NO / EXTENT OF ROOTS:

EVIDENCE OF TANK LEAKAGE: No.

EVIDENCE OF NON-PERMITTED CONNECTIONS, SUCH AS DOWNSPOUTS OR SUMP PUMPS: No.

DOES SYSTEM HAVE PUMP TANK? No.

LOCATION OF CONTROL PANEL/ALARM: NA.

ELECTRICAL CONNECTIONS ARE IN PLACE AND PROPERLY GROUNDED: NA.

AUDIBLE AND VISIBLE ALARMS (AS APPLICABLE) WORK: NA.

PUMP TURNS ON AND EFFLUENT IS DELIVERED TO NEXT COMPONENT: NA.

UNABLE TO OPERATE PUMP DUE TO LACK OF ELECTRICITY AT SITE AT TIME OF INSPECTION:

DISPERSAL FIELD: TYPE OF SYSTEM:  CONVENTIONAL /  ALTERNATIVE

CONDITIONS PRESENT THAT PREVENTED OR HINDERED THE INSPECTION:

ADVERSE CONDITIONS PRESENT THAT REQUIRES REPAIR OR SUBSEQUENT OBSERVATION OR WARRANTS FURTHER EVALUATION BY THE LOCAL HEALTH DEPARTMENT\_:

OTHER PERTINENT FACTS NOTED DURING INSPECTION: There are three drain field lines.

DATE TANK WAS LAST PUMPED: Unknown.

NO REPRESENTATION, WARRANTIES OR OPINIONS ARE HEREBY GIVEN, WRITTEN OR EXPRESSED OTHERWISE, AS TO THE FUTURE PERFORMANCE OF THE ONSITE WASTEWATERSYSTEM DESCRIBED HEREIN. THIS ONSITE WASTEWATER SYSTEM INSPECTION IS A PRESENTATION OF SYSTEM FACTS IN PLACE ON DATE OF INSPECTION.

INSPECTOR SIGNATURE:  DATE: 10/9/24

VA CERTIFICATION- #1942001226 #1944001056

MATTHEWS SANITATION SERVICES, LLC  
1226 HUDSON RD  
VIRGINIA, VA 24598  
434-572-6098  
[matthews.sanitation03@gmail.com](mailto:matthews.sanitation03@gmail.com)

This document serves as evidence that the Septic System on the property located at 2181 Siouan Rd. Ebony, VA is in compliance with the requirements set down by the State of Virginia, that the soils around the septic tank and over the drain field be firm and show no evidence of effluent breakout. The compliant conditions were determined during a visual inspection of the surface area and in probing the soils in the area of septic tank and the drain field.

The inspection was performed on 10/09/2024.

**\*\*INSPECTIONS ARE GOOD FOR 30 DAYS\*\***

Thank you,

*Diag S. Matthews*

Matthews Sanitation Services, LLC  
License # 1942001226