

# Loudoun County, Virginia www.loudoun.gov

Friday, July 25, 2014

(map not to scale)



PIN 231-48-7463 / Tax Map # /48/A//21//11/ 204 NTH KING ST Primary Zoning LB: R-HD

# RECONNAISSANCE LEVEL SURVEY REPORT



# DEPARTMENT OF HISTORIC RESOURCE RECONNAISSANCE SURVEY FORM

DHR Idenfication Number: 253-0035-0643

Other DHR Number:

Property Date(s) 1850-1865

PROPERTY NAMES

House, 204 North King Street House, 46 North King Street

EXPLANATION

Current Historic

County/Independent City: Loudoun

State: Virginia

Magisterial District:

Tax Parcel: 48A-21-11

USGS Quad Map Name: LEESBURG

UTMs of Boundary: \*\*\*\*\*\*\*\*\*\*\*

Center UTM: \*\*\*\*\*\*\*\*\*\*\*

Restrict location and UTM data? N

ADDRESSES

Number

Thoroughfare Name

Explanation

North King Street

Current

46

North King Street

Number change

Vicinity:

Town/Village/Hamlet: Leesburg

Name of National Register Historic District:

Leesburg Historic District

Name of DHR Eligible Historic District:

Name of Local Historic District:

Old and Historic District (Leesburg)

Physical Character of General Surroundings: Town

Site Description/Notable Landscape Features:

The house sits close to the street on a level lot with mature trees.

Ownership: Private

NR Resource Type: Building

WUZITS

Seq. #	# of	Wuzit Types	Historic?
1.0	1	Single Dwelling	Historic
1.1	1	Garage	Historic
1.1	1	Barn	Historic

TOTAL: Historic:

3

### PRIMARY RESOURCE EXTERIOR COMPONENT DESCRIPTION

onent	#	Comp Type/Form	Material	Material Treatment
Foundation Structural System Door(s) Window(s) Portico Roof Chimney		Solid Frame Single Leaf Sash, double-hung 1-story, 1-bay Gable: Front Interior end	Stone Wood Wood Wood Metal Brick	Random Rubble German Siding Paneled 6/6 Turned Posts Standing Seam Corbeled Cap

#### INDIVIDUAL RESOURCE INFORMATION

SEQUENCE NUMBER: 1.0 WUZIT: Single Dwelling

Primary Resource? Yes

Estimated Date of Construction: 1850-1865

Source of Date: Site Visit State Survey

Architectural Style: Other

Description:

The three-bay wide vernacular dwelling features cornice returns, a two-light transom above the entry, and board-and-batten siding on the north and south elevations. Queen Anne in detail, the portico features scroll-sawn brackets at the corners.

Condition: Good

eats to Resource: None Known

Additions/Alterations Description:

The facade of the foundation has been clad with a brick veneer. There is a 2-story frame addition on the rear of the house that was built soon after the original construction. There is also a 1-story, rear, frame addition from the 1920s.

Number of Stories: 2.5

Interior Plan Type:

Accessed? No

Interior Description:

SEQUENCE NUMBER: 1.1 WUZIT: Garage

Primary Resource? No

Estimated Date of Construction: 1920-1935

Source of Date: Site Visit State Survey

Architectural Style: Other

Description:

There is a 1-bay wide wood frame garage with board and batten siding. The garage has a 2-leaf, sliding, wood door that is paneled with diagonal matchbaord treatment, a 6-light window on the south elevation, and a front gable roof with standing seam metal.

Condition: Good

Threats to Resource: None Known

Additions/Alterations Description:

Number of Stories: 1.0

erior Plan Type:

Accessed? No

Interior Description:

SEQUENCE NUMBER: 1.2 WUZIT: Barn

Primary Resource? No

Estimated Date of Construction: 1900 ca

Source of Date: Site Visit State Survey

Architectural Style: Other

Description:

There is a vertical board barn with 1-leaf, vertical board doors on both the north and west elevations. It sits on a poured concrete foundation, and has a front gable, standing seam metal roof with exposed rafter tails.

Condition: Good

Threats to Resource: None Known

Additions/Alterations Description:

The alterations to the barn include a 1-story, brick addition on the east elevation and roll-up doors that were installed on the north elevation.

Number of Stories: 2.0

Interior Plan Type:

essed? No

Interior Description:

Relationship of Secondary Resources to Property:

DHR Historic Context: Architecture/Community Planning

Domestic

Subsistence/Agriculture

Significance Statement:

su 1975 survey also This modest frame dwelling was constructed during the second period of growth (circa 1830-1878) for the town of Leesburg. Vernacular in style, the house is reflective of the buildings that were constructed within the corporate boundaries of Leesburg during this time. In 1858, the corporate boundaries of the town were expanded, as seen on Gray's New Map of Leesburg from 1878. The dwelling is located along King Street, an original road in the Nicholas Minor section of town and known in the colonial era as the Old Carolina Road, connecting Maryland to the Carolinas. King Street was a major thoroughfare throughout the history of Leesburg, with dwellings and commercial buildings constructed upon its length. Many of the larger lots of land along North King Street have been subdivided with smaller houses subsequently built upon them. The house is contributing to both the National Register Historic District and the Leesburg Old and Historic District.

GRAPHIC DOCUMENTATION

Medium Medium ID # Frames Date

#### BIBLIOGRAPHIC DATA

Sequence #: 1.0 Bibliographic Record Type: Map

Author: Sanborn Map Company

Citation Abbreviation:

Fire Insurance Maps of Leesburg 1886-1937

Notes:

Sequence #: 1.1 Bibliographic Record Type: Survey, DHR

17988

Author: Lewis, John (1972) and Hartzog, Lader & Richards (1975)

Citation Abbreviation:

Reconnaissance level architectural survey of Leesburg HD

Notes:

Sequence #: 1.2 Bibliographic Record Type: Map

Author: Gray, O.W.

Citation Abbreviation:

Gray's New Map of Leesburg, 1878

Notes:

# CULTURAL RESOURCE MANAGEMENT EVENTS

Date: 1/29/2000

Cultural Resource Management Event: Reconnaissance Survey

Organization or Person: RJW/CVN/AMD-Traceries

# Associated with Event: 253-0035-0643

CRM Event Notes or Comments:

# MAILING ADDRESS

Honorif:

First : William C : Whitmore Last

Suffix : Jr. Title :

Company:

Address: P.O. Box 267

State: VA


City : Leesburg Zip : 20178-0267 Country:


Phone/extension:

Individual Category Codes:


Mailing Address Notes:


Surveyor's Notes:





















TOWN OF LEESBURG, VIRGINIA - Architect	tural-Historic Inventory Card
104	
Street Address: 46 No. King Jt.	Tax Map: 48 A Block: 2 Lot:
Present Owner: Wm C. Whitrhes, Jr.	Deed Reference: WE84- 228
Mailing Address: Box 267	Style/Date Vernacular
	Construction Date Cic. 1890
Issent Use: residence - rental	source style
	Builder/Architect
Original Use: residence	Height in Stories 2
Original Owner:	Roof Form gable and to street
Physical Description (materials): Charm End to the street. Coverd in German sidil bound and batten. Picturesque structure Additions:	ing 3 bay, 2 story unit set gable ng except the northern side which is
Odditions to the rear Distinguishing Architectural Details:	
Exterior: Forch with turned posts, sau Cornice returns on pable end.	in brack-t-
Cornice returns on pable end.	orn brackers, and plain ballistracle.
Interior:	
224	
Alterations:	
Quildings: Type -2 Stry frame bar Condition - fair - good	n, cinderblock garage
Historic Significance: National State There was a pottery shop here C. 1900 - The p	Local
red bottoms.	The state of the s
	2
Architectural Significance:	Photo: Roll# 13 Negative 14
Outstanding Excellent	
Significant Contributory	THE ACTION AND ADDRESS OF THE ACTION
Physical Condition:	
Good Fair Poor	
Structure:	
Grounds:	
Neighborhood:	
Preservation Index: 4 B	
Comments:	
Comments:	26
Continue	
	THE THE WALL STREET

Filed By: M. Shormaker\_Date: 12175
HARTZOG, LADER & RICHARDS