Lot Number	Title	Description
0	Preview & Removal Information	*There Will Be No Buyer's Premium Added To The Buyer's Total For Each Item Purchased. However, There Will Be A 3% Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**
		Preview : (By Appointment Only-Mandatory-No Exceptions) Tuesday, February 12, 2019 (Hours Of Operation: 8:00 a.m 5:00 p.m.)
		Location 1:(Lot 1 -5) 4706 Airport Ave., Rosenberg, Tx 77471Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Friday, February 15, 2019/Monday, February 18, 2019 /Tuesday, February 19, 2019 (Hours Of Operation: 8:00 a.m 5:00 p.m.) Preview & Removal Contact: Brenda Chapa, (281)239-1356 Tracy Graves, (281)239-1351
		Location 2:(Lot 6) 2715 Cypress Point, Missouri City, Tx 77459 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Friday, February 15, 2019/Monday, February 18, 2019 /Tuesday, February 19, 2019 (Hours Of Operation: 8:00 a.m 5:00 p.m.) Preview & Removal Contact: Mary Wentz, (346)702-5006 Saundra Denman, (832)600-9204
	(1) 2005 Ford Freestar Van Vin #1944 - Will Need To Be Towed	Will Need To Be Towed - No Power - Gas - Battery: Dead - Does Not Run - Hydraulic Brakes - Automatic - Approx. Mileage Unknown - Interior Condition: Fair - Interior Problems: Needs Cleaning, Torn - Body Condition: Fair - Inspection Sticker Date: 07/19 - Body Problems: Paint Job Needed - Tires Condition: Poor - Tire Problems: Worn
		Current Condition Unknown
1		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.
2	(1) 2005 Chevy Astro Van Vin #6650	Engine Size/Type: 4.3L V6 - Gas - Battery: Yes - Runs - Transmission Type: 4 Speed - Automatic - Approx. Mileage Reads: 182,525**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Carpet Needs Major Cleaning - Body Condition: Poor - Inspection Sticker Date: 06/17 - Body Problems: Front Fender Damage & Scratch, Front Door Hinges Damage - Tires Condition: Fair
		Current Condition Unknown
		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.
3	(1) 2007 Chevy Malibu Sedan LS Vin #8992	Engine Size/Type: 3.9L V6 - Gas - Battery: Yes - Runs - Transmission Type: 4 Speed - Automatic - Approx. Mileage Reads: 133,152**Unknown Actual Mileage** - Interior Condition: Fair - Body Condition: Fair - Inspection Sticker Date: 07/19 - Body Problems: Rust On The Hood, Crack On Windshield - Tires Condition: Fair - Some Water In The Trunk
		Current Condition Unknown
		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.
4	(1) 2008 Chevy Uplander Maroon Van Vin #6637 - Will Need To Be Towed	Will Need To Be Towed - Gas - Battery: Dead - Does Not Run - Transmission Condition: Poor - Hydraulic Brakes - Automatic - Approx. Mileage Unknown - Interior Condition: Poor - Interior Problems: Needs Cleaning, Vent Broken On Top - Body Condition: Fair - Inspection Sticker Torn Off - Body Problems: Dents - Tires Condition: Fair
		Current Condition Unknown
		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.

5	(1) 2008 Chevy Uplander Dark Brown Van Vin #5241	Engine Size/Type: 4 Speed 3.9L V6 - Gas - Battery: Yes - Runs - Transmission Type/Condition: Unknown/4 Speed - Automatic - Approx. Mileage Reads: 159,120**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Glove Box Lever Broken, Carpet Needs Major Cleaning - Body Condition: Fair - Body Problems: Passenger Mirror Is Broken - Tires Condition: Fair - All Doors Work Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
6	(1) 2001 Chevy Malibu Vin #2687 - Will Need To Be Towed	Will Need To Be Towed - Gas - Battery: Dead - Engine Problems: Showing Many Codes, Stops & Will Not Start - Does Not Run - Transmission Condition: Fair - Automatic - Approx. Mileage Reads: 148,200**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Upholstery Torn - Body Condition: Poor - Inspection Sticker Date: 09/18 - Tires Condition: Fair - Per Repair Shop Vehicle Is Beyond Economical Repair - Auctioneers Recommends Preview Of This Unit Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**