Lot Number	Title	Description		
0	Preview & Removal Information	All purchases will be subject to a 13% buyer's premium.		
		Preview: Please Contact Seller For Preview Information		
		Location: Galena Park ISD Warehouse, 13705 B Force, Houston, TX 77015  Removal: Please view description on each lot for removal instructions-Removal Dates Will Be STRICTLY ENFORCED Preview & Removal Contacts: Lynn Nutt, (832)386-1006		
		Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Galena Park ISD And Must Contact Galena Park ISD For Requirement Information.***Movers Will Need To Check With The City On Moving Permits & Hours And Days Allowed**		
2	(1) Portable Building /Classrooms	Removal: STRICTLY ENFORCED(By Appointment Only - Mandatory - No Exceptions) Must Be Removed During Tuesday, June 4, 2019 - Friday, June 7, 2019  Building #: PB-05 A/B - Double - Year Mfg: Unknown - Approx. Size: 24' X 59' - No Restrooms - (2) Classrooms - Hardiplank Siding - Asphalt Roof - Metal Skid - (4) Wall Mount A/C Heat Units - Exterior Condition: Surface Scratches, Minor Damage On Hardiplank - Interior Condition: Some Dents On Wall - Double Entry On Front		
		- Current Condition Unknown		
		Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Galena Park ISD And Must Contact Galena Park ISD For Requirement Information.***		
4	(1) Portable Building /Classrooms	Removal: STRICTLY ENFORCED (By Appointment Only - Mandatory - No Exceptions) Must Be Removed During Tuesday, June 4, 2019 - Friday, June 7, 2019  Building #: PB-02 A/B PB06 - Double - Year Mfg: Unknown - No Restrooms - Approx. Size: 24' X 57' - No Restrooms - (2) Classrooms - Metal Siding - Metal Roof - Wood Skid - (2) Wall Mount A/C Heat Units - Exterior Condition: Dents & Scratches, More Dents On Rear Of Building Than Front - Interior Condition: Some Ceiling Tiles Have Water Stains/Could Be Current Roof Damage Or Leaks - Double Entry On Front		
		- Current Condition Unknown		
		Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Galena Park ISD And Must Contact Galena Park ISD For Requirement Information.***		
		Removal: STRICTLY ENFORCED (By Appointment Only - Mandatory - No Exceptions) Must Be Removed During Tuesday,		
5	(1) Portable Building /Classrooms	June 4, 2019 - Friday, June 7, 2019  Building #: PB-01 A/B Bldg.: PB51 - Year Mfg: Unknown - Double - Approx. Size: 24' X 57' - No Restrooms - (2)  Classrooms - Metal Siding - Metal Roof - Wood Skid - (2) Wall Mount A/C Heat Units - Exterior Conditions: Some Dents,  Scratches - Interior Condition: Will Need Some Painting, Has Pass Through Door Between Rooms - Double Entry In Front		
		- Current Condition Unknown		
		Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Galena Park ISD And Must Contact Galena Park ISD For Requirement Information.***		
	(1) Portable Building /Classrooms	Removal: STRICTLY ENFORCED (By Appointment Only - Mandatory - No Exceptions) Must Be Removed During Tuesday,		
6		June 4, 2019 - Friday, June 7, 2019  Building #: PB-04 A/B Bldg PB50 - Year Mfg: Unknown - Double - Approx. Size: 24' X 57' - No Restrooms - (2) Classrooms - Metal Siding - Metal Roof - Wood Skid - Exterior Condition: Minor Dents & Scratches - Interior Condition: Has A Pass Through Door Between Rooms, Walls Need Painting, Ceiling Stains On (1) Corner Of Room A - Double Entry In Front		
		- Current Condition Unknown		
		Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Galena Park ISD And Must Contact Galena Park ISD For Requirement Information.***		

7	(1) Portable Building /Classrooms	Removal: STRICTLY ENFORCED (By Appointment Only - Mandatory - No Exceptions) Must Be Removed By 4:00 pm Wednesday, May 1, 2019  Building #: PB16/T 5/6 - Double - Year Mfg: Unknown - Approx. Size: 24' X 57' - No Restrooms - (2) Classrooms - Metal Siding - Metal Roof - Wood Skid - (2) Wall Mount A/C Heat Units - Exterior Condition: Some Dents & Scratches, Very Light Appearance Of Prior Graffiti On Back In 3 Places, Most Of The Dents Are On The Back Of Building - Interior Condition: Has A Pass Through Door Between Classrooms, Walls Will Need Painting, Damage On Wall In Front Of A/C Heat Wall Mount Unit On T5 - Double Entry In Front  - Current Condition Unknown  Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Galena Park ISD And Must Contact Galena Park ISD For Requirement Information.***
10	(1) Portable Building /Classrooms	Removal: STRICTLY ENFORCED (By Appointment Only - Mandatory - No Exceptions) Must Be Removed By 4:00 pm Wednesday, May 1, 2019  Building #: PB13/T2/T1 - Year Mfg: Unknown - Double - Approx. Size: 24' X 57' - No Restrooms - (2) Classrooms - Metal Siding - Metal Roof - Wood Skid - (2) Wall Mount A/C Heat Unit - Exterior Condition: Surface Scratches & Dents, Peeling On Right Side Wall, Graffiti Line On Right Side Front, Peeling Paint On Doors, Dents All Over - Interior Condition: Wall Needs Painting, Damaged Ceiling Tiles In Both, Vent Cover Missing On Wall Mount Unit In T1 - Double Entry In Front  - Current Condition Unknown  Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Galena Park ISD And Must Contact Galena Park ISD For Requirement Information.***
11	(1) Portable Building /Classrooms	Removal: STRICTLY ENFORCED (By Appointment Only - Mandatory - No Exceptions) Must Be Removed By 4:00 pm Wednesday, May 1, 2019  Building #: PB14/T10/T9 - Year Mfg: Unknown - Double - Approx. Size: 24' X 57' - No Restrooms - (2) Classrooms - Metal Siding - Metal Roof - Wood Skid - (2) Wall Mount A/C Heat Units- Exterior Conditions: Some Dents & Scratches, Peeling Paint On Entry Doors & Door Frames, On Back Very Light Appearance Of Prior Graffiti Under Paint, Some Peeling On Right Side Of Building, (Approx. 3) Man Mad Holes On Top Near Roof On Right Side - Interior Condition: Will Need To Paint Walls, Peeling On Paneling Rear Windows, Several Tiles Have Water Spots On Ceiling On T9 & T10 - Double Entry On Front  - Current Condition Unknown  Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLP Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Galena Park ISD And Must Contact Galena Park ISD For Requirement Information.***