

Lot Number	Title	Description
0	Preview & Removal Information	<p><b>* There Will Be A 10% Buyer's Premium Added To The Buyer's Total For Each Item Purchased. There Will Be A 3% Convenience Fee On All Credit Card Purchases*</b></p> <p><b>Preview:</b> (By Appointment Only-Mandatory-No Exceptions) Monday, Monday, June 24, 2019 (Hours Of Operation: 8:00 a.m. - 4:30 p.m.)</p> <p><b>Location:</b> Student Transportation Services, 401 Carver St., Lockhart, Tx 78644 <a href="#">Driving Directions</a></p> <p><b>Removal: (By Appointment Only-Mandatory-No Exceptions)</b> Monday, July 8, 2019/Tuesday, July 9, 2019/Wednesday, July 10, 2019/Thursday, July 11, 2019 (Hours Of Operation: 8:00 a.m. - 4:30 p.m.)</p> <p><b>Preview &amp; Removal Contact:</b> Crystal Flores, (512)376-8703 or (512)398-0030 Tanya Homann, (512)398-0052</p> <p><b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</b></p>
1	(1) 2011 International PB 10500 School Bus Vin #2121 - Runs	<p>Unit #: 1171121 - Conventional Style - Passengers: 71 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Engine Problems: High Pressure Pump - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Type/Condition: Allison/Fair - Air Brakes - Approx. Mileage Reads: 145,229**Unknown Actual Mileage** - Interior Problems: Torn Seats - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
2	(1) 2011 International PB 10500 School Bus Vin #2247 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 1177247 - Conventional Style - Passengers: 77 - Engine Size/Type: Max Force Seven V8 - Engine In Front - Engine Problems: Bad Motor- Diesel - Battery: Dead - Does Not Run - Automatic Transmission - Transmission Type: Allison - Air Brakes - Approx. Mileage Reads: 83,486**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
3	(1) 2011 International PB 10500 School Bus Vin #2245 - Runs	<p>Bus #: 1177245 - Conventional Style - Passengers:77 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Engine Problems: High Pressure Pump - Diesel - Battery: Yes - Runs - Automatic - Transmission Type/Condition: Allison/Fair - Air Brakes - Approx. Mileage Reads: 123,695**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats - Body Condition: Fair - Body Problems: Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
4	(1) 2011 International PB 10500 School Bus Vin #2149 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 1171149 - Conventional Style - Passengers: 71 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Engine Problems: EGR Cooler - Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Transmission Type/Condition: Allison/Bad Electrical Condition - Air Brakes - Approx. Mileage Reads: 151,951 **Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

5	(1) 2011 International PB 10500 School Bus Vin #2145 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 1171145 - Conventional Style - Passengers: 71 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Engine Problems: Turbo DPF/DOC- Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Transmission Type/Condition: Allison/Fair - Air Brakes - Approx. Mileage Reads: 125,272**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats - Body Condition: Fair - Body Problems: Back Bumper Dent On Rear Back - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
6	(1) 2011 International PB 10500 School Bus Vin #8998 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 1148998 - Conventional Style - Passengers: Unknown - Engine Size/Type: Max Force 7 V8 - Engine In Front - Engine Problems: Meter, Turbo DPF DOC - Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Transmission Type/Condition: Allison/Fair - Air Brakes - Inspection Sticker Date: 05/18 - Approx. Mileage Reads: 182,582**Unknown Actual Mileage** - Wheel Chair Lift, Condition: Fair - Interior Condition: Poor - Interior Problems: Seats - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
7	(1) 2011 International PB 10500 School Bus Vin #3996 - Runs	<p>Bus #: 1148996 - Conventional Style - Passengers: Unknown - Engine In Front - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Type/Condition: Allison/Fair - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 196436**Unknown Actual Mileage** - Wheel Chair Lift, Condition Unknown - Interior Condition: Fair - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
8	(1) 2011 International PB 10500 School Bus Vin #3995 - Runs	<p>Bus #: 1148995 - Conventional Style - Passengers: Unknown - Engine Size/Type: Max Force 7 V8 - Engine In Front - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Condition/Type: Fair/Allison - Air Brakes - Approx. Mileage Reads: 176,165**Unknown Actual Mileage** - Wheel Chair Lift, Condition: Fair - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
9	(1) 2011 International PB 10500 School Bus Vin #3993 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 1148993 - Conventional Style - Passengers: Unknown - Engine Size/Type: Max Force 7 V8 - Engine In Front - Diesel - Battery: Yes - Does Not Run - Automatic - Transmission Type/Condition: Allison/Fair - Air Brakes - Inspection Sticker Date: 07/18 - Approx. Mileage Reads: 117,635**Unknown Actual Mileage** - Wheel Chair Lift, Condition: Fair - Interior Condition: Fair - Body Condition: Fair - Tires Condition: Fair - Tire Problems: Left Rear Low</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

10	(1) 2011 International PB 10500 School Bus Vin #2154 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 1171154 - Conventional Style - Passengers: 71 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Engine Problems: Broke Bolt Exhaust - Diesel - Battery: Yes - Unknown If Running - Automatic Transmission - Transmission Condition/Type: Fair/Allison - Air Brakes - Approx. Mileage Reads: 137,958**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
11	(1) 2011 International PB 10500 School Bus Vin #2152 - Runs	<p>Bus #: 1171152 - Conventional Style - Passengers: 71 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Engine Problems: Broken Bolts Exhaust In Engine Hood - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Condition/Type: Fair/Allison - Air Brakes - Approx. Mileage Reads: 144,368**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats - Body Condition: Fair - Body Problems: Dent's Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
12	(1) 2011 International PB 10500 School Bus Vin #2151 - Runs	<p>Bus #: 1171151 - Conventional Style - Passengers: 71 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Condition/Type: Fair/Allison - Air Brakes - Approx. Mileage Reads: 160,322**Unknown Actual Mileage** - Interior Problems: Torn Seats - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
13	(1) 2011 International PB 10500 School Bus Vin #2144	<p>Bus #: 1171144 - Conventional Style - Passengers: 71 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Type/Condition: Allison/Fair - Air Brakes - Approx. Mileage Reads: 151,526**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
14	(1) 2011 International PB 10500 School Bus Vin #2127 - Runs	<p>Bus #: 1171127 - Conventional Style - Passengers: 71 - Engine Size/Type: Max Force 7 V8 - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Type: Allison - Air Brakes - Approx. Mileage Reads: 148,498**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

15	(1) 2011 International PB 10500 School Bus Vin #2124 - Runs	<p>Bus #: 1171124 - Conventional Style - Passengers: 71 - Engie Size/Type: Max Force 7 V8 - Diesel- Battery: Yes - Runs - Automatic - Transmission Type: Allison - Air Brakes - Approx. Mileage Reads: 155,227**Unknown Actual Mileage** - Interior Problems: Torn Seats - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
16	(1) 2011 International PB 10500 School Bus Vin #2123 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 1171123 - Passengers: 71 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Engine Problems: EGR Coolant Heads - Diesel - Battery: Yes - Unknown If Running - Automatic Transmission - Transmission Type: Allison - Air Brakes - Approx. Mileage Reads: 176,735**Unknown Actual Mileage** - Interior Problems: Torn Seats - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
17	(1) 2011 International PB 10500 School Bus Vin #3997 - Runs	<p>Bus #: 1148997 - Conventional Style - Passengers: 48 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Type/Condition: Allison/Fair - Air Brakes - Inspection Sticker Date: 07/18 - Wheel Chair Lift, Condition Unknown - Interior Condition: Fair - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
18	(1) 2000 Chevy Bus Vin #1221 - Runs	<p>Unit #: 21112 - Conventional Style - Type A - Engine Size/Type: 5.7 - Engine In Front - Gas - Battery: Yes - Runs - Automatic Transmission Type/Condition: Chevy 350/Fair - Hydraulic Brakes - Approx. Mileage Reads: 154,212 **Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning- Body Condition: Fair - Body Problems: Paint Dull, Back Bumper Dent - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
19	(1) 2014 International CE300 Vin #6466 Runs	<p>Bus #: 1448466 - Conventional Style - Passengers: 48 - Engine Size/Type: Max Force 7 V8 - Engine In Front - Engine Problems: Lost Power - Diesel - Battery: Yes - Runs - Automatic Transmission Type/Condition: Allison/Fair - Air Brakes - Approx. Mileage Reads: 121,612**Unknown Actual Mileage** - Wheel Chair Lift - Interior Condition: Fair - Body Condition: Fair - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>