

Lot Number	Title	Description
0	Preview & Removal Information	<p>**There Will Be A 13% Buyer's Premium Added To The Buyer's Total For Each Item Purchased.**</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, July 16, 2019 (Hours Of Operation: 9:00 a.m. - 3:00 p.m.)</p> <p>Location: 1703 Wilson Rd., Building A, Humble, Tx 77396 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Monday, July 22, 2019/Tuesday, July 23, 2019/Wednesday, July 24, 2019 (Hours Of Operation: 9:00 a.m. - 3:00 p.m.)</p> <p>Preview & Removal Contact: auctions@humbleisd.net</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. A Forklift Is Available For Removal. Buyer Is In Charge Of Own Manpower, Tie Downs, Etc.</p>
1	(1) 1999 Chevy Step Van Vin #2634 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 528 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7L - Gas - Battery: Yes /Dead - Engine In Front - Engine Problems: Bad Starter, Engine Issues, Unknown If Other Issues - Auctioneer Recommends Preview - Does Not Run - Hydraulic Brakes - Automatic - Approx. Mileage Reads: 106,660**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seat On Drivers Side, Tears On Passenger Side, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 08/19 - Body Problems: Surface Scratches & Dents, Oxidized Paint, Some Scratches on Right Rear - Tires Condition: Good - Body: Union City Body Co - Cargo Area Length: Approx. 18' 5" Long - Wood Floor In Cargo Area</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
2	(1) 2001 Chevy Express Cargo 2500 Van Vin #9039 - Will Need To Be Towed	<p>Will Need To Be Towed - Recommend Salvage Use - Unit #: 551 - Passengers: 2 - Engine Size/Type: 5.0L - Gas - Battery: No - Engine In Front - Engine Problems: Bad Engine, Issues Unknown, Possible Parts Missing - Does Not Run - Hydraulic Brakes - Automatic - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Passenger Seat Missing, Needs Cleaning, Door Panels Are Loose Inside Unit, Rear View Mirror Is Loose, Parts Missing - Body Condition: Poor - Inspection Sticker Date: 10/13 - Body Problems: Missing Handle On Passenger Entry Door In Cargo Area, Peeling Paint, Oxidized Paint, Cargo Area Needs Cleaning, Rust On Roof, Needs Cleaning, Parts Missing, Missing Front Left Headlight, Crack On Windshield - Tires Condition: Tires Appear Fair To Good - Unit Has Been Sitting Up For Several Years & Tires Could Be Dry Rotted - Has Protection Cage/Weather Guard</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
3	(1) 1995 Ford F350 XL Crew Cab Dually Pickup Truck Vin #8695 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 505 - Conventional Style - Passengers: 6 - Engine Size/Type: 5.8L - Gas - Battery: No - Engine In Front - Engine Problems: Unknown, Has Been Sitting Up For Several Years, Ran When Parked - Does Not Run - Hydraulic Brakes - Automatic - Approx. Mileage Reads: Unable To Read/Dead Battery - Interior Condition: Fair To Poor - Interior Problems: Driver's Seat Poor & Will Need Replacing, Needs Cleaning, Rear View Mirror Needs Reattaching, Normal Wear - Body Condition: Fair - Inspection Sticker Date: 05/16 - Body Problems: Door Locks On Rear Left Broken, Oxidized Paint, Poor Repair On Left Dually Wheelcover, Surface Rust, Surface Scratches, Scratches, Mismatched Tailgate, Crack On Right Wheel Well, Has 3 Tool Boxes/Rusty/No Key, Peeling Paint, Rust On Roof, Hole Rust On Right Side Of Roof - Tires Condition: Fair - Ran When Parked In 2016</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

4	(1) 1997 Ford Aerostar Cargo Van Vin #8155 - Runs	<p>Unit #: 512 - Passengers: 2 - Conventional Style - Engine Size/Type: 3.0L - Gas - Battery: Yes/Dead - Engine In Front - Runs - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 66,840**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Needs Cleaning, Worn, Plastic Broken/Hole On Drivers Side Panel, Tear On Drivers Seat, Stains On Carpet In Front, Cargo Area Normal Wear - Body Condition: Poor - Body Problems: Needs Cleaning, Surface Rust, Surface Rust On Passenger Door, Right Front Hub Cap/Damaged, Some Dents, Surface Rust On Drivers Door, Rear Bumper Damage - Tires Condition: Fair - Tire Problems: Possible Dry Rot From Sitting Up</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
5	(1) 2001 Chevy 2500 Silverado Pickup Truck Vin #2653 - Runs	<p>Unit #: 549 - Conventional Style - Passengers: 3 - Engine Size/Type: 6.0 L - Gas - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Reads: 20,753**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Missing Headliner, Drivers Seat Poor, Panel Drivers Side Poor/Needs Replacing, Needs Cleaning, Radio Is Missing - Body Condition: Fair - Body Problems: Oxidized Paint, Dents, Surface Rust, Slight Damage On Right Front Bumper, Bumper Appears To Be Sitting Low On Front, Dent On Bed Front & Back On Right Side, Dent On Rear Bumper, Left Rear Bed Dent - Tires Condition: Fair - Tire Problems: Unit Has Been Sitting UP, Possible Dry Rot</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
6	(1) 1997 Ford Cargo Van Vin #8156 - Runs	<p>Unit#: 513 - Conventional Style - Passengers: 2 - Engine Size/Type: 3.0L - Gas - Battery: Yes/Dead - Bring A Backup Battery, Will Not Hold A Charge - Engine In Front - Engine Problems: Unknown - Runs - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 57,865**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seat, Worn Upholstery, Dash, & Door Handles, Passenger Door Panel Damage & Needs Replacing, Needs Headliner, Cargo Area Okay - Body Condition: Poor - Inspection Sticker Date: 01/18 - Body Problems: Oxidized Paint, Surface Rust On Doors, Scratches, Surface Scratches, Rust On Roof, Needs Cleaning, Bumper Damage, Rust Windshield Wipers, Unit Needs Cleaning - Tires Condition: Fair - Tire Problems: Some Tires Are Low On Air, Possible Dry Rot On Tires From Sitting Up</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
7	(1) 1998 Chevy Passenger Astro Van Vin #0453 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 930 - Conventional Style - Passengers: 8 - Engine Size/Type: Vortec - Gas - Engine In Front - Engine Problems: Unknown Problems, Will Turn Over But Will Not Start - Does Not Run - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 70,175**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Cracks & Parts Missing On Panel, Worn & Torn Door Panels, Needs Cleaning, Missing Rubber Floor Carpet - Body Condition: Poor - Inspection Sticker Date: 07/16 - Body Problems: Oxidized Paint, Surface Scratches, Scratched, Paint Cracked On Roof, Needs Cleaning - Tires Condition: Fair - Tire Problems: Possible Dry Rot From Sitting Up For Several Years</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

8	(1) 1998 Chevy Astro Passenger Van Vin #9399 - Runs	<p>Unit #: 928 - Conventional Style - Passenger: 5 - Engine Size/Type: 4.3L - Gas - Battery: Yes/Dead - Engine In Front - Runs - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 151,327**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Dash Covers Are Missing, Door Panels Are Worn & Damaged, Rear View Mirror Needs Reattaching - Body Condition: Poor - Inspection Sticker Date: 01/18 - Body Problems: Needs Cleaning, Peeling Paint, Cracks On Paint, Oxidized Paint, Surface Rust, Surface Scratches, Scratches, Dents, Scratches On Left Rear - Tires Condition: Fair - Tire Problems: Possible Dry Rot</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
9	(1) 1998 Chevy Astro Passenger Van Vin #9302 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 929 - Conventional Style - Passengers: 8 - Engine Size/Type: 4.3L - Gas - Battery: Yes /Dead - Engine Problems: Unknown - Does Not Run/Dead Battery - Will Possibly Need To Be Towed - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 162,861**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Missing Panels On Dash, Door Panels Are Damaged, Needs Cleaning, Missing Carpet /Rubber Flooring - Body Condition: Fair - Inspection Sticker Date: 05/18 - Body Problems: Oxidized Paint, Surface Scratches, Dents, Scratches/Dent On Right Rear, Peeling Paint, Cracks On Paint - Tires Condition: Fair - Tire Problems: Possible Dry Rot</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
10	(1) 1999 Chevy Express Cargo Van Vin #7133 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 936 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.0L - Gas - Battery: Yes - Engine Problems: Unknown, Will Turn Over, Will Not Start - Unknown If Running - Will Possible Need Towed - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 110,113**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Poor, Cargo Area Has Weather Guard Shelving, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Peeling Paint, Surface Scratches, Rust On Roof - Tires Condition: Fair - Tire Problems: Possible Dry Rot, Has Been Sitting Up For Several Years</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
11	(1) 2004 Ford Explorer SUV Vin #1648 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - No Key - Unit #: 550 - Conventional Style - Passengers: 5 - Engine Size/Type: 4.0L - Gas - Battery: Yes/Dead - Engine Problems: No Key, Running Condition Unknown - Unknown If Running - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Unable To Read/No Key - Interior Condition: Fair - Interior Problems: Stains On Carpet & Seats, Missing Parts On Console - Body Condition: Fair - Inspection Sticker Date: 08/16 - Body Problems: Needs Cleaning, Surface Scratches, Oxidized Paint, Missing Rear Windshield Wiper, Large Dent On Bottom Of Passenger Door - Tires Condition: Fair - Tire Problems: Possible Dry Rot, Has Been Sitting Up Several Years - Police Cage Will Be Removed From Vehicle Prior To Auction Removal</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

12	(1) 1993 Bluebird School Bus Vin #0138 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 287 - Conventional Style - Passengers: 71 - Engine Size/Type: 366 - Gas - Battery: Yes /Dead - Engine In Front - Engine Problems: Will Not Start/Unknown Problem - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 165,516**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Needs Cleaning, Floor Will Need Repair - Body Condition: Fair - Inspection Sticker Date: 10/16 - Body Problems: Oxidized Paint, Surface Scratches, Needs Cleaning, Surface Rust Under Window 5 - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
13	(1) 1993 Bluebird School Bus Vin #0047 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 285 - Conventional Style - Passengers: 72 - Engine Size/Type: 366 - Gas - Battery: Yes /Dead - Engine In Front - Engine Problems: Unknown, Will Not Start - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 164,288**Unknown Actual Mileage** - Interior Condition: Fair - Inspection Sticker Date: 04/19 - Body problems: Some Oxidized Paint, Large Dent/Scratch On Right Side, Under Wheels 4,5,8. Surface Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
14	(1) 1993 Bluebird School Bus Vin #0179 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 288 - Conventional Style - Passengers: 72 - Engine Size/Type: 6.0 - Gas - Battery: Yes /Dead - Engine In Front - Engine Problems: Unknown/Will Not Start - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 191,074**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Some Torn Seats, Needs Cleaning, Entry Step Needs Repairs, Drivers Seat Torn - Body Condition: Fair - Inspection Sticker Date: 09/19 - Body Problems: Oxidized Paint, Surface Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
15	(1) 1993 Bluebird School Bus Vin #0267 - Runs	<p>Bus #: 290 - Conventional Style - Passengers: 72 - Engine Size/Type: 6.0/366 - Gas - Battery: Yes/Dead - Engine In Front - Engie Problems: Problems Unknown - Runs - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 202,042 **Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Needs Cleaning, Some Tears On Passenger Seats - Body Condition: Fair - Inspection Sticker Date: 02/20 - Body Problems: Surface Scratches, Dent On Right Rear In Front Of Rear Bumper, Long Scratch/Dent On Left Side Under Window 35, Surface Rust Under Window 6 Left Side, Rock Chip On Windshield - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

16	(1) 1994 GMC Bluebird School Bus Vin #3194 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 297 - Conventional Style - Passengers: 72 - Engine Size/Type: 6.0 - Gas - Battery: Yes /Dead - Engine In Front - Engine Problems: Will Not Start, Problem Unknown - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 165,805**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Poor, Tears On Passenger Seats - Body Condition: Fair - Inspection Sticker Date: 05/18 - Body Problems: Some Oxidized Paint, Surface Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
17	(1) 1994 GMC Bluebird School Bus Vin #3212 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 298 - Conventional Style - Passengers: 71 - Engine Size/Type: 6.0 - Gas - Battery: Yes /Dead - Engine In Front - Engine Problems: Will Not Run, Problem Unknown - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 160,163**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 05/19 - Body Problems: Oxidized Paint, Surface Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
18	(1) 2000 Thomas School Bus Vin #3554 - Will Need To Be Towed	<p>Will Need To Be Towed - Recommend Salvage Use - Unit #: 352 - Transit Style - Passengers: 72 - Engine Size/Type: Cummins - Diesel - Battery: No - Engine In Front - Engine Problems: Will Not Start, Problem Unknown, Engine Parts Missing - Does Not Run - Air Brakes - Automatic Transmission - Dash Removed, Mileage Unknown - Interior Condition: Poor - Interior Problems: Seats Are Poor, Parts Missing On Dash, Some Seats Are Torn, Needs Clearing - Body Condition: Fair - Inspection Sticker Date: 05/17 - Body Problems: Oxidized Paint, Surface Scratches, Needs Cleaning, Parts Missing - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
19	(1) 2000 Thomas School Bus Vin #3568 - Will Need To Be Towed	<p>Will Need To Be Towed - W/ Wheel Chair Lift - Bus #: 160 - Conventional Style - Passengers: 37 - Engine Size/Type: Cummins 24 Valve - Diesel - Battery: No - Engine In Front - Engine Problems: Will Not Start, Problem Unknown - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 15,414**Unknown Actual Mileage** - Interior Condition: Poor - Wheel Chair Lift, Condition: Unknown - Interior Problems: Additional Seats Added To Bus, Condition Of Seats Unknown, Needs Cleaning - Body Condition Fair - Inspection Sticker Date: 05/17 - Body Problems: Oxidized Paint, Surface Scratches, Needs Cleaning - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
20	(1) Exmark Riding Lawn Mower	<p>Diesel - Lazer ZXS - Approx. Hours Reads: 10553 - Does Not Run - Problems Unknown - 72" Cut - This Lot Is Located Outside & Is Susceptible To Weather Conditions</p> <p>- Current Condition Unknown</p>
21	(1) Toro Riding Lawn Mower	<p>60" - Tri Vantage - Commercial - Missing Rear Left Tire - Model: LZ25KC603 - Has Kohler Gas Engine - Does Not Run - Possible Parts Missing - This Lot Is Located Outside & Is Susceptible To Weather Conditions</p> <p>- Current Condition Unknown</p>

22	(1) Exmark Riding Lawn Mower	Triton 60 - Possible Parts Missing - Diesel - Lazer ZXS- Missing Rear Tires & Wheels - Approx. Hours: 06107 - Will Not Run - This Lot Is Located Outside & Is Susceptible To Weather Conditions - Current Condition Unknown
23	(1) John Deere Riding Turf Mower	Model: 2653A - Bad Seat - Pro Utility Mow - Approx. Hours Read: 02809 - 3 Wheel - Diesel - Possible Parts Missing - Will Not Run - This Lot Is Located Outside & Is Susceptible To Weather Conditions - Current Condition Unknown
24	(1) Industrial Twin Head Air Compressor	Not Operable - Parts Unit Only - (Approx. 3) Electric Motor: 3 Phase - 230/460 - - This Lot Is Located Outside & Is Susceptible To Weather Conditions - Current Condition Unknown
25	(1) Ingersoll Rand Industrial Air Compressor	Model: UP6-10TAS-210 W/D - 3 Phase - 60 Hz - Pump Speed: 3200 RPM - 460/3/60 - 115/1/60 - This Lot Is Located Outside & Is Susceptible To Weather Conditions - Current Condition Unknown
26	(Lot) Dover 18,000 lb. Capacity Rotary Support Stands	(Approx. 2) Portable - RS18/Weight: 123 lbs. - Adjustment Height: 56" X 82" - This Lot Is Located Outside & Is Susceptible To Weather Conditions - Current Condition Unknown
27	(Lot) Dover 18,000 lb. Capacity Rotary Support Stands	(Approx. 3) Portable - RS18/Weight: 123 lbs. - Adjustment Height: 56" X 82" - This Lot Is Located Outside & Is Susceptible To Weather Conditions - Current Condition Unknown
28	(Lot) Track & Field Mats	Mfg: AAE- Qty: Unknown - This Lot Is Located Outside & Is Susceptible To Weather Conditions - Current Condition Unknown
29	(1) Westward 1 Ton Air /Manual Telescoping Transmission Jack	Model: 13X041 - Portable - Jack Did Move Up When Demonstrated By Lemons Auctioneers - Auctioneer Did Not Further Testing - This Lot Is Located Outside & Is Susceptible To Weather Conditions - Current Condition Unknown
400	(1) 2000 Thomas School Bus Vin #3555 - Will Need To Be Towed	Will Need To Be Towed - Bus #: 342 - Transit Style - Passengers: 72 - Engine Size/Type: Cummins - Diesel - Battery: No - Engine In Front - Engine Problems: Will Not Start, Problem Unknown - Does Not Run - Automatic Transmission - Approx. Hours Read: 9511 - Interior Condition: poor - Interior Problems: Will Need Cleaning, Missing A Few Passenger Seats, Has Been Sitting Up, Seat Poor Near Rear Entry Door Due To Weather - Inspection Sticker Date: 05/17 - Body Problems: Oxidized Paint, Surface Scratches, Rear Door Is Removed From Bus & Sitting Outside On Ground - Tires Condition: Fair - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**