Lot Number	Title	Description
0		**There Will Be A 13% Buyer's Premium Added To The Buyer's Total For Each Item Purchased.**
	Preview & Removal Information	Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, August 8, 2019 (Hours Of Operation: 8:00 a.m 11:30 a.m./1:00 p.m 3:00 p.m.)
		Location: Administration Department, 4339 4th St., Banquete, Tx 78339 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Wednesday, August 14, 2019/Thursday, August 15, 2019/Monday, August 19, 2019 (Hours Of Operation: 8:00 a.m 11:30 a.m./1:00 p.m 3:00 p.m.) Preview & Removal Contact: Ricky Resendez, Transportation Supervisor, (361)387-2551 X160 - email: rresendez@banqueteisd.net Lifting Equipment & Manpower Are Not Available For Removal. Buyer Is Solely Responsible For Own Removal. Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed
1	(1) 2010 International School Bus Vin #6148 - Will Need To Be Towed	Will Need To Be Towed - Conventional Style - Bus #: 2 - Passengers: 77 - Engine Size/Type: MaxxForce 7 - Diesel - Battery: Yes/Dead - Engine In Front - Engine Problems: Will Not Run, Drive Shaft Removed & Loose Inside Bus, Bad Engine - Does Not Run - Air Brakes - Automatic Transmission - Approx Mileage Unknown/Unable To Read - Interior Condition: Fair - Inspection Sticker Date: 10/18 - Interior Problems: Some Torn Seat, Needs Cleaning, Some Panels Loose - Body Condition: Fair - Body Problems: Slight Indention On Lower Right Side Panel Under Windows 4-6, Surface Scratches, Scratches On Right Rear Panel, Missing Lights On Rear, Missing Additional Lights, Front Grill Loose, Missing Front Mirrors - Tires Condition: Fair - Tire Problems: (1) Poor Tire Right Rear, Rest Are Fair Condition - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.
	(1) 1994 Ford	Bus #: 9 - Passengers: 71 - Diesel - Battery: Yes - Engine In Front - Engine Problems: Runs - Transmission Type /Condition: Will Forward & Reverse Highway Use Unknown - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 216,751**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Needs Cleaning, Worn - Body Condition: Poor - Inspection Sticker Date: 01/19 - Body Problems: Surface Rust, Oxidized Paint, Rust All Over, Dent On Plate Behind Entry Door, Rust On Rear Of Bus Rust Holes - Tires Condition: Fair To Poor - Tire Problems: Possibly Dry Rot, Tires Appear Fair
2	/Thomas B700 School	- Current Condition Unknown
	Bus Vin #3308 - Runs	There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.
3	(1) 1995 International Wayne 3800 School Bus Vin #0109 - Will Need To Be Towed	Will Need To Be Towed - Recommend Salvage Use Only - Parts Only Vehicle - Bus #: 14 - Passengers: 71 - Engine Size /Type: T444E - Diesel - Battery: No -Engine Problems: Bad Engine/Parts Missing - Does Not Run - Automatic Transmission - Air Brakes - Approx. Mileage Reads: 183,722**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Parts Missing, Torn Seats, Needs Cleaning - Body Condition: Poor - Inspection Sticker Date: 11/13 - Body Problems: Parts Missing, Missing Passenger Windows, Rust Oxidized Paint, Lights Missing, Scratches, Oxidized Paint, (1) Broken Wheel Well/Left Side, Damaged Hood, Missing Front Mirrors - Tires Condition: Fair - Tire Problems: Possible Dry Rot
		- Current Condition Unknown
		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.

4	(1) 1993 International Bluebird School Bus Vin #7487 - Will Need To Be Towed	Will Need To Be Towed - Recommend Salvage Use Only - Conventional Style - Bus #: 13 - Passengers: 71 - Engine Size /Type: Unknown - Diesel - Battery: No - Engine In Front - Engine Problems: Will Not Run, Bad Engine, Parts Missing - Does Not Run - Air Brakes - Transmission Condition: Unknown - Automatic Transmission - Approx. Mileage Reads: 249,443**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Exposed To Weather /Broken Passenger Windows, Broken Front Windshield, Broken Rear Window, Seats Poor, Inside Bus Broken Glass, Parts Missing - Body Condition: Poor - Inspection Sticker Date: 01/14 - Body Problems: Oxidized Paint, Parts Missing On Hood, Needs Cleaning, Dented Rear Bumper, Missing Rear Lights, Scratch/Dent Rear Left Panel - Tires Condition: Fair - Tire Problems: Possible Dry Rot - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
5	(1) 2000 Chevy LS Silverado 1500 Pickup Truck Vin #2209 - Will Need To Be Towed	Will Need To Be Towed - Conventional Style - Passengers: 6 - Engine Size/Type: 4.8L - Gas - Battery: No - Engine In Front - Engine Problems: Ran When Parked, Has Been Sitting Up - Does Not Run - Transmission Condition: Bad Transmission - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Torn Seat, Stains, Poor Seats, Worn Upholstery, Front Panel Loose On Dash, Interior Parts Missing - Body Condition: Poor - Inspection Sticker Date: 04/17 - Body Problems: Oxidized Paint, Surface Scratches, Dents, Dents On Bed On Both ides, Rock Chip On Windshield - Tires Problems: Front Right Tire Flat, Right & Left Rear Needs Air, Front Left Needs Air, Possible Dry Rot - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
6	(1) 1995 Ford F250 XL Pickup Truck Vin #9329 - Will Need To Be Towed	Will Need To Be Towed - Recommend Salvage Use - Engine Size/Type: Power Stroke - Diesel - Battery: No - Engine In Front - Engine Problems: Unknown - Does Not Run - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Unable To Read/Dash Loose - Interior Condition: Poor - Interior Problems: Missing Parts, Panels Missing, A/C Missing, Steering Wheel Loose, Many Parts Missing - Body Condition: Poor - Inspection Sticker Date: 12/11 - Body Problems: Peeling Paint, Scratches, Parts Missing, Rock Chip On Windshield, Missing Front Of Truck, Missing Door Windows In Front, Missing Rear Light Assemblies - Tire Problems: Missing Left Front Wheel & Tire, Dry Rot Tires, Missing Right Front Tire & Wheel, Flat Tires On Rear - Lift Gate Stuck Down On Ground - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
7	(1) 1997 Ford Club Wagon Van Vin #1038 - Will Need To Be Towed	Will Need To Be Towed - Engine Size/Type: 5.4L - Gas- Battery: Yes/Dead - Engine Problems: Bad Catalytic Converter, Ran When Parked - Does Not Run - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 186,087 **Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Work Van, Needs Cleaning - Body Condition: Poor - Body problems: Chipped Paint All Over, Cracked Windshield, Surface Rust, Needs Cleaning, Dent On Right Rear, Rust On Roof - Tires Condition: Fair - Tire Problems: Low Tires, Needs Air, Possible Dry Rot - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**

8	(1) 1993 Chevy S10 Service Truck Vin #3477 - Will Need To Be Towed	Will Need To Be Towed - Passengers: 3 - Engine Size/Type: 4.3L - Gas - Battery: Yes/dead - Engine In Front - Engine Problems: Ran When Parked - Runs - Transmission Condition: Bad Transmission, Will Not Go Into Reverse - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 088,950**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seat, Needs Cleaning, Cracks On Dash, Worn Upholstery, Door Panel On Drivers Side Missing Parts - Body Condition: Fair - Inspection Sticker Date: 10/18 - Body Problems: Oxidized Paint, Surface Scratches, Handle Broken On Door On Passenger Side, Dents, Peeling Paint - Tires Condition: Poor - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
9	(1) John Deere Front End Loader /Backhoe	Model: T0310CA135449 - Has Key - Model: 310C - Bad Engine - Has Been Sitting Up For A Long Time - Tires Possible Dry Rot - Current Condition Unknown - Has Outriggers In Rear - Approx. Hours Read: 4869 - Engine Serial #: T04239D155348/4239DT003
10	(1) Allis Chalmers Maintainer	Vintage - Ran When Parked A Long Time Ago - Rebuilt Engine/Year Unknown, Rust All Over - Recommend Parts Unit - Model: D4243 - No Key - Current Condition Unknown
11	(1) Airco Welder	Model: EV-300II - 208 Volts/230/460 - 3 Phase - Portable - Current Condition Unknown
12	(1) Insulated Transport Container	Mfg: Cambro - Stationary - Broken Latch - Current Condition Unknown
13	(1) Titan Industrial Heavy Duty Commercial Trash Pump	Portable - Current Condition Unknown
14	(1) Titan Industrial Portable Air Compressor	8 Gallon - Heavy Duty - 5.5 HP - Current Condition Unknown
15	(1) Field Lazer	Mfg: Gray Co Honda Engine - Needs To Be Cleaned - Portable - Current Condition Unknown
16	(Lot) Heat Buster Shop Fans	(Approx. 2) Triangle Engineering - Needs Repair - Portable - Current Condition Unknown
17	(1) Titan Industrial Air Compressor	Portable - Commercial - Heavy Duty - 8 Gallon - Model: TAC-2T - Current Condition Unknown
18	(1) Pressure Washer	Power Boss - Missing (1) Wheel - Missing Want - Missing Nozzles, Need Repair - Current Condition Unknown
19	(Lot) Welders & Charger	Including: (Approx. 3) Lincoln 225 Amp Electric Welders - Wire Leads Are Cut - Need Repair, (1) Solar 480/6/12 Volt Battery Charger - Started - Wires Cut - Need Repair - Current Condition Unknown
20	(1) Electric Shop Heater	Old Style - Needs Cleaning - Rust On Guard - Current Condition Unknown
21	(1) Beckett Commercial Shop Heater	RW Bickett Corp Diesel Fueled - Portable - Current Condition Unknown
22	(1) Port-A- Can	Skid-O-Can - Unassembled - Unused - No Hardware - Complete Unknown - Current Condition Unknown
23	(1) Nobles Floor Machine	- Current Condition Unknown

	I	
24	(1) Coffee & Tea Maker	Fetco Coffee Brewer
		- Current Condition Unknown
25	(1) True Line	
	Paint Sprayer	- Current Condition Unknown
26	(1) Insulated Container	Hardigg Ind Cage 11214
		- Current Condition Unknown
27	(Lot) Military Storage Trunks	(Approx. 2)
		- Current Condition Unknown
28	(1) Scot Pump	Style: Military - 3200 RPM - 24 Volts
		- Current Condition Unknown
	(Lot) U Shaped Mezzanine & Scrap	Including: (Approx. 2) Metal Stairs - Various Conditions
29		- Current Condition Unknown
	Metal	
30	(Lot) Hoist	Mfg: A-Frame - Portable - 169" Long - 8 Ton - Missing (2) Casters - Buyer Must Make An Appointment For Removal
		- Current Condition Unknown
31	(Lot) Weight Stands	(Approx. 13)
	Jeanas	- Current Condition Unknown
32	(1) Weight Bench	
		- Current Condition Unknown
33	(1) Weight Bench	
	(Lot) Weight Benches	- Current Condition Unknown
34		(Approx. 3) Seats Are Torn
		- Current Condition Unknown
35	(Lot) Incline Weight Benches	(Approx. 3) Seats Are Torn
		- Current Condition Unknown
36	(Lot) Squat Racks	(Approx. 2)
		- Current Condition Unknown
37	(1) Squat Rack	Constant Constitution United and
		- Current Condition Unknown Including: (Approx. 2) Squat Racks, (Approx. 3) Bars - Assorted Barbells - Various Conditions
38	(Lot) Racks & Bars	
	(Lot) 4	- Current Condition Unknown (Approx. 7) Legal & Letter - Various Conditions
39	Drawer File	
	(Lot) Student Combo Desk /Chairs	- Current Condition Unknown (Approx. 240) High School Size - Matching - Located In Band Hall Mezzanine Upstairs - Will Have to Be Removed By
40		Buyer Down The Stairs & Out A Hallway To The Loading Area - No Assistance Provided
		- Current Condition Unknown
	(Lot)	(Approx. 40)
41	Student Combo Desk /Chairs	- Current Condition Unknown
	(Lot) Band Hats & Misc.	Including: Band Hats - Qty: Unknown, (Approx. 2) Igloo Coolers - Hinge Needs Repair, (1) Marching Tuba, (Approx. 17)
42		Stacking Chairs, (1) Folding Table, Box Of Plumbs
		- Current Condition Unknown
43	(1) Yamaha Trombone	W/ Case - Dents, Oxidation, & Scratches
		- Current Condition Unknown

44	(1) Bass Clarinet	W/ Neck & Bell - Vito Resotone, USA - Neck Is Stuck On Unit - W/ Case - Current Condition Unknown
		Missing Valves - Dents - Needs Repair - Scratches & Oxidization
45	(1) Jupiter Euphonium	IMISSING Valves - Delits - Needs Repair - Scratches & Oxidization
	Euphonium	- Current Condition Unknown
46	(Lot) Band Instruments	Including: (1) Trumpet/Bach - Missing Valves - Dented, (1) King Horn - Dented, (1) French Horn - Dented - Yamaha - YHR3-3, (1) Trombone - No Mfg Dented, All Units Need Repair
		- Current Condition Unknown
47	(Lot) Concert	Including: Helmets, Suit Jackets, & Suit Pants
	Band Uniforms	- Current Condition Unknown
48	(Lot) Drum Harness	(Approx. 5) Mfg: Musser, Ludwig, & Other
		- Current Condition Unknown
	(1) Hobart 30 Qt. Mixer	D-300 - 1 Phase
49		- Current Condition Unknown
50	(1) Hobart 6 Door Q3	115 Volts - 60 Hz - Single Sided - Stationary
	Commercial Refrigerator	- Current Condition Unknown
F1	(1) Coleman	(Approx. 20) Model: 6277/6218 & Other Mfg.
51	ice Chest	- Current Condition Unknown
	(1) Vollrath	
52	Salad Bar	- Current Condition Unknown
	(1) Vollrath	W/ Plug
53	Salad Bar	- Current Condition Unknown
	(1) Metal Cart	Mfg: Lakeside - Portable
54		- Current Condition Unknown
	(Lot)	(Approx. 3) Disassembled - AA801 Model
55	Lakeshore	- Current Condition Unknown
	Cribs (Lot) Kinder Chairs	(Approx. 60) Various Conditions & Colors - Some Are Scratched
56		- Current Condition Unknown
	(Lot)	(Approx. 5) Various Conditions
57	Rectangle Elementary	
	Tables	- Current Condition Unknown
58	(1) Play Kitchen	W/ Plastic Sink Insert - Wood Type
		- Current Condition Unknown
59	(1) Play	Plastic
	Kitchen	- Current Condition Unknown
60	(Lot) Round Tables	(Approx. 3) Various Types - Childs Size - Adjustable
00		- Current Condition Unknown
64	(Lot)	(Approx. 17)
61	Cafeteria Tables	- Current Condition Unknown
	(Lot) Cafeteria Tables	(Approx. 8) Stool Type
62		- Current Condition Unknown
63	(Lot) Overhead Projectors	(Approx. 25) Various Types & Metal Carts
		- Current Condition Unknown