

Lot Number	Title	Description
0	Preview & Removal Information	<p>All purchases will be subject to a 13% buyer's premium.</p> <p><b>Preview:</b> (By Appointment Only - Mandatory - No Exceptions) Wednesday, October 9, 2019 <b>Location 1:</b> Hours Of Operation: 7:30 a.m. - 3:30 p.m. <b>Location 2:</b> Hours Of Operation: 8:00 a.m. - 4:00 p.m. <b>Location 1: (Lots 1-3)</b> GISD Warehouse, 4302 Ave. Q, Galveston, Tx 77550 <a href="#">Driving Directions</a>. <b>Removal:</b> (By Appointment Only - Mandatory - No Exceptions) Tuesday, October 15, 2019/Wednesday, October 16, 2019/Thursday, October 17, 2019 (Hours Of Operation: 7:30 a.m. - 3:30 p.m.) <b>Preview &amp; Removal Contacts:</b> Robert Simpson, (409)761-6185 or (409)789-1155 Email: Robertsimpson@gisd.org <b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</b></p> <p><b>Location 2: (Lots 4-34)</b> GISD Transportation, 3101 83rd St., Galveston, TX 77550 <a href="#">Driving Directions</a> <b>Removal:</b> (By Appointment Only - Mandatory - No Exceptions) Tuesday, October 15, 2019/Wednesday, October 16, 2019/Thursday, October 17, 2019 (Hours Of Operation: 8:00 a.m. - 4:00 p.m.) <b>Preview &amp; Removal Contacts:</b> Dave Tisdale, (409)761-6175 or dave.tisdale@gisd.org <b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</b></p>
1	(1) 2006 Ford F650 XL Super Duty Box Truck Vin #8963 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: NA - Conventional Style - Passengers: 3 - Engine Size/Type: IH VT 365 - Engine In Front - Engine Problems: Unknown, Auctioneer Tried Starting Unit &amp; Would Not Turn Over, Possible Battery Completely Dead, Running Condition Unknown, Ran When Parked, Current Unknown - Diesel - Battery: Yes/Dead - Ran When Parked - Current Running Condition Unknown - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 10/18 - Approx. Mileage Reads: 32,660**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Torn Drivers Seat, Needs Cleaning, Normal Wear On Upholstery - Body Condition: Fair - Body Problems: Surface Scratches, Oxidized Paint, Crack On Right Side Hood, Rust On Steps, Some Dents On Box - Tires Condition: Good - Supreme Box /Has Lift Gate/Waltco - Has (1) Large Tank - Approx. Size: 15' Long Box</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
2	(1) 2006 Ford F450 XL Super Duty Dump Truck Vin #2147 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Unit #: NA - Conventional Style - Passengers: 3 - Engine Size/Type: V8/Power Stroke Turbo/6.0 - Engine Problems: Unknown, Has Been Sitting, Ran When Parked, Current Condition Unknown - Diesel - Battery: Yes/Dead - Unknown Running Condition - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 12/18 - Approx. Mileage Reads: 32,616**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Torn Seats Drivers Side, Needs Cleaning, Normal Wear On Upholstery - Body Condition: Fair - Body Problems: Damage On Front Bumper, Emblem Missing, Front Crack On Windshield, Minor Dents, Surface Scratches - Tires Condition: Fair - Dump Was Operable - Approx. Dump Size: 14' X 4' Height X 8' - Bed Has Rust &amp; Some Holes/Mfg: Unknown</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
4	(1) 1997 Ford Crown By Carpenter School Bus Vin #7644 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 8777 - Conventional Style - Passengers: 65 - Engine Size/Type: 5.9L - Engine In Front - Engine Problems: Engine Problems, Not Running, Possible Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 05/19 - Approx. Mileage Reads: 198,232**Unknown Actual Mileage** - Approx. Hub Reads: 136,731 - Interior Condition: Some Torn Seats, Needs Cleaning, Rust Hole On Metal Headliner In Front, Upholstery Worn, Surface Rust, Possible Parts Missing - Body Condition: Poor - Body Problems: Rust All Over, Oxidized Paint, Surface Scratches, Needs Cleaning, Recommend Preview, Bad Rust on Roof, Possible Parts Missing - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

5	(1) 1997 Ford Crown By Carpenter School Bus Vin #9515 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 8723 - Conventional Style - Passengers: 65 - Engine Size/Type: 5.9L - Engine In Front - Engine Problems: Bad Engine, Possible Parts Missing - Diesel - Battery: Yes/dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 02/19 - Approx. Mileage Reads: 211,582**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Torn, Needs Cleaning, Possible Parts Missing, Upholstery Worn, Surface Rust - Body Condition: Poor - Body Problems: Possible Parts Missing, Rust All Over, Oxidized Paint, Dents, Scratches, Bad Rust On Right Side Panel &amp; Rub Rail, Large Dent/Scratch On Right Rear, Bad Rust On Roof, Hole On Roof - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
6	(1) 1997 Ford Crown By Carpenter School Bus Vin #9508 - Will Need To Be Towed	<p>Will Need To Be Towed - Auctioneer Recommends Salvage - Bus #: 8810 - Conventional Style - Passengers: 65 - Engine Size/Type: 5.9L - Engine In Front - Engine Problems: Bad Engine, Possible Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 04/18 - Approx. Mileage Reads: 147,404 **Unknown Actual Mileage** - Approx. Hub Reads: 39,749 - Interior Condition: Poor - Interior Problems: Seats Are Poor, Floor Needs Repair, Missing (1) Emergency Roof Hatch, Needs Cleaning, Surface Rust, Parts Missing - Body Condition: Poor - Body Problems: Parts Missing, Rust All Over, Rust On Rub Rails, Badly Oxidized Paint, Rubber Molding On Rear Bumper Damaged, Rust On Cowl - Tires Condition: Fair To Poor</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
7	(1) 1997 Ford Crown By Carpenter School Bus Vin #8754 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 8754 - Conventional Style - Passengers: 65 - Engine Size/Type: 5.9L Cummins - Engine In Front - Engine Problems: Bad Engine, Possible Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 02/18 - Approx. Mileage Reads: 177,167**Unknown Actual Mileage** - Approx. Hub Reads: 37,755 - Interior Condition: Poor - Interior Problems: Floor Needs Replacing, Torn Seats, Needs Cleaning, Rust Inside Bus/Damage From Rust Inside Bus - Body Condition: Poor - Body Problems: Rust All Over Bus, Rust On Roof/Damage, Rust Damage On Right Rear, Damage On Rear Left Side Bumper, Rust On Cowl - Tires Condition: Poor - Tire Problems: Poor In Rear, Fair In Front</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
8	(1) 1997 Ford Crown By Carpenter School Bus Vin #9288 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 8803 - Conventional Style - Passengers: 65 - Engine Size/Type: 5.9L Cummins - Engine In Front - Engine Problems: Bad Engine, Possible Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic - Air Brakes - Inspection Sticker Date: 05/18 - Approx. Mileage Reads: 154,200**Unknown Actual Mileage** - Approx. Hub Reads: 36,735 - Interior Condition: Poor - Interior Problems: Floor Will Need Replacing, Parts Possibly Missing, Rust Inside Box, Torn Seats, Needs Cleaning - Body Condition: Poor - Body Problems: Dents, Scratches, Parts Missing, Rust All Over, Crack On Entry Door Glass, Large Scratch/Dent On Right Side Lower Panel, Damage On Rubber Rear Bumper, Oxidized Paint, Rust On Cowl - Tires Condition: Poor</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

9	(1) 2010 International School Bus Vin #5802 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 1067 - Conventional Style - Passengers: 65 - Engine Size/Type: Maxx Force - Engine In Front - Engine Problems: Bad Engine/Parts Missing - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 02/19 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Tears On Seats, Needs Cleaning, Parts Missing, Entry Door Parts Missing - Body Condition: Fair - Body Problems: Surface Rust, Oxidized Paint, Missing (1) Rear Light, Missing Parts, Dent On Left Rear, Indention On Left Rear Lower Panel Under Window #6, Cracks On Windshield, Possible Parts Missing - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
10	(1) 1997 Ford Crown School Bus Vin #6764 - Will Need To Be Towed	<p>Will Need to Be Towed - Recommend Salvage - Bus #: 8785 - Conventional Style - Passengers: 65 - Engine Size/Type: 5.9 L Cummins - Engine In Front - Engine Problems: Bad Engine, Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 01/18 - Approx. Mileage Reads: 191,310**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Needs Cleaning, Floor Needs Repair, Has Rust Inside Bus, Possible Parts Missing - Body Condition: Poor - Body Problems: Badly Oxidized, Bad Rust All Over, Rust On Roof, Scratches, Parts Missing, Large Indention On Left Lower Panel, Right On Cowl - Tires Condition: Fair To Poor</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
11	(1) 1997 Ford Crown School Bus Vin #8747 - Will Need To Be Towed	<p>Will Need To Be Towed - Recommend Salvage - Bus #: 8747 - Conventional Style - Passengers: 65 - Engine Size/Type: Cummins 5.9L - Engine In Front - Engine Problems: Bad Engine, Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 05/18 - Approx. Mileage Reads: 193,708 **Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Needs Cleaning, Rust Inside Bus, Floor Needs Repair, Possible Parts Missing - Body Condition: Poor - Body Problems: Scratches, Broken Entry Door Glass, Parts Missing, Oxidized Paint, Rust All Over, Rust On Roof, Rust On Cowl, Badly Oxidized - Tires Condition: Fair To Poor</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
12	(1) 1997 Ford Crown By Carpenter School Bus Vin #8760 - Will Need To Be Towed	<p>Will Need To Be Towed - Recommend Salvage - Bus #: 8760 - Conventional Style - Passengers: 65 - Engine Size/Type: Cummins 5.9L - Engine In Front - Engine Problems: Bad Engine, Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 05/18 - Approx. Mileage Reads: 058,686 **Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Holes In Floor, Needs Cleaning, Rust, Rust Inside Unit, Parts Missing - Body Condition: Poor - Body Problems: Bad Rust All Over, Oxidized Paint, Bad Rust Right Rear, Dent Left Rear, Bad Rust Left Side, Rust On Cowl, Parts Missing - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

13	(1) 1997 Ford Crown By Carpenter School Bus Vin #9510 - Will Need To Be Towed	<p>Will Need To Be Towed - Recommend Salvage - Bus #: 8724 - Conventional Style - Passengers: 65 - Engine Size/Type: Cummins 5.9L - Engine In Front - Engine Problems: Bad Engine, Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 04/18 - Approx. Mileage Reads: 212,624  <b>**Unknown Actual Mileage**</b> - Interior Condition: Poor - Interior Problems: Rust All Over Inside Bus, Torn Seats, Holes In Floor, Rust, Needs Cleaning, Parts Missing - Body Condition: Poor - Body Problems: Large Gash &amp; Dent On Right Side, Rust All Over, Rust On Roof, Badly Oxidized Paint, Dent On Right Rear, Dent Left Rear, Bad Rust Damage On Left Side Rub Guard, Rust On Cowl</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
14	(1) 2004 Ford E250 Cargo Van Vin #3824 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Passengers: 2 - Engine Size/Type: 4.6L - Engine In Front - Engine Problems: Possible Engine Problems, Running Condition Unknown - Gas - Battery: Yes/Dead - Does Not Run, Current Condition Unknown - Automatic Transmission - Transmission Condition: Has Problems - Hydraulic Brakes - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Needs Cleaning, Worn Upholstery, Light Cover On Roof - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Minor Surface Rust, Rust Damage On Left Rear, Dent In Rear Bumper, Rust On Roof, (1) Entry Door In Cargo Area, Badly Dented, No Key Door Mechanism, Windshield Scratches Due To Poor Wipers - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
15	(1) 2006 Dodge Ram 1500 Crew Cab Pickup Truck Vin #0356 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Passengers: 6 - Engine Size/Type: 4.7L - Engine In Front - Engine Problems: Running Condition Unknown - Gas - Battery: Yes/Dead - Unknown If Running - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Normal Wear, Needs Cleaning, Damage On Drivers Side Seat Panel - Body Condition: Fair To Poor - Body Problems: Rust Under Carriage Due To Possible Exposure To High Water, Rust On Right Rear Passenger Door, Surface Rust On Roof, Rust On Cowl, Rust On Tailgate - Tires Condition: Fair - Dent On Rear Bumper &amp; Rust, Needs Cleaning, Crack On Windshield Drivers Side, Temporary Repair On Roof From Rust</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
16	(1) 1997 Ford Crown By Carpenter School Bus Vin #6744 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 8698 - Passengers: 65 - Engine Size/Type: Cummings 5.9L - Engine In Front - Engine Problems: Bad Engine, Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 03/19 - Approx. Mileage Reads: 188,963<b>**Unknown Actual Mileage**</b> - Interior Condition: Poor - Interior Problems: Torn Seats, Floors Need Repair, Rust Inside Bus, Needs Cleaning, Worn - Body Condition: Poor - Body Problems: Rust All Over, Oxidized Paint/Bad, Large Indention Of Left Side Lower Panel, Rust On Cowl, Rock Chip On Windshield - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

17	(1) 2008 Ford E150 Passenger Van Vin #8591 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Passengers: 8 - Engine Size/Type: 4.6L - Engine In Front - Engine Problems: Running Condition Unknown - Gas - Battery: Yes/dead - Does Not Run - Transmission Condition: Bad - Hydraulic Brakes - Inspection Sticker Date: 02/19 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Needs Cleaning, Looks Okay - Body Condition: Fair - Body Problems: Rock Chip On Windshield, Minor Surface Scratches, Minor Rust On Roof - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
18	(1) 2008 Ford Cargo Van E250 Super Duty Vin #5843 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: F3208 - Conventional Style - Passengers: 2 - Engine Size/Type: 4.6L - Engine In Front - Engine Problems: Running Condition Unknown - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 05/19 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Headliner Needs Replacing, Worn Upholstery - Body Condition: Fair - Body Problems: Surface Rust, Missing Rear Taillight On Right Side, Dents, Scratches - Tires Condition: Good To Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
19	(1) 2010 Thomas School Bus Vin #2975 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 202 - Conventional Style - Passengers: 54 Size, Equips 24 + Driver + (1) Wheel Chair Space - Engine Size/Type: 6.7 Cummins - Engine In Front - Engine Problems: Unknown, Possible Parts Missing, Running Condition Unknown - Diesel - Battery: Yes/Dead - Unknown Running Condition/Ran When Parked - Automatic Transmission - Air Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Unable To Read/Dead Battery - Wheel Chair Lift, Condition Unknown - Interior Condition: Fair - Interior Problems: Needs Cleaning, Minor Torn Seats, Parts Missing - Body Condition: Fair - Body Problems: (2) Broken Passenger Windows, Surface Scratches, Some Peeling Paint, Some Rust, Possible Parts Missing - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
20	(1) 2006 Dodge Dakota Crew Cab Pickup Truck Vin #9154 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: F2706 - Conventional Style - Passengers: 5 - Engine Size/Type: 3.7L/V6 - Engine In Front - Engine Problems: Running Condition Unknown - Gas - Battery: Yes/Dead - Unknown Running Condition - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 12/19 - Approx. Mileage Unable To Read/Dead battery - Interior Condition: Fair - Interior Problems: Needs Deep Cleaning, Upholstery &amp; Panels Are Worn, Stains On Seats, Floorboard &amp; Headliner - Body Condition: Fair - Body Problems: Needs Cleaning, Dent/Rust On Drivers Side Door, Surface Scratches, Rust On Bed (Scratches) On Right Rear, Paint Bubbled On Wheel Well Right Side From Rust - Tires Condition: Fair - Rust Damage &amp; Dent On Right Rear Passenger Door, Rust on Right Front Wheel Well Panel Near Bumper</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

21	(1) 2002 Chevy 3500 Service Silverado Pickup Truck Vin #6005 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: NA - Conventional Style - Passengers: 3 - Engine Size/Type: 6.0 - Engine In Front - Engine Problems: Not Running, Problem Unknown - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: NA - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Drivers Seat Bad/Torn, Upholstery Stained &amp; Worn, Panels Are Worn, Steering Wheel Pad Worn, Headliner Needs Replacing, Needs Cleaning - Body Condition: Fair To Poor - Body Problems: Oxidized Paint, Surface Scratches, Scratches On Service Bed, Rust On Push Guard, Needs Cleaning, Surface Rust, Rust On Service Bed, Rear Bumper Dented - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
22	(1) 2010 Thomas School Bus Vin #3051 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: 13 - Conventional Style - Passengers: 45 - Engine Size/Type: Cummins 6.7 - Engine In Front - Engine Problems: Running Condition Unknown, Has Been Sitting UP - Diesel - Battery: Yes/Dead - Unknown If Running, Possibly Needs Towing - Automatic Transmission - Air Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Some Surface Rust, Surface Scratches, Scratch Right Rear Near Back Of Bus, Broken Rear Glass, Missing (2) Rear Lights, Rust On Front Bumper - Tires Condition: Poor Right Rear, Remainder Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
23	(1) 2010 Thomas School Bus Vin #2964 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: 1085 - Conventional Style - Passengers: 54 Passenger Size, Equips 24 + Driver + (1) Wheel Chair Space - Engine Size/Type: 6.7 Cummins - Engine In Front - Engine Problems: Not Running, Has Been Sitting UP - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 10/20 - Approx. Mileage Unable To Read/Dead Battery - Wheel Chair Lift, Condition: Unknown - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Surface Scratches, Some Rust, Minor Rub/Dent Right Rear, Rock Chip On Windshield, Crack On Windshield, Rust On Front Bumper - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
24	(1) 2009 Chevy Thomas Van Bus Vin #5431 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 1010 - Conventional Style - Passengers: 15 - Engine Size/Type: Vortec 6.0L - Engine In Front - Engine Problems: Unknown, Not Running - Gas - Battery: Yes/Dead - Unknown If Running - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Surface Rust, Rust, Rock Chip On Windshield - Tires Condition: Poor on Left Rear, Remainder Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

25	(1) 2009 Chevy Thomas Van Bus Vin #4916 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: 1009 - Conventional Style - Passengers: 15 - Engine Size/Type: 6.0 - Engine In Front - Engine Problems: Unknown, Not Running - Gas - Battery: Yes/Dead - Unknown If Running - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 01/19 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Some Torn Seat, Bottom Step Needs Repair On Entry Door Passenger Side, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Crack On Windshield, Chipped Paint, Some Rust, Rust On Front Bumper - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
26	(1) 2004 Chevy 2500 Silverado HD Service Truck Vin #1944 - Runs	<p>Unit #: F2004 - Conventional Style - Passengers: 3 - Engine Size/Type: 6.0 - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes/Dead - Runs - Automatic - Hydraulic Brakes - Inspection Sticker Date: N/A - Approx. Mileage Reads: 109,846**Unknown Actual Mileage** - Interior Condition: Fair To Poor - Interior Condition: Very Worn, Needs Cleaning, Visor Needs Replacing, Steering Wheel Padding Worn, Upholstery Worn - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rust On Bed, Rubber Needs Reattaching On Bumper In Front, Rust On Push Guard - Tires Condition: Questionable, Appear Worn - Rawson Koening Bed/No Key</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
27	(1) 2010 Freightliner School Bus Vin #3049 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: 1001 - Conventional Style - Passengers: Equip 44 + Driver - Engie Size/Type: 6.7 Cummins - Engine In Front - Engine Problems: Unknown/Not Running - Diesel - Battery: Yes/Dead - Unknown If Running - Automatic Transmission - Air Brakes - Inspection Sticker Date: NA - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair To Poor - Interior Problems: There Are A Lot Of Torn &amp; Damaged Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Surface Scratches, Dent/Scratch On Right Panel Under Window 5, Large Rub On Right Rear &amp; Dent Near Reflector, Some Surface Rust - Tires Condition: Fair - Rust On Front Bumper</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
28	(1) 2010 Thomas School Bus Vin #3052 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: 1087 - Conventional Style - Passengers: 44 + Driver - Engine Size/Type: 6.7 Cummins - Engine In Front - Engine Problems: Unknown, Not Running - Diesel - Battery: Yes/Dead - Unknown If Running - Automatic Transmission - Air Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Unable To Read /Dead Battery - Interior Condition: Fair To Poor - Interior Problems: A Large Amount Of Seats Are Torn Or Damaged, Missing Front Protection Guard/Pad In Front, Drivers Seat Poor - Body Condition: Fair - Body Problems: Surface Scratches, Rub On Right Rear, Broken Glass On Rear Door, Crack On Windshield - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>



29	(1) 2010 Freightliner School Bus Vin #3053 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: 1094 - Conventional Style - Passengers: 44 + Driver - Engine Size/Type: 6.7 Cummins - Engine In Front - Engine Problems: Unknown, Not Running - Diesel - Battery: Yes/Dead - Unknown If Running - Automatic Transmission - Air Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Torn Seats Throughout The Bus, Needs Cleaning, Missing Front Protection Guard Pad - Body Condition: Fair - Body Problems: Surface Scratches, Mild Indentions On Rub Guard Right Side, Scratch/Dent Right Rear, Scratch Left Rear, Rust On Front Bumper - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
30	(1) 2010 Freightliner School Bus Vin #3050 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: 1093 - Conventional Style - Passengers: 44 + Driver - Engine Size/Type: 6.7 Cummins - Engine In Front - Engine Problems: Unknown, Not Running - Diesel - Battery: Yes/Dead - Unknown If Running - Automatic Transmission - Air Brakes - Inspection Sticker Date: 10/20 - Approx. Mileage Unable To Read /Dead Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Surface Scratches, Slight Indention On Rub Guard Right Side, Right Side Dent/Scratch, Some Surface Rust, Crack On Windshield, Rust On Front Bumper - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
31	(1) 2010 Freightliner School Bus Vin #3047 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: 1092 - Conventional Style - Passengers: Unknown - Engine Size/Type: 6.7 Cummins - Engine In Front - Engine Problems: Unknown, Not Running - Diesel - Battery: Yes/Dead - Unknown if Running - Automatic Transmission - Air Brakes - Inspection Sticker Date: 10/20 - Approx. Mileage Unable To Read /Dead Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Surface Scratches, Some Surface Rust, Minor Chipped Paint - Tires Condition: Fair - Tire Problems: Front Questionable, Rear Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
32	(1) 1997 Ford Crown By Carpenter School Bus Vin #6755 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 8738 - Recommend Salvage Use - Conventional Style - Passengers: 65 - Engine Size /Type: 5.9L Cummins - Engine In Front - Engine Problems: Not Running, Parts Missing - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 01/19 - Approx. Mileage Reads: 91,674**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Possible Parts Missing, Needs Cleaning, Rust Inside Bus - Body Condition: Poor - Body Problems: Rust All Over, Bad Rust On Right Side, Rust On Cowl, Parts Missing, Mirror Broken Off On Drivers Side Due To Rusty Mount, Bad Rust On Left Side, Rust On Roof - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>



33	(1) 1997 Ford Crown By Carpenter School Bus Vin #7649 - Will Need To Be Towed	<p>Will Need To Be Towed - Salvage Use - Bus #: 8691 - Conventional Style - Passengers: 65 - Engine Size/Type: 5.9L - Engine In Front - Engine Problems: Bad Engine, Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 01/18 - Approx. Mileage Reads: 136,588**Unknown Actual Mileage** - Approx. Hub Reads: 40,403 - Interior Condition: Poor - Interior Problems: Needs Cleaning, Torn Seat, Possible Parts Missing, Rust In Bus, Floor Soft - Body Condition: Poor - Body Problems: Rust All Over, Bad Rust On Left &amp; Right Side, Oxidized Paint, Gash/Rust On Right Rear - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
34	(1) 2008 Ford E250 Super Duty Cargo Van Vin #5842 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: E3108 - Conventional Style - Passengers: 2 - Engine Size/Type: 4.6L - Engine In Front - Engine Problems: Unknown/Not Running - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: NA - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair To Poor - Interior Problems: Needs Cleaning, Worn Upholstery - Body Condition: Fair - Body Problems: Oxidized Paint, Scratches/Dent On Left Side Cargo Area, Rust, Cracks On Windshield, Surface Rust On Roof Dents On Front Bumper - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>