Lot Number	Title	Description
0		All purchases will be subject to a 13% buyer's premium.
	Preview & Removal Information	Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, October 8, 2019 (Hours Of Operation: 9:00 a.m 11:00 a.m./1:00 p.m 3:00 p.m.)
		Location 1: (Lots 1-10) Lamar CISD Support Services, 4901 Avenue I, Rosenberg, Tx 77471 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, October 15, 2019/Wednesday, October 16, 2019 /Thursday, October 17, 2019 (Hours Of Operation: 9:00 a.m 11:00 a.m./1:00 p.m 3:00 p.m.) Preview & Removal Contact: Robert Langston, (832)520-7415 Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed.
		Location 2: (Lots 11-76) LCISD Distribution Warehouse, 1441 1/3 Band Rd., Rosenberg, Tx 77471 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, October 15, 2019/Wednesday, October 16, 2019/Thursday, October 17, 2019 (Hours Of Operation: 9:00 a.m 11:00 a.m./1:00 p.m 3:00 p.m.) Preview & Removal Contact: Robert Langston, (832)520-7415 Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. Forklift Available For Removal.
		Location 3: (Lot 77) Lamar High School, 4606 Mustang Ave., Rosenberg, Tx 77471 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, October 15, 2019/Wednesday, October 16, 2019 /Thursday, October 17, 2019 (Hours Of Operation: 9:00 a.m 11:00 a.m./1:00 p.m 3:00 p.m.) Preview & Removal Contact: Robert Langston, (832)520-7415 Forklift NOT Available For Removal.
		Location 4: (Lot 78) Campbell Elementary, 1000 Shadow Bend Dr., Sugar Land, Tx 77479 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, October 15, 2019/Wednesday, October 16, 2019 /Thursday, October 17, 2019 (Hours Of Operation: 9:00 a.m 11:00 a.m./1:00 p.m 3:00 p.m.) Preview & Removal Contact: Robert Langston, (832)520-7415 Forklift NOT Available For Removal
	(1) 2005	Unit #: P-5 - Has Key - Conventional Style - Passengers: 5 - Engine Size/Type: 4.6L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic - Hydraulic Brakes - Inspection Sticker Date: 03/19 - Approx. Mileage Reads: 85,312**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Normal Wear, Hole On Headliner From Equipment Mounted, Has Standard Police Rear Seat/Vinyl - Body Condition: Fair - Body Problems: Oxidized Paint, Hole On Left Passenger Door, Surface Scratches, Some Chipped Paint & Peeling Paint, Surface Rust On Roof, Hood Peeling & Surface Rust, Rock Chip On Windshield - Tires Condition: Good - Police Equipment Will Be Removed By Lamar CISD
1	Ford Crown Victoria Vin	- Current Condition Unknown
	#4286 - Runs	There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.
2	(1) 1998 Chevy Astro Van Vin #0763 - Runs	Unit #: C-6 - Has Key - Conventional Style - Passengers: 2 - Engine Size/Type: Vortec/4.3L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/18 - Interior Condition: Poor - Interior Problems: Worn Upholstery, Torn Seat, Dash Sittings Loose On Top - Body Condition: Fair - Body Problems: Drivers Door Has Issue When Closing, Surface Scratches, Oxidized Paint, Dent Right Rear Door, Scratches/Dents On Passenger Door, Dents, Surface Rust & Cracked Paint On Hood, Needs Cleaning - Tires Condition: Fair
		- Current Condition Unknown
		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.

3	(1) 1999 Chevy Astro Cargo Van Vin #5856 - Will Need To Be Towed	Will Need To Be Towed - Auctioneer Recommends Salvage - No Key - Unit #: Tech 4 - Conventional Style - Passengers: 2 - Engine Size/Type: 4.3L - Engine In Front - Engine Problems Present - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 10/14 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Extremely Dirty, Needs Cleaning, Torn Seats - Body Condition: Fair - Body Problems: Needs Cleaning, Scratches, Dents, Peeling Paint, Surface Rust, Peeling Paint - Tires Condition: Fair - Tire Problems: Need Air - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
4	(1) 1994 Ford Ranger XL Pickup Truck Vin #3420 - Will Need To Be Towed	Will Need To Be Towed - Has Key - Unit #: S-07 - Conventional Style - Passengers: 2 - Engine Size/Type: 2.3L - Engine In Front - Engine Problems: Fuel Pump Possibly Needs Replacing, Will Not Run - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 02/17 - Approx. Mileage Reads: 47,174 **Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Dash Damage, Torn Seats, Worn Upholstery, Needs Cleaning, Needs Headliner - Body Condition: Fair - Body Problems: Dent On Left Rear Bed, Scratches, Oxidized Paint, Crack On Windshield, Dents On Bumper - Tires Condition: Fair - Tire Problems: Some Need Air - Has Toolbox/No Key - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
5	(1) 2000 Chevy Astro Van Vin #9654 - Runs	Unit #: Tech 5 - Has Key - Conventional Style - Passengers: 2 - Engine Size/Type: 4.3L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Reads: 43,686**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Tear On Drivers Seat, Needs Cleaning, Worn Upholstery, Dash Loose On Top - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Peeling Paint - Tires Condition: Fair - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
6	(1) 2000 International 3800 Bluebird School Bus Vin #8126 - Will Need To Be Towed	Will Need To Be Towed - Has Key - Bus #: 24 - Conventional Style - Passengers: 77 - Engine Size/Type: T444E - Engine In Front - Engine Problems - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 10/18 - Approx. Mileage Reads: 137,446**Unknown Actual Mileage** - Approx. Hub Reads: 138,717 - Interior Condition: Poor - Interior Problems: Needs Cleaning, Torn Drivers Seat, Floor Soft In A Few Places, Normal Wear, Seat Torn - Body Condition: Fair - Body Problems: Scratch/Dent Under Window #6, Oxidized Paint, Surface Scratches, Rock Chip On Windshield - Tires Condition: Fair - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**

7	(1) 2008 International CE200 School Bus Vin #3578 - Will Need To Be Towed	Will Need To Be Towed - Bus #: 28 - Conventional Style - Passengers: 77 - Engine Size/Type: Model: A215/VT 365 Engine Family - Engine In Front - Engine Problems Present - Diesel - Battery: No - Runs - Automatic Transmission - Has Key - Air Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Worn Upholstery, Needs Cleaning, Torn Seats - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches - Tires Condition: Fair In Front, Good In Rear - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
8	(1) 2008 International CE200 School Bus Vin #3584 - Will Need To Be Towed	Will Need To Be Towed - Bus #: 11 - Conventional Style - Passengers: 77 - Engine Size/Type: Model: A215/VT 365 Engine Family - Engine In Front - Engine Problems: Bad Engine - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 02/18 - Approx. Mileage Unable To Read/No Battery - Interior Condition: Poor - Interior Problems: Torn Seats, Needs Cleaning, Worn Upholstery - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Broken Glass On Rear Entry Door - Tires Condition: Fair All Over, Poor Left Rear - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
9	(1) 2005 Freightliner Thomas School Bus Vin #1518 - Will Need To Be Towed	Will Need To Be Towed - Wrecked In Front - Recommend Salvage Use - Has Key - Bus #: 207 - Conventional Style - Passengers: 77 - Engine Size/Type: CAT C7 - Engine In Front - Ran When Wrecked - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Unable To Read/Dead Battery - Approx. Hub Reads: 123,401**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Missing Most Of The Seats & Interior Parts, Needs Cleaning, Drivers Seat Torn - Body Condition: Poor - Body Problems: Wrecked In Front/Bent Frame, Parts Missing, Missing Front Bumper, Emblems, Hood Damaged, Front Damage, Oxidized Paint, Surface Scratches, Missing Exterior Parts, Rear Bumper Out Of Alignment - Tires Condition: Fair - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
10	(1) 2008 International CE200 School Bus Vin #3577 - Will Need To Be Towed	Will Need To Be Towed - Recommend Salvage - Bus #: 15 - Conventional Style - Passengers: 77 - Engine Size/Type: Model: A215/VT 365 Family - Engine In Front - Engine Problems: Bad Engine, Missing Steering, Missing Gear Box - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 01/17 - Approx. Mileage Unable To Read/No Battery - Interior Condition: Poor - Interior Problems: Worn Upholstery, Parts Missing, Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rock Chip On Windshield, Damage On Left Front Wheel Well - Tires Condition: Fair - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**

11	(1) 1996 International 3800 Amtra Vin #7846 - Will Need To Be Towed	Will Need To Be Towed - Recommend Salvage Use - No Key - Bus #: 39 - Conventional Style - Passengers: 71 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Sitting Up A Long Time, Parts Missing - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 00/14 - Approx. Mileage Reads: 192,191 **Unknown Actual Mileage - Interior Condition: Poor - Interior Problems: Torn Seats, Needs Cleaning, Worn Upholstery - Body Condition: Poor - Body Problems: Oxidized Paint, Scratches, Needs Cleaning, Parts Missing, Peeling Paint On Hood & Cowl - Tires Condition: Poor - Tire Problems: Tires Are Probably Dry Rotted - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
12	(1) Serving Line	Approx. Size: 234" Long X 33" Wide - Unit Is (1) Solid Piece - Stationary - Missing Parts - Was A 6 Well Unit
	Line	- Current Condition Unknown
13	(1) Serving Line	Approx. Size: 250" Long X 33" Wide - Unit Is (1) Solid Piece - Stationary - Parts Missing - 7 Well
		- Current Condition Unknown
14	(1) Serving Line	Approx. Size: 234" Long X 33" Wide - (1) Solid Piece - Stationary - 6 Well - Current Condition Unknown
		Approx Size: 234" Long X 33" Wide - (1) Solid Piece - Stationary - 6 Well
15	(1) Serving Line	
		- Current Condition Unknown
16	(1) Steam Table	7 Well - 100" Long X 33" Wide - Stationary - Laying On It's Side In Photo - Current Condition Unknown
	(Lot) Cafeteria Tables	(Approx. 2) Bench Style
17		- Current Condition Unknown
18	(1) EZ Go Textron Electric 4	W/ Bed - Has Batteries - Has Charger - Seat Needs Cleaning - No Key - Needs Repair - Upholstery Worn - Tires Are Worn
	Wheel Golf Cart	- Current Condition Unknown
19	(1) Cafeteria Table	Bench Style
		- Current Condition Unknown
20	(Lot) Cafeteria	(Approx. 3) Bench Style
	Tables	- Current Condition Unknown
21	(Lot) Cafeteria Tables	(Approx. 6)
	(Lot)	- Current Condition Unknown (Approx. 5)
22	Cafeteria Tables	- Current Condition Unknown
	(Lot)	(Approx. 6)
23	Cafeteria Tables	
		- Current Condition Unknown (Approx. 21) Adult Size
24	(Lot) Wood Chairs	- Current Condition Unknown
2.5	(Lot) Wood	(Approx. 21) Adult Size
25	Chairs	- Current Condition Unknown
26	(Lot) Wood Chairs	(Approx. 21) Adult Size
26		- Current Condition Unknown
27	(Lot) Wood	(Approx. 21) Adult Size
	Chairs	- Current Condition Unknown

28	(Lot) Versalite	W/ Carts - Unknown If Complete
	Platform Systems	- Current Condition Unknown
29	(Lot) Carts & Stand	Including: (Approx. 2) Metal Carts, (1) Computer Stand, Smart Technology Remotes, Promethean Remotes & Printers, E-Instruction Remotes
	Stanu	- Current Condition Unknown
30	(Lot) Carts & Misc.	Including: (Approx. 2) Metal Carts, Printers, Keyboards, Boom Box, Scanner, Promethean Remotes, Shredder & Misc.
30		- Current Condition Unknown
21	(1) Toss Back	Varsity 100- Portable - W/ Net
31		- Current Condition Unknown
22	(Lot) Computer Table & Misc.	Including: Table, Leap Front Leapster 2s, Speakers, iPod, Leapster Instructional Software Chips
32		- Current Condition Unknown
	(Lot) File	Including: (Approx. 2) 4 Drawer Legal & Letter File Cabinet, (Approx. 3) Flat Screen Monitors/View Sonic
33	Cabinets & Monitors	- Current Condition Unknown
	(Lot) File	Including: (1) 2 Drawer Lateral File Cabinet, (Approx. 2) Flat Screen Monitors, ViewSonic
34	Cabinets & Monitors	- Current Condition Unknown
	(1) 5 Drawer	
35	Lateral File Cabinet	- Current Condition Unknown
	(Lot) 4	(Approx. 4)
36	Drawer File Cabinets	- Current Condition Unknown
	(1) GE	
37	Stackable Washer &	Missing Dryer Nob
	Dryer	- Current Condition Unknown
	(1) 2 Drawer Metal	W/ Shelves
38	Storage	- Current Condition Unknown
	Cabinet	
39	(Lot) Cart & Monitor	Including: (1) Laptop Cart - Portable, (1) ViewSonic Flat Screen Monitors - No Stand
	I I I I I I I I I I I I I I I I I I I	- Current Condition Unknown
40	(Lot) Cart &	Including: (Approx. 2) Laptop Carts, (Approx. 2) B & D Drill Press - Table Top Style - Both Possibly Need Repair - Switch Loose
40	Drill Press	- Current Condition Unknown
	(Lot) Cart &	Including: (1) Metal Cart, (Approx. 2) Dell Printers
41	Printers	- Current Condition Unknown
	(1) Maytag	
42	(1) Maytag Electric Stove	- Current Condition Unknown
	(1 0+)	Including: (Approx. 4) Cisco System Catalyst 6500E & Possible Others, (Approx. 3) UPS/Liebert/GXT In Box - (1) Unit Is
43	(Lot) Networking	Unknown
	Equipment	- Current Condition Unknown
44	(1) Science	W/ Sink - Approx. Size: 48" Long X 27" Wide - Portable - Missing Mirror
44	Cabinet	- Current Condition Unknown
	(1) Science Cabinet	W/ Sink - Approx. Size: 48" Long X 27" Wide - Portable - Missing Mirror - Top Loose On Left Corner - Missing Mirror
45		- Current Condition Unknown
46	(Lot) Bourg Booklet Makers	Including: (1) Bourg Stacker - TD-D, (1) Bourg Booklet Maker - PASBM4, (1) Bourg Booklet Maker - AGRSBM4, (Approx.
		2) Boug Collators - BST10-DT & Box Of Mix
	iviakers	- Current Condition Unknown

	(1) Olevia	
47	Video	
	Conferencing Cart	- Current Condition Unknown
48	(1) Olevia	
	Video Conferencing	Constant Constitution Hallon and
	Cart	- Current Condition Unknown
	(1) Olevia Video	
49	Conferencing	- Current Condition Unknown
	(Lot)	Including: (Approx. 5) Flat Screen Monitor - ViewSonic, (Approx. 2) Metal Carts, (1) iPad Carts/Charging Cart
50	Monitors &	
	Misc.	- Current Condition Unknown Including: (Approx. 3) Metal Carts, (1) Computer Cabinet, Printers, Flip Videos, Olympus Camera, VCRs, Shredder,
	(Lot) Carts &	Math Wix, Leap Frog Leapster, Sewing Machine, (Approx. 2) Flat Screen Monitors/View Sonic, (1) Litton Commercial
51	Misc.	Microwave Oven
		- Current Condition Unknown
52	(Lot) Kitchen	Including: (Approx. 6) Childs Kitchen Items, (Approx. 5) Puppeteers, (Approx. 4) Learning Sticks
	Items & Misc.	- Current Condition Unknown
	(1) Delta Shop Master	
53	10"	Model: MS250 - 120 Volts - 60 Hz - Type 1
	Compound Power Mitre	- Current Condition Unknown
	Saw	Thurs 2 DAMIZON 2011 Charles Phases
54	(1) DeWalt Scroll Saw	Type 2 - DW788 - 20" - Single Phase
	Scron Saw	- Current Condition Unknown
55	(1) DeWalt Scroll Saw	Type 2 - DW788 - 20" - Single Phase
	Scron Saw	- Current Condition Unknown
56	(1) DeWalt Scroll Saw	Type 2 - DW788 - 20" - Single Phase
	SCIOII Saw	- Current Condition Unknown
57	(1) DeWalt	Type 2 - DW788 - 20" - Single Phase
	Scroll Saw	- Current Condition Unknown
58	(1) DeWalt	Type 2 - DW788 - 20" - Single Phase
	Scroll Saw	- Current Condition Unknown
59	(1) Concrete	Kushlan - Portable - Has Electric Motor
	Mixer	- Current Condition Unknown
60	(Lot) Bells	(Approx. 2) Jarvis/Musser - Parts Missing - Musser: 661 - Portable - (1) Unit Needs Air In Tires
00	(LOT) Bells	- Current Condition Unknown
C1	(1)	Yamaha YM 2400 - Possible Parts Missing - W/ Stand - (1) Extra Stand - Needs Air In Tires
61	Xylophone	- Current Condition Unknown
63	(1) Porter	PCB370SS - 120 Volts - 60 Hz - 500-1500 RPM
62	Cable Scroll Saw	- Current Condition Unknown
	(1) Porter Cable Scroll Saw	PCB370SS - 120 Volts - 60 Hz - 500-1500 RPM
63		- Current Condition Unknown
	(1) Porter Cable Scroll Saw	PCB375SS - 120 Volts - 60 Hz - Marked Needs Repair
64		- Current Condition Unknown
	(1) Porter Cable Scroll Saw	PCB370SS - 120 Volts - 60 Hz - 500-1500 RPM
65		- Current Condition Unknown
	1	

66	(1) Porter Cable Scroll	PCB370SS - 120 Volts - 60 Hz - 500-1500 RPM
	Saw	- Current Condition Unknown
67	(Lot) Laptop Carts	(Approx. 5) Charging Carts - W/ (Approx. 5) ViewSonic Flat Screen Monitors
		- Current Condition Unknown
68	(Lot) Cart & Misc.	Including: (1) Laptop Cart W/ Writer Plus, (Approx. 30) Keyboards, (1) ViewSonic Flat Screen Monitor
	IVIISC.	- Current Condition Unknown
69	(Lot) Laptop Carts	Including: (Approx. 4) Laptop Charging Carts - No Key, (Approx. 4) ViewSonic Flat Screen Monitors
	(1)	- Current Condition Unknown
70	(Lot) Octagon	(Approx. 3) Approx. Size: 36" X 36" - Adjustable
, 0	Tables	- Current Condition Unknown
71	(Lot) U- Shaped	(Approx. 4) Adjustable
/ 1	Tables	- Current Condition Unknown
72	(Lot) Discarded Library Books & Educational Material	- Current Condition Unknown
73	(Lot) Discarded Library Books & Educational Material	- Current Condition Unknown
74	(Lot) Discarded Library Books & Educational Material	- Current Condition Unknown
75	(Lot) Double Sided	(Approx. 5) Approx Size: 48" Long - Heavy Particle Board
	Bookcases	- Current Condition Unknown
76	(Lot) Scrap Metal	Large Qty - Current Condition Unknown
77	(1) Traulsen Refrigerator	Single Phase - 115 Volts - Model: RHT132WREFHS - Possible Parts Missing - Condition Unknown - Single Door - Single Sided
		- Current Condition Unknown
78	(1) Hobart Refrigerator	Single Phase - 120 Volts - Model: QFI - Single Door - Single Sided
70		- Current Condition Unknown