Lot Number	Title	Description
0	Preview & Removal Information	**All purchases will be subject to a 3% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.** Preview: (By Appointment Only-Mandatory-No Exceptions) Monday, October 28, 2019 (Hours Of Operation: 8:00 a.m 4:00 p.m.) Location: 926 Bobcat Blvd, Krum, Tx 76249 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Thursday, October 31, 2019/Friday, November 1, 2019/Monday, November 4, 2019 (Hours Of Operation: 8:00 a.m 4:00 p.m.) Preview & Removal Contact: Bobby Carey, (940)482-2556 Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed
1	(1) 1999 International School Bus Vin #5557 - Will Need To Be Towed	Will Need To Be Towed - Bus #: 1 - Conventional Style - Passengers: 71 - Engine Size/Type: DT466E - Engine Problems: Air Tank Leak, Unable To Hold Air Pressure, Fuel Housing Leaks, Transmission Clutch Slippage - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Type/Condition: AT545 Allison - Air Brakes - Approx. Mileage Reads: 142,342.5**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Torn Seats - Body Condition: Fair - Body Problems: Dents, Head Light Bezel Missing - Tires Condition: Fair - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
2	(1) 1999 International School Bus Vin #5556 - Will Need To Be Towed	Will Need To Be Towed - Bus #: 2 - Engine Size/Type: DT4666E - Engine Problems: Air Compressor Mounts & Pump Failure, Transmission Clutch Slippage, Wiring Issues, Unable To Start Engine - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Type/Condition: AT 545 Allison - Air Brakes - Approx. Mileage Reads: 146,354.3 **Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Torn Seats - Body Condition: Fair - Tires Condition: Fair - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
3	(1) 2005 Bluebird School Bus Vin #3944 - Will Need To Be Towed	Will Need To Be Towed - Bus #: 3 - Engine Size/Type: 6.0L Ford Powerstroke - Engine Problems: Oil Leaks, Transmission Unable To Shift Gears, A/C Complete Overhaul, Electrical Issues, Unable To Start - Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Transmission Type: 5R110W - Hydraulic Brakes - Approx. Mileage Reads: 121,076 **Unknown Actual Mileage** - Interior Condition: Fair - Body Condition: Fair - Tires Condition: Poor - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**

1	(1) 2005	Will Need To Be Towed - Bus #: 4 - Engine Size/Type: C7 ACER Cat - Engine Problems: Electrical Issues, Transmission Clutch Slippage - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Type/Condition: AT545 Allison - Air Brakes - Approx. Mileage Reads: 87,498.6**Unknown Actual Mileage** - Interior Condition: Fair - Body Condition: Fair - Body Problems: Hood Latch Missing, Amber Light Cover Missing - Tires Condition: Fair
	Bluebird	- Current Condition Unknown
	School Bus Vin #4448 - Will Need To Be Towed	There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.