

Lot Number	Title	Description
0	Preview & Removal Information	<p>All purchases will be subject to a 13% buyer's premium.</p> <p>Preview: Contact Seller For Preview Information</p> <p>Location: GISD Transportation, 3101 83rd St., Galveston, TX 77550 Driving Directions</p> <p>Removal: Contact Seller For Removal Information</p> <p>Preview & Removal Contacts: Dave Tisdale, (409)761-6175 or dave@tisdale.org</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p>
5	(1) 1997 Ford Crown By Carpenter School Bus Vin #9515 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 8723 - Conventional Style - Passengers: 65 - Engine Size/Type: 5.9L - Engine In Front - Engine Problems: Bad Engine, Possible Parts Missing - Diesel - Battery: Yes/dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 02/19 - Approx. Mileage Reads: 211,582**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Torn, Needs Cleaning, Possible Parts Missing, Upholstery Worn, Surface Rust - Body Condition: Poor - Body Problems: Possible Parts Missing, Rust All Over, Oxidized Paint, Dents, Scratches, Bad Rust On Right Side Panel & Rub Rail, Large Dent/Scratch On Right Rear, Bad Rust On Roof, Hole On Roof - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
9	(1) 2010 International School Bus Vin #5802 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 1067 - Conventional Style - Passengers: 65 - Engine Size/Type: Maxx Force - Engine In Front - Engine Problems: Bad Engine/Parts Missing - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 02/19 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Tears On Seats, Needs Cleaning, Parts Missing, Entry Door Parts Missing - Body Condition: Fair - Body Problems: Surface Rust, Oxidized Paint, Missing (1) Rear Light, Missing Parts, Dent On Left Rear, Indention On Left Rear Lower Panel Under Window #6, Cracks On Windshield, Possible Parts Missing - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
15	(1) 2006 Dodge Ram 1500 Crew Cab Pickup Truck Vin #0356 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Passengers: 6 - Engine Size/Type: 4.7L - Engine In Front - Engine Problems: Running Condition Unknown - Gas - Battery: Yes/Dead - Unknown If Running - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Normal Wear, Needs Cleaning, Damage On Drivers Side Seat Panel - Body Condition: Fair To Poor - Body Problems: Rust Under Carriage Due To Possible Exposure To High Water, Rust On Right Rear Passenger Door, Surface Rust On Roof, Rust On Cowl, Rust On Tailgate - Tires Condition: Fair - Dent On Rear Bumper & Rust, Needs Cleaning, Crack On Windshield Drivers Side, Temporary Repair On Roof From Rust</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>