

Lot Number	Title	Description
0	Preview & Removal Information	<p>IMPORTANT NOTICE FOR ALVIN I.S.D. AUCTION: All purchases will be subject to a 13% buyer's premium. There Will Be A 3% Administrative Fee On All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order Or Wire Transfer**</p> <p>**Items Not Removed By Deadline Will Be Forfeited & No Refund Will Be Issued**</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, November 19, 2019 (Hours of Operation: 8:00 a.m. - 10:30 a.m./1:00 p.m. - 3:00 p.m.)</p> <p>Location: Alvin ISD Transportation Department, 2780 Hwy 6, Alvin, Tx 77511 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Friday, November 22, 2019/Monday, November 25, 2019/Tuesday, November 26, 2019 (Hours of Operation: 8:00 a.m. - 10:30 a.m./1:00 p.m. - 3:00 p.m.)</p> <p>Preview & Removal Contact: Andreas Montes, (281)245-2989 Yvonne Albarran, (281)245-2974</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. Removal Is The Sole Responsibility Of The Buyer. There Will Be NO Forklift, Pallet Jack, Dolly, Or Staff To Assist.</p> <p>After the final removal date, a storage charge of \$10.00 per day, per item/lot will be charged by the Seller.</p> <p>***Important Note: All Lots Are Located At A Secure Unattended Location. Appointments For Viewing & Pickups Are Required. Pickup Dates Are Firm. Under No Circumstances Will An Extension Be Given. Buyer Is Responsible For All Aspects of Removal. There Will Be NO Assistance Available For Removal. There Will Be No Dollies, Pallet Jacks, Tools, Or Personnel To Assist***</p> <p>**All buyers must have a paid receipt from Lemons Auctioneers, LLC at time of pickup. **</p>
400	(1) 2006 International School Bus Vin #4911 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 21 - Conventional Style - Passengers: 77 - Engine Size/Type: 6.0 Intl - Engine In Front - Engine Problems: Hot No Start, Engine Problems - Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Transmission Type: Allison - Air Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 151,259**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Need Cleaning, Torn Or Missing Seats - Body Condition: Fair- Body Problems: Missing Rear Bumper, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
402	(1) 2006 International School Bus Vin #4924 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 34 - Conventional Style - Passengers: 77 - Engine Size/Type: 6.0 Intl - Engine In Front - Engine Problems: Engine Knocking, Worn Out - Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Allison Transmission - Air Brakes - Inspection Sticker Date: 02/18 - Approx. Mileage Reads: 110,306**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Need Cleaning, Seats Torn Or Missing - Body Condition: Fair - Body Problems: Faded Paint, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

403	(1) 2007 International School Bus Vin #4927 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 37 - Conventional Style - Passengers: 77 - Engine Size/Type: 6.0 Intl - Engine In Front - Engine Problems: Engine Overheat, Blown Head Gasket - Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Allison Transmission - Air Brakes - Inspection Sticker Date: 01/19 - Approx. Mileage Reads: 80,620**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Need Cleaning, Torn Or Missing Gauge Cluster - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
404	(1) 2006 International School Bus Vin #4928 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 38 - Conventional Style - Passengers: 77 - Engine Size/Type: 6.0 Intl - Engine In Front - Engine Problems: Engine Noise Blow By - Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Allison Transmission - Air Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Reads: 96,693**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Need Cleaning, Torn Or Missing - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
405	(1) 2010 Bluebird School Bus Vin #9020 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 80 - Conventional Style - Passengers: 77 - Engine Size/Type: 8.1 GM - Engine In Front - Engine Problems: Engine Misfire, Bad Cam - Propane - Battery: Yes - Does Not Run - Automatic Transmission - Allison Transmission - Air Brakes - Inspection Sticker Date: 02/19 - Approx.. Mileage Reads: 154,145**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Need Cleaning, Torn Or Missing - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair - Tire Problems: Missing Outer Dual Tires - Missing Differential</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
406	(1) 2010 Bluebird School Bus Vin #9015 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 85 - Conventional Style - Passengers: 77 - Engine Size/Type: 8.1 GM - Engine In Front - Engine Problems: Engine Misfire, Blown Head Gasket - Propane - Battery: Yes - Does Not Run - Automatic Transmission - Allison Transmission - Air Brakes - Inspection Sticker Date: 07/17 - Approx. Mileage Reads: 141,227**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Need Cleaning, Torn Or Missing - Body Condition: Fair - Body Problems: Missing Front Bumper, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

407	(1) 2005 International School Bus Vin #3459 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 190 - Conventional Style - Passengers: 77 - Engine Size/Type: 6.0 Intl - Engine In Front - Engine Problems: Engine Misfire, Blown Head Gasket - Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Allison Transmission - Air Brakes - Inspection Sticker Date: 11/19 - Approx. Mileage Reads: 123,819**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Need Cleaning, Torn Or Missing Seats & Gauge Cluster - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
408	(1) 2004 Bluebird School Bus Vin #7963 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 846 - Conventional Style - Passenger: 47 - Engine Size/Type: C7 CAT - Engine In Front - Engine Problems: Engine Runs Rough - Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Allison Transmission - Air Brakes - Inspection Sticker Date: 12/19 - Approx. Mileage Reads: 211,501**Unknown Actual Mileage** - Wheel Chair Lift, Condition: Does Not Work - Interior Condition: Poor - Interior Problems: Seats Need Cleaning, Torn Or Missing - Body Condition: Fair- Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
409	(1) 2007 International School Bus Vin #5207 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 853 - Conventional Style - Passengers: 47 - Engine Size/Type: 6.0 Intl - Engine In Front - Engine Problems: Engine Misfire, Bad Cam, Missing Parts - Diesel - Battery: Yes - Does Not Run - Automatic Transmission - Allison Transmission - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 229,368**Unknown Actual Mileage** - Wheel Chair Lift, Does Not Work - Interior Condition: Poor - Interior Problems: Seats Need Cleaning, Torn Or Missing Seats - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
410	(1) 2006 Chevy 2500 Cargo Van Vin #1187 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: D100 - Conventional Style - Passenger: Cargo Van - Engine Size/Type: 5.3 GM - Engine In Front - Engine Problems: Engine Oil Leak - Gas - Battery: Yes - Runs - Automatic Transmission - Transmission Type: GM 4L60E - Hydraulic Brakes - Inspection Sticker Date: 11/19 - Approx. Mileage Reads: 119,781**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Need Cleaning, Torn At Some Areas Worn Out - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

411	(1) 2003 Chevy 3500 Cargo Van Vin #5428 - Runs	<p>Unit #: M09 - Conventional Style - Passenger: Cargo Van - Engine Size/Type: 5.3 GM - Engine In Front - Engine Problems: Old Unit Worn Out, Faded Paint - Gas - Battery: Yes - Runs - Automatic Transmission - Transmission Type: GM 4L60E - Hydraulic Brakes - Inspection Sticker Date: 11/19 - Approx. Mileage Reads: 96,843**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Need Cleaning, Torn At Some Areas, Worn Out - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
412	(1) 2004 Chevy 2500 HD Pickup Truck Vin #8295 - Runs	<p>Unit #: M24 - Conventional Style - Passengers: Pickup - Engine Size/Type: 6.0 GM - Engine In Front - Engine Problem: Old Unit, Worn Out, Faded Paint - Gas - Battery: Yes - Runs - Automatic Transmission - Transmission Type: GM 4L80E - Hydraulic Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Reads: 87,324**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Need Cleaning, Torn At Some Areas, Worn Out - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
415	(1) 2006 Chevy 2500 Pickup Truck Vin #1002 - Runs	<p>Unit #: M32 - Conventional Style - Passengers: Pickup W/ Toolbox - Engine Size/Type: 6.0 GM - Engine In Front - Engine Problems: Fair Shape, High Mileage - Gas - Battery: Yes - Runs - Automatic Transmission - Transmission Type: GM 4L80E - Hydraulic Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Reads: 90,230**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Need Cleaning, Torn At Some Areas, Worn Out, Air Bag Light On - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
416	(1) 2006 Chevy Colorado Vin #1045 - Runs	<p>Unit #: M34 - Conventional Style - Passengers: 2 Door Pickup Truck - Engine Size/Type: 3.5 GM - Engine In Front - Engine Problems: Fair Shape, High Mileage - Gas - Battery: Yes - Runs - Automatic Transmission - Transmission Type: GM - Hydraulic Brakes - Approx. Mileage Reads: 95,963**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Need Cleaning, Torn At Some Areas, Worn Out - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

418	(1) 2007 Chevy Colorado Vin #3895 - Runs	<p>Unit #: M53 - Conventional Style - Passengers: 2 Door Extended Pickup - Engine Size/Type: 3.5 GM - Engine In Front - Engine Problems: Fair Shape, High Mileage - Gas - Battery: Yes - Runs - Automatic Transmission - Transmission Type: GM - Hydraulic Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 109,219**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Need Cleaning, Torn At Some Areas, Worn Out - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
419	(1) 2010 Chevy HHR Vin #9696 - Runs	<p>Unit #: M78 - Conventional Style - Passengers: 2 Door - Engine Size/Type: 2.2 GM - Engine In Front - Engine Problems: Fair Shape, High Mileage - Gas - Battery: Yes - Runs - Automatic Transmission - Transmission Type: GM - Hydraulic Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 93,500**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Needs Cleaning, Torn At Some Areas, Worn Out - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents, Worn Out Suspension - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
420	(1) 2010 Chevy HHR Vin #9695 - Runs	<p>Unit #: M79 - Conventional Style - Passengers: 2 Door - Engine Size/Type: 2.2 GM - Engine In Front - Engine Problems: Fair Shape, High Mileage - Gas - Battery: Yes - Runs - Automatic Transmission - Transmission Type: GM - Hydraulic Brakes - Inspection Sticker Date: 02/20 - Approx. Mileage Reads: 91,524**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Need Cleaning, Torn At Some Ares, Worn Out - Body Condition: Fair - Body Problems: Paint Faded, Scratches & Dents, Worn Out Suspension - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
421	(1) 2008 Ford F350 Vin #3762 - Runs	<p>Unit #: V05 - Conventional Style - Passengers: 4 Door Pickup - Engine Size/Type: 6.4 Ford - Engine In Front - Engine Problems: Fair Shape, High Mileage, Turbo Noise- Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Type: Ford - Hydraulic Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 172,123**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Need Cleaning, Torn At Some Areas, Worn Out - Body Condition air - Body Problems: Paint Faded, Scratches & Dents, Worn Out Suspension - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
422	(Lot) Chevy Tailgates	<p>(Approx. 3) (1 Pallet) - Removed New</p> <p>- Current Condition Unknown</p>
423	(Lot) Tahoe Third Seats	<p>(Approx. 2 Pallets) (Approx. 8) Removed New</p> <p>- Current Condition Unknown</p>
424	(1) EZGO Golf Cart	<p>Not Titled - Does Not Run - Missing Parts</p> <p>- Current Condition Unknown</p>