Lot Number	Title	Description
0	Preview & Removal Information	All purchases will be subject to a 13% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**
		<b>Preview:</b> (By Appointment Only-Mandatory-No Exceptions) Thursday, November 21, 2019 (Hours Of Operation: 8:00 a.m 3:00 p.m.)
		Location : Southside ISD Warehouse, 3105 S. Loop 1604 E, San Antonio, TX 78264 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Wednesday, December 4, 2019/Thursday, December 5, 2019/Friday, December 6, 2019 (Hours Of Operation: 8:00 a.m 3:00 p.m.) Preview & Removal Contact: Robert Garcia, (210)529-1797 email: roberto.garcia@southsideisd.org Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed No Lifting Equipment Available. Buyer Solely Responsible For Removal.
	(1) 1992 Chevy S10	Will Need To Be Towed - Unit #: S-5 - Conventional Style - Passengers: 2 - Engine Size/Type: 4.3L - Engine In Front - Engine Problems: Transmission Bad, Fuel Pump Bad, Not Running - Gas - Battery: Yes/Dead - Does Not Run - Standard Transmission - Bad Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/17 - Approx. Mileage Reads: 61,350 **Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seat Poor, Rust All Over, No Headliner, Needs Cleaning, Cracks On Dash, Has Been Exposed To The Elements - Body Condition: Poor - Body Problems: Window Railing Is Broken On Doors, Rust All Over, Oxidized Paint, Scratches, Dents, Cracks On Windshield, Rear Bumper Rubber Molding Missing, Dents - Tires Condition: Fair
1	Pickup Truck Vin #1316 -	- Current Condition Unknown
	Will Need To Be Towed	There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
	(1) 2012 International	Will Need To Be Towed - Bus #: 4 - Conventional Style - Passengers: 27 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: Bad Engine, Needs An Alternator, A/C Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 02/18 - Approx. Mileage Unable To Read/Dead Battery - Wheel Chair Lift, Condition: Not Working - Interior Condition: Fair - Interior Problems: Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Needs Hood Spring Hinges, Drive Is IN Rear Inside Bus, Oxidized Paint, Surface Scratches, Scratches On Hood - Tires Condition: Fair
2	CE School Bus Vin	- Current Condition Unknown
	#5883 - Will Need To Be Towed	There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
	(1) 2000 International Bluebird 3800 School Bus Vin #1659 - Will Need To Be Towed	Will Need To Be Towed - Bus #: 52 - Conventional Style - Passengers: 77 - Engine Size/Type: T444E - Engine In Front - Engine Problems: No A/C - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 03/19 - Approx. Mileage Reads: 217,116**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Torn Seats, Needs Cleaning, Upholstery Worn - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Scratches, Roofing Paint Worn & Needs Cleaning, Peeling On Cowl & Hood, Rock Chip On Windshield, Some Damage On Hood- Tires Condition: Fair
3		- Current Condition Unknown
		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**

4	(1) 2010 International School Bus Vin #6142 - Will Need To Be Towed	<ul> <li>Will Need To Be Towed - Bus #: 38 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: No A/C Belt, Retired, Current Condition Unknown - Diesel - Battery: Yes/Dead - Unknown Running Condition - Automatic Transmission - Air Brakes - Inspection Sticker Date: 04/18 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Floor Will Need Some Repair In The Future, Worn Upholstery, Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rear Lights (White) Lens Are Cracked - Tires Condition: Fair4</li> <li>- Current Condition Unknown</li> <li>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</li> <li>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</li> </ul>
5	(1) 2010 International CE School Bus Vin #6143 - Will Need To Be Towed	<ul> <li>Will Need To Be Towed - Bus #: 41 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: Not Running, Engine Problem Unknown - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 04/18 - Approx. Mileage Unable To Read/No Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning, Missing (2) A/C Vents On Dash - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Dents On Right Rear, Lights Missing On Rear - Tires Condition: Fair</li> <li>Current Condition Unknown</li> <li>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</li> <li>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</li> </ul>
6	(1) 2010 International School Bus Vin #6162 - Will Need To Be Towed	<ul> <li>Will Need To Be Towed - Bus #: 42 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: No ECM, Not Running - Diesel - Battery: No - Does Not Run - Air Brakes - Inspection Sticker Date: 02/18 - Approx. Mileage Unable To Read/No Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Scratch On Right Rear, Missing Passenger Window On Left Rear - Tires Condition: Fair</li> <li>- Current Condition Unknown</li> <li>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</li> <li>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</li> </ul>
7	(1) 2001 International 3800 Thomas School Bus Vin #3595 - Will Possibly Need To Be Towed	<ul> <li>Will Possibly Need To Be Towed - Bus #: 28 - Conventional Style - Passengers: 77 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Bus Retired, Has Electrical Problems, Current Driving Condition - Diesel - Battery: Yes/Dead - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 09/19 - Approx. Mileage Reads: 162,529</li> <li>**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Seats Are Torn, Needs Cleaning, Some Panels Are Loose Inside Bus, Possible Parts Missing - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Slight Indention &amp; Scratch On Right Rear, Roof Needs Cleaning &amp; Paint Worn, Windshield Cracked On Left Front, Peeling On Cowl &amp; Hood - Tire Problems: Front Left Tire Low, Good In Rear, Fair In Front</li> <li>- Current Condition Unknown</li> <li>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</li> <li>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</li> </ul>

8	(1) 2003 Freightliner Thomas School Bus Vin #9451 - Will Need To Be Towed	<ul> <li>Will Need To Be Towed - Bus #: 36 - Conventional Style - Passenger: 77 - Engine Size/Type: Cummins 24 Valve - Engine In Front - Engine Problems: Ran When Parked, Current Condition Unknown, Unit Was Retired - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 10/18 - Approx. Mileage Reads: 206,872</li> <li>**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Worn Upholstery, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Some Dents, Missing Front Mirrors - Tires Condition: Good In Front, Fair On Rear</li> <li>- Current Condition Unknown</li> <li>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</li> <li>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</li> </ul>
9	(1) 2010 International CE School Bus Vin #6160 - Will Need To Be Towed	<ul> <li>Will Need To Be Towed - Bus #: 40 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: Ran When Parked - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Transmission Control Module Missing - Air Brakes - Inspection Sticker Date: 04/18 - Approx. Mileage Unable to Read /Battery Dead - Interior Condition: Fair - Interior Problems: Some Seats Torn, Needs Cleaning, Some Molding Loose On Bus, Door Entry Parts Missing - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Some Screws Missing On Entry Door Panel, Scratch On Right Rear, Lights Missing On Rear - Tires Condition: Good On Rear, Fair In Front</li> <li>- Current Condition Unknown</li> <li>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</li> <li>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</li> </ul>
10	(1) 2012 International School Bus Vin #7578 - Will Need To Be Towed	<ul> <li>Will Need To Be Towed - Bus #: 50 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: Not Running, Engine Was Rebuilt &amp; Still Is Not Running, Problem Unknown, Engine Parts Inside Bus - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 05/18 - Approx. Mileage Unknown/Dead Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning, Some Stained Seats, Engine Parts Loose Inside Bus, Parts Possibly Missing - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Scratch On Right Rear, Front Grill Loose Inside Bus - Tires Condition: Good In Rear, Fair In Front</li> <li>Current Condition Unknown</li> <li>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</li> <li>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</li> </ul>
11	(1) 2010 International School Bus Vin #6155 - Will Need To Be Towed	<ul> <li>Will Need To Be Towed - Bus #: 70 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: No Idler Puller, Gas Pedal Removed - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 04/18 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning, (1) AC Vent Missing On Dash, Floor Will Need Minor Repair - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Lights Missing On Rear - Tires Condition: Good In Rear, Fair In Front</li> <li>Current Condition Unknown</li> <li>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</li> <li>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</li> </ul>

12	(1) 2010 International CE School Bus Vin #6153 - Will Need To Be Towed	<ul> <li>Will Need To Be Towed - Bus #: 48 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: Not Running, Engine Problem Unknown - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 03/17 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Some Tron Seats, Needs Cleaning, Possible Parts Missing, (1) AC Vent Missing - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches - Tires Condition: Good In Rear, Fair In Front</li> <li>Current Condition Unknown</li> <li>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</li> <li>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</li> </ul>
13	(1) 2010 International CE School Bus Vin #6152 - Will Need To Be Towed	<ul> <li>Will Need To Be Towed - Bus #: 19 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine Problems: Not Running, Problem Engine Unknown - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 01/20 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Minor Tears ON Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Slight Indention On Right Rear - Tires Condition: Good In Rear, Fair In Front</li> <li>Current Condition Unknown</li> <li>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</li> <li>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</li> </ul>
14	(Lot) Playground Roofs Only	(Approx. 2) Hard Plastic - Color: Blue & Red - Current Condition Unknown
15	(Lot) Playground Roofs Only	(Approx. 2) Hard Plastic - Color: Blue - Current Condition Unknown
16	(Lot) Playground Roofs Only	(Approx. 2) Hard Plastic - Color: Blue & Green - Blue Roof Has A Crack - Current Condition Unknown
17	(1) Taco Pump	Model: 2513 - Missing Motor - Parts Unit - Current Condition Unknown
18	(Lot) AC & Heat Equipment	Including: (1) Carrier Furnace, (1) Ac Unit - Mfg.: Unknown, (1) Alliance Compressor - Current Condition Unknown
19	(Lot) Curbco Curb Adaptor	(Approx. 7) Model: R278 - Current Condition Unknown
20	(1) Baldor Electric Motor	15 HP - 230/460 Volts - Cat #: EM2513T - Phase 3 - Current Condition Unknown
21	(Lot) A/C, Furnace, & Misc.	Including: (1) Copeland Compressor, (1) Paint Striper - Needs Repair - Gas Cylinder Not Included, (1) AC Parts, (1) Carrier Furnace - Parts - Current Condition Unknown
22	(Lot) Copeland Compressors	(Approx. 6) Various Conditions - Current Condition Unknown
23	(Lot) Carrier Furnace, Compressors, & Misc.	Including: (1) Carrier Furnace - Parts Unit, (Approx. 2) Copeland Compressors & Misc. - Current Condition Unknown
24	(1) Air Conditioner & Furnace	Mfg.: Unknown - Carrier Infinity Puron - Current Condition Unknown
25	(Lot) Compressors	(Approx. 6) Copeland & Possible Others - W/ (1) Fan - Current Condition Unknown

	1	
26	(Lot) A/C Equipment	Including: (Approx. 2) Parts Units & Misc.
		- Current Condition Unknown
27	(1) Disassembled	W/ Tecumseh, Heat Craft, Bohn - Size & Condition Unknown
	Walk In Cooler	- Current Condition Unknown
28	(Lot) Assorted	Including: Hatco Booster Heater, (1) Blakeslee Dishwasher, (1) Metal Desk, (Approx. 3) Curbco Units
	Scrap	- Current Condition Unknown
29	(Lot) Stage Platforms	(Approx. 8) Assorted Types - Located Outside & Susceptible To Weather Condition
		- Current Condition Unknown
	(1) Ruud Commercial	Model: RKNL-A036DK08B - Outdoor Use
30	Series A/C Chiller	- Current Condition Unknown
	(1) Rheem A	Model: RKKA-A036DL08E - Mfg.: 02/06
31	/C Chiller	- Current Condition Unknown
	(1) Rheem A	Model: RKNL-A036DK08E - Mfg.: 01/09
32	/C Chiller	- Current Condition Unknown
	(Lot) Ruud A	(Approx. 3) Including: (1) Model: RKKAA036DL08E, (1) RKNL-A036DK08E, (1) Unknown
33	/C Chiller Units	- Current Condition Unknown
	(Lot) Rheem A	(Approx. 3) Including: (1) Model: RKNL-A036DK08E - 01/10, (1) RKNL-A036DK08E - 01/09, (1) Unknown
34	/C Chiller Units	- Current Condition Unknown
	(Lot) Rheem	Including: (1) Model: UKKA-A036JK08E - 09/01, (1) RKKA-A036DK08E - 06/07, (1) Unknown
35	& Ruud A/C Chiller Units	- Current Condition Unknown
2.6	(1) Ruud &	Including: (1) RKKA036DL08E - 12/06, (1) RKNL A036DKAE - 01/09, (1) Unknown
36	Rheem A/C Chiller Units	- Current Condition Unknown
37	(1) Rheem &	(Approx. 2) RKKA-A036DL08E - 02/08 - Rheem: RNSLB042CK - 08/14
57	Ruud A/C Chillers	- Current Condition Unknown
38	(Lot) Loddors	Including: (Approx. 2) Extension - 24' Fiberglass Extension, (Approx. 2) Step Ladders - Size Unknown
50	(Lot) Ladders	- Current Condition Unknown
39	(Lot) Office	(Approx. 20) Arm, Executive, Various Conditions, Colors, & Types
	Chairs	- Current Condition Unknown
40	(Lot) Combo	(Approx. 27) Color Block - High School Size
40	Desk Chairs	- Current Condition Unknown
	(1) Canon Image	Model: IPF8100 - Portable
41	Prograf Printer	- Current Condition Unknown
42		(Approx. 2) Metal & Plastic - W/ Paper Cutters, DVD/VHS Player, & Misc.
42	(Lot) Carts	- Current Condition Unknown
43	(1) Laptop	Bretford - Portable
40	Cabinet	- Current Condition Unknown
44	(Lot) Student Combo Desk	(Approx. 26) Assorted Colors, Types - Assorted Sizes
	/Chairs	- Current Condition Unknown
45	(Lot) Student Desks	(Approx. 24) Open Front
		- Current Condition Unknown
46	(Lot) Dock	(Approx. 5) Box Hardware
	Bumper	- Current Condition Unknown

	1	
47	(1) EJ Vista IS Wheel Chair	Medium Size
	wheel Cildli	- Current Condition Unknown
48	(1) Cafeteria	Stool Type
	Table	- Current Condition Unknown
49	(1) Cafeteria Table	Stool Type
		- Current Condition Unknown
50	(Lot) Cafeteria Tables	(Approx. 2) Missing Some Stool
50		- Current Condition Unknown
51	(Lot) Cafeteria Tables	(Approx. 2) Missing Some Stool
51		- Current Condition Unknown
50	(Lot)	(Approx. 3) Only Tables - Portable
52	Cafeteria Tables	- Current Condition Unknown
F 2	(Lot) Pre-K	Including: Play Kitchen - No Sink Inserts, Cubby Cabinet, Pre-K Cabinet, (1) Rectangle Table & Misc.
53	Furniture	- Current Condition Unknown
EA	(Lot)	(Approx. 3) Only Tables - Portable
54	Cafeteria Tables	- Current Condition Unknown
55	(Lot) File	(Approx. 2) 2 Drawer - Legal
55	Cabinets	- Current Condition Unknown
56	(Lot) Metal	(Approx. 2) Carts - W/ Printers, Camcorders, Digital Video Recorder
50	Carts & Misc.	- Current Condition Unknown
57	(Lot) Student	(Approx. 40) Various Sizes, Conditions, & Types
57	Chairs	- Current Condition Unknown
58	(Lot) Pre-K	Including: Wood Bookcase, Cubby, Peg Board Rack
50	Furniture	- Current Condition Unknown
59	(Lot) Wood Doors	(Approx. 29) Assorted Types - Flush Hardwood 1 3/8" Hollow Core - 36" X 80" - Warnock Hershey - Door ProSystem - Used
		- Current Condition Unknown
60	(Lot) File	(Approx. 2) 4 & 5 Drawer - Legal & Letter - Assorted Types & Conditions
00	Cabinets	- Current Condition Unknown
61	(1) Allison	Part #: 29505061 - AT 545
01	Transmission	- Current Condition Unknown
62	(Lot) Office	(Approx. 9) Arm & Steno - Assorted Colors, Types, & Conditions
	Chairs	- Current Condition Unknown
63	(Lot) Tables	(Approx. 9) Rectangle, Science, Square, Trapezoid
		- Current Condition Unknown
64	(1) Hutch Desk	Approx 72" Long - Some Damage/Particle Board
		- Current Condition Unknown
65	(1) Corner Bookcase	Custom Built - 5 Shelf
		- Current Condition Unknown
66	(Lot) Desk & Return	
		- Current Condition Unknown
67	(Lot)	Including: (Approx. 2) Computer Tables, (1) Return -Particle Board
	Furniture	- Current Condition Unknown

68	(1) Corner Desk	Particle Board
	DESK	- Current Condition Unknown
69	(1) GE	Model: GRS18DMCRWW - 110-12& VAC - 60 Hz
	Refrigerator	- Current Condition Unknown
70	(1) Whirlpool	Broken Knob - Electric - Surface Rust
	(1) Whiripool Dryer	- Current Condition Unknown
	(1) Skutt Electric Table Top Kiln	Model: KS-609 - Electric
71		- Current Condition Unknown
	(Lot) Metal	(Approx. 2) Single Ped.
72	Desks	- Current Condition Unknown
	(1) Clinic	
73	Couch	- Current Condition Unknown
		(Approx. 9) Round, Square, Rectangle, Folding
74	(Lot) Tables	- Current Condition Unknown
	(Lot) Powr-	Model: PAS20DX - 24 Volts - 220 lb.
75	Flite Floor Machine	- Current Condition Unknown
	(1) Consew Commercial	206RB-3 - Electric
76	Sewing	
	Machine & Table	- Current Condition Unknown
77	(Lot) Metal	(Approx. 2) Double Ped - Missing Handle
//	Desks	- Current Condition Unknown
70	(1)	Approx. 10' Long
78	Disassembled Aquarium	- Current Condition Unknown
=0	(1) Xerox	Work Centre 7835
79	(1) Xerox Copier	- Current Condition Unknown
80	(1) Xerox	Work Centre 5855
80	Copier	- Current Condition Unknown
81	(1) Xerox Work Centre	Damaged
01	5335	- Current Condition Unknown
0.2	(1) Callatan	Damaged - Type Unknown
82	(1) Collator	- Current Condition Unknown
	(1) Xerox	
83	Work Centre 5875 Copier	- Current Condition Unknown
	(1) Xerox	
84	Work Centre 5890 Copier	- Current Condition Unknown
0.5	(1) Xerox	Missing Front Cover
85	Work Centre 5335	- Current Condition Unknown
0.0	(1) Xerox	
86	Work Centre 7835 Copier	- Current Condition Unknown
87	(1) Xerox	
0/	Work Centre 7835 Copier	- Current Condition Unknown
88	(1) Xerox Work Centre	
00	5335 Copier	- Current Condition Unknown

-		
89	(1) Xerox Work Centre	
	5330 Copier	- Current Condition Unknown
90	(Lot) Copier & Collators	Including: (1) Xerox Work Centre 7835 Copier, (Approx. 3) Collators
		- Current Condition Unknown
91	(1) LeBlanc Bass Clarinet	Model: III - W/ Case & Bell - No Neck
		- Current Condition Unknown
92	(1) Bari Saxophone	Mfg.: Buescher - Dents/Oxidization - Has Case & Neck
		- Current Condition Unknown
93	(1) Bari Saxophone	Buescher 400 W/ Case - W/ Neck
		- Current Condition Unknown
94	(Lot) Drums W/ Case	Qty: Unknown - Various Conditions
	vv/ case	- Current Condition Unknown
95	(1) Vito	W/ Case
	Saxophone	- Current Condition Unknown
96	(Lot) Musical Instruments	Including: (Approx. 2) Drum Line Drums, (1) Classical Guitar, (1) Stagg Electrical Guitar, (1) Sage Studio Lighting Control
	Instruments	- Current Condition Unknown
97	(Lot) Drums & Cases	Including: Drums, Cases, Stand, (1) JVC Cassette Desk
	& Cases	- Current Condition Unknown
98	(1) Dynasty Baritone	Dented - Missing Valve Cover
	Horn W/ Case	- Current Condition Unknown
99	(1) Mercedes Vicent	Missing Valve Cover - Stuck Valves
		- Current Condition Unknown
100		W/ Case - Dent - Missing Valve Covers
	Mellophone	- Current Condition Unknown
101	(1) Dynasty Baritone	Worn
	Horn W/ Case	- Current Condition Unknown
102	(1) Dynasty Baritone	Worn
	Horn W/ Case	- Current Condition Unknown
103	(1)	Mfg.: Buescher - Dented - Missing Neck - W/ Case
	Saxophone	- Current Condition Unknown
104	(1) Yamaha	Missing Parts - No Neck - W/ Case
	Saxophone	- Current Condition Unknown
105	(Lot) Clarinets	Including : (1) Buffe, (1) Paul Duran Corvette, (1) Unknown - Possible Parts Missing, With Cases
		- Current Condition Unknown
106	(Lot) Clarinets	Including: (1) Bundy, (1) Buescher, (1) Selmer 100, W/ Case - In Various Conditions - Missing Parts
		- Current Condition Unknown
107	(Lot) Clarinets	Including: (1) Signet, (1) Bundy, (1) Vito, W/ Cases, In Various Conditions - Missing Parts
		- Current Condition Unknown
108	(Lot) Clarinets	Including: (1) Normandy, (1) Bundy, In Various Conditions - Missing Parts
		- Current Condition Unknown
109	(1) Mossler Fire Proof	No Key - Combo Has Been Removed - Inside: (1) Door & (3) Drawer File Cabinet
	Safe	- Current Condition Unknown