Lot Number	Title	Description
0	Preview & Removal Information	**All purchases at will be subject to a 13% buyer's premium.** Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, December 3, 2019 (Hours Of Operation: 8:00 a.m 1:00 p.m.) Location: 11330 Falcon Rd. A, Houston, Tx 77065 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Monday, December 9, 2019/Tuesday, December 10, 2019/Wednesday, December 11, 2019/Thursday, December 12, 2019 (Hours of Operation: 8:00 a.m 1:00 p.m.) Removal Contact: Kristi Giron, 281-517-6366 Buyer Will Need To Pick Up The Key For Their Unit At 11330 Falcon Rd. A, Houston, Tx 77065 Driving Directions Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed No Cash Payments Accepted On Site
1	(1) 2000 Chevy LS Express 3500 Passenger Van Vin #4566 - Will Need To Be Towed	 Will Need To Be Towed - Unit #: 1854 - Conventional Style - Passengers: 14 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Not Running, Problem Unknown - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 02/20 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Needs Cleaning, Upholstery Worn - Body Condition: Fair - Body Problems: Surface Rust, Oxidized Paint, Surface Scratches, Peeling Paint, Minor Surface Rust, Scratches, Minor Dents - Tires Condition: Fair - Vehicle Has 4 Passenger Seats, (1) Drivers Seat, (1) Front Passenger Seat - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
2	(1) 2000 Chevy Express 3500 Van Vin #0498 - Will Need To Be Towed	 Will Need To Be Towed - Unit #: 1841 - Conventional Style - Passengers: 2 - Engine Size/Type: 350/5.7L - Engine Problems: Not Running, Problems Unknown - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Unable To Read - Interior Condition: Poor - Interior Problems: Drivers Side Door Panel Worn & Needs Replacing, Headliner Needs Replacing, Needs Cleaning, Upholstery Worn - Body Condition: Fair - Body Problems: Peeling All Over, Oxidized Paint, Crack On Windshield, Some Dents, Surface Scratches, Scratches - Tires Condition: Fair - Has Protection Cage, Has Headache Rack - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
3	(1) 1997 Chevy 3500 Van Vin #4405 - Runs	Unit #: 1808 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Unknown Problems - Gas - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 08/19 - Approx. Mileage Reads: 233,794**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Normal Wear Upholstery, Needs Cleaning, Minor Cracks On Dash, Seats Are Cracked & Worn - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Some Dents, Dents/Scratch On Left Rear, Surface Rust, Rock Chips On Windshield, Blue Tape On Right Mirror, Chipped Paint On Rear Doors - Tires Condition: Fair - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**

4	(1) 2000 Chevy 3500 Van Vin #8891 - Will Need To Be Towed	 Will Need To Be Towed - Unit #: 1847 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Runs, Problems Unknown - Gas - Battery: Yes/Dead - Runs - Auctioneer Recommends Towing - Automatic Transmission - Transmission Condition: Bad Transmission, Makes A Rumble Sound When Engaged - Hydraulic Brakes - Inspection Sticker Date: 02/20 - Approx. Mileage Unknown/Dead Battery - Interior Condition: Fair - Interior Problems: Worn Van, Passengers Seat Tron, Needs Cleaning, Upholstery Worn - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Surface Rust On Roof, Peeling All Over, Some Dents - Tires Condition: Fair - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.
5	(1) 2006 Chevy 3500 Cargo Van Vin	Unit #: 1875 - Conventional Style - Passengers: 2 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown Problems - Gas - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 04/20 - Approx. Mileage Reads: 149,274**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Normal Wear, Headliner Will Need Replacing - Body Condition: Fair - Body Problems: Scratches, Oxidized Paint, Peeling Paint, Has Rock Chips On Windshield - Tires Condition: Fair - Has Protection Cage, Has A Headache Rack, Has Shop Made Cabinets In Cargo Area - Current Condition Unknown
	#5601 - Runs	There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
	nuns	**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
	(1) 1997 Chev 3500 Cargo Van Vin #7050 - Runs	Unit #: 1816 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Unknown Problems - Gas - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 12/19 - Approx. Mileage Reads: 185,401**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Headliner Needs Replacing, Both Seats Are Torn, Upholstery Worn, Needs Cleaning - Body Condition: Fair - Body Problems: Peeling Paint, Oxidized Paint, Surface Scratches, Scratches All Over, Rock Chips On Windshield, Surface Rust ON Front Bumper, Surface Rust On Roof - Tires Condition: Fair - Has Headache Rack, Has Protection Case
6		- Current Condition Unknown
		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.
7	(1) 2000 Chevy 3500 Van Vin #9482 - Will Need To Be Towed	Will Need To Be Towed - Unit #: 1884 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Engine Problem, Turns Over But Will Not Start - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 01/20 - Approx. Mileage Reads: 134,693**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Normal Wear Upholstery, Needs Cleaning, Work Van, Panel Loose On Dash, Headliner Needs Replacing - Body Problems: Has Shop Built Cabinet In Cargo Area, Oxidized Paint, Chipped & Peeling Paint, Surface Rust On Roof, Minor Dents - Has Protection Cage, Has Headache Rack
		- Current Condition Unknown
		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.

8	(1) 1997 Chevy 3500 Express Van Vin #1129 - Will Need To Be Towed	 Will Need To Be Towed - Unit #: 1802 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Engine Problems, Type Unknown - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Tape On Dash, Headliner Needs Replacing, Needs Cleaning, Upholstery Worn - Body Condition: Fair - Body Problems: Tape On Left Side Window, Window On Drivers Side Stuck Down, Oxidized Paint, Surface Rust, Surface Scratches, Long Scratch On Right Passenger Door To Rear Panel, Peeling Paint On Front - Tires Condition: Fair - Has Protection Cage, Has Headache Rack - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
9	(1) 2007 Chevy 2500 Heavy Duty Pickup Truck Vin #1694 - Runs	Unit #: 1333 - Conventional Style - Passengers: 3 - Engine Size/Type: 6.0 - Engine In Front - Engine Problems Unknown - Gas - Battery: Yes/Dead - Runs - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Unable To Read - Interior Condition: Fair - Interior Problems: Normal Wear, Needs Cleaning, Tear On Center Console, Tear On Drivers Seat, Floor Board Has Hole On Rubber Matting & On Drivers Side - Body Problems: Gear Indicator Is Not Working On Dash, Slightly Difficult To Turn Key On, Ignition Problem Oxidized Paint, Scratches, Surface Rust, Some Dents, Surface Rust/Scratch on Hood, Dent On Chrome Bumper - Tires Condition: Fair - Has A Lift Gate On Rear - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
10	(1) 2008 Chevy 2500 Heavy Duty Pickup Truck Vin #7249 - Runs	Unit #: 1335 - Conventional Style - Passengers: 3 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown Problems, Steering Column Having Problem At Ignition - Gas - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 09/19 - Approx. Mileage Reads: 161,148**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Tear On Drivers Seat, Worn Upholstery, Needs Cleaning, Steering Wheel Cover Worn - Body Condition: Fair - Body Problems: Dimple On Drivers Door, Oxidized Paint, Surface Scratches, Tommy Lift Gate Is Out Of Alignment, Right Rear Panel Is Scratched & Dents, Rock Chip On Windshield - Tires Condition: Fair - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
11	(1) 2000 Chevy 3500 Express Van Vin #1425 - Runs	Unit #: 1846 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Unknown Problems - Gas - Battery: Yes/Dead - Runs - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 02/20 - Approx. Mileage Reads: 168,443**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Worn Upholstery - Body Condition: Poor - Body Problems: Scratches On Drivers Side Door, Peeling Paint All Over, Surface Rust, Scratches/Rub On Left Rear, Dent On Right Front Wheel Well, Rockchip On Windshield - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**

-		
12	(1) 2007 Chevy Cargo Express Van Vin #8372 - Runs	Unit #: 1877 - Conventional Style - Passengers: 2 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown Problem - Gas - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Reads: 63,922**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Needs Cleaning, Upholstery Normal Wear - Body Condition: Fair - Body Problems: Oxidized Paint, Peeling Paint, Surface Scratches, Dents On Rear Entry Doors - Tires Condition: Fair
		- Current Condition Unknown
		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.
13	(1) 2006 Chevy 3500 Cargo Van Vin #1150 - Runs	Unit #: 1868 - Conventional Style - Passengers: 2 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown Problem - Gas - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 09/19 - Approx. Mileage Reads: 118,179**Unknown Actual Mileage**- Interior Condition: Fair To Pair - Interior Problems: Seat On Drivers Side Torn, Door Panel Arm Rest Broken, Needs Cleaning, (1) Loose Visor, Headliner Stained - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Peeling Paint On Rear Doors, Peeling Paint All Over, Some Dents, Surface Rust On Roof, Crack On Windshield - Tires Condition: Fair - Has Protection Cage, Has Headache Rack - Current Condition Unknown
		There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.
		All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.