Lot	Title	Description	Thumbnail
Number	Title	**There Will Be No Buyer's Premium Added To The Buyer's Total For Each Item	Titaliibilali
		Purchased. However. There Will Be A 3% Administrative Fee On All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order Or Wire Transfer**	
		Preview: Location 1: (Lots 1-14 & 26) Clute Service Center (Pct 1), 1432 Highland Park, Clute, TX 77531 Driving Directions (Bv Appointment Only-Mandatory-No Exceptions) Tuesday, June 23, 2020 (Hours: 8:00 am – 10:00 am and 1:30 pm - 3:00 pm). Appts MUST be made NO LATER than Monday June 22	
		NO APPOINTMENT NO INSPECTION – THIS WILL BE STRICTLY ENFORCED! NO WALK INS WILL BE ALLOWED. Each Appointment Time Limit Is For 30 Min. If You Are 15 Minutes Late, Your Appointment Will Be Canceled. You May (But Not	
		Guaranteed) Be Able To Reschedule IF There Are Other Available Appointments.	
		Location 2: (Lots 15-25) West Service Center (Pct 4), 121 N. 10th Street, West Columbia, Texas 77486 Driving Directions (Bv Appointment Only-Mandatory-No Exceptions) Wednesday, June 24, 2020 (Hours: 8: 00 am – 10:00 am and 1:30 pm - 3:00 pm). Appts MUST be made NO LATER than Tuesday June 23	
		NO APPOINTMENT NO INSPECTION – THIS WILL BE STRICTLY ENFORCED! NO WALK INS WILL BE ALLOWED.	
		Each Appointment Time Limit Is For 30 Min.  If You Are 15 Minutes Late, Your Appointment Will Be Canceled. You May (But Not Guaranteed) Be Able To Reschedule IF There Are Other Available Appointments.	
		Removal: Location 1: (Lots 1-14 & 26) Clute Service Center (Pct 1), 1432 Highland Park, Clute, TX 77531 Driving Directions Removal: By Appointment Only (to be scheduled 1 business day in advance) - Mandatory - No Exceptions.	
		Monday, June 29, 2020/Tuesday, June 30, 2020/Wednesday, July 1, 2020 (Hours Of Operation: 8:00 am – 10:30 am/1:30 pm – 3:30 pm (No Pickups Thursday or Friday) If vou are 15 minutes late, appointment to be re-scheduled for another day You are allowed 30 min removal Buver Solely Responsible For Removal. No Lifting Equipment Or Assistance Will Be	
0	0	Available Additional Notes Due To Corona Virus: Social distancing will be enforced at all locations Customers will not be allowed inside to use the restrooms. No Exceptions! Appointment MUST BE scheduled prior to removal. Customers may be turned away without an appointment scheduled	
	Preview & Removal Information	Everything Is Sold *As Is-Where Is* and with all faults and defects therein with No Warranties Or Guarantees Of Any Kind. Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied.  There Will Be NO Assistance Available For Removal. There Will Be No Dollies, Pallet	Read Me
		Jacks, Tools, Or Personnel To Assist  Preview & Removal Contact: Christy Browne, (979)864-1464, christyb@brazoria-county.	
		Location 2: (Lots 15-25) West Service Center (Pct 4), 121 N. 10th Street, West Columbia, Texas 77486 Driving Directions  Removal: By Appointment Only (to be scheduled 1 business day in advance) -  Mandatory - No Exceptions.  Monday, July 6, 2020/Tuesday, July 7, 2020/Wednesday, July 8, 2020 (Hours Of Operation: 8:00 am – 10:30 am /1:30 pm – 3:30 pm (No Pickups Thursday or Friday)	

	0	If vou are 15 minutes late, appointment to be re-scheduled for another day You are allowed 30 min removal Buver Solely Responsible For Removal. No Lifting Equipment Or Assistance Will Be Available Additional Notes Due To Corona Virus: Social distancing will be enforced at all locations Customers will not be allowed inside to use the restrooms. No Exceptions! Appointment MUST BE scheduled prior to removal. Customers may be turned away without an appointment scheduled	
		Everything Is Sold *As Is-Where Is* and with all faults and defects therein with No Warranties Or Guarantees Of Any Kind. Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied.  There Will Be NO Assistance Available For Removal. There Will Be No Dollies, Pallet Jacks, Tools, Or Personnel To Assist	
		Preview & Removal Contact: Christy Browne, (979)864-1464, christyb@brazoria-county.com	
		Please Click Here To Review Auction Terms For This Auction	
1	(1) 1997 International Water Truck - Red - Vin #1241 - UNIT MUST BE TOWED	UNIT MUST BE TOWED Approx. Mileage (NOT ACTUAL): 187,111 Specs: Diesel - Manual Windows & Locks Issues: No Battery - Engine Won't Run - Heavy Rust - A/C Not Working - Paint Missing On Doors Due To Decal Removal Heavy Wear Interior & Exterior Tire Condition: Unknown - TIRES ARE MISSING - Noted As Dry Rotted  **Units With Tires Missing, MUST Be Moved As Is. Tires CANNOT Be Installed On The Property In Order To Make Unit Driveable**  Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed	O
2	(1) 1987 International Water Truck - 1234 Vin #3660 - UNIT MUST BE TOWED	- Current Condition Unknown  UNIT MUST BE TOWED Approx. Mileage (NOT ACTUAL): 110,865 Specs: Diesel - Manual Windows & Locks Issues: No Battery - Engine Won't Run - Heavy Rust - A/C Not Working - Paint Missing On Doors Due To Decal Removal Heavy Wear Interior & Exterior Tire Condition: Unknown - Noted As Dry Rotted  Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed  - Current Condition Unknown	Onlinepress.com
3	(1) 2003 Chevrolet 2500 - 1252 - Vin #9091	Started And Ran NO GUARANTEE IT WILL START AT TIME OF PICKUP Approx. Mileage (NOT ACTUAL): 204,224 Specs: Vortex 6-cylinder Gas - Auto - Power Steering - Power Brakes - Power Windows - Power Locks Issues: Engine Is Starting To Wear - Paint Missing On Doors Due To Decal Removal - Heavy Interior Wear Tire Condition: Unknown Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Current Condition Unknown	

4	(1) 2003 Chevrolet 2500 - 1253 - Vin #9379	Started And Ran NO GUARANTEE IT WILL START AT TIME OF PICKUP Approx. Mileage (NOT ACTUAL): 181,657 Specs: Vortex 6-cylinder Gas - Auto - Power Steering - Power Brakes - Power Windows - Power Locks Issues: Engine Is Starting To Wear - Hood Damage - Tailgate Handle Missing - Paint On Doors Missing Due To Decal Removal - Heavy Interior Wear Tire Condition: Unknown Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Current Condition Unknown	WAR A
5	(1) 2004 International Dump Truck - 1262 - Vin #2954 - UNIT MUST BE TOWED	UNIT MUST BE TOWED Approx. Mileage (NOT ACTUAL): 201,017 Specs: DT-466 Diesel - Air Brakes - Power Steering - Manual Windows & Locks Issues: Diesel Leak Behind Motor - Low Power - Paint Missing On Doors Due To Decal Removal - Heavy Interior Wear Tire Condition: Unknown - Tires Are MISSING  **Units With Tires Missing, MUST Be Moved As Is. Tires CANNOT Be Installed On The Property In Order To Make Unit Driveable**  Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed  - Current Condition Unknown	loom loom
6	(1) 2009 International Dump Truck - 1288 - Vin #3652 - UNIT MUST BE TOWED	UNIT MUST BE TOWED Approx. Mileage (NOT ACTUAL): 177,414 Specs: DT-466 Diesel - Air Brakes - Power Steering - Manual Windows & Locks Issues: Emission Issues - Paint Missing On Doors Due To Decal Removal - Heavy Interior Wear Tire Condition: Unknown - Tire MISSING  **Units With Tires Missing, MUST Be Moved As Is. Tires CANNOT Be Installed On The Property In Order To Make Unit Driveable**  Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Current Condition Unknown	
7	(1) 1997 Chevrolet 3500 W /Mechanic Bed - 1308 - Vin #7820 - MAY NEED TO BE TOWED	MAY NEED TO BE TOWED - Did Not Start Battery Reports As Dead - NO GUARANTEE IT WILL START AT TIME OF PICKUP Approx. Mileage (NOT ACTUAL): 120,863 Specs: v8 Gas - Manual Windows & Locks Issues: Electrical Short On Motor - Paint Missing On Doors Due To Decal Removal - Heavy Interior Wear Tire Condition: Unknown -Dual Wheel  **Motorola Radio In Photos Has Been REMOVED. Not Part Of Auctioned Unit.  Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed  - Current Condition Unknown	
8	(1) 2017 Mack Dump Truck - 1324 - Vin #3058 - UNIT MUST BE TOWED	TOTALED - UNIT MUST BE TOWED Approx. Mileage (NOT ACTUAL): Specs: GU713 Diesel - Power Brakes & Steering - Standard Issues: Paint Missing On Doors Due To Decal Removal - Interior Is Weathered Due To Shattered Glass Tire Condition: Unknown Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Current Condition Unknown	
9	(Lot) Spectra & Topcon Lasers	(Approx. 9 Cases) Models Unknown Overall Working Condition: Unknown Noted As Broken - Reason Unknown - Current Condition Unknown	On ros.com

10	(Lot) L- Shaped Fuel Tanks	(Approx. 6) Condition Unknown Dims Unknown - Current Condition Unknown	
11	(Lot) Toolboxes	(Approx. 6) Headache Rack - Condition Unknown Dims Unknown - Current Condition Unknown	On to on.
12	(1) Essick C60W Cement Mixer	Serial 92006762 Working Condition: Unknown - Current Condition Unknown	W
13	(1) Truck Cab	NO Assistance Will Be Available To Load - Current Condition Unknown	
14	(Lot) Lights	(Approx. 8) Have Been Stored Outside Working Condition: Unknown - Current Condition Unknown	
15	(1) Strick Trailer	Model: 7400S33NFWG Vin #3618 Heavy Wear Roof Leaks Floor Weak Doors Do Not Seal Tire Condition: Unknown	
16	(1) Case 395 Tractor	- Current Condition Unknown  Vin #3009  Hours: Unknown 3 Cylinder Diesel Extremely Rusted No Top Link Tire Condition: Unknown  - Current Condition Unknown	
17	(1) 1988 Homemade Trailer	Vin #5916 Needs New Decking Extremely Rusted Tire Condition: Unknown - (1) Is Flat - Current Condition Unknown	
18	(1) 2001 Ford F250 - 4302 - Vin #7761 - MAY NEED TO BE TOWED	MAY NEED TO BE TOWED - Unit Was Jump Started - NO GUARANTEE IT WILL START AT TIME OF PICKUP Approx. Mileage (NOT ACTUAL): 239,754 Specs: 5.4L Triton, Gas - Power Brakes - Power Steering - Auto - Manual Windows - Power Locks Issues: Residue On Door Due To Decal Removal - Heavy Interior Wear - Huge Crack In Windshield Tire Condition: Unknown Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Current Condition Unknown	

19	(1) 2004 Chevrolet 2500 - Vin #7665 - MAY NEED TO BE TOWED	MAY NEED TO BE TOWED - Unit Was Jump Started - NO GUARANTEE IT WILL START AT TIME OF PICKUP Approx. Mileage (NOT ACTUAL): 184,047 Specs: 6L Vortec, Gas - Power Brakes - Power Steering - Auto - Manual Windows - Power Locks Issues: Runs In Limp Mode - Paint Missing On Doors Due To Decal Removal - Heavy Interior Wear - Tailgate Handle Missing - Passenger Door Will Not Close Tire Condition: Unknown Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Current Condition Unknown	
		Started & Ran. NO GUARANTEE IT WILL START AT TIME OF PICKUP	
20	(1) 2006 Dynapac Roller CP142 - Vin #2142	Specs: Cummins/B4.5 Diesel Tire Condition Unknown  Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed  - Current Condition Unknown	
21	(1) 2007 Ford LCF W /EZ Liner Striper - 4341 - Vin #8658 - MAY NEED TO BE TOWED	MAY NEED TO BE TOWED - Unit Was Jump Started - NO GUARANTEE IT WILL START AT TIME OF PICKUP Approx. Mileage (NOT ACTUAL): 239,754 Specs: V6 Diesel - Power Brakes - Power Steering - Auto - Manual Windows & Locks Tire Condition: Unknown Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed	
	TOVVLD	- Current Condition Unknown	
22	(Lot) Storm Generators & Air Compressors	(Approx. 1 Pallet) (Approx. 3) Universal Storm Generators - Honda & Kohler Engines (Approx. 2) Air Compressors - Working Condition Unknown Winning Bidder Is Responsible For Brining Own Equipment To LOAD Lot - Current Condition Unknown	
23	(1) 1600 Gallon Wylie Tank	Mounted On Frame To Fit Dump Bed Winning Bidder Is Responsible For Brining Own Equipment To LOAD Lot - Current Condition Unknown	
24	(1) 3400 Gallon Tank	Winning Bidder Is Responsible For Brining Own Equipment To LOAD Lot - Current Condition Unknown	
25	(1) Holmes FW-25 5th Wheeler Wrecker & Whitco 4030 Steam Cleaner	Working Condition Unknown Winning Bidder Is Responsible For Brining Own Equipment To LOAD Lot - Current Condition Unknown	
26	(Lot) Liftmore Truck Mounted Cranes	(Approx. 2) Model Unknown Working Condition: Unknown - Current Condition Unknown	