











Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p><b>IMPORTANT NOTICE FOR WALLER ISD AUCTION: <b>**All purchases will be subject to a 13% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</b></b></p> <p><b>*Social distancing will be enforced</b></p> <p><b>*Customers will not be allowed inside to use the restrooms. No Exceptions!</b></p> <p><b>*Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled.</b></p> <p><b>*We recommend wearing gloves and face mask for personal safety and health while on auction location.</b></p> <p><b>Preview Location 1:</b> (By Appointment Only-Mandatory-No Exceptions) Thursday, June 25, 2020 (Hours Of Operation: 8:00 a.m. - 12:00 p.m.)</p> <p><b>Location:</b> Waller Transportation, 19203 Stokes Rd, Waller, TX 77484 <a href="#">Driving Directions</a></p> <p><b>Removal:</b> (By Appointment Only-Mandatory-No Exceptions) Wednesday, July 1, 2020 /Monday, July 6, 2020/Tuesday, July 7, 2020 (Hours Of Operation: 8:00 a.m. - 2:00 p.m.)</p> <p><b>Preview &amp; Removal Contact:</b> Bridget Roome 936-372-2116 x1506</p> <p><b>There Will Be No Assistance Available For Removal. Buyer Must Provide Own Manpower &amp; Removal Equipment</b></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>	
1	(1) 1980 International Winch Truck Vin #5637 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED</p> <p>Passenger: 2</p> <p>Engine Problems: Unknown</p> <p>Diesel</p> <p>Has Battery</p> <p>Does Not Run</p> <p>Standard</p> <p>Inspection Sticker Month: May 2019</p> <p>Approx. Mileage (NOT ACUTAL): 6,550</p> <p>Interior Condition: Fair</p> <p>Interior Problems: Needs Cleaning - Steering Wheel Worn</p> <p>Body Condition: Fair</p> <p>Body Problems: Rust On Flat Bed &amp; Chains</p> <p>Tires Condition: Fair</p> <p>Tire Problems: Unknown</p> <p>Additional Information: Has Winch - Condition Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



2	(1) 1996 International Bus Vin #3676	<p>Unit #86  Passenger: 72  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Inspection Sticker Month: December 2019  Approx. Mileage (NOT ACUTAL): 243,146  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Some Scratches, Rust &amp; Dents  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
3	(1) 1996 International Bus Vin #5160	<p>Unit #92  Passenger: 71  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Inspection Sticker Month: December 2018  Approx. Mileage (NOT ACUTAL): 179,585  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Some Scratches, Rust &amp; Dents  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

4	(1) 1997 International Bus Vin #9625 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED  Unit #96  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine Problems: Transmission Issues  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: December 2019  Approx. Mileage (NOT ACUTAL): 225,590  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Seats Need Deep Cleaning - Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Some Scratches, Rust &amp; Dents  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
5	(1) 1997 International Bus Vin #9627	<p>Unit #93  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: December 2018  Approx. Mileage (NOT ACUTAL): 205,463  Interior Condition: Fair  Interior Problems: Torn Drivers Seat - Some Torn Seats In Back - Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



6	(1) 1998 International Bus Vin #0423	<p>Unit #102  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: December 2018  Approx. Mileage (NOT ACUTAL): 234,603  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Some Scratches, Rust &amp; Dents - Rust On Back Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
7	(1) 1997 International Bus Vin #9623	<p>Unit #97  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: December 2019  Approx. Mileage (NOT ACUTAL): 183,654  Interior Condition: Fair  Interior Problems: Torn Drivers Seat - Needs Cleaning - Some Torn Seats In Back  Body Condition: Fair  Body Problems: Paint Peeling On Hood - Oxidized Paint - Broken Window Beside The Very Back Passenger Side - Some Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

8	(1) 1996 International Bus Vin #3275	<p>Unit #85  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Inspection Sticker Month: December 2019  Approx. Mileage (NOT ACUTAL): 229,307  Interior Condition: Fair  Interior Problems: Torn Drivers Seat - Rust On Dashboard &amp; Steering Wheel - Needs Cleaning  Body Condition: Fair  Body Problems: Paint Peeling On Hood - Oxidized Paint - Some Scratches, Rust &amp; Dents  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
9	(1) 1998 International Bus Vin #0424	<p>Unit #104  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: January 2018  Approx. Mileage (NOT ACUTAL): 205,788  Interior Condition: Fair  Interior Problems: Torn Drivers Seat - Rust On Dashboard - Some Torn Seats In Back  Body Condition: Fair  Body Problems: Peeling Paint On Hood - Oxidized Paint - Some Scratches, Rust &amp; Dents - Window Cracked In Last Seat On Passenger Side - Rust On Back Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	


10	(1) 1998 International Bus Vin #0425	<p>Unit #10  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: January 2020  Approx. Mileage (NOT ACUTAL): 315,750  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Some Seats Torn In Back - Needs Cleaning  Body Condition: Fair  Body Problems: Peeling Paint On Hood - Oxidized Paint - Some Scratches, Rust &amp; Dents - Back Bumper Rusted  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
11	(1) 1996 International Bus Vin #3277	<p>Unit #89  Engine Size/Type: 3800 DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: November 2017  Approx. Mileage (NOT ACUTAL): 277,748  Interior Condition: Fair  Interior Problems: Needs Cleaning - Some Torn Seats In Back  Body Condition: Fair  Body Problems: Peeling Paint On Hood - Oxidized Paint - Some Scratches, Rust &amp; Dents - Rust On Back Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

12	(1) 1998 International Bus Vin #0456	<p>Unit #12  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: November 2017  Approx. Mileage (NOT ACUTAL): 200,423  Wheel Chair Lift: No  Interior Condition: Fair  Interior Problems: Torn Drivers Seat - Some Torn Seats In Back - Needs Cleaning  Body Condition: Fair  Body Problems: Peeling Paint On Hood - Oxidized Paint - Some Scratches, Rust &amp; Dents - Scratches &amp; Rust Above Wheel Well On Passenger Side - Rust On Back Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
13	(1) 1997 International Bus Vin #9622	<p>Unit #94  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: January 2018  Approx. Mileage (NOT ACUTAL): 201,749  Interior Condition: Fair  Interior Problems: Small Tears On Drivers Seat - Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Some Scratches, Rust &amp; Dents - Dent On Passenger Side Behind Wheel Well - Rust On Bumper  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: Radio Works</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



14	(1) 1997 International Bus Vin #9626	<p>Unit #95  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: October 2017  Approx. Mileage (NOT ACUTAL): 234,188  Interior Condition: Fair  Interior Problems: Rust On Dashboard - Torn Drivers Seat - Broken Window On Seat #10 - Needs Cleaning - Some Torn Seats In Back  Body Condition: Fair  Body Problems: Peeling Paint - Oxidized Paint - Some Scratches, Rust &amp; Dents - Rust On Back Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
15	(1) 1996 International Bus Vin #3273 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED  Unit #87  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: October 2017  Approx. Mileage (NOT ACUTAL): 218,165  Interior Condition: Fair  Interior Problems: Small Tears In Drivers Seat - Rust On Dashboard - Some Teas In Back Seats - Needs Cleaning  Body Condition: Fair  Body Problems: Cracked Windshield - Oxidized Paint - Peeling Paint - Scratches, Dents &amp; Rust - Rust On Back Bumper  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: Broken Frame - No Alternator</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



<p>16</p>	<p>(1) 1997 International Bus Vin #9624 - WILL NEED TO BE TOWED</p>	<p>WILL NEED TO BE TOWED  Unit #98  Passenger: 72  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Bad Engine Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: November 2017  Approx. Mileage (NOT ACUTAL): 141,607  Interior Condition: Fair  Interior Problems: Torn Drivers Seat - Rust On Dashboard - Needs Cleaning - Some Torn Seats In Back  Body Condition: Fair  Body Problems: Oxidized Paint - Some Scratches, Rust &amp; Dents - Rust On Back Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
-----------	---	---	---