


Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>**There Will Be No Bover's Premium Added To The Bover's Total For Each Item Purchased. However, There Will Be A 3% Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</p> <p>*Social distancing will be enforced *Customers will not be allowed inside to use the restrooms. No Exceptions! *Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled. *We recommend wearing gloves and face mask for personal safety and health while on auction location.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, June 4, 2020 (Hours Of Operation: 8:00 a.m. - 5:00 p.m.)</p> <p>Location: 4910 Airport Avenue, Rosenberg, TX 77471 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Thursday, June 11, 2020/Friday, June 12, 2020 (Hours Of Operation: 8:00 a.m. - 5:00 p.m.)</p> <p>Preview & Removal Contact: Tracy Graves (281) 239-1351 & Brenda Chapa, (281)239-1356</p> <p>Please Call For Appointment On Removal @ 281-239-1356 For The Vehicles: There Will Be A \$25.00 Title Preparation Fee Added To The Buyer's Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buvers responsibility once purchased by buyer. Bover should be aware that they are purchasing a used vehicle as it sits on the auction location with "No warranty" or "Guarantee Whatsoever". Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyer's to thoroughly inspect each vehicle prior to bidding.**</p>	
800	2005 Chevrolet Malibu Vin #4557	<p>Engine Size/Type: 3.5L, V6 Gas Has Battery Transmission Type: Automatic Brakes: Hydraulic (Approx. Mileage) NOT ACTUAL: 76,587 Interior Condition: Fair Interior Problems: Normal Wear & Tear Body Condition: Fair Body Problems: Some Paint Wear Inspection Sticker Month: June 2020 Tires Condition: Poor Tire Problems: Dry rot - Rims Have Paint Peel Additional Information: Automatic Lock Buttons Do Not Work - Rear Passenger Window Does Not Work - Check Engine Light Is On; It Needs EGR Valve Repair & Complete Update There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	