| Lot Number | Title | Description | Thumbnail |
|---------------|--|---|---------------------|
| 0 | Preview & Removal Information | **All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes** IMPORTANT NOTICE FOR MAGNOLIA ISD AUCTION: All purchases will be subject to a 14% buver's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.** *Social distancing will be enforced *Customers will not be allowed inside to use the restrooms. No Exceptions! *Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled. *We recommend wearing gloves and face mask for personal safety and health while on auction location. Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, July 16, 2020 (Hours Of Operation: 8:00 a.m 3:30 p.m.) Location 1: (Lots 7-34) Magnolia ISD Maintenance, 31138 Nichols Sawmill Rd., Magnolia, Tx 77355 - Behind Magnolia Jr. High/Tan Metal Warehouse Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Wednesday. July 22, 2020 (Thursday, July 23, 2020/Monday, July 27, 2020 (Hours Of Operation: 8:00 a.m 3:30 p. m.) Preview & Removal Contact: Rachel Collins. (281)252-2186 X1305 No Lifting Equipment And/Or Manpower Will Be Available. Buyer Solely Responsible For Removal. Location 2: (Lots 1-6) Transportation Department, 315 Sanders St., Magnolia, Tx 77355 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Wednesday. July 22. 2020 /Thursday, July 23, 2020/Monday, July 27, 2020 (Hours Of Operation: 8:00 a.m 3:30 p. m.) Preview & Removal Contact: Rachel Collins, (281)252-2186 X1305 Magnolia ISD Will Be Handling All Title Work For This Auction. Please Contact Seller For Title Information. Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. | 'ATTENTION' Read Me |
| 1 | (1) 2001 Thomas Bus Vin #6099 - WILL NEED TO BE TOWED | WILL NEED TO BE TOWED Unit #4136 Transit Style Passenger: 71 Engine Size/Type: 6.6L/L-6 Engine In Rear Engine Problems: Severe Oil Leak - Ran When Last Parked Diesel Has Battery Runs Automatic Transmission Type Or Condition: Unknown Brakes: Air Inspection Sticker Month: June 2020 Approx. Mileage (NOT ACTUAL): Unable To Read Interior Condition: Fair Interior Problems: Torn Drivers Seat Body Condition: Fair Body Problems: Back Bumper Rusted - Scratches, Dents & Rust - Some Peeling Paint Tires Condition: Fair Tire Problems: Unknown - Current Condition Unknown | |

| 2 | (1) 1996 International Bus Vin #4654 - WILL NEED TO BE TOWED | WILL NEED TO BE TOWED Unit #4105 Passenger: 71 Engine Size/Type: T444E/7.3L/V8 Engine Problems: Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Transmission Type Or Condition: Unknown Brakes: Unknown Inspection Sticker Month: July 2019 Approx. Mileage (NOT ACTUAL): 324,669 Interior Condition: Fair Interior Problems: Some Torn Seats - Needs Cleaning Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Scratches, Dents & Rust - Rust On Rear Bumper - Peeling Paint On Cowl Tires Condition: Fair Tire Problems: Unknown **Unit Was Used For Parts** - Current Condition Unknown | |
|---|---|--|--|
| 3 | (1) 1995 International Bus Vin #1234 - WILL NEED TO BE TOWED | WILL NEED TO BE TOWED Unit #4092 Passenger: 71 Engine Size/Type: 7.3L/V8 OHV 16V Engine Problems: Bad Motor Diesel Has Battery, Dead Unknown If It Runs Automatic Transmission Type Or Condition: Unknown Brakes: Air Inspection Sticker Month: June 2020 Approx. Mileage (NOT ACTUAL): 314,692 Interior Condition: Fair Interior Problems: Torn Drivers Seat - Needs Cleaning Body Condition: Fair Body Problems: Oxidized Paint - Scratches, Dents & Rust - Rust On Rear Bumper - Peeling Paint On Cowl Tires Condition: Fair Tire Problems: Unknown | |
| 4 | (1) 1963 International Loadstar Wrecker Vin #213F - WILL NEED TO BE TOWED | WILL NEED TO BE TOWED Unit #4092 Conventional Style Passenger: 2 Engine Size/Type: International Engine Problems: Needs Carburetors - Will Not Run Gas Does Not Have Battery Unknown If It Will Run Automatic Transmission Type Or Condition: Possibly Eaton 2 Or 3 Speed Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 04238 Interior Condition: Fair Interior Problems: Needs Cleaning - Rust On Drivers Side Door Panel - Rust On Floor Board - Missing Window Handle - Missing Inside Door Exit Handles Body Condition: Fair Body Problems: Rust On Grill & Front Bumper - Rust On Winch & Chain Tires Condition: Fair Tires Problem: Unknown Additional Information: Additional Gas Tank On Bed - Has Dual Fuel Tank On Truck - Has A Chelsea PTO - Has Heavy Duty Wrecker Bed W/Fuel Tank - Type Of Winch Unknown Information From Plate Located On Glove Compartment: Nomenclature: Truck - Tractor - Make & Model: 1800-151-WB - Mfg.: SN SB-382213-F - Vehicle Weight Unloaded: 7760 - Payload Max: 16,065 - Gross Weight Max: 40,000 - Date & Delivery: Nov 1963 - Current Condition Unknown | |

| 5 | (1) 2000 Chevy Cargo Van 1500 Express Vin #4113 - WILL NEED TO BE TOWED | WILL NEED TO BE TOWED Unit #5081 Passenger: 2 Engine Size/Type: 5.7L/V8 OHV 16V Engine Problems: Unknown Gas Has Battery, Dead Does Not Run Automatic Approx. Mileage: Unable To Read Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair to Poor Body Problems: Peeling Paint - Scratches, Dents & Rust - Cracked Windshield Tires Condition: Fair Tire Problems: Unknown Additional Information: Protection Cage - Shelf In Cargo Area | |
|----|---|---|-----------------|
| 6 | (1) 1987 International S1700 Bus Vin #7438 - WILL NEED TO BE TOWED | WILL NEED TO BE TOWED Unit #4061 Conventional Style Passenger: 71 Engine Size/Type: 6.9L/L-6 Engine In Front Engine Problems: Unknown Diesel Does Not Run Automatic Brakes: Air Inspection Sticker Date: July 2020 Approx. Mileage (NOT ACTUAL): 264,895 Interior Condition: Poor Interior Problems: Seats Torn - Hatches On roof Need Replacing - Interior Steps Soft Body Condition: Fair To Poor Body Problems: Oxidized Paint - Hood Is Loose On Bus - Some Damage On Hood - Rear Window Missing On Door End - Scratch On Rear Left Panel - Some Surface Rust - Current Condition Unknown | |
| 7 | (Lot) Bretford Wood Chairs | (Approx. 40) Elementary Size - Current Condition Unknown | 3 /4-1-1 |
| 8 | (Lot) Wood Chairs - Rocking | (Approx. 6) - Current Condition Unknown | |
| 9 | (Lot) Wood Chairs - Rocking | (Approx. 12) - Current Condition Unknown | |
| 10 | (Lot) Wood Chairs - Rocking | (Approx. 8) - Current Condition Unknown | |
| 11 | (Lot) Wood Chairs - Rocking | (Approx. 11) - Current Condition Unknown | |

| 12 | (1) Clarke Boost Floor Cleaner | (Approx. 32" Deck) Needs New Deck Worked At Time Of Removal - Current Condition Unknown | |
|----|--|--|--|
| 13 | (1) Clarke Walk Behind Floor Scrubber | Model: Focus II/Disk 26 Working At Time Of Removal - Current Condition Unknown | |
| 14 | (1) Clarke Walk Behind Floor Scrubber | Model: Focus II/Disk 26 Not Working, Missing Parts - Current Condition Unknown | |
| 15 | (Lot) Floor Machines | (1) Clarke Cleantrack 18 Carpet Scrubber - Missing Parts - Does Not Work (1) Clarke Summit20 Shopvac - Does Not Work (1) Clarke Summit20 Shopvac - Does Not Work (1) Alto Extractor Image26B Shampooer - Does Not Work - Current Condition Unknown | |
| 16 | (Lot) Clarke Boost Floor Scrubbers | (1) Floor Scrubber (1) Lid Missing - Works, But Does Not Move (1) Back Motor Is Out - Drain Pipe Needs Replacing - Does Not turn Left - Missing Deck - Current Condition Unknown | |
| 17 | (Lot) Clarke Focus II Boost Walk Behind Auto Scrubbers | (Approx. 3) (1) Works But Does Not Have A Vacuum (Approx. 2) Do Not Work - Current Condition Unknown | |
| 18 | (Lot) Clarke Focus II Boost Walk Behind Auto Scrubbers | (Approx. 3) (1) Unknown If It Works (1) Makes Popping Sound - Water Pours Out (1) Worked When Removed - Current Condition Unknown | |
| 19 | (Lot) Floor Buffer & Shopvac | (1) Propane Floor Buffer - Mfg. Eagle - Hours: 245 (1) Right Stuff Shopvac - 6.5hp - Current Condition Unknown | |
| 20 | (1) Winston Industries Thurm & Hold Warming Cabinet | 2 Doors Portable Cat:411GJ 3 Phase, 208V - Current Condition Unknown | |
| 21 | (1) Blodgett Double Convection Oven | Dual Flow Natural Gas Portable - Current Condition Unknown | |

| 22 | (1) Hobart Commercial Dishwasher | Model:C44A 3 Phase, 480V - Current Condition Unknown | |
|----|---|--|--|
| 23 | (1) Hobart Double Convection Oven | Natural Gas Model:HGC5 Stationary - Current Condition Unknown | |
| 24 | (1) Chest Type Freezer Made By Montgomery Wards | Model:89161 23.0 Cubic Feet (Approx. 35"High x 65-1/4" Wide x 29-1/2" Deep) Poor Condition - Current Condition Unknown | |
| 25 | (1) Hobart Double Convection Oven | Gas Stationary Model:HGC5-33 - Current Condition Unknown | |
| 26 | (1) Randell Prep Cabinet | Model Unknown 115V, Single Phase Insert Missing - Current Condition Unknown | |
| 27 | (1) Hobart 60 Qt Mixer | Model: H-600T Electric, 3 Phase, 200V Includes: Bowl, Paddle & Whisk - Current Condition Unknown | |
| 28 | (1) Hobart 60 Qt Mixer | Model: H-600T Electric, 3 Phase, 460V Includes: Bowl, Whisk & Protection Guard - Current Condition Unknown | |
| 29 | (1) Hatco Booster Water Heater | Model:S-13 3 Phase, 480V - Current Condition Unknown | |
| 30 | (1) Hatco Compact Series Booster Heater | Model: C-36 3 Phase, 480V - Current Condition Unknown | |
| 31 | (Lot) Levelators By Serve-O- Lift | (Approx. 3) Model:TCA2215 & Possibly Others - Current Condition Unknown | |

| 32 | (Lot) Levelators By Serve-O- Lift | (Approx. 3) Model:TCA2215 & Possibly Others - Current Condition Unknown | |
|----|--|---|--|
| 33 | (Lot) Levelators By Serve-O- Lift | (Approx. 3) Model:TCA2215 & Possibly Others - Current Condition Unknown | |
| 34 | (Lot) Levelators By Serve-O- Lift | (Approx. 2) Model:TCA2215 & Possibly Others - Current Condition Unknown | |