1	(1) Portable Building	Building ID #: C1-01552-A&B Mfg.: CoMark Bldg. Systems Year Mfg.: January 22, 2002 Double Approx. Size: 80' x 34' W/Eaves Restrooms: Yes, How Many: (2) Student & (1) Teacher Classroom(s): Yes, How Many: 2, Additional Rooms: (1) Conference Room & (1) Office Type Of Siding: Metal Type Of Roof: Metal Skid: Yes, What Type: Wood & Metal A/C Units Yes, How Many: 2 Brand A/C Units & Type: Package A/C Heat Units - Mfg.: Eubank Exterior Condition/Problems: Some Dents & Scratches Interior Condition/Problems: Some Dents & Scratches Interior Condition/Problems: Captorage Rooms - (1) Janitorial/Water Heater Room - Ceiling Tiles & Floor Look Okay - Will Need Minor Repairs & Restoration - Wood Ramps Conveyed W /Building - Fully Skirted Double Front Entry & Single Rear Entry Overall Condition: Fair *Some Of The Contents May Be Removed* Location: Winnsboro ISD Elementary, 310 West Coke Rd., Winnsboro, TX 75494, *Condition Unknown*, *This Item Is Being Sold "As/Is",* **Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions!**The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Winnsboro ISD And Must Contact Winnsboro ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977 - Current Condition Unknown	
2	(1) Portable Building	Single Approx. Size: 35' x 30' W/Eaves Restrooms: No Classroom(s): Yes, How Many: 1 Type Of Siding: Galvalume Metal Type Of Roof: Composition Skid: Yes, What Type: Wood A/C Units: Yes, How Many: 1 Brand A/C Units & Type: Package A/C Heat Units - Mfg.: Unknown Exterior Condition/Problems: Roof Will Need Some Repair - Some Dents & Scratches - (1) Gash On Rear About 10" Long - Unit Will Need Cleaning Interior Condition/Problems: On Right Side Ceiling Tiles Have Water Damage - Needs To Be Painted - Floor Appears Okay, Needs Cleaning - Has (1) Storage Room - Has (1) Mop Sink In Right Front Corner - Wood Ramp Will Be Conveyed Single Entry Overall Condition: Fair *Some Of The Contents May Be Removed* Location: Winnsboro ISD Elementary, 310 West Coke Rd., Winnsboro, TX 75494, *Condition Unknown*, *This Item Is Being Sold "As/Is",* **Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions** Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding, This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!**The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding Is The Sole For Requirement Information.*** Lemons Auctioneers 281-357-4977 - Current Condition Unknown	

3	(1) Portable Building	Repair On Left Side - Some Dents & Scratches - Will Need Some Roof Repair - Right Side Lower Panel Some Cuts On Panel & Trim Board Missing Interior Condition/Problems: (1) Room: Has Built In Counter W(2) Cabinets - (1) Room: Has Built In Bookcases & (1) Storage Cabinet - Some Tiles In Room #1 Has Water Stains & Damage To Tile - Room #2 Has (1) Wood Cabinet W/Formica Top Double Front Entry Overall Condition: Fair Location: Winnsboro ISD Elementary, 310 West Coke Rd., Winnsboro, TX 75494, *Condition Unknown*, *This Item Is Being Sold "As/Is", **Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions** Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Winnsboro ISD And Must Contact Winnsboro ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977 - Current Condition Unknown Double Approx. Size: 65' x 30' W/Eaves Restrooms: No Classroom(s): Yes, How Many: 2 Type Of Siding: Galvalume Metal Type Of Roof: Composition Skid: Yes, What Type: (Moor A/C Units: Yes, How Many: 3 Brand A/C Units & Type: (Approx. 2) Window Units - (1) Package A/C Heat Units Exterior Condition/Problems: Some Dents & Scratches - Fully Skirted - Lower Trim Board Will Need Replacing On Left Side - Needs Cleaning - Has Small Gash Under Rear Window - Paneling Slightly Warped On Right Side - (1) Small Gash On Right Side Interior Condition/Problems: Some Ceiling Tiles Are Damaged - Floor Tiles Okay, May Need Cleaning	
4	(1) Portable Building	 There Is A Door Between Both Rooms - Has (1) Teachers Cabinet - Wood Ramp & Platform Conveyed With Building Double Front Entry Overall Condition: Fair Location: Winnsboro ISD High School, 409 Newsome Street Winnsboro, TX 75494, *Condition Unknown*, *This Item Is Being Sold "As/Is",* **Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions** Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding on Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Winnsboro ISD And Must Contact Winnsboro ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977 - Current Condition Unknown 	

5	(1) Portable Building	Double Approx. Size: 65' x 30' W/Eaves Restrooms: No Classroom(s): Yes, How Many: 2 Type Of Siding: Galvalume Metal Type Of Roof: Composition Skid: Yes, What Type: Wood A/C Units: Yes, How Many: 5 Brand A/C Units: Type: Room #1: (1) Package AC/Heat Unit & (1) Window Unit - Room #2: (1) AC /Heat Package Unit, (1) Window Unit & (1) Mini Split 3 Ton Unit Exterior Condition/Problems: Some Dents & Scratches - Fully Skirted - Some Damage On Skirting - Has Notable Dents On Right Rear Side Interior Condition/Problems: There Are A Few Stains On Ceiling Tiles, Some Are Damaged - Floor Okay, Some Stains - Room #2: Has Missing Ceiling Tile Double Front Entry Overall Condition: Fair Location: Winnsboro ISD Middle School, 505 S Chestnut St., Winnsboro, TX 75494, *Condition Unknown*, *This Item Is Being Sold "As/Is",* **Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions** Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!**The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding Is The Sole For Requirement Information.*** Lemons Auctioneers 281-357-4977 - Current Condition Unknown	
6	(1) Portable Building	Unit: G Hall Double Approx. Size: 65' x 30' W/Eaves Restrooms: Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Roof: Composition Skid: Yes, What Type: Wood A/C Units: Yes, How Many: 3 Brand A/C Units & Type: Has Package Unit But Utilizes A Mini Split Unit Exterior Condition/Problems: Some Dents & Scratches - Will Need Some Refresh Painting - Skirting In Poor Condition/Problems: Some Dents & Scratches - Will Need Some Refresh Painting - Skirting In Poor Condition/Problems: Some Dents & Scratches - Will Need Some Refresh Painting - Skirting In Poor Condition/Problems: A Few Interior Ceiling Tiles Have Water Stains - Room #1: (Approx. 6) Tub/Mop Sinks, (Approx. 4) Science Cables/Compartment, (1) Water Heater, (1) Bathroom - Room #2: (1) Water Fountain & (1) Bathroom Double Front Entry Overall Condition: Fair *Unit Was Utilized As A Science Lab* Location: Winnsboro ISD Middle School, 505 S Chestnut St., Winnsboro, TX 75494, *Condition Unknown*, *This Item Is Being Sold "As/Is",* **Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions** Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Winnsboro ISD And Must Contact Winnsboro ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977 - Current Condition Unknown	

7	(1) Portable Building	Unit: WISD DAEP (District Alternative School) Double Approx. Size: 80' x 30' W/Eaves Restrooms: Yes, How Many: 2 Classroom(s): Yes, How Many: 1 Room W/(2) Offices Type Of Roof: Metal Skid: Yes, What Type: Wood A/C Units: Yes, How Many: 2 Brand A/C Units & Type: Central A/C & Heat Units Exterior Condition/Problems: A Few Pieces Of Hardiplank Are Damaged Interior Condition/Problems: A Few Pieces Of Hardiplank Are Damaged Interior Condition/Problems: T5% Of The Interior Flooring Needs To Be Replaced, Floor Is Sagging - Has Water Heater - Has Water Fountain Double Front Entry & (1) Rear Door Entry Overall Condition: Exterior: Fair - Interior: Poor *Concrete Steps Will Be Conveyed W/Building* **Furniture Will Not Convey W/Building* **Furniture Will Not Convey W/Building* Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions!!**The Cost And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions!!**The Cost And Removal Of Each Building Is The Sole (Building Mover Prior To Bidding, This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!**The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding Is The Sole For Requirement Information.*** Lemons Auctioneers 281-357-4977 - Current Condition Unknown	
---	-----------------------------	--	--