Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	 **All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes** IMPORTANT NOTICE FOR EL CAMPO I.S.D. AUCTION: **All purchases will be subject to a 8% buyer's premium. However, There Will Be A 3% Administrative Fee On All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order Or Wire Transfer** *Social distancing will be enforced *Customers will not be allowed inside to use the restrooms. No Exceptions! *Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled. *We recommend wearing gloves and face mask for personal safety and health while on auction location. Preview: There Is No Preview For This Auction Location: El Campo ISD Transportation Department, 310 West Loop, El Campo, TX 77437 Driving Directions Removal: (By Appointment Only - Mandatory - No Exceptions) Monday, August 10, 2020/Tuesday, August 11, 2020 (Hours Of Operation: 8:00 a.m 4:00 p.m.) Preview & Removal Contacts: Mark Freeman 979-543-5252 There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** Must Call & Set An Appointment For Preview & Removal. There Will Be No Assistance Available With Removal. Buyer Is Solely Responsible For Bringing Own Manpower & Loading Equipment. 	FATTENTION Read Me
2	(1) 2006 Ford Pickup Vin #8164	Engine Size/Type: V6 Gas Has Battery Runs Standard Transmission Type Or Condition: Automatic/Good Brakes: Hydraulic Inspection Sticker Month: January 2021 Approx. Mileage (NOT ACTUAL): 96,587 Interior Condition: Poor Interior Problems: Torn Seats - Stained Seats Body Condition: Fair Body Problems: Rust Along Bed Rail - Dents In Front Right & Rear Right Fender Tires Condition: Fair There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	

7	(1) 2007 Chevy Cargo Van Vin #2478	Passenger: 2 Engine Size/Type: 4.8L V8 Engine In Front Gas Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Hydraulic Inspection Sticker Month: August 2020 Approx. Mileage (NOT ACTUAL): 48,914 Interior Condition: Good Interior Problems: None Body Condition: Fair Body Problems: Paint Peeling In Several Areas - Minor Rust On Body Tires Condition: Fair Additional Information: Food Service Serving Tray Rack Mounted To Interior Of Cargo Area - New Battery There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	
10	(1) 2004 Ford Pickup Vin #5487	Passenger: 5 Engine Size/Type: 6.0 Powerstroke Engine In Front Engine Problems: Runs Good - Needs To Warm Up - Needs Injector & Drivers Front Hub Diesel Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Hydraulic Inspection Sticker Month: December 2020 Approx. Mileage (NOT ACTUAL): 152,476 Interior Condition: Good Interior Problems: Stains On Seats - Needs Cleaning Body Condition: Good Body Problems: Rust On Wheel Hubs Tires Condition: Poor Tire Problems: Needs New Tires There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	

12	(1) 2016 Ford Pickup Vin #8810	Passenger: 6 Engine Size/Type: 6.7 Powerstroke Engine In Front Engine Problems: Exhaust/Emission System Issue - DEF Tank Needs To Be Replaced Diesel Has Battery Runs Automatic Transmission Type Or Condition: Unknown Brakes: Hydraulic Inspection Sticker Month: November 2020 Approx. Mileage (NOT ACTUAL): 64,313 Interior Condition: Good Interior Problems: Needs Cleaning Body Condition: Good Body Problems: None Tires Condition: Good There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	
22	(1) 2004 International Bus Vin #3028	Unit # 52 Passenger: 35 Conventional Style Engine Size/Type: 7.3 Engine In Front Engine Problems: Engine Runs Excellent - Electrical Fault In Gauge Cluster - Gauges Have Intermittent Issues Diesel Has Battery Runs Automatic Brakes: Air Inspection Sticker Date: March 2021 Approx. Mileage (NOT ACTUAL): 211,597 Interior Condition: Fair Interior Problems: Normal Wear Body Condition: Fair Body Problems: Dent On Front Overhead By Flashing Light - Paint Discoloration & Wear Tires Condition: Good There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown	